

**AGENDA
MEETING WITH NMED
JUNE 20, 1997**

 ENTERED

LOCATION: NMED Offices--Runnels Building, Santa Fe, NM
TIME: 9:30am

INTRODUCTION

PURPOSE OF MEETING

PRESENTATION OF STATUS OF THE MANAGEMENT OF
UNDERGROUND WATER AT THE WIPP

DISCUSSION

970616








Figure B-11
Plan View of the Underground Showing Midheight Centers of Underground Disposal Area at the Orange Marker Band Relative to Sea Level

WIPP SAR




FIGURE 4.3-1. Waste Shaft and Waste Hoist Equipment Arrangements
January 1983

Management of Brine in the WIPP Underground: Status Report

New Mexico Environment Department
Harold Runnels Building

June 20, 1997

June 20, 1997

1



Purpose

- Bring the NMED up to date on what has transpired since the shaft liner leak was identified *Found in May 95*
 - Salt cake on probes at Station A *early 90's*
 - Increased flow in the Waste Shaft Sump *change of fan operations*
 - June '95 newspaper articles on the WIPP "leak"
 - September 1995 meeting with NMED (*Secretary trip*)
 - December 1996 conference call with NMED

June 20, 1997

2



Purpose


- Provide current status of activities to manage brine
 - brine collection
 - brine analysis
 - liner leak mitigation
 - brine disposition

June 20, 1997

3




Plan View of WIPP Underground Facility



June 20, 1997

Schematic Drawing WIPP Exhaust Shaft and Waste Shaft



June 20, 1997

5



Historical Summary

Sources of Water in the U/G

- Shaft leakage prior to grouting 1985
 - small volume leak
 - water used for dust control
- Concrete curing in the WHB/WS 1985
 - used for dust control



Historical Summary

Sources of Water in the U/G

- Air Intake Shaft 1989 - 1994

1684 – Flushing of the upreaming bit (progress was slowed by worn cutter bits) ~ *20,000 gallons*

- **ceased using water for dust control (1992)**

– Inflow from water bearing strata prior to grouting (first large quantity of water pumped from the underground) 1990



Historical Summary

Sources of Water in the U/G

- Air Intake Shaft (cont.)
 - Prior to grouting, water was pumped into a “frac” tank — *tested before disposal*
 - Emergency permit to discharge into the salt pile evaporation pond

June 20, 1997

8



Historical Summary of Water Pumped

(continued)

- Evaporation cell added to WIPP sewage lagoon for discharge of non-hazardous brines
- Discharge Permit (DP-831) obtained from NMED Groundwater Protection Bureau *1500 - 2000 gal / day
must meet MCL's*

June 20, 1997

9



Historical Summary of Water Pumped

- 1993 - No Records: quantities were generally small
- 1994 - 5,850 gallons: drought/full fan operations
- 1995 - 11,660 gallons
 - reduced fan operations
 - drought ending
 - increase in volume caused additional sampling
- 1996 - 10,373 gallons
- 1997 - 6,012 gallons *to date*

June 20, 1997

10



Water Sources

- Condensation
- Liner Leakage

June 20, 1997

11



Condensation

- Can produce large quantities but only during summer when relative humidity is high.
- Intake air contribution may reach 75% to 95% of water introduced when surface relative humidity is high, depending on amount of diesel equipment in use.

underground weather stations measure relative humidity



Liner Leakage

- Small, consistent flow first noted May, 1995, during a video inspection of the ES. It may not reach shaft bottom except when ventilation flow rate is low or condensation rate is high. *estimate ~ 1/2 gallon/min*
- Leakage is not significant compared to normal mine operations *- simply adds to water balance*
- Ventilation reduced on weekends starting October 1994.
- Indications of moisture in shaft were observed as salt build-up on Station A probe.

June 20, 1997

13



Liner Leakage

*Possible Sources - Fresh water
Not identified yet*

- Precipitation infiltration
- Establishment of local recharge areas
- Domestic water line leakage

*in a trench, since many lead to
exhaust shaft.*

*Fire line is pressurized, pumps cycle on/off
to maintain pressure - indicate minor leak*



Exhaust Shaft Liner Leakage

- Underground Lead/Brine Working Group (NMED participant) formed in July 1995.
- Catchment basin installed on 3/12/96 to facilitate operational efficiency to prevent brine from reaching WS sump in large volumes.
- At installation, there was no indication that catchment basin brine would contain Pb at hazardous levels.

June 20, 1997

15




Description of Catchment Basin

- High density polyethylene (HDPE) plastic
- 250 mil thick
- 19' wide x 28' long x 1' deep - segmented
- Deflection shield connects the two segments as well as diverts condensation droplets away from the seam and into either side (500 mil thick)
- Welds visually leak detected by vacuum and soap solution &/or a spark tester

*2600 gal capacity
1600 effective cap*



Assembled Catchment Basin




NOTE:
INTERNAL AND OR EXTERNAL
SUPPORTS ALLOWED AS REQUIRED
BY CONTRACTOR DESIGN

June 20, 1997

17



Elevation View of Catchment Basin




June 20, 1997



19



Detail of Catchment Basin



DETAIL A
CATCHMENT BASIN MODULE



DETAIL B
CENTER DEFLECTOR SHIELD



Lead

- First noted any lead in WS Sump - August, 1993
- no sampling in 94 (drought)
- First detected hazardous levels in WS Sump of Pb in February, 1995
- Discussed with NMED on 9/1/95 trip to Santa Fe.
Den Robertson, SOE
- First detected hazardous levels of lead in ES catchment basin in May 1996

June 20, 1997

21



Lead Sources

- Lead as impurity in galvanizing zinc on chain link mesh used for support.
- *Analysis of Corrosion Testing Results from Galvanized Mesh Material Obtained from the Waste Isolation Pilot Plant, New Mexico (DOE/WIPP 96-2212)*

Lead/Zinc ratios indicate high probability that lead leached from galvanized shaft support material.



The Lead/Zinc Ratio's Relationship with Boron

- High concentrations of boron indicate indigenous Salado Formation brine as in the case of Borehole EE37B
- Graph indicates Pb/Brine in ES basin WS sump and proximate boreholes are comprised of non-indigenous brine, i.e., brine results from inflow of condensation. *of*



Current Activities

- **Brine** *Removed on a weekly basis, checked daily*
 - Managed under DP-831
 - Disposed of as hazardous waste – *all of it*
- **Leak**
 - Preparing de-watering holes
 - Investigating cause – *drilled 3 holes to determine location of water, flow direction*

*will drill 2 more "upstream" holes
dewater by pumping*

June 20, 1997

25



Current Activities

- Part B Permit Application - Changes to Corrective Action Chapter
 - closed ES Sump SWMU
 - added ES Catchment Basin
 - revised description to WS sump SWMU
- Increased fan usage
 - 3rd fan for reliability



Summary

- Managing brine to minimize impacts on operations
- Investigating source of water leaking through liner
- Disposing of all brine as hazardous waste

June 20, 1997

27



Summary

- If NMED has any questions or concerns please contact us
 - Kevin Donovan at 234-8325
 - Craig Snider at 234-7452
 - Cooper Wayman at 234-7329
 - Gloria Barnes at 234-8383
 - Bob Kehrman at 234-8690
 - Wille Most at 234-8961
- If the public raises issues which we can help resolve, please contact any of the above

June 20, 1997

28

