

HWB PHOTO SHEET



Facility: Las Cruces Airport

Photo #: 2766

Date/Time: 1/28/20 4:04 pm

Location: west side of Southwest Aviation hangars facing north.

Description: concrete structure used to store used oil. Used oil is leaking out of the bottom corner.

Violation(s): Failure to respond to releases of used oil. 40 CFR 279.22(d).



Facility: Las Cruces Airport

Photo #: 2767

Date/Time: 1/28/20 4:04 pm

Location: Facing north.

Description: Same as above.

Violation(s): Same as above.

HWB PHOTO SHEET



Facility: Las Cruces Airport

Photo #: 2768

Date/Time: 1/28/20 4:04 pm

Location: inside the concrete structure.

Description:

Violation(s):



Facility: Las Cruces Airport

Photo #: 2770

Date/Time: 1/28/20 4:04 pm

Location: south side of concrete structure.

Description: oil contaminated debris.

Violation(s): same as above.