



REPLY TO
ATTENTION OF:



DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1 PERSHING ROAD
FORT BLISS, TEXAS 79916-3803



December 14, 2012

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On April 13, 2012, the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site inspection of the McGregor Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 18/FTBL-013 as per NMED letter dated June 12, 2007. The correspondence indicated that the following information must be included in the site inspection; observations of the run-on controls, landfill cover and submit photographs and descriptions of the site to NMED annually.

During the inspection of April 13, 2012, the landfill cover, native vegetative, fence and signage of SWMU-18 landfill were found to in very good condition. There is evidence of some minor erosion on the extreme edges of the site; however this is not affecting the cover of the landfill.

If you have any questions concerning this report, please do not hesitate to contact Joel Reyes, at 915-568-6993, joel.reyes20.civ@mail.mil.

Sincerely,

Vicki G. Hamilton, R.A.
Chief, Environmental Division
Directorate of Public Works

Enclosures

**McGregor Range Camp Rubble Landfill Inspection
SWMU-18/FTBL-013**

Unit: IMBW- PWE

Inspection Date: 04-13-2012

Facility ID: FTBL-13

Facility Name: SWMU-18

Assessor: Joel Reyes

Telephone Number: (915) 568-6993

Email Address: joel.reyes20.civ@mail.mil


List of Observations:

1. Observation: A small amount of erosion was found on the extreme southwest portion of SWMU-18 / FTBL-013; however, there is no subsidence and/or erosion on the cover of the landfill.
2. Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.
3. Observation: Signage was in good condition. The fence on the southern portion of SWMU-18 / FTBL-013 shows signs of sagging, however, in January 2013 the entire fence around this will be restrung.

Observations #1 and #2

Observation: A small amount of erosion was found on the extreme southwest portion of SWMU-18 / FTBL-013; however there is no subsidence and/or erosion on the cover of the landfill.

Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.



**McGregor Range Camp Rubble Landfill Inspection
SWMU-18/FTBL-013**

Observation #3

Signage was in good condition. The fence on the southern portion of SWMU-18 / FTBL-013 shows signs of sagging, however, in January 2013 the entire fence around this landfill will be restrung and tightened.

