



REPLY TO  
ATTENTION OF:

**DEPARTMENT OF THE ARMY**  
US ARMY INSTALLATION MANAGEMENT COMMAND  
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS  
1 PERSHING ROAD  
FORT BLISS, TEXAS 79916-3803

 **ENTERED**



December 14, 2012

Environmental Division

Mr. David Cobrain  
Project Leader  
New Mexico Environmental Department-HWB  
2905 Rodeo Park Drive East, Building 1  
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On April 17, 2012, the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site inspection of the Dona Ana Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 29/FTBL-011 as per NMED letter dated May 27, 2008. The correspondence indicated that the following information must be included in the site inspection: observations of the run-on controls, landfill cover and submit photographs and descriptions of the site to NMED annually.

During the inspection of April 17, 2012, the landfill cover, native vegetative, fence and signage of SWMU-29 landfill were found to in very good condition. There is evidence of some minor erosion on the extreme edges of the site, however this will not affect the capped area.

If you have any questions concerning this report, please do not hesitate to contact Joel Reyes, at 915-568-6993 or joel.reyes20.civ@mail.mil.

Sincerely,

Vicki G. Hamilton, R.A.  
Chief, Environmental Division  
Directorate of Public Works

Enclosures

**Dona Range Camp Sanitary Landfill Inspection  
SWMU-29/FTBL-011**

Unit: IMBW- PWE

Inspection Date: 04-17-2012

Facility ID: FTBL-11

Facility Name: SWMU-29

Assessor: Joel Reyes

Telephone Number: (915) 568-6993

Email Address: joel.reyes20.civ@mail.mil

List of Observations:

1. Observation: A small amount of erosion was found on SWMU-29 / FTBL-011 landfill.
2. Observation: Vegetation is very healthy on the surrounding area of the landfill and on the final cover.
3. Observation: Signage and fences were in good condition.

Observations #1

Observation:  
A small amount of erosion was found on SWMU-29 / FTBL-011 landfill. However this erosion is not affecting the capped area.



**Dona Range Camp Sanitary Landfill Inspection  
SWMU-29/FTBL-011**

Observation #2

Observation:  
Vegetation is very healthy on the surrounding area of the landfill and on the final cover.



Observation #3

Observation:  
Signage and fences were in good condition

