



REPLY TO  
ATTENTION OF:

**DEPARTMENT OF THE ARMY**  
US ARMY INSTALLATION MANAGEMENT COMMAND  
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS  
1741 MARSHALL ROAD  
FORT BLISS, TEXAS 79916

 **ENTERED  
RECEIVED**

**JAN - 8 2014**

NMED  
Hazardous Waste Bureau

January 2, 2014

Environmental Division

Mr. David Cobrain  
Project Leader  
New Mexico Environmental Department-HWB  
2905 Rodeo Park Drive East, Building 1  
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On May 30, 2013, the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site inspection of the Closed McGregor Range Camp Rubble Landfill #13, Solid Waste Management Unit (SWMU) No. 18/FTBL-013 as required per NMED letter dated June 12, 2007. The correspondence indicated that the following information must be included in the site inspection; observations of the run-on controls, landfill cover and submit photographs and descriptions of the site to NMED annually.

During the inspection of May 30, 2013, the landfill cover, native vegetative, fence and signage of SWMU-18 landfill were found to be in very good condition. There is evidence of some minor erosion on the southern boundary of the site; however, this does not affect the landfill's evapo-transpiration cover of the landfill.

If you have any questions concerning this report, please do not hesitate to contact Joel Reyes, at 915-568-6993, joel.reyes20.civ@mail.mil.

Sincerely,

Vicki G. Hamilton, R.A.  
Chief, Environmental Division  
Directorate of Public Works

Enclosures

# McGregor Range Camp Rubble Landfill Inspection

## SWMU-18/FTBL-013

Unit: IMBW- PWE

Inspection Date: 5-31-2013

Facility ID: SWMU-18/FTBL-13

Facility Name: Closed McGregor Range Camp Rubble Pit #13

Assessor: Joel Reyes

Telephone Number: (915) 568-6993

Email Address: joel.reyes20.civ@mail.mil

### List of Observations:

1. Observation: Looking across the landfill to the southwest, there is no subsidence and/or erosion on the cover of the landfill.
2. Observation: Vegetation condition is healthy on the surrounding area of the landfill and the final cover.
3. Observation: Signage was in good condition. The fence on the southern portion of SWMU-18 / FTBL-013 shows signs of sagging; however, on January 23, 2013, the retighting of the wire fence around the landfill was completed.

<u>Observations #1</u>	
<p>Looking Southwest there is no subsidence and/or erosion on the cover of the landfill.</p> <p>Observation: Vegetation condition is healthy on this portion of the landfill. All area of the landfill has a good cover of vegetation.</p>	

**McGregor Range Camp Rubble Landfill Inspection  
SWMU-18/FTBL-013**

<p><u>Observation #2</u></p> <p>Looking Northeast Vegetation condition is healthy on the surrounding area of the landfill and the final cover.</p>	 <p>A photograph showing a wide, flat desert landscape under a clear blue sky. The ground is sandy and covered with numerous small, scrubby bushes and grasses. In the distance, a line of utility poles or fence posts is visible against the horizon. The overall appearance is that of a well-maintained or naturally recovering desert environment.</p> <p>31 924</p>
--	--

<p><u>Observation #3</u></p> <p>Looking North the fence wires have been retightened and the signage is in good condition. The fence wire work was completed on January 23, 2013.</p>	 <p>A photograph of a desert landscape looking north. A fence line runs across the middle ground, with a small white sign attached to it. The terrain is sandy with sparse vegetation. The sky is clear and blue. The overall scene shows a well-maintained boundary area.</p> <p>31 924</p>
--	--