



REPLY TO
ATTENTION OF:

DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1741 MARSHALL ROAD
FORT BLISS, TEXAS 79916

 **ENTERED**

RECEIVED

JAN 8 2014

**NMED
Hazardous Waste Bureau**

January 2, 2014

Environmental Division

Mr. David Cobrain
Project Leader
New Mexico Environmental Department-HWB
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303

Dear Mr. Cobrain:

On May 30, 2013, the Directorate of Public Works, Environmental Division conducted the annual Post-Closure Site inspection of the Dona Ana Range Camp Landfill, Solid Waste Management Unit (SWMU) No. 29/FTBL-011 as per NMED letter dated May 27, 2008. The correspondence indicated that the following information must be included in the site inspection: observations of the run-on controls, landfill cover and submit photographs and descriptions of the site to NMED annually.

During the inspection, the landfill cover, native vegetation, fence and signage of SWMU-29 landfill were found to be in very good condition. There is evidence of some minor erosion on the eastern/western boundary of the site. However this will not affect the capped area what so ever.

If you have any questions concerning this report, please do not hesitate to contact Joel Reyes, at 915-568-6993 or joel.reyes20.civ@mail.mil.

Sincerely,

Vicki G. Hamilton, R.A.
Chief, Environmental Division
Directorate of Public Works

Enclosures

Dona Range Camp Sanitary Landfill Inspection
SWMU-29/FTBL-011

Unit: IMBW- PWE

Inspection Date: 05-30-2013

Facility ID: SWMU-29/FTBL-011

Facility Name: Dona Ana Range Camp Sanitary Landfill #11

Assessor: Joel Reyes

Telephone Number: (915) 568-6993

Email Address: joel.reyes20.civ@mail.mil

List of Observations:

1. Observation: An area approximately 2 x 3 of erosion was found on SWMU-29/ FTBL-011 landfill.
2. Observation: Vegetation is healthy on the surrounding area of the landfill and the final cover.
3. Observation: Signage and fences were in good condition.

<u>Observation #1</u>	
<p>Observation: An area approximately 2' x 3' of erosion was on the landfill. However, this erosion does not affect the capped area.</p>	

**Dona Range Camp Sanitary Landfill Inspection
SWMU-29/FTBL-011**

Observation #2

Looking Northwest:
Vegetation condition is healthy on the surrounding area of the landfill and the final cover.



Observation #3

Looking Northwest :
Signage and fences were in good condition

