



DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1741 MARSHALL ROAD
FORT BLISS, TEXAS 79916



ENTERED

DEC 21 2018



Directorate of Public Works

Mr. David Cobrain
Project Leader
New Mexico Environmental Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6303

RE: Submittal of Annual Post-Closure Site Inspection Report, Fort Bliss Site No. 13 (FTBL-013)/Solid Waste Management Unit 18 (SWMU-18) McGregor Range Camp Landfill, Fort Bliss, New Mexico

Dear Mr. Cobrain:

The annual post-closure site inspection of the McGregor Range Camp Landfill, FTBL-013/SWMU-18 took place on October 24, 2018, in accordance with the requirements stated in the New Mexico Environmental Department letter, dated June 12, 2007.

The correspondence stipulated an annual inspection and photographs of the landfill cover, drainage system and vegetation. The inspection found the landfill cover, drainage structures, vegetative layer, perimeter fence and warning signs remain in good condition (Enclosure).

Should you have any questions, please contact Mr. Jesus D. Moncada, Chief, Compliance Branch, Environmental Division, at (915) 568-2632 or jesus.d.moncada.civ@mail.mil.

Sincerely,

Alfredo J. Riera, P.E.
Director of Public Works

Enclosure

McGregor Range Camp Landfill – Annual Inspection

FTBL-013/SWMU-18

Unit: IMBL- PWE

Inspector: Sergio H. Celis

Facility ID: FTBL-013/SWMU-18

Telephone Number: (915) 568-5205

Facility Name: McGregor Range Camp Landfill

Email: sergio.h.celis.ctr@mail.mil

Inspection Date: October 24, 2018

List of Observations:

1. The landfill cover remains uniform and in good condition. There is no evidence of erosion or depression on the cap's surface.
2. The vegetative layer on the landfill cap and immediate areas within the fenced property remains in good condition.
3. The site perimeter fence, warning signs and drainage structures remain in good condition. The site perimeter fence and gate did not require maintenance or repairs.

Inspection photographs

Photograph No. 1

View of landfill gate facing Southeast.

Landfill gate and site perimeter fence remain in good condition.

Lock and chain remain in good condition and functioning properly.



McGregor Range Camp Landfill – Annual Inspection FTBL-013/SWMU-18

Photograph No.2

View of landfill cap facing North.

No signs of erosion or depression on landfill cap.

The vegetative layer remains in good condition.

West – East fencing and signage remain in good condition.



Photograph No. 3

View of landfill cap and fence facing South.

No signs of erosion or depression on landfill cap.

The vegetative layer remains in good condition.

Fence and signage remain in good condition.



McGregor Range Camp Landfill – Annual Inspection FTBL-013/SWMU-18

Photograph No. 4

View of landfill cap facing South.

No signs of erosion or depression on landfill cap.

The vegetative layer remains in good condition.

NW-SE fencing and signage remain in good condition.



Photograph No. 5

View of landfill cap facing Northeast.

No signs of erosion or depression on landfill cap.

The vegetative layer remains in good condition.

Eastern fencing and signage remain in good condition.



**McGregor Range Camp Landfill – Annual Inspection
FTBL-013/SWMU-18**

Photograph No. 6

Eastern fence and signage remain in good condition.

No evidence of significant erosion.

Vegetative layer remains in good condition.



Photograph No. 7

Southern fence facing North.

Site perimeter fence remains in good condition.



**McGregor Range Camp Landfill – Annual Inspection
FTBL-013/SWMU-18**

Photograph No. 8

Western fence
facing South.

Site perimeter fence
remains in good
condition.

