



DEPARTMENT OF THE ARMY
US ARMY INSTALLATION MANAGEMENT COMMAND
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT BLISS
1741 MARSHALL ROAD
FORT BLISS, TEXAS 79916

DEC 21 2018

 **ENTERED**



Directorate of Public Works

Mr. David Cobrain
Project Leader
New Mexico Environmental Department
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6303

RE: Submittal of Annual Post-Closure Site Inspection Report, Fort Bliss Site No. 11 (FTBL-011)/Solid Waste Management Unit 29 (SWMU-29) Doña Ana Range Camp Sanitary Landfill, Fort Bliss, New Mexico


Dear Mr. Cobrain:

The annual post-closure site inspection of the Doña Ana Range Camp Sanitary Landfill, FTBL-011/SWMU 29, took place on October 24, 2018, in accordance with requirements stated in the New Mexico Environmental Department letter, dated May 27, 2008.

The correspondence stipulated an annual inspection and photographs of the run-on controls and landfill cover. The inspection found the landfill cover, run-on controls, vegetative layer, perimeter fence and warning signs remain in good condition. (Enclosure).

Should you have any questions, please contact Mr. Jesus D. Moncada, Chief, Compliance Branch, Environmental Division, at (915) 568-2632 or jesus.d.moncada.civ@mail.mil.

Sincerely,


Alfredo J. Riera, P.E.
Director of Public Works

Enclosure

Doña Ana Range Camp Sanitary Landfill – Annual Inspection SWMU-29/FTBL-011

Unit: IMBL- PWE

Inspector: Sergio H. Celis

Facility ID: FTBL-11/SWMU-29

Telephone Number: (915) 568-5205

Facility Name: Dona Ana Range Camp Sanitary Landfill

Email: sergio.h.celis.ctr@mail.mil

Inspection Date: October 24, 2018

List of Observations:

1. The landfill cap is uniform and in good condition. There was no evidence of erosion or depressions on the cap's surface.
2. The vegetative layer on the landfill cap and immediate areas within the fenced property remains in good condition.
3. The site perimeter fence and warning signs remain in good condition. The perimeter fence did not require maintenance or repairs.

Inspection photographs

Photograph No. 1

Landfill gate and sign due North.

Gate lock works properly.

Site perimeter fence and signage remain in good condition.



**Doña Ana Range Camp Sanitary Landfill – Annual Inspection
SWMU-29/FTBL-011**

Photograph No.2

View of landfill cap facing North.

No signs of erosion or depressions on landfill cap.

Vegetative layer is in good condition.

Swale remains in good condition. No obstructions present and slopes remain intact.



Photograph No. 3

View of landfill cap facing East.

No signs of erosion or depressions on landfill cap.

Vegetative layer is in good condition.

NW-SE fencing and signage remain in good condition.



Doña Ana Range Camp Sanitary Landfill – Annual Inspection SWMU-29/FTBL-011

Photograph No. 4

View of landfill cap facing South.

No signs of erosion or depressions on landfill cap.

Vegetative layer is in good condition.

Fencing and signage remain in good condition.



Photograph No. 5

View of landfill cap facing West.

Site perimeter fence and warning signs remain in good condition.



**Doña Ana Range Camp Sanitary Landfill – Annual Inspection
SWMU-29/FTBL-011**

Photograph No. 6

View of swale trending South.

Swale is in good condition. No obstructions are present and slopes remain intact.

