

**WIPP TOUR AGENDA
New Mexico Environment Department
Tuesday, January 8, 2012**

7:00 a.m.	Visitors arrive at Skeen Whitlock Building and meet CBFO and WTS representatives in the lobby area
7:20 a.m.	Transport to WIPP
8:05 a.m.	Visitors arrive on site -Security Office for visitor badges Auditorium Guard & Security Building - view safety briefing
9:00 a.m.	To Lamp Room for underground safety equipment and accountability tags Underground tour – Wes Boatwright, RES & Rey Carrasco, NWP ➤CH – TRU waste emplacement process ➤RH - TRU waste canister insertion equipment
11:00 a.m.	Return to Surface
11:15 a.m.	No host lunch site cafeteria
12:00 p.m.	Surface tour – Randy Britain Meet in lamproom and obtain TLDs for surface tour (escorts Randy Britain & Steve Travis) Waste Handling Building ➤CH Bay ➤RH Bay TRUPACT-III
1:30 p.m.	Tour concludes
2:00 p.m.	Depart site
2:45 p.m.	Arrive SWB/Meetings with RES & CBFO

Photo ID Required

Prohibited attire: dresses, skirts, shorts, open-toe shoes, high-heeled shoes and sandals

Revised: 1/7/2013






VOC CABINET
52-P-103D





VOC CABINET
52-P-100
















POST-CLOSURE
VOC MONITORING
IN SERVICE

OUT OF
SERVICE

DO NOT
REMOVE



POST-CLOSURE
VOC MONITORING
IN SERVICE

Yellow label













V. Garcia
A. 2953
R. Egger
X 8478

DALLS
P&S Corporation

DALLS
P&S Corporation