

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: WESTERN REFINING	Contact: Beck Larsen
Address: I-40 / EXIT 39, JAMESTOWN, NM 87347	Telephone No. (505) 722-0258
Facility Name: WESTERN RENINING (GALLUP REFINERY)	Facility Type: Petroleum Refinery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	28	15 N	15 W					MCKINLEY

Latitude 35° 029' 024" Longitude 108° 024' 024"

NATURE OF RELEASE


Type of Release: Kerosene	Volume of Release 7 bbls (oil)	Volume Recovered: 6.5 bbls
Source of Release: Kerosene Rundown Charge Line Bleeder Valve	Date and Hour of Occurrence 09/27/13 @ 1730 hrs	Date and Hour of Discovery 09/27/13 @ 1730 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? (HWB-R. Horowitz (msg), K Vanhorn (msg)); (OCD -C Chavez (msg), B Powell (msg))	
By Whom? Beck Larsen	Date and Hour: 9/28/2013 (HWB-R. Horowitz (msg; 1350), K Vanhorn (msg; 1358)); (OCD -C Chavez (msg; 1402), B Powell (1355))	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.* On September 27, 2013 at about 1730 hours, the pumper gauger was called to start the KHT Charge Pumps. When we got to the pump, it was found that the bleeder valve was cracked open on the rundown charge line. He immediately blocked in the valve. The off-site supervisor was notified. Maintenance was also notified to dispatch the on-site vacuum truck to vacuum up all kerosene that was released.

Describe Area Affected and Cleanup Action Taken.*
Vacuum Truck was dispatch to clean up Kersoene from ground. The vacuum truck removed as muck kerosene as possible. Some soil removal will be required for total cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Beck Larsen:	Approved by Environmental Specialist:		
Title: Environmental Engineer	Approval Date:	Expiration Date:	
E-mail Address: Thurman.larsen@wnr.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: <u>10/7/13</u> Phone (505) 722-0258			

* Attach Additional Sheets If Necessary