Los Alamos Environmental Restoration Records Processing Facility

ER Record I.D.# 0007934

DATE RECEIVED: 08-07-92 PROCESSOR: TAP

ENTERED

LOS ALAMOS

LOS ALAMOS NATIONAL LABORATORY

ENVIRONMENTAL RESTORATION
Records Processing Facility
ER Record Index Form
(Side 1 of 2)

Part I: Complete all fields; indicate if not applicable or appropriate; please write legibly.

DOCUMENT TO: W-3 file DOCUMENT DATE: 12/14/56

ORIGINATOR NAME: Homer C. Milford ORGANIZATION: H-5

SYMBOL: — PAGE COUNT: 1

SUBJECT/TITLE: Visit to Group W-3 at TA-33

RECORD TYPE (Circle relevant type for primary record; type of attachments should be selected on *Keywords List*):

Analytical Data	FAX	Map	Plan	Study
Chain-of-Custody	Figure	Memo	Procedure	Telephone Record
Computer Output	Form	Microform	Purchase Request	Transcription
Contract	Interview	Notebook	Receipt Acknowledgment	Video
Controlled Distribution	Letter	Personal Notes	Report	Work Plan
Drawing	Logbook	Photo	Review	Other

RECORD CATEGORY: P
(P for Programmatic or R for Reference)

RECORD PACKAGE #:

RECORD FILMED (Y/N): Y

RECORD LOCATION:
(Indicate location of record if not filmed.)

Part II: Complete all fields; indicate if not applicable or appropriate; please write legibly. Use *ER Record Index Form Attachment Sheet* if needed.

ATTACHMENTS FILMED (Y/N): —
(Were attachments to this record filmed?)

LOCATION:
(Indicate location of attachments.)

TECH AREA(S)	ADS NO(S)	WBS NO(S)	STRUCTURE NO(S)/MDA
LIST RELEVANT TECH AREA(S)	LIST RELEVANT ADS NO(S)	LIST RELEVANT WBS NO(S)	LIST RELEVANT STRUCTURE NO(S)/MDA
33	1122	1.5.16	—

32262

Part III: Complete all fields; indicate if not applicable or appropriate; please write legibly. Use *ER Record Index Form Attachment Sheet* if needed.

PRS NO(S)	DOCUMENT TO	ORIGINATOR NAMES
LIST RELEVANT PRS NO(S)	LIST MULTIPLE RECIPIENTS	LIST MULTIPLE ORIGINATORS

CORRECTION (Y/N):_____
(Is this a correction to a record previously processed?)

CORRECTED #:_____
(If answer is Yes, please give ER Record # for corrected record.)

CORRECTION DESCRIPTION (Optional):_____

SUPERCEDE:_____ REPLACE:_____ DELETE:_____ ADD:_____ REVISE:_____

ATTACHMENT LIST

KEYWORDS: Circle relevant KEYWORDS from the list below for ER Record #: 0009934

MISCELLANEOUS (List other indexing criteria as necessary; please write legibly): visit, Glass laminated, titanate, compounds, silica, Epoxy resin fumes

Abandon
Aboveground Tank
Absorption
Abstract
Accelerator
Access
Accident
Accumulation
Acid
Active
Administrative
ADS (Activity Data Sheet)
Adsorption
AEC (Atomic Energy Commission)
Aerial
Agenda
Agreement
Air
Alpha
Americium
Analysis
Analytical
AOC (Area of Concern)
Approval
Aquifer
ARAR (Applicable, Relevant, or Appropriate Requirements)
Archeology
Archive
Area
Arsenic
Asbestos
Asphalt
Assessment
Audit

Bacteria
Barium
Baseline
BCP (Baseline Change Proposal)
Beds
Bermed Area
Beryllium
Beta
Biology
Blank
Boiler
Boneyard
Buried
Burn
Burn Site

Cadmium
Caisson
Calibration
Canyon
Capacitor
Caustic
CEARP (Comprehensive Environmental Assessment and Response Program)
Cement
CERCLA (Comprehensive Environmental Response, Compensation, and Liability Act)
Certification
Cesium
Chain-of-Custody
Chamber
Change Control
Change Order
Charge
Chart
Checklist
Chemical
Chromium
Cleanup
Clearance
Clothing
Closure
CMI/RA (Corrective Measures Implementation/Remedial Action)
CMS/FS (Corrective Measures Study/ Feasibility Study)
Comment
Committee
Community Relations
Compliance
Compressed Gas
Computer Modeling
Computer Output
Concern
Concrete
Concurrence
Configuration
Construction
Container
Containment
Contaminant
Contract
Control

Controlled Distribution
Core
Corrective Action
Correspondence
Criteria

Data
Deadline
Debris
Decision Analysis
Decommission
Decontamination
Deficiency
Deliverables
Demolition
Description
Detection
Detonation
Development
Discharge
Disposal
Documentation
DOE (Department of Energy)
DQO (Data Quality Objectives)
Draft
Drainage
Drainline
Drawing
Drilling
Drop Tower
Drum
Dry Well
Dump
Duplicates

Ecology
Effluent
EIS (Environmental Impact Statement)
Emission
Engineering
Environmental
EPA (Environmental Protection Agency)
Equipment
ERDA (Energy Research and Development Administration)
Erosion
Error
ES&H (Environment, Safety, and Health)
Estimate

Evacuation
Evaluation
Evaporator
Excavation
Exclusion
Exhaust
Experiment
Explosive
Exposure
Extension
Extraction

Facility
Farm
FAX
Fence
Field
Figure
Filter
FIMAD (Facility for Information Management, Analysis, and Display)
Finding
Fire
Firing Site
Fiscal
Five Year Plan
Flowchart
Fluid
Form
Framework
Free
Fuel

Gamma
Gas
Generation
Generic
Geochemistry
Geology
Geophysics
Glass Breaker
Glove Box
Graph
Guidance
Gun

Handling
Hazardous
Health
HE (High Explosive)
History
Hole
Home Owner

HSWA (Hazardous and Solid Waste Amendments)
Hydrology
Hygiene

Implementation
Implosion
Impoundment
Inactive
Incinerator
Industrial
Injection Well
Inorganic
Inspection
Installation
Interim
Interim Action
Internal
Interview
Inventory
Investigation
IRM (Interim Remedial Measure)
Isotope
IWP (Installation Work Plan)

Lab Job
Laboratory
Lagoon
Land
Landfill
Laundry
Leach
Lead
Leak
Legal
Letter
Limit
Lines
Liquid
List
Log
Logbook

Magazine
Management
Manhole
Map
Material
MDA (Material Disposal Area)
Media
Meeting

Memo
Mercury
Metal
Microform
Minimization
Minutes
MIS (Management Information System)
Mixed Waste
MOA (Memo of Agreement)
Model
Modification
Money (Allocation, Appropriation, Budget, Cost, Funding, etc.)
Monitoring
Monthly Report
Mortar Impact Area
MOU (Memo of Understanding)
MSA (Major System Acquisition)

NEPA (National Environmental Policy Act)
NFA (No Further Action)
Nitrate
NMED (New Mexico Environmental Division)
NMEID (New Mexico Environmental Improvement Division)
NOD (Notice of Deficiency)
Non-explosive
Notebook
Notification
NPDES (National Pollutant Discharge Elimination System)
NRC (Nuclear Regulatory Commission)
Nuclear

Observation
Off-gas
Oil
Open
Open Burning
Operation
Order
Organic
Organization
OSHA (Occupational Safety & Health Administration)
OU (Operable Unit)
Outfall
Outline

PA/RFA (Preliminary Assessment /RCRA Facility Assessment)
PCB (Polychlorinated Biphenyl)
Permit
Personal Notes
Personnel
Personnel Qualification
Photo
Pilot Study
Pipe
Pit
Plan
Plant
Plutonium
Pollution
Polonium
Polaroid
Potential
Presentation
Prevention
Priority
Procedure
Program
Programmatic
Project
Project Leader
Propellant
Property
Proposal
Protection
Protocol
PRS (Potential Release Site)
Public
Pump
Purchase Request

Quality
QA (Quality Assurance)
QP (Quality Procedure)
Quarterly Report

Radioactive
Radiochemistry
Radionuclide
Rationale
RCRA (Resource, Conservation, and Recovery Act)
Reactor
Receipt Acknowledgment
Recommendation
Reconnaissance
Records
Recovery
Recycle
Reduction
Reference
Regulation
Release
Remediation
Removal
Report
Request
Requirements
Research
Resin Bed
Resolution
Resource
Response
Restoration
Restriction
Results
Review
Revision
RFI/RI (RCRA Facility Investigation/Remedial Investigation)
Risk
RPF (Records Processing Facility)

Safety
Salamander
Salvage
Sample
Sampling Plan
Sanitary
Satellite
Schedule
Scope
Scrap Detonation Site
Screening
Scrubber
Security
Seep
Seminar
Semivolatile
Septic
Sewer
Shaft
Shell
Shot
Silver
Site
Sludge
Soil
Solid
Solvent
SOP (Standard Operating Procedure)
SOW (Statement of Scope of Work)
Specific
Spill
Stack
Standard
Statistics
Steamline
Steel
Storage
Strontium
Structure
Study
Subcontractor
Subsurface
Summary
Sump
Support
Surface
Surveillance
Survey
Swipe
SWMU (Solid Waste Management Unit)
System

Tank
Task
TCLP (Toxicity Characteristic Leaching Procedure)
TDD (Technical Document Description)
Technical
Technical Team
Technology
Telephone Record
Test Area
Testing
TLD (Thermoluminescent Dosimeter)
TOC (Table of Contents)
Townsite
Toxic
Tracking
Training
Transcription
Transfer
Transformer
Transport
Treatment
Trench
Trip Report
Tritium
TRU (Transuranic)
TSCA (Toxic Substances Control Act)
Tuballoy
Tuff

Underground
Uranium
Urine
USGS (United States Geological Survey)
UST (Underground Storage Tanks)
Utility

Validation
Variance
VE (Value Engineering)
Ventilation
Verification
Video
Volatile
Volume

Warehouse
Waste
Water
WBS (Work Breakdown Structure)
Weapon
Well
Work
Working Group

Zinc

LOS ALAMOS SCIENTIFIC LABORATORY
UNIVERSITY OF CALIFORNIA
LOS ALAMOS, NEW MEXICO

OFFICE MEMORANDUM

TO : ~~The File, H-5~~ W-3 File

DATE: December 14, 1956

FROM : Homer C. Milford

SUBJECT: VISIT TO GROUP W-3 AT TA-33

SYMBOL : H-5

On December 12, 1956, I had a visit with Vernon Johnson of W-3 at TA-33. He is now expanding the work being done at Area 6, Bldg. 16, TA-33.

At the present time nine men are working in this building. Their main effort is being expended on materials to improve a holding device; they are exploring various kinds of laminated materials. At present, they are machining, polishing, and grinding a glass laminated material (we have a letter off to the manufacturer), and several materials such as barium titonate, Pb Zn O_3 mixed with Pb Ti O_3, and epoxy resin. They are planning to explore all possibilities of laminations. The immediate hazard is free silica in the laminated glass. Also, epoxy resin fumes. The tools are all exhausted and the resin is mixed in a fume hood.

Homer C. Milford

jc

Homer C. Milford

Best Available Copy

Received by ER-RPF
AUG 07 1992