Please print or type in the unshaded areas only (fill-in areas are spaced for elite type, i.e., 12 characters/inch).

Form Approved OMB No. 158-R0175

U.S. ENVIRONMENTAL PROTECTION AGENCY

GENERAL INFORMATION

Consolidated Permits Program

(Read the "General Instructions" before starting.)

GENERAL

I. EPA I.D. NUMBER

F NM0890010515 D

LABEL ITEMS

I. EPA I.D. NUMBER

III. FACILITY NAME

V. FACILITY MAILING ADDRESS

VI. FACILITY LOCATION

Department of Energy
Attn: Mr. Harold Valencia
Los Alamos Area Office
Los Alamos, N.M. 87544

GENERAL INSTRUCTIONS

If a preprinted label has been provided, affix it in the designated space. Review the information carefully; if any of it is incorrect, cross through it and enter the correct data in the appropriate fill-in area below. Also, if any of the preprinted data is absent *(the area to the left of the label space lists the information that should appear)*, please provide it in the proper fill-in area(s) below. If the label is complete and correct, you need not complete Items I, III, V, and VI *(except VI-B which must be completed regardless)*. Complete all items if no label has been provided. Refer to the instructions for detailed item descriptions and for the legal authorizations under which this data is collected.

II. POLLUTANT CHARACTERISTICS

INSTRUCTIONS: Complete A through J to determine whether you need to submit any permit application forms to the EPA. If you answer "yes" to any questions, you must submit this form and the supplemental form listed in the parenthesis following the question. Mark "X" in the box in the third column if the supplemental form is attached. If you answer "no" to each question, you need not submit any of these forms. You may answer "no" if your activity is excluded from permit requirements; see Section C of the instructions. See also, Section D of the instructions for definitions of bold-faced terms.

SPECIFIC QUESTIONS	MARK 'X' YES	MARK 'X' NO	MARK 'X' FORM ATTACHED
A. Is this facility a publicly owned treatment works which results in a discharge to waters of the U.S.? (FORM 2A)		X	
B. Does or will this facility *(either existing or proposed)* include a concentrated animal feeding operation or aquatic animal production facility which results in a discharge to waters of the U.S.? (FORM 2B)		X	
C. Is this a facility which currently results in discharges to waters of the U.S. other than those described in A or B above? (FORM 2C)	X		NO
D. Is this a proposed facility *(other than those described in A or B above)* which will result in a discharge to waters of the U.S.? (FORM 2D)		X	
E. Does or will this facility treat, store, or dispose of hazardous wastes? (FORM 3)	X		YES
F. Do you or will you inject at this facility industrial or municipal effluent below the lowermost stratum containing, within one quarter mile of the well bore, underground sources of drinking water? (FORM 4)		X	
G. Do you or will you inject at this facility any produced water or other fluids which are brought to the surface in connection with conventional oil or natural gas production, inject fluids used for enhanced recovery of oil or natural gas, or inject fluids for storage of liquid hydrocarbons? (FORM 4)		X	
H. Do you or will you inject at this facility fluids for special processes such as mining of sulfur by the Frasch process, solution mining of minerals, in situ combustion of fossil fuel, or recovery of geothermal energy? (FORM 4) Geothermal	X		NO
I. Is this facility a proposed stationary source which is one of the 28 industrial categories listed in the instructions and which will potentially emit 100 tons per year of any air pollutant regulated under the Clean Air Act and may affect or be located in an attainment area? (FORM 5)		X	
J. Is this facility a proposed stationary source which is NOT one of the 28 industrial categories listed in the instructions and which will potentially emit 250 tons per year of any air pollutant regulated under the Clean Air Act and may affect or be located in an attainment area? (FORM 5)		X	

III. NAME OF FACILITY

1 SKIP LOS ALAMOS NATIONAL LABORATORY

IV. FACILITY CONTACT

A. NAME & TITLE *(last, first, & title)*	B. PHONE *(area code & no.)*
2 HAROLD VALENCIA	505 667 5105

FTS 843-5105

V. FACILITY MAILING ADDRESS

A. STREET OR P.O. BOX

3 LOS ALAMOS AREA OFFICE

B. CITY OR TOWN	C. STATE	D. ZIP CODE
4 LOS ALAMOS	NM	87544

VI. FACILITY LOCATION

A. STREET, ROUTE NO. OR OTHER SPECIFIC IDENTIFIER

5 LOS ALAMOS

14967

B. COUNTY NAME

LOS ALAMOS

C. CITY OR TOWN	D. STATE	E. ZIP CODE	F. COUNTY CODE *(if known)*
6 LOS ALAMOS	NM	87544	

EPA Form 3510-1 (6-80)

CONTINUE ON REVERSE

CONTINUED FROM THE FRONT

VII. SIC CODES (4 digits in order of priority)

A. FIRST	B. SECOND
7 (specify) NATIONAL SECURITY	7 (specify)
C. THIRD	**D. FOURTH**
7 (specify)	7 (specify)

VIII. OPERATOR INFORMATION

A. NAME: 8 LOS ALAMOS NATIONAL LABORATORY

B. Is the name listed in Item VIII-A also the owner? ☐ YES ☒ NO

C. STATUS OF OPERATOR (Enter the appropriate letter into the answer box; if "Other", specify.)
F = FEDERAL, S = STATE, P = PRIVATE, M = PUBLIC (other than federal or state), O = OTHER (specify): F (specify)

D. PHONE (area code & no.): A 505 667 5021

E. STREET OR P.O. BOX: PO BOX 1663 MS K490

F. CITY OR TOWN: B LOS ALAMOS

G. STATE: NM

H. ZIP CODE: 87545

IX. INDIAN LAND

Is the facility located on Indian lands? ☐ YES ☒ NO

X. EXISTING ENVIRONMENTAL PERMITS

A. NPDES (Discharges to Surface Water)	D. PSD (Air Emissions from Proposed Sources)
9 N NM0028355	9 P
B. UIC (Underground Injection of Fluids)	**E. OTHER (specify)**
9 U	9 NM0028576 (specify) NPDES
C. RCRA (Hazardous Wastes)	**E. OTHER (specify)**
9 R	9 (specify)

XI. MAP

Attach to this application a topographic map of the area extending to at least one mile beyond property bounderies. The map must show the outline of the facility, the location of each of its existing and proposed intake and discharge structures, each of its hazardous waste treatment, storage, or disposal facilities, and each well where it injects fluids underground. Include all springs, rivers and other surface water bodies in the map area. See instructions for precise requirements.

XII. NATURE OF BUSINESS (provide a brief description)

The mission of Los Alamos National Laboratory (LANL) is the application of science and technology to solve national problems including weapons development and energy supply and conservation programs, while basic science research complements and strengthens its fundamental technical capabilities. The LANL is owned by the US Department of Energy and operated under contract by the University of California.

XIII. CERTIFICATION (see instructions)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attachments and that, based on my inquiry of those persons immediately responsible for obtaining the information contained in the application, I believe that the information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A. NAME & OFFICIAL TITLE (type or print)	B. SIGNATURE	C. DATE SIGNED
Harold Valencia Los Alamos Area Manager	H. Valencia	7-18-88

COMMENTS FOR OFFICIAL USE ONLY

C

(Please print or type in the unshaded areas only. (fill-in areas are spaced for elite type, i.e., 12 characters/inch).)

Form Approved OMB No. 158-S80004

FORM 3 RCRA

EPA

U.S. ENVIRONMENTAL PROTECTION AGENCY

HAZARDOUS WASTE PERMIT APPLICATION

Consolidated Permits Program

(This information is required under Section 3005 of RCRA.)

I. EPA I.D. NUMBER

F N M 0 8 9 0 0 1 0 5 1 5

FOR OFFICIAL USE ONLY

APPLICATION APPROVED	DATE RECEIVED (yr., mo., & day)	COMMENTS

II. FIRST OR REVISED APPLICATION

Place an "X" in the appropriate box in A or B below *(mark one box only)* to indicate whether this is the first application you are submitting for your facility or a revised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number in Item I above.

A. FIRST APPLICATION *(place an "X" below and provide the appropriate date)*

☐ 1. EXISTING FACILITY *(See instructions for definition of "existing" facility. Complete item below.)*

FOR EXISTING FACILITIES, PROVIDE THE DATE *(yr., mo., & day)* OPERATION BEGAN OR THE DATE CONSTRUCTION COMMENCED *(use the boxes to the left)*

☐ 2. NEW FACILITY *(Complete item below.)*

FOR NEW FACILITIES, PROVIDE THE DATE *(yr., mo., & day)* OPERATION BEGAN OR IS EXPECTED TO BEGIN

B. REVISED APPLICATION *(place an "X" below and complete Item I above)*

☒ 1. FACILITY HAS INTERIM STATUS

☐ 2. FACILITY HAS A RCRA PERMIT

III. PROCESSES – CODES AND DESIGN CAPACITIES

A. PROCESS CODE – Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering codes. If more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes below, then describe the process *(including its design capacity)* in the space provided on the form *(Item III-C)*.

B. PROCESS DESIGN CAPACITY – For each code entered in column A enter the capacity of the process.

1. AMOUNT – Enter the amount.
2. UNIT OF MEASURE – For each amount entered in column B(1), enter the code from the list of unit measure codes below that describes the unit of measure used. Only the units of measure that are listed below should be used.

PROCESS	PROCESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY
Storage:		
CONTAINER *(barrel, drum, etc.)*	S01	GALLONS OR LITERS
TANK	S02	GALLONS OR LITERS
WASTE PILE	S03	CUBIC YARDS OR CUBIC METERS
SURFACE IMPOUNDMENT	S04	GALLONS OR LITERS
Disposal:		
INJECTION WELL	D79	GALLONS OR LITERS
LANDFILL	D80	ACRE-FEET *(the volume that would cover one acre to a depth of one foot)* OR HECTARE-METER
LAND APPLICATION	D81	ACRES OR HECTARES
OCEAN DISPOSAL	D82	GALLONS PER DAY OR LITERS PER DAY
SURFACE IMPOUNDMENT	D83	GALLONS OR LITERS

PROCESS	PROCESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY
Treatment:		
TANK	T01	GALLONS PER DAY OR LITERS PER DAY
SURFACE IMPOUNDMENT	T02	GALLONS PER DAY OR LITERS PER DAY
INCINERATOR	T03	TONS PER HOUR OR METRIC TONS PER HOUR; GALLONS PER HOUR OR LITERS PER HOUR
OTHER *(Use for physical, chemical, thermal or biological treatment processes not occurring in tanks, surface impoundments or incinerators. Describe the processes in the space provided. Item III-C.)*	T04	GALLONS PER DAY OR LITERS PER DAY

UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE
GALLONS	G	LITERS PER DAY	V	ACRE-FEET	A
LITERS	L	TONS PER HOUR	D	HECTARE-METER	F
CUBIC YARDS	Y	METRIC TONS PER HOUR	W	ACRES	B
CUBIC METERS	C	GALLONS PER HOUR	E	HECTARES	G
GALLONS PER DAY	U	LITERS PER HOUR	H		

EXAMPLE FOR COMPLETING ITEM III *(shown in line numbers X-1 and X-2 below)*: A facility has two storage tanks, one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.

C DUP 1

LINE NUMBER	A. PROCESS CODE (from list above)	B. PROCESS DESIGN CAPACITY 1. AMOUNT (specify)	B. PROCESS DESIGN CAPACITY 2. UNIT OF MEASURE (enter code)	FOR OFFICIAL USE ONLY	LINE NUMBER	A. PROCESS CODE (from list above)	B. PROCESS DESIGN CAPACITY 1. AMOUNT	B. PROCESS DESIGN CAPACITY 2. UNIT OF MEASURE (enter code)	FOR OFFICIAL USE ONLY
X-1	S 0 2	600	G		5	T 0 2	500	U	
X-2	T 0 3	20	E		6	T 0 3	0.56	D	
1	S 0 1	275,820	G		7	T 0 4	NA(See IIIC.)		
2	S 0 2	6,600	G		8	T 0 4	2,534	U	
3	S 0 4	5,000	G		9				
4	T 0 1	7,680	U		10				

Continued from the front.

III. PROCESSES *(continued)*

C. SPACE FOR ADDITIONAL PROCESS CODES O[illegible]R DESCRIBING OTHER PROCESSES *(code "TO[illegible]* [illegible] FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

- Discrete pieces of High Explosives (HE) waste are collected, packaged, and burned at the TA-16 burning ground. Two burn pads (388, 399) are used to burn the discrete pieces of HE while pad 287 is used to flash HE-contaminated equipment. Two pressure vessels (401, 406) are used to burn HE sludge from various processing facilities located at the Laboratory. The sludge is collected at various sumps located throughout the HE processing areas and taken directly to the pressure vessels for treatment. The sumps are regulated under NPDES permits. The sludge is placed on layers of sand in the vessels, the water allowed to drain from the bottom into an evaporation pond and the residue on the sand burned. These vessels do not contain an accumulation of liquids; therefore, they are not considered tanks. Sand from burn pads 388 and 399 have been found to be EP toxic for Barium. This sand has in the past been disposed of at Area P. Engineering drawings and location of the sites are included under item V. Design capacities are not applicable because the treatment process is performed on an as-needed basis.

- Waste sludges from the TA-54, Area L treatment tanks and the TA-50 Batch Waste Treatment facility are mixed with portland cement and/or envirostone and placed in 55-gallon drums. The cement serves to bind any fluid remaining in the sludge. The process is performed at Area L waste handling facilities and has a design capacity of 2,534 gallons per day.

IV. DESCRIPTION OF HAZARDOUS WASTES

A. EPA HAZARDOUS WASTE NUMBER – Enter the four–digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four–digit number*(s)* from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.

B. ESTIMATED ANNUAL QUANTITY – For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non–listed waste*(s)* that will be handled which possess that characteristic or contaminant.

C. UNIT OF MEASURE – For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	K
TONS	T	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:
   For listed hazardous waste: For each listed hazardous waste entered in column A select the code*(s)* from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.
   For non–listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code*(s)* from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non–listed hazardous wastes that possess that characteristic or toxic contaminant.
   Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code*(s)*.

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER – Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
2. In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING ITEM IV *(shown in line numbers X-1, X-2, X-3, and X-4 below)* – A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non–listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

LINE NO.	A. EPA HAZARD. WASTE NO (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D(1))
X-1	K054	900	P	T03 D80	
X-2	D002	400	P	T03 D80	
X-3	D001	100	P	T03 D80	
X-4	D002				*included with above*

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M D 0 8 9 0 0 1 0 5 1 5 — T/A: 1	W DUP — T/A: 2 — DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	D 0 0 1	100,000	P	S 0 1 T 0 3	
2	D 0 0 2	300,000	P	S 0 1 T 0 1	
3	D 0 0 3	7,500	P	S 0 1 T 0 1 T 0 4	Reacted at TA-16 (See III C.)
4	D 0 0 3	5,000	P	S 0 1 T 0 3 T 0 1	Lithium Hydride only
5	D 0 0 4	2,000	P	S 0 1	
6	D 0 0 5	60,000	P	S 0 1 T 0 1	Sand from cleanout of explosives burn pads.
7	D 0 0 6	1,000	P	S 0 1 T 0 1	
8	D 0 0 7	1,500	P	S 0 1 T 0 1	
9	D 0 0 8	50,000	P	S 0 1	May contain other metals (D004-D011)
10	D 0 0 9	5,000	P	S 0 1 T 0 1	
11	D 0 1 0	500*	P	S 0 1	
12	D 0 1 1	1,250	P	S 0 1 T 0 1	
13	D 0 1 2	500*	P	S 0 1 T 0 3	
14	D 0 1 6	1,000	P	S 0 1 T 0 3	
15		END OF D DESIGNATOR			
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M D 8 9 0 0 1 0 5 1 5 — T/A C: 1	W DUP — T/A C: 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	F001	180,000	P	S01 S02 T03 T04	Solidified if treatment standards are met
2	F002	5,000	P	S01 S02 T03 T04	
3	F003	5,000	P	S01 S02 T03 T04	
4	F004	500*	P	S01 T03	
5	F005	5,000	P	S01 S02 T03 T04	
6	F006	500*	P	S01 T01	
7	F007	12,500	P	S01 T01	
8	F008	1,000	P	S01 T01	
9	F009	6,000	P	S01 T01	
10	F027	700	P	S01 T03	
11	F028	700	P	S01 T03	
12		END OF F DESIGNATOR			
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A C 1	W DUP — T/A C 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	K 0 4 4	50,000	P	S 0 1 T 0 4	Reacted at TA-16 (See III C.)
2	K 0 4 7	500#	P	S 0 1 T 0 4	
3		END OF K DESIGNATOR			
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY	
W N M 0 8 9 0 0 1 0 5 1 5	T/A C 1	W DUP	T/A C 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	P001	500*	P	S01 T03	
2	P002	500*	P	S01 T03	
3	P003	500*	P	S01 T03	
4	P004	500*	P	S01 T03	
5	P005	500*	P	S01 T03	
6	P006	500*	P	S01 T04	
7	P007	500*	P	S01 T03	
8	P008	500*	P	S01 T03	
9	P009	500*	P	S01 T04	
10	P010	500*	P	S01	
11	P011	500*	P	S01	
12	P012	500*	P	S01	
13	P013	500*	P	S01 T01	
14	P014	500*	P	S01 T03	
15	P015	500*	P	S01	
16	P016	500*	P	S01 T03	
17	P017	500*	P	S01 T03	
18	P018	500*	P	S01 T03	
19	P020	500*	P	S01 T03	
20	P021	500*	P	S01 T01	
21	P022	500*	P	S01 T04	
22	P023	500*	P	S01 T03	
23	P024	500*	P	S01 T03	
24	P026	500*	P	S01 T03	
25	P027	500*	P	S01 T03	
26	P028	500*	P	S01 T03	

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY	
W N M 0 8 9 0 0 1 0 5 1 5	T/A C 1	W DUP	T/A C 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	P029	500*	P	S01 T01	
2	P030	500*	P	S01 T01	
3	P031	500*	P	S01 T04 T03	
4	P033	500*	P	S01 T04 T03	
5	P034	500*	P	S01 T03	
6	P036	500*	P	S01 T03	
7	P037	500*	P	S01 T03	
8	P038	500*	P	S01 T03	
9	P039	500*	P	S01 T03	
10	P040	500*	P	S01 T03	
11	P041	500*	P	S01 T03	
12	P042	500*	P	S01 T03	
13	P043	500*	P	S01	
14	P044	500*	P	S01 T03	
15	P045	500*	P	S01 T03	
16	P046	500*	P	S01 T03	
17	P047	500*	P	S01 T03	
18	P048	500*	P	S01 T03	
19	P049	500*	P	S01 T03	
20	P050	500*	P	S01 T03	
21	P051	500*	P	S01 T03	
22	P054	500*	P	S01 T01 T04	
23	P056	500*	P	S01	
24	P057	500*	P	S01 T03	
25	P058	500*	P	S01	
26	P059	500*	P	S01 T03	

EPA Form 3510-3 (6-80)

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1): W N M 0 8 9 0 0 1 0 5 1 5 — T/A: C: 1

FOR OFFICIAL USE ONLY: W DUP — T/A: C: 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	P060	500*	P	S01 T03	
2	P062	500*	P	S01 T03	
3	P063	500*	P	S01 T03 T04	
4	P064	500*	P	S01 T03 T04	
5	P065	500*	P	S01 T04	
6	P066	500*	P	S01 T03	
7	P067	500*	P	S01 T03	
8	P068	500*	P	S01 T03	
9	P069	500*	P	S01 T03 T04	
10	P070	500*	P	S01 T03	
11	P071	500*	P	S01 T03 T04	
12	P072	500*	P	S01 T03	
13	P073	500*	P	S01 T01 T04	
14	P074	500*	P	S01 T01	
15	P075	500*	P	S01 T03	
16	P076	500*	P	S01 T01 T04	
17	P077	500*	P	S01 T03 T04	
18	P078	500*	P	S01 T01	
19	P081	500*	P	S01 T04	
20	P082	500*	P	S01 T03	
21	P084	500*	P	S01 T03	
22	P085	500*	P	S01 T03	
23	P087	500*	P	S01	
24	P088	500*	P	S01 T03	
25	P089	500*	P	S01 T03	
26	P092	500*	P	S01	

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A: 1 — C:	W DUP — T/A: — C: 2 — DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	P093	500*	P	S01 T03	
2	P094	500*	P	S01 T03	
3	P095	500*	P	S01 T03	
4	P096	500*	P	S01 T03 T04	
5	P097	500*	P	S01 T03	
6	P098	500*	P	S01 T01	
7	P099	500*	P	S01 T01	
8	P101	500*	P	S01 T03	
9	P102	500*	P	S01 T03	
10	P103	500*	P	S01 T03	
11	P104	500*	P	S01 T01	
12	P105	500*	P	S01	
13	P106	500*	P	S01 T01	
14	P107	500*	P	S01 T04	
15	P108	500*	P	S01 T03	
16	P109	500*	P	S01 T03	
17	P110	500*	P	S01 T03	
18	P111	500*	P	S01 T03	
19	P112	500*	P	S01 T03 T04	
20	P113	500*	P	S01	
21	P114	500*	P	S01	
22	P115	500*	P	S01	
23	P116	500*	P	S01 T03	
24	P118	500*	P	S01 T03	
25	P119	500*	P	S01	
26	P120	500*	P	S01	

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY	
W N M 0 8 9 0 0 1 0 5 1 5	Y/A C 1	W DUP	Y/A C 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	P121	500*	P	S01T01	
2	P122	500*	P	S01T04	
3	P123	500*	P	S01T03	
4		END OF P DESIGNATOR			
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — 1	W DUP — 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1)
1	U001	500*	P	S01	T03			
2	U002	1000	P	S01	T03			
3	U003	500*	P	S01	T03			
4	U004	500*	P	S01	T03			
5	U005	500*	P	S01				
6	U006	500*	P	S01	T04			
7	U007	500*	P	S01	T03			
8	U008	500*	P	S01	T03	T04		
9	U009	500*	P	S01	T03			
10	U010	500*	P	S01	T03			
11	U011	500*	P	S01	T03			
12	U012	500*	P	S01	T03			
13	U014	500*	P	S01	T03			
14	U015	500*	P	S01	T03			
15	U016	500*	P	S01	T03			
16	U017	500*	P	S01	T03			
17	U018	500*	P	S01	T03			
18	U019	500*	P	S01	T03			
19	U020	500*	P	S01	T03	T04		
20	U021	500*	P	S01	T03			
21	U022	500*	P	S01	T03			
22	U023	500*	P	S01	T03	T04		
23	U024	500*	P	S01	T03			
24	U025	500*	P	S01	T03			
25	U026	500*	P	S01	T03			
26	U027	500*	P	S01	T03			

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A: 1 — C:	W — DUP — T/A: — C: 2 — DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	U028	500*	P	S01 T03	
2	U029	500*	P	S01 T03	
3	U030	500*	P	S01 T03	
4	U031	500*	P	S01 T03	
5	U032	500*	P	S01 T01	
6	U033	500*	P	S01 T04	
7	U034	500*	P	S01 T03	
8	U035	500*	P	S01 T03	
9	U036	500*	P	S01 T03	
10	U037	500*	P	S01 T03	
11	U038	500*	P	S01 T03	
12	U039	500*	P	S01 T03	
13	U041	500*	P	S01 T03	
14	U042	500*	P	S01 T03 T04	
15	U043	500*	P	S01 T03 T04	
16	U044	1000	P	S01 T03	
17	U045	500*	P	S01 T03 T04	
18	U046	500*	P	S01 T03	
19	U047	500*	P	S01 T03	
20	U048	500*	P	S01 T03	
21	U049	500*	P	S01 T03	
22	U050	500*	P	S01 T03	
23	U051	500*	P	S01 T03	
24	U052	500*	P	S01 T03	
25	U053	500*	P	S01 T03	
26	U055	500*	P	S01 T03	

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A C 1	W DUP — T/A C 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	U056	500*	P	S01 T03	
2	U057	500*	P	S01 T03	
3	U058	500*	P	S01 T03	
4	U059	500*	P	S01 T03	
5	U060	500*	P	S01 T03	
6	U061	500*	P	S01 T03	
7	U062	500*	P	S01 T03	
8	U063	500*	P	S01 T03	
9	U064	500*	P	S01 T03	
10	U066	500*	P	S01 T03	
11	U067	500*	P	S01 T03	
12	U068	500*	P	S01 T03	
13	U069	500*	P	S01 T03	
14	U070	500*	P	S01 T03	
15	U071	500*	P	S01 T03	
16	U072	500*	P	S01 T03	
17	U073	500*	P	S01 T03	
18	U074	500*	P	S01 T03	
19	U075	500*	P	S01	
20	U076	500*	P	S01 T03	
21	U077	500*	P	S01 T03	
22	U078	500*	P	S01 T03	
23	U079	500*	P	S01 T03	
24	U080	500*	P	S01 T03	
25	U081	500*	P	S01 T03	
26	U082	500*	P	S01 T03	

EPA Form 3510-3 (6-80)

CONTINUE ON REVERSE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A C 1	W DUP — T/A C 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U083	500*	P	S01	T03			
2	U084	500*	P	S01	T03			
3	U085	500*	P	S01	T03			
4	U086	500*	P	S01	T03			
5	U087	500*	P	S01	T03			
6	U088	500*	P	S01	T03			
7	U089	500*	P	S01	T03			
8	U090	500*	P	S01	T03			
9	U091	500*	P	S01	T03			
10	U092	500*	P	S01	T04			
11	U093	500*	P	S01	T03			
12	U094	500*	P	S01	T03			
13	U095	500*	P	S01	T03			
14	U096	500*	P	S01	T03			
15	U097	500*	P	S01	T03			
16	U098	500*	P	S01	T03			
17	U099	500*	P	S01	T03			
18	U101	500*	P	S01	T03			
19	U102	500*	P	S01	T03			
20	U103	500*	P	S01	T03			
21	U105	500*	P	S01	T03			
22	U106	500*	P	S01	T03			
23	U107	500*	P	S01	T03			
24	U108	500*	P	S01	T03			
25	U109	500*	P	S01	T03			
26	U110	500*	P	S01	T03			

EPA Form 3510-3 (6-80)

CONTINUE ON REVERS

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — 1	W DUP — 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U 1 1 1	500#	P	S 0 1 T 0 3	
2	U 1 1 2	500#	P	S 0 1 T 0 3 T 0 4	
3	U 1 1 3	500#	P	S 0 1 T 0 3 T 0 4	
4	U 1 1 4	500#	P	S 0 1 T 0 3	
5	U 1 1 5	500#	P	S 0 1 T 0 3 T 0 4	
6	U 1 1 6	500#	P	S 0 1 T 0 3	
7	U 1 1 7	500#	P	S 0 1 T 0 3 T 0 4	
8	U 1 1 8	500#	P	S 0 1 T 0 3 T 0 4	
9	U 1 1 9	500#	P	S 0 1 T 0 3	
10	U 1 2 0	500#	P	S 0 1 T 0 3	
11	U 1 2 1	500#	P	S 0 1	
12	U 1 2 2	500#	P	S 0 1 T 0 3	
13	U 1 2 3	500#	P	S 0 1	
14	U 1 2 4	500#	P	S 0 1 T 0 3	
15	U 1 2 5	500#	P	S 0 1 T 0 3	
16	U 1 2 6	500#	P	S 0 1 T 0 3	
17	U 1 2 7	500#	P	S 0 1 T 0 3	
18	U 1 2 8	500#	P	S 0 1 T 0 3	
19	U 1 2 9	500#	P	S 0 1 T 0 3	
20	U 1 3 0	500#	P	S 0 1 T 0 3	
21	U 1 3 1	500#	P	S 0 1 T 0 3	
22	U 1 3 2	500#	P	S 0 1 T 0 3	
23	U 1 3 3	500#	P	S 0 1 T 0 3 T 0 4	
24	U 1 3 4	10,000	P	S 0 1 T 0 1	
25	U 1 3 5	500#	P	S 0 1 T 0 4 T 0 3	
26	U 1 3 6	500#	P	S 0 1	

CONTINUE ON REVERSE

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A: C: 1	W DUP — T/A: C: 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	U137	500*	P	S01 T03	
2	U138	500*	P	S01 T03	
3	U139	500*	P	S01 T03	
4	U140	500*	P	S01 T03	
5	U141	500*	P	S01 T03	
6	U142	500*	P	S01 T03	
7	U143	500*	P	S01 T03	
8	U144	500*	P	S01	
9	U145	500*	P	S01	
10	U146	500*	P	S01	
11	U147	500*	P	S01 T03	
12	U148	500*	P	S01 T03	
13	U149	500*	P	S01 T03	
14	U150	500*	P	S01 T03	
15	U151	500*	P	S01	
16	U152	500*	P	S01 T03	
17	U153	500*	P	S01 T03	
18	U154	500*	P	S01 T03	
19	U155	500*	P	S01 T03	
20	U156	500*	P	S01 T03	
21	U157	1000	P	S01 T03	
22	U158	500*	P	S01 T03	
23	U159	1000	P	S01 T03	
24	U160	500*	P	S01 T03 T04	
25	U161	500*	P	S01 T03	
26	U162	500*	P	S01 T03	

EPA Form 3510-3 (6-80)

CONTINUE ON REVERSE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY	
W N M 0 8 9 0 0 1 0 5 1 5	T/A C 1	W DUP	T/A C 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U163	500*	P	S01 T03	
2	U164	500*	P	S01 T03	
3	U165	500*	P	S01 T03	
4	U166	500*	P	S01 T03	
5	U167	500*	P	S01 T03	
6	U168	500*	P	S01 T03	
7	U169	500*	P	S01 T03	
8	U170	500*	P	S01 T03	
9	U171	500*	P	S01 T03	
10	U172	500*	P	S01 T03	
11	U173	500*	P	S01 T03	
12	U174	500*	P	S01 T03	
13	U176	500*	P	S01 T03	
14	U177	500*	P	S01 T03	
15	U178	500*	P	S01 T03	
16	U179	500*	P	S01 T03	
17	U180	500*	P	S01 T03	
18	U181	500*	P	S01 T93	
19	U182	500*	P	S01 T03	
20	U183	500*	P	S01 T03	
21	U184	500*	P	S01 T03	
22	U185	500*	P	S01 T03	
23	U186	500*	P	S01 T03	
24	U187	500*	P	S01 T03	
25	U188	500*	P	S01 T03	
26	U189	500*	P	S01 T04 T03	

CONTINUE ON REVERS

Continued from page 2.
NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A: — C: 1	W DUP — T/A: — C: 2 — DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	U190	500*	P	S01 T03	
2	U191	500*	P	S01 T03	
3	U192	500*	P	S01 T03	
4	U193	500*	P	S01 T03	
5	U194	500*	P	S01 T03	
6	U196	500*	P	S01 T03	
7	U197	500*	P	S01 T03	
8	U200	500*	P	S01 T03	
9	U201	500*	P	S01 T03	
10	U202	500*	P	S01 T03	
11	U203	500*	P	S01 T03	
12	U204	500*	P	S01	
13	U205	500*	P	S01 T04	
14	U206	500*	P	S01 T03	
15	U207	500*	P	S01 T03	
16	U208	500*	P	S01 T03	
17	U209	500*	P	S01 T03	
18	U210	500*	P	S01 T03	
19	U211	500*	P	S01 T03	
20	U212	500*	P	S01 T03	
21	U213	500*	P	S01 T03 T04	
22	U214	500*	P	S01 T03	
23	U215	500*	P	S01	
24	U216	500*	P	S01	
25	U217	500*	P	S01 T04	
26	U218	500*	P	S01 T03	

CONTINUE ON REVERS

Continued from page 2.
NOTE: Photocopy this page before completing if you have [illegible] than 26 wastes to list. [illegible]rm Approved OMB No. 158-S80004

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W N M 0 8 9 0 0 1 0 5 1 5 — T/A C 1	W DUP — T/A C 2 DUP

IV DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1.)
1	U219	500*	P	S01 T03	
2	U220	1000	P	S01 T03	
3	U221	500*	P	S01 T03	
4	U222	500*	P	S01 T03	
5	U223	1000	P	S01 T03	
6	U225	500*	P	S01	
7	U226	1500	P	S01 T03	
8	U227	500*	P	S01 T03	
9	U228	2000	P	S01 T03	
10	U230	500*	P	S01 T03	
11	U231	500*	P	S01 T03	
12	U232	500*	P	S01 T03	
13	U233	500*	P	S01 T03	
14	U234	500*	P	S01 T04	
15	U235	500*	P	S01 T03	
16	U236	500*	P	S01 T03	
17	U237	500*	P	S01 T03	
18	U238	500*	P	S01 T03	
19	U239	1000	P	S01 T03	
20	U240	500*	P	S01 T03	
21	U242	500*	P	S01 T03	
22	U243	500*	P	S01 T03	
23	U244	500*	P	S01 T03	
24	U246	500*	P	S01	
25	U247	500*	P	S01 T03	
26		END OF U DESIGNATOR			

CONTINUE ON REVERSE

Continued from the front.

IV. DESCRIPTION OF HAZARDOUS WASTES *(continued)*

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM ITEM D(1) ON PAGE 3.

*All entries with an asterisk in column IV B on page 3 are generated in small volumes only. If a new process or activity will cause more than the stated volume to be stored, treated, or disposed, a revised Part A will be submitted.

EPA I.D. NO. *(enter from page 1)*

F N M 0 8 9 0 0 1 0 5 1 5 T/A C 0

V. FACILITY DRAWING

All existing facilities must include in the space provided on page 5 a scale drawing of the facility *(see instructions for more detail)*.

VI. PHOTOGRAPHS

All existing facilities must include photographs *(aerial or ground—level)* that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites of future storage, treatment or disposal areas *(see instructions for more detail)*.

VII. FACILITY GEOGRAPHIC LOCATION

LATITUDE *(degrees, minutes, & seconds)*	LONGITUDE *(degrees, minutes, & seconds)*
35 49 051	106 14 015

VIII. FACILITY OWNER

☐ A. If the facility owner is also the facility operator as listed in Section VIII on Form 1, "General Information", place an "X" in the box to the left and skip to Section IX below.

B. If the facility owner is not the facility operator as listed in Section VIII on Form 1, complete the following items:

1. NAME OF FACILITY'S LEGAL OWNER	2. PHONE NO. *(area code & no.)*
E United States Department of Energy	505-667-5105

3. STREET OR P.O. BOX	4. CITY OR TOWN	5. ST.	6. ZIP CODE
F Los Alamos Area Office	G Los Alamos	NM	87545

IX. OWNER CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A. NAME *(print or type)*	B. SIGNATURE	C. DATE SIGNED
Harold Valencia Los Alamos Area Office	H Valencia	7-18-88

X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.

A. NAME *(print or type)*	B. SIGNATURE	C. DATE SIGNED
Siegfried S. Hecker Director	Siegfried S. Hecker	7/15/88

CONTINUE ON PAGE 5