FORM IAM057

THE ZIA COMPANY

Ic WORK ORDER 3 DATE 5-15-57

W/R Fu[illegible]

I ion	[illegible]-0			Work Order No. [illegible]
Requesting Div. Or Tenant	[illegible] Lab Job 1757		ESTIMATE: Labor	Budget No. [illegible]101
Contract No.	[illegible]	IA/RA	Material	AEC - U of C or Housing Code [illegible]701
Inspector	[illegible] -O-	Back Charge	Equipment	Project No.
Priority	A	Capital	Other	Request No. [illegible]
H I Clearance	[illegible]	Expense	Total	[illegible]
Cost Centers	[illegible] [illegible] [illegible] 182			[illegible]

DESCRIPTION OF JOB:

Roads and Labor Section:
Ironworkers:

Transportation Div.:
5-22-57
Moving heavy equipment.

Carpenters: 6-13-57

Clear right of way from East gate in Omega Canyon approx 1/2 mile to West perimeter fence of DP Laundry.

Remove 200 steel posts and 2,000 lineal feet of 8' chain link fence and outriggers from Omega Canyon starting on West end and working east.

Relocate above fence and outriggers at the new contaminated pit.

Extend fence in Omega Canyon approx 150 lineal feet along east end and install an 8' gate per field directions.

HAVE YOU THOUGHT OF SAFETY ON THIS JOB?

Ref: 901 783
3-8-57

Non Haz

PERFORMED BY:	DATE:					PERFORMED BY:	DATE:				

5377

MATERIAL USED: YES _____ NO _____ SIGNATURE OF FOREMAN _____ DATE _____

LASL-ERDA-OFFICIAL