To Benito
Toni
Susan
Ron cc Bartom file

MEMORANDUM

ERM PROGRAM MANAGEMENT COMPANY

LANL TA-21

To: **Alex Puglissi**

cc: Garry Allen
Cas Mason
John Smith
19576.7

From: **Gary McMath**

Date: **April 14, 1995**

Regarding: **TA-21 RFI and D&D Schedule Information**

Per your request at the meeting yesterday regarding NMED concerns at TA-21, attached are draft schedules for the RFI and D&D at TA-21. A complete copy of each schedule is provided as well as a copy of the particular page that contains specific information for work on the Building 3N area. The TA-21 RFI Work Plan describes the investigation for SWMU 21-022(c), located at the north east corner of building 3N, in Chapter 18.9. There are three other investigations near the area of concern for SWMUs 21-023(a,b,d). These SWMUs require coordination with the D&D work, however the schedule for these investigations has not been determined at this time. The schedule will be revised to coordinate with the D&D schedule and will be submitted for approval by April 1996.

Please call me at 662-3700 if you have any questions.

Looks like investigation would not be initiated until after 2001!

10189

TR

TA-21 RFI

DRAFT

A103A52008	TA21 18.8 Data Quality Assurance Ph1						
ES 10NOV99	EF 17NOV99	LS 21DEC05	LF 29DEC05	OD 5	BC	1880	
A103A52014	TA21 18.8 Prepare IDW Disposal Documentation						
ES 10NOV99	EF 3DEC99	LS 24AUG06	LF 14SEP06	OD 15	BC	8160	
A103A52015	TA21 18.8 IDW Disposal						
ES 6DEC99	EF 17DEC99	LS 15SEP06	LF 28SEP06	OD 10	BC	12149	
A103A52010	TA21 18.8 Data Assessment Ph1						
ES 13DEC99	EF 20JAN00	LS 30DEC05	LF 6FEB06	OD 25	BC	27912	
A103A52016	TA21 18.8 Risk Assessment						
ES 21JAN00	EF 10FEB00	LS 7FEB06	LF 28FEB06	OD 15	BC	19524	
A104A52001	TA21 18.8 RFI Report Prep. Ph1						
ES 21JAN00	EF 17MAR00	LS 7FEB06	LF 4APR06	OD 40	BC	0	
A103A52017	TA21 18.8 Decision Analysis						
ES 11FEB00	EF 17FEB00	LS 1MAR06	LF 7MAR06	OD 5	BC	7849	
A103A52020	TA21 18.8 RFI FIELD WORK COMPLETE Ph1						
	EF 17FEB00		LF 3JAN95	OD 0	BC	0	
A104A52004	TA21 18.8 Write RFI Report						
ES 18FEB00	EF 17MAR00	LS 8MAR06	LF 4APR06	OD 20	BC	42454	
A104A52005	TA21 18.8 LANL/DOE Review Ph1						
ES 20MAR00	EF 14APR00	LS 5APR06	LF 2MAY06	OD 20	BC	1534	
A104A52006	TA21 18.8 Incl. LANL/DOE Comments Ph1						
ES 17APR00	EF 12MAY00	LS 3MAY06	LF 31MAY06	OD 20	BC	22061	
A104A52007	TA21 18.8 Issue EPA Draft Ph1						
ES 15MAY00	EF 26MAY00	LS 1JUN06	LF 14JUN06	OD 10	BC	4257	
A104A52008	TA21 18.8 EPA Draft Complete Ph1						
	EF 26MAY00		LF 14JUN06	OD 0	BC	0	
A104A52009	TA21 18.8 EPA Review Ph1						
ES 30MAY00	EF 31JUL00	LS 15JUN06	LF 16AUG06	OD 44	BC	793	
A104A52010	TA21 18.8 Incl. EPA Comments Ph1						
ES 1AUG00	EF 28AUG00	LS 17AUG06	LF 14SEP06	OD 20	BC	22061	
A104A52011	TA21 18.8 Issue Final Rpt./WP Mod. Ph1						
ES 29AUG00	EF 12SEP00	LS 15SEP06	LF 28SEP06	OD 10	BC	1922	
A103A53017	TA21 18.9 RFI FIELD WORK COMPLETE FM 1						
	EF 30SEP94		LF 14JUN06	OD 0	BC	0	
A103A53016	TA21 18.8 START RFI FIELD WORK PH1						
ES 30CT94		LS 29SEP06		OD 0	BC	0	
A104A53016	TA21 18.9 START RFI REPORT Ph1			SM			
ES 30CT94		LS 29SEP06		OD 0	BC	0	
A103A53002	TA21 18.9 Drill/Sample Ph1						
ES 7MAY99	EF 13MAY99	LS 2JUN05	LF 8JUN05	OD 5	BC	28377	
A103A53003	TA21 18.9 Field Analysis Ph1						
ES 7MAY99	EF 13MAY99	LS 17JAN06	LF 23JAN06	OD 5	BC	10000	
A103A53005	TA21 18.9 Laboratory Analysis Ph1						
ES 7MAY99	EF 18NOV99	LS 2JUN05	LF 13DEC05	OD 135	BC	86945	
A103A53011	TA21 18.9 IDW Char. Analysis						
ES 7MAY99	EF 18NOV99	LS 13FEB06	LF 23AUG06	OD 135	BC	3160	
A103A53007	TA21 18.9 Data Tracking Ph1						
ES 7MAY99	EF 20DEC99	LS 9JUN05	LF 23JAN06	OD 155	BC	14075	
A103A53010	TA21 18.9 IDW Monitoring						
ES 7MAY99	EF 20DEC99	LS 21FEB06	LF 28SEP06	OD 155	BC	1992	
A103A53009	TA21 18.9 IDW Mgt						
ES 7MAY99	EF 29DEC99	LS 21FEB06	LF 28SEP06	OD 160	BC	0	
A103A53001	TA21 Ph1 Subs. Agg. 18.9: 21-022h-j						
ES 7MAY99	EF 6SEP00	LS 2JUN05	LF 28SEP06	OD 334	BC	0	
A103A53004	TA21 18.9 Document Locations Ph1						
ES 14MAY99	EF 14MAY99	LS 23JAN06	LF 23JAN06	OD 1	BC	1713	
A103A53012	TA21 18.9 Prepare IDW Disposal Documentation						
ES 19NOV99	EF 13DEC99	LS 24AUG06	LF 14SEP06	OD 15	BC	8160	
A103A53013	TA21 18.9 IDW Disposal						
ES 14DEC99	EF 29DEC99	LS 15SEP06	LF 28SEP06	OD 10	BC	12149	
A103A53006	TA21 18.9 Data Quality Assurance Ph1						
ES 21DEC99	EF 29DEC99	LS 17JAN06	LF 23JAN06	OD 5	BC	1971	
A103A53008	TA21 18.9 Data Assessment Ph1						
ES 30DEC99	EF 28JAN00	LS 24JAN06	LF 21FEB06	OD 20	BC	22331	
A103A53014	TA21 18.9 Risk Assessment						
ES 31JAN00	EF 11FEB00	LS 22FEB06	LF 7MAR06	OD 10	BC	13022	
A104A53001	TA21 18.9 RFI Report Prep. Ph1						
ES 31JAN00	EF 13MAR00	LS 22FEB06	LF 4APR06	OD 30	BC	0	
A103A53015	TA21 18.9 Decision Analysis						
ES 14FEB00	EF 18FEB00	LS 8MAR06	LF 14MAR06	OD 5	BC	7849	
A104A53004	TA21 18.9 Write RFI Report						
ES 22FEB00	EF 13MAR00	LS 15MAR06	LF 4APR06	OD 15	BC	31839	
A104A53005	TA21 18.9 LANL/DOE Review Ph1						
ES 14MAR00	EF 10APR00	LS 5APR06	LF 2MAY06	OD 20	BC	1534	



TA-21 D&D

DRAFT

ACTIVITY ID	ACTIVITY DESCRIPTION	TOTL FLT	ORIG DUR	EARLY START	EARLY FINISH
	DECOMMISSIONING TA-21				
	DECOM. TA-21 WASTE MANAGEMENT AND DISPOSAL				
B369700065	TA-21: WASTE DISPOSAL FOR SB286	0	124	20CT00	4APR01
B369700070	TA-21: WASTE DISPOSAL FOR SB402	0	124	5APR01	28SEP01
B369700075	TA-21: WASTE DISPOSAL FOR LWB257	0	124	10CT01	3APR02
B369700080	TA-21: WASTE DISPOSAL FOR SB228	1	124	4APR02	27SEP02
	DECOM. TA-21 DISMANTLEMENT				
B370702035	TA-21: SPB4 REMOVE ESSENTIAL UTILITIES	1523	11	3JAN95	17JAN95
B370702025	TA-21: SPB4 DISC/REM/DISMNTLE/PIPING & E	1500	34	3JAN95	21FEB95
B370702055	TA-21: SPB4 DISMNTLE/DEMOLISH OUTSIDE ST	1458	76	3JAN95	20APR95
B370702011	TA-21: DISMANTLEMENT FOR SPB3 & SPB4	1458	189	3JAN95	20APR95
B370702M07	TA-21: COMPLETE DISMANTLEMENT FOR SPB4	1385	0		3AUG95
B370702M02	TA-21: START REMEDIATION ON FILTER BLD S	1419	0	1SEP95	
B370701M09	TA-21: START DISMANTLEMENT FOR OFB146	1419	0	10OCT95	
B370701066	TA-21: OFB146 DISMNTLE/DEMOLISH OUTSIDE	1445	20	10OCT95	6NOV95
B370701062	TA-21: OFB146 REMOVE ESSENTIAL UTILITIES	1451	30	10OCT95	21NOV95
B370701060	TA-21: OFB146 DISC/REM/DISMNTLE/PIPG & E	1446	35	10OCT95	30NOV95
B370701064	TA-21: OFB146 DISM/DEMOLISH INSIDE STRUC	1445	16	7NOV95	1DEC95
B370701M11	TA-21: COMPLETE DISMANTLEMENT FOR OFB146	1445	0		1DEC95
B370701M13	TA-21: START DISMANTLEMENT FOR FB324	1385	0	8APR96	
B370701070	TA-21: FB324 REMOVE ESSENTIAL UTILITIES	1458	30	8APR96	17MAY96
B370701068	TA-21: FB324 DISC/REM/DISMNTLE/PIPING &	1453	35	8APR96	24MAY96
B370701072	TA-21: FB324 DISM/DEMOLISH INSIDE STRUCT	1385	40	8APR96	3JUN96
B370701074	TA-21: FB324 DISMNTLE/DEMOLISH OUTSIDE S	1385	63	4JUN96	30AUG96
B370701M15	TA-21: COMPLETE DISMANTLEMENT FOR FB324	1385	0		30AUG96
B370700M04	TA-21: SPB5 REMEDIATION START	0	0	10CT96	
B370700076	TA-21: DISMANTLEMENT FOR SPB5	0	124	10CT96	3APR97
B370700M06	TA-21: NPB5 REMEDIATION START	0	0	4APR97	
B370700078	TA-21: DISMANTLEMENT FOR NPB5	0	125	4APR97	30SEP97
B370700M08	TA-21: RB21 REMEDIATION START	0	0	10CT97	
B370700080	TA-21: DISMANTLEMENT FOR RB21	0	124	10CT97	3APR98
B370700M10	TA-21: SPB2 REMEDIATION START	0	0	6APR98	
B370700082	TA-21: DISMANTLEMENT FOR SPB2	0	125	6APR98	30SEP98
B370700M12	TA-21: NPB2 REMEDIATION START	0	0	10CT98	
B370700084	TA-21: DISMANTLEMENT FOR NPB9	0	124	10CT98	5APR99
B370700M14	TA-21: NPB3 REMEDIATION START	0	0	6APR99	
B370700086	TA-21: DISMANTLEMENT FOR NPB3	0	125	6APR99	30SEP99
B370700M16	TA-21: NPB4 REMEDIATION START	0	0	10CT99	
B370700088	TA-21: DISMANTLEMENT FOR NPB4	0	124	10CT99	4APR00
B370700M18	TA-21: PB150 REMEDIATION START	0	0	5APR00	
B370700090	TA-21: DISMANTLEMENT FOR PB150	1	124	5APR00	28SEP00
B370700M20	TA-21: SB286 REMEDIATION START	0	0	20CT00	
B370700092	TA-21: DISMANTLEMENT FOR SB286	0	124	20CT00	4APR01
B370700M22	TA-21: SP402 REMEDIATION START	0	0	5APR01	
B370700M24	TA-21: LWB257 REMEDIATION START	124	0	5APR01	
B370700094	TA-21: DISMANTLEMENT FOR SB402	0	124	5APR01	28SEP01



Plot Date 13APR95
Data Date 2JAN95
Project Start 1JUL93
Project Finish 30SEP02

Activity Bar/Early Dates
Critical Activity
Progress Bar
Milestone/Flag Activity

DBCP

Sheet 5 of 7

LOS ALAMOS NATIONAL LABORATORY
DECOMMISSIONING
(BC-01) Baseline Working Schedule

ENVIRONMENTAL RESTORATION

Date	Revision	Checked	Approved

(c) Primavera Systems, Inc.

TA-21 RFI

DRAFT

1	Start OU 1106 03JAN95							
AS 3JAN95				OD	0	BC	0
2	END OU 1106 03JAN95							
	EF 14JAN98		LF 28SEP06	OD	0	BC	12149
	OU 1106 ACT ONLY						
A103110634	TA21 16.1 Group						
ES 3JAN95	EF 27APR95	LS 6JUN06	LF 28SEP06	OD	81	BC	0
A103110616	TA21 14.3 Group						
ES 3JAN95	EF 30JUN95	LS 3APR06	LF 28SEP06	OD	126	BC	0
A103110618	TA21 14.4 Group						
ES 3JAN95	EF 30JUN95	LS 3APR06	LF 28SEP06	OD	126	BC	0
A103110622	TA21 14.6 Group						
ES 3JAN95	EF 30JUN95	LS 3APR06	LF 28SEP06	OD	126	BC	0
A103110626	TA21 14.8 Group						
ES 3JAN95	EF 3JUL95	LS 31MAR06	LF 28SEP06	OD	127	BC	0
A103110624	TA21 14.7 Group						
ES 3JAN95	EF 21JUL95	LS 14MAR06	LF 28SEP06	OD	140	BC	0
A103110644	TA21 16.6 Group						
ES 3JAN95	EF 25AUG97	LS 14APR06	LF 28SEP06	OD	662	BC	0
A103110640	TA21 16.4 Group						
ES 3JAN95	EF 17SEP98	LS 18MAY06	LF 28SEP06	OD	927	BC	0
A103110608	TA21 12.5 Group						
ES 3JAN95	EF 8JAN99	LS 11OCT05	LF 28SEP06	OD	1001	BC	0
A103110638	TA21 16.3 Group						
ES 3JAN95	EF 19FEB99	LS 24AUG06	LF 28SEP06	OD	1029	BC	0
A103110614	TA21 14.2 Group						
ES 3JAN95	EF 30SEP99	LS 29MAR06	LF 28SEP06	OD	1185	BC	0
A103110612	TA21 12.6 Group						
ES 3JAN95	EF 7MAR00	LS 31JUL01	LF 28SEP06	OD	1289	BC	0
A103110620	TA21 14.5 Group						
ES 3JAN95	EF 11MAY00	LS 3APR06	LF 28SEP06	OD	1336	BC	0
A103110646	TA21 16.7 Group						
ES 3JAN95	EF 11AUG00	LS 18MAR05	LF 28SEP06	OD	1400	BC	0
A103110648	TA21 16.8 Group						
ES 3JAN95	EF 6SEP00	LS 4DEC96	LF 28SEP06	OD	1417	BC	0
A103110636	TA21 16.2 Group						
ES 3JAN95	EF 27SEP00	LS 23JUN95	LF 28SEP06	OD	1432	BC	0
A102110600	TA21 RFI						
ES 3JAN95	EF 28SEP06	LS 3JAN02	LF 28SEP06	OD	2928	BC	0
A108110628	TA21 15.3 Group						
ES 1FEB95	EF 30DEC96	LS 8FEB95	LF 28SEP06	OD	477	BC	0
A103110632	TA21 15.5 Group						
ES 1FEB95	EF 14FEB97	LS 16SEP04	LF 28SEP06	OD	509	BC	0
A103110666	TA21 Mobilization Group						
ES 1FEB95	EF 6APR99	LS 15FEB95	LF 24MAR05	OD	1041	BC	0
A103110630	TA21 15.4 Group						
ES 1FEB95	EF 16DEC99	LS 23AUG04	LF 28SEP06	OD	1216	BC	0
A103110642	TA21 16.5 Group						
ES 26SEP97	EF 4AUG00	LS 19APR05	LF 28SEP06	OD	711	BC	0
A102110670	TA21 17.2 Group						
ES 20CT97	EF 12SEP00	LS 25APR05	LF 28SEP06	OD	733	BC	0
A102110672	TA21 17.3 Group						
ES 70CT97	EF 3AUG00	LS 28APR05	LF 14SEP06	OD	703	BC	0
A102110674	TA21 17.4 Group						
ES 100CT97	EF 11FEB99	LS 3MAY05	LF 28SEP06	OD	330	BC	0
A102110676	TA21 17.5 Group						
ES 200CT97	EF 130CT00	LS 10MAY05	LF 28SEP06	OD	744	BC	0
A102110678	TA21 17.6 Group						
ES 7APR99	EF 26JUL00	LS 26APR05	LF 28SEP06	OD	327	BC	0
A102110680	TA21 18.8 Group						
ES 8APR99	EF 12SEP00	LS 27APR05	LF 28SEP06	OD	359	BC	0
A103110662	TA21 18.9 Group						
ES 7MAY99	EF 6SEP00	LS 2JUN05	LF 28SEP06	OD	334	BC	0
	TA21 15.2-6/8-9 RFI Report Group (1B/C Addendum)						
A104A00502	TA21 1C Add. Issue EPA Draft Ph1						
ES 3JAN95	EF 31JAN95	LS 10JAN95	LF 7FEB95	OD	20	BC	7654
A104A00501	TA21 Ph 1 Surf. Agg. 15.2-6/8-9 (Outfalls)						
ES 3JAN95	EF 16MAY95	LS 10JAN95	LF 28SEP06	OD	94	BC	0
A104A00503	TA21 1C Add. EPA Draft Complete Ph1						
	EF 31JAN95		LF 14JUN06	OD	0	BC	0
A104A00504	TA21 1C Add. EPA Review Ph1						
ES 1FEB95	EF 4APR95	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A00505	TA21 1C Add. Incl. EPA Comments Ph1						
ES 5APR95	EF 2MAY95	LS 17AUG06	LF 14SEP06	OD	20	BC	6780



	TA21 15.2-6/8-9 RFI Report Group (1B/C Addendum)					
A104A00506	TA21 1C Add. Issue Final RFI Rpt. Ph1					
ES 3MAY95	EF 16MAY95 LS 15SEP06 LF 28SEP06	OD	10	BC	1922	
A104A00507	TA21 1C Add. Final RFI Rpt. Complete Ph1					
	EF 16MAY95 LF 28SEP06	OD	0	BC	0	
	TA21 Ph1 Subs. Agg. 12.5: LAPD 3 & 4					
A104A01013	TA21 LADP 3&4 RFI REPORT COMPLETE FM 1					
	EF 30SEP94 LF 28SEP06	OD	0	BC	0	
A104A01015	TA21 LADP 3&4 Start RFI Report					
ES 30CT94	LS 29SEP06	OD	0	BC	0	
A103A01005	TA21 LADP3 Data Quality Assurance Ph1					
ES 3JAN95	EF 9JAN95 LS 9JAN95 LF 13JAN95	OD	5	BC	1880	
A103A01006	TA21 LADP4 Data Quality Assurance Ph1					
ES 3JAN95	EF 9JAN95 LS 9JAN95 LF 13JAN95	OD	5	BC	1880	
A103A01002	TA21 LADP 3 Geo-Hydro Analysis Ph1					
ES 3JAN95	EF 24JAN95 LS 11OCT05 LF 31OCT05	OD	15	BC	0	
A103A01003	TA21 LADP4 Geo-Hydro Analysis Ph1					
ES 3JAN95	EF 24JAN95 LS 11OCT05 LF 31OCT05	OD	15	BC	45000	
A103A01001	TA21 Ph1 Subs. Agg. 12.5: LADP3&4					
ES 3JAN95	EF 30AUG96 LS 11OCT05 LF 28SEP06	OD	418	BC	0	
A103A01008	TA21 LADP 3&4 IDW Drum Sampling					
ES 15FEB95	EF 21FEB95 LS 22FEB95 LF 27FEB95	OD	4	BC	5416	
A103A01009	TA21 LADP 3&4 IDW Char. Analysis					
ES 15FEB95	EF 16MAY95 LS 22FEB95 LF 22MAY95	OD	64	BC	31600	
A103A01007	TA21 LADP 3&4 IDW Mgt					
ES 15FEB95	EF 21JUN95 LS 22FEB95 LF 27JUN95	OD	89	BC	0	
A103A01010	TA21 LADP 3&4 Prepare IDW Disposal Documentation					
ES 17MAY95	EF 7JUN95 LS 23MAY95 LF 13JUN95	OD	15	BC	6981	
A103A01011	TA21 LADP 3&4 IDW Disposal					
ES 8JUN95	EF 21JUN95 LS 14JUN95 LF 27JUN95	OD	10	BC	12152	
A103A01012	TA21 LADP 3&4 Fieldwork Complete Ph1					
	EF 21JUN95 LF 27JUN95	OD	0	BC	0	
A103A01004	TA21 LADP4 Complete Ph1					
ES 3JUL95	EF 10JUL95 LS 22SEP06 LF 28SEP06	OD	5	BC	13846	
A103A01013	TA21 LADP 3&4 Data Assessment Ph1					
ES 20CT95	EF 7DEC95 LS 1NOV05 LF 6JAN06	OD	45	BC	66355	
A103A01015	TA21 LADP 3&4 Risk Assessment					
ES 8DEC95	EF 21DEC95 LS 9JAN06 LF 23JAN06	OD	10	BC	12976	
A104A01001	TA21 LADP 3&4 RFI Report Prep. Ph1					
ES 8DEC95	EF 7MAR96 LS 9JAN06 LF 4APR06	OD	60	BC	0	
A103A01014	TA21 LADP 3&4 Decision Analysis					
ES 22DEC95	EF 2JAN96 LS 24JAN06 LF 30JAN06	OD	5	BC	7849	
A104A01004	TA21 LADP 3&4 Write RFI Report					
ES 3JAN96	EF 7MAR96 LS 31JAN06 LF 4APR06	OD	45	BC	71320	
A104A01005	TA21 LADP 3&4 LANL/DOE Review Ph1					
ES 8MAR96	EF 4APR96 LS 5APR06 LF 2MAY06	OD	20	BC	1534	
A104A01006	TA21 LADP 3&4 Incl. LANL/DOE Comments Ph1					
ES 5APR96	EF 2MAY96 LS 3MAY06 LF 31MAY06	OD	20	BC	15786	
A104A01007	TA21 LADP 3&4 Issue EPA Draft Ph1					
ES 3MAY96	EF 16MAY96 LS 1JUN06 LF 14JUN06	OD	10	BC	4257	
A104A01008	TA21 LADP 3&4 EPA Draft Complete Ph1					
	EF 16MAY96 LF 14JUN06	OD	0	BC	0	
A104A01009	TA21 LADP 3&4 EPA Review Ph1					
ES 17MAY96	EF 19JUL96 LS 15JUN06 LF 16AUG06	OD	44	BC	793	
A104A01010	TA21 LADP 3&4 Incl. EPA Comments Ph1					
ES 22JUL96	EF 16AUG96 LS 17AUG06 LF 14SEP06	OD	20	BC	6780	
A104A01011	TA21 LADP 3&4 Issue Final Rpt./WP Mod. Ph1					
ES 19AUG96	EF 30AUG96 LS 15SEP06 LF 28SEP06	OD	10	BC	1922	
	TA21 Ph1 Subs. Agg. 12.5: MDV-V-DP					
A104A02012	TA21 V DP Start RFI Report SM 1					
ES 30CT94	LS 29SEP06	OD	0	BC	0	
A102110601	TA21 15.2-6/8-9 RFI Report Group (1B/C Addendum)					
ES 3JAN95	EF 16MAY95 LS 10JAN95 LF 28SEP06	OD	94	BC	0	
A103A02002	TA21 V-DP Drill/Sample Ph1					
ES 8MAY95	EF 18MAY95 LS 22MAY95 LF 2JUN95	OD	9	BC	151133	
A103A02003	TA21 V-DP Field Analysis Ph1					
ES 8MAY95	EF 18MAY95 LS 22JAN96 LF 1FEB96	OD	9	BC	18000	
A103A02007	TA21 V-DP Laboratory Analysis Ph1					
ES 8MAY95	EF 27NOV95 LS 22MAY95 LF 11DEC95	OD	139	BC	22384	
A103A02014	TA21 V DP IDW Char. Analysis					
ES 8MAY95	EF 27NOV95 LS 22MAY95 LF 11DEC95	OD	139	BC	3160	
A103A02011	TA21 V DP Data Tracking Ph1					
ES 8MAY95	EF 27DEC95 LS 12JUN95 LF 1FEB96	OD	159	BC	14446	
A103A02012	TA21 V DP IDW Mgt					
ES 8MAY95	EF 27DEC95 LS 17JAN06 LF 13JAN06	OD	159	BC	0	



A103A02013	TA21 V DP IDW Monitoring						
ES 8MAY95	EF 26JAN96	LS 17JAN06	LF 28SEP06	OD	179	BC	2305
A103A02001	TA21 Ph1 Subs. Agg. 12.5: MDA-V-DP						
ES 8MAY95	EF 22NOV96	LS 22MAY95	LF 28SEP06	OD	388	BC	0
A103A02008	TA21 V-DP Geo-Hydro Analysis Ph1						
ES 19MAY95	EF 12SEP95	LS 30CT95	LF 1FEB96	OD	80	BC	27240
A103A02004	TA21 V-DP Log/Test Ph1						
ES 19JUN95	EF 26JUN95	LS 22DEC95	LF 3JAN96	OD	6	BC	58250
A103A02005	TA21 V DP Complete Ph1						
ES 27JUN95	EF 5JUL95	LS 23JAN96	LF 30JAN96	OD	6	BC	13846
A103A02009	TA21 V-DP Geo Logging Analysis Ph1						
ES 27JUN95	EF 25JUL95	LS 4JAN96	LF 1FEB96	OD	20	BC	15100
A103A02006	TA21 V-DP Document Locations Ph1						
ES 6JUL95	EF 7JUL95	LS 31JAN96	LF 1FEB96	OD	2	BC	3426
A103A02010	TA21 V-DP Data Quality Assurance Ph1						
ES 28NOV95	EF 4DEC95	LS 5JAN96	LF 11JAN96	OD	5	BC	1997
A103A02015	TA21 V DP Prepare IDW Disposal Documentation						
ES 28NOV95	EF 18DEC95	LS 12DEC95	LF 4JAN96	OD	15	BC	6450
A103A02016	TA21 V DP IDW Disposal						
ES 19DEC95	EF 27DEC95	LS 5JAN96	LF 11JAN96	OD	5	BC	6073
A103A02017	TA21 V DP Fieldwork Complete						
	EF 27DEC95		LF 11JAN96	OD	0	BC	0
A103A02018	TA21 V DP Data Assessment Ph1						
ES 28DEC95	EF 4MAR96	LS 2FEB96	LF 5APR96	OD	45	BC	66355
A103A02020	TA21 V DP Risk Assessment						
ES 5MAR96	EF 18MAR96	LS 8APR96	LF 19APR96	OD	10	BC	13022
A104A02001	TA21 V DP RFI Report Prep. Ph1						
ES 5MAR96	EF 28MAY96	LS 8APR96	LF 1JUL96	OD	60	BC	0
A103A02019	TA21 V DP Decision Analysis						
ES 19MAR96	EF 25MAR96	LS 22APR96	LF 26APR96	OD	5	BC	7849
A104A02004	TA21 V DP Write RFI Report						
ES 26MAR96	EF 28MAY96	LS 29APR96	LF 1JUL96	OD	45	BC	71320
A104A02005	TA21 V DP LANL/DOE Review Ph1						
ES 29MAY96	EF 25JUN96	LS 2JUL96	LF 30JUL96	OD	20	BC	1534
A104A02006	TA21 V DP Incl. LANL/DOE Comments Ph1						
ES 26JUN96	EF 24JUL96	LS 31JUL96	LF 27AUG96	OD	20	BC	15786
A104A02007	TA21 V DP Issue EPA Draft Ph1						
ES 25JUL96	EF 7AUG96	LS 28AUG96	LF 11SEP96	OD	10	BC	4257
A104A02008	TA21 V DP EPA Draft Complete Ph1						
	EF 7AUG96		LF 11SEP96	OD	0	BC	0
A104A02009	TA21 V DP EPA Review Ph1						
ES 8AUG96	EF 9OCT96	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A02010	TA21 V DP Incl. EPA Comments Ph1						
ES 10OCT96	EF 7NOV96	LS 17AUG06	LF 14SEP06	OD	20	BC	6780
A104A02011	TA21 V DP Issue Final Rpt./WP Mod. Ph1						
ES 8NOV96	EF 22NOV96	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A104A03012	TA21 LADP-1 START RFI REPORT						
ES 3OCT94		LS 29SEP06		OD	0	BC	0
A103A03002	TA21 LADP-1 Drill/Sample Ph1						
ES 1MAY97	EF 13MAY97	LS 31JAN05	LF 10FEB05	OD	9	BC	55133
A103A03003	TA21 LADP-1 Field Analysis Ph1						
ES 1MAY97	EF 13MAY97	LS 19OCT05	LF 31OCT05	OD	9	BC	18000
A103A03006	TA21 LADP-1 Laboratory Analysis Ph1						
ES 1MAY97	EF 18NOV97	LS 10MAR05	LF 23SEP05	OD	139	BC	44041
A103A03014	TA21 LADP-1 IDW Char. Analysis						
ES 1MAY97	EF 18NOV97	LS 7FEB06	LF 23AUG06	OD	139	BC	0
A103A03010	TA21 LADP-1 Data Tracking Ph1						
ES 1MAY97	EF 18DEC97	LS 17MAR05	LF 31OCT05	OD	159	BC	11721
A103A03013	TA21 LADP-1 IDW Monitoring						
ES 1MAY97	EF 18DEC97	LS 14FEB06	LF 28SEP06	OD	159	BC	1659
A103A03012	TA21 LADP-1 IDW Mgt						
ES 1MAY97	EF 29DEC97	LS 14FEB06	LF 28SEP06	OD	164	BC	0
A103A03001	TA21 Ph1 Subs. Agg. 12.5: LADP-1						
ES 1MAY97	EF 25NOV98	LS 31JAN05	LF 28SEP06	OD	393	BC	0
A103A03004	TA21 LADP-1 Document Locations Ph1						
ES 14MAY97	EF 14MAY97	LS 31OCT05	LF 31OCT05	OD	1	BC	1713
A103A03005	TA21 LADP-1 Log/Test Ph1						
ES 14MAY97	EF 23MAY97	LS 21SEP05	LF 30SEP05	OD	8	BC	58250
A103A03007	TA21 LADP 1 Geo-Hydro Analysis Ph1						
ES 14MAY97	EF 5SEP97	LS 8JUL05	LF 31OCT05	OD	80	BC	36960
A103A03008	TA21 LADP-1 Geo Logging Analysis Ph1						
ES 27MAY97	EF 23JUN97	LS 3OCT05	LF 31OCT05	OD	20	BC	15100
A103A03015	TA21 LADP-1 Prepare IDW Disposal Documentation						
ES 19NOV97	EF 11DEC97	LS 24AUG06	LF 14SEP06	OD	15	BC	6450



A103A03016	TA21 LADP-1 IDW Disposal						
ES 12DEC97	EF 29DEC97	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A03009	TA21 LADP-1 Data Quality Assurance Ph1						
ES 19DEC97	EF 29DEC97	LS 25OCT05	LF 31OCT05	OD	5	BC	1593
A103A03011	TA21 LADP-1 Data Assessment Ph1						
ES 30DEC97	EF 5MAR98	LS 1NOV05	LF 6JAN06	OD	45	BC	66355
A103A03018	TA21 LADP-1 Risk Assessment						
ES 6MAR98	EF 19MAR98	LS 9JAN06	LF 23JAN06	OD	10	BC	13022
A104A03001	TA21 LADP-1 RFI Report Prep. Ph1						
ES 6MAR98	EF 29MAY98	LS 9JAN06	LF 4APR06	OD	60	BC	0
A103A03017	TA21 LADP-1 Decision Analysis						
ES 20MAR98	EF 26MAR98	LS 24JAN06	LF 30JAN06	OD	5	BC	7849
A103A03019	TA21 LADP-1 RFI Field Work Complete						
	EF 26MAR98		LF 30JAN06	OD	0	BC	7849
A104A03004	TA21 LADP-1 Write RFI Report						
ES 27MAR98	EF 29MAY98	LS 31JAN06	LF 4APR06	OD	45	BC	71320
A104A03005	TA21 LADP-1 LANL/DOE Review Ph1						
ES 1JUN98	EF 26JUN98	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A03006	TA21 LADP-1 Incl. LANL/DOE Comments Ph1						
ES 29JUN98	EF 27JUL98	LS 3MAY06	LF 31MAY06	OD	20	BC	15786
A104A03007	TA21 LADP-1 Issue EPA Draft Ph1						
ES 28JUL98	EF 10AUG98	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A03008	TA21 LADP-1 EPA Draft Complete Ph1						
	EF 10AUG98		LF 14JUN06	OD	0	BC	0
A104A03009	TA21 LADP-1 EPA Review Ph1						
ES 11AUG98	EF 13OCT98	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A03010	TA21 LADP-1 Incl. EPA Comments Ph1						
ES 14OCT98	EF 11NOV98	LS 17AUG06	LF 14SEP06	OD	20	BC	6780
A104A03011	TA21 LADP-1 Issue Final Rpt./WP Mod. Ph1						
ES 12NOV98	EF 25NOV98	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A04017	TA21 LADP-2 RFI FIELD WORK COMPLETE						
	EF 30SEP94		LF 28SEP06	OD	0	BC	0
A103A04018	TA21 LADP-2 START RFI FIELD WORK						
ES 3OCT94		LS 29SEP06		OD	0	BC	0
A104A04012	TA21 LADP-2 START RFI REPORT						
ES 3OCT94		LS 29SEP06		OD	0	BC	0
A103A04002	TA21 LADP-2 Drill/Sample Ph1						
ES 15MAY97	EF 28MAY97	LS 14FEB05	LF 25FEB05	OD	9	BC	55133
A103A04003	TA21 LADP-2 Field Analysis Ph1						
ES 15MAY97	EF 28MAY97	LS 19OCT05	LF 31OCT05	OD	9	BC	18000
A103A04014	TA21 LADP-2 IDW Char. Analysis						
ES 15MAY97	EF 18JUL97	LS 21JUN06	LF 23AUG06	OD	45	BC	0
A103A04012	TA21 LADP-2 IDW Mgt						
ES 15MAY97	EF 22AUG97	LS 14FEB06	LF 28SEP06	OD	70	BC	0
A103A04006	TA21 LADP-2 Laboratory Analysis Ph1						
ES 15MAY97	EF 4DEC97	LS 10MAR05	LF 23SEP05	OD	139	BC	44041
A103A04010	TA21 LADP-2 Data Tracking Ph1						
ES 15MAY97	EF 6JAN98	LS 17MAR05	LF 31OCT05	OD	159	BC	11721
A103A04013	TA21 LADP-2 IDW Monitoring						
ES 15MAY97	EF 6JAN98	LS 14FEB06	LF 28SEP06	OD	159	BC	1659
A103A04001	TA21 Ph1 Subs. Agg. 12.5: LADP-2						
ES 15MAY97	EF 11DEC98	LS 14FEB05	LF 28SEP06	OD	393	BC	0
A103A04004	TA21 LADP-2 Document Locations Ph1						
ES 29MAY97	EF 29MAY97	LS 31OCT05	LF 31OCT05	OD	1	BC	1713
A103A04007	TA21 LADP 2 Geo-Hydro Analysis Ph1						
ES 29MAY97	EF 19SEP97	LS 8JUL05	LF 31OCT05	OD	80	BC	36960
A103A04005	TA21 LADP-2 Log/Test Ph1						
ES 12JUN97	EF 24JUN97	LS 20SEP05	LF 30SEP05	OD	9	BC	58250
A103A04008	TA21 LADP-2 Geo Logging Analysis Ph1						
ES 25JUN97	EF 23JUL97	LS 30OCT05	LF 31OCT05	OD	20	BC	15100
A103A04015	TA21 LADP-2 Prepare IDW Disposal Documentation						
ES 21JUL97	EF 8AUG97	LS 24AUG06	LF 14SEP06	OD	15	BC	6450
A103A04016	TA21 LADP-2 IDW Disposal						
ES 11AUG97	EF 22AUG97	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A04009	TA21 LADP-2 Data Quality Assurance Ph1						
ES 7JAN98	EF 13JAN98	LS 25OCT05	LF 31OCT05	OD	5	BC	1593
A103A04011	TA21 LADP-2 Data Assessment Ph1						
ES 14JAN98	EF 19MAR98	LS 1NOV05	LF 6JAN06	OD	45	BC	66355
A104A04002	TA21 LADP-2 Risk Assessment						
ES 20MAR98	EF 2APR98	LS 9JAN06	LF 23JAN06	OD	10	BC	13022
A104A04001	TA21 LADP-2 RFI Report Prep. Ph1						
ES 20MAR98	EF 12JUN98	LS 9JAN06	LF 4APR06	OD	60	BC	0
A104A04003	TA21 LADP-2 Decision Analysis						
ES 3APR98	EF 9APR98	LS 24JAN06	LF 30JAN06	OD	5	BC	7849



A104A04004	TA21 LADP-2 Write RFI Report						
ES 10APR98	EF 12JUN98	LS 31JAN06	LF 4APR06	OD	45	BC	71320
A104A04005	TA21 LADP-2 LANL/DOE Review Ph1						
ES 15JUN98	EF 13JUL98	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A04006	TA21 LADP-2 Incl. LANL/DOE Comments Ph1						
ES 14JUL98	EF 10AUG98	LS 3MAY06	LF 31MAY06	OD	20	BC	15786
A104A04007	TA21 LADP-2 Issue EPA Draft Ph1						
ES 11AUG98	EF 24AUG98	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A04008	TA21 LADP-2 EPA Draft Complete Ph1						
	EF 24AUG98		LF 14JUN06	OD	0	BC	0
A104A04009	TA21 LADP-2 EPA Review Ph1						
ES 25AUG98	EF 27OCT98	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A04010	TA21 LADP-2 Incl. EPA Comments Ph1						
ES 28OCT98	EF 25NOV98	LS 17AUG06	LF 14SEP06	OD	20	BC	6780
A104A04011	TA21 LADP-2 Issue Final Rpt./WP Mod. Ph1						
ES 30NOV98	EF 11DEC98	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A104A05012	TA21 LADP-5 START RFI REPORT						
ES 30CT94		LS 29SEP06		OD	0	BC	0
A103A05002	TA21 LADP-5 Drill/Sample Ph1						
ES 30MAY97	EF 12JUN97	LS 1MAR05	LF 14MAR05	OD	10	BC	58726
A103A05003	TA21 LADP-5 Field Analysis Ph1						
ES 30MAY97	EF 12JUN97	LS 18OCT05	LF 31OCT05	OD	10	BC	20000
A103A05014	TA21 LADP-5 IDW Char. Analysis						
ES 30MAY97	EF 5DEC97	LS 21FEB06	LF 23AUG06	OD	130	BC	0
A103A05006	TA21 LADP-5 Laboratory Analysis Ph1						
ES 30MAY97	EF 19DEC97	LS 9MAR05	LF 23SEP05	OD	140	BC	44041
A103A05012	TA21 LADP-5 IDW Mgt						
ES 30MAY97	EF 14JAN98	LS 13FEB06	LF 28SEP06	OD	155	BC	0
A103A05013	TA21 LADP-5 IDW Monitoring						
ES 30MAY97	EF 22JAN98	LS 13FEB06	LF 28SEP06	OD	160	BC	1950
A103A05001	TA21 Ph1 Subs. Agg. 12.5: LADP-5						
ES 30MAY97	EF 8JAN99	LS 1MAR05	LF 28SEP06	OD	400	BC	0
A103A05004	TA21 LADP-5 Document Locations Ph1						
ES 13JUN97	EF 13JUN97	LS 15MAR05	LF 15MAR05	OD	1	BC	1713
A103A05007	TA21 LADP 5 Geo-Hydro Analysis Ph1						
ES 13JUN97	EF 6OCT97	LS 8JUL05	LF 31OCT05	OD	80	BC	36960
A103A05010	TA21 LADP-5 Data Tracking Ph1						
ES 16JUN97	EF 6FEB98	LS 16MAR05	LF 31OCT05	OD	160	BC	20537
A103A05005	TA21 LADP-5 Log/Test Ph1						
ES 27JUN97	EF 9JUL97	LS 21SEP05	LF 30SEP05	OD	8	BC	58250
A103A05008	TA21 LADP-5 Geo Logging Analysis Ph1						
ES 10JUL97	EF 6AUG97	LS 30CT05	LF 31OCT05	OD	20	BC	15100
A103A05015	TA21 LADP-5 Prepare IDW Disposal Documentation						
ES 8DEC97	EF 30DEC97	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A05016	TA21 LADP-5 IDW Disposal						
ES 31DEC97	EF 14JAN98	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A05009	TA21 LADP-5 Data Quality Assurance Ph1						
ES 23JAN98	EF 29JAN98	LS 25OCT05	LF 31OCT05	OD	5	BC	1593
A103A05011	TA21 LADP-5 Data Assessment Ph1						
ES 9FEB98	EF 13APR98	LS 1NOV05	LF 6JAN06	OD	45	BC	66355
A103A05018	TA21 LADP-5 Risk Assessment						
ES 14APR98	EF 27APR98	LS 9JAN06	LF 23JAN06	OD	10	BC	13022
A104A05001	TA21 LADP-5 RFI Report Prep. Ph1						
ES 14APR98	EF 8JUL98	LS 9JAN06	LF 4APR06	OD	60	BC	0
A103A05017	TA21 LADP-5 Decision Analysis						
ES 28APR98	EF 4MAY98	LS 24JAN06	LF 30JAN06	OD	5	BC	7849
A103A05019	TA21 LADP-5 RFI FIELD WORK COMPLETE						
	EF 1MAY98		LF 3JAN95	OD	0	BC	0
A104A05004	TA21 LADP-5 Write RFI Report						
ES 5MAY98	EF 8JUL98	LS 31JAN06	LF 4APR06	OD	45	BC	71320
A104A05005	TA21 LADP-5 LANL/DOE Review Ph1						
ES 9JUL98	EF 5AUG98	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A05006	TA21 LADP-5 Incl. LANL/DOE Comments Ph1						
ES 6AUG98	EF 2SEP98	LS 3MAY06	LF 31MAY06	OD	20	BC	15786
A104A05007	TA21 LADP-5 Issue EPA Draft Ph1						
ES 3SEP98	EF 17SEP98	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A05008	TA21 LADP-5 EPA Draft Complete Ph1						
	EF 17SEP98		LF 14JUN06	OD	0	BC	0
A104A05009	TA21 LADP-5 EPA Review Ph1						
ES 18SEP98	EF 20NOV98	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A05010	TA21 LADP-5 Incl. EPA Comments Ph1						
ES 23NOV98	EF 22DEC98	LS 17AUG06	LF 14SEP06	OD	20	BC	6780
A104A05011	TA21 LADP-5 Issue Final Rpt./WP Mod. Ph1						
ES 23DEC98	EF 8JAN99	LS 15SEP06	LF 28SEP06	OD	10	BC	1922



A104A06012	TA21 MDA-U-DP START RFI REPORT				
ES 30CT94		LS 29SEP06	OD 0	BC	0
A103A06002	TA21 MDA-U-DP Drill/Sample Ph1				
ES 29JUL96	EF 8AUG96	LS 10MAR05	LF 22MAR05	OD 9	BC 55133
A103A06003	TA21 MDA-U-DP Field Analysis Ph1				
ES 29JUL96	EF 8AUG96	LS 19OCT05	LF 31OCT05	OD 9	BC 18000
A103A06006	TA21 MDA-U-DP Laboratory Analysis Ph1				
ES 29JUL96	EF 20FEB97	LS 10MAR05	LF 23SEP05	OD 139	BC 14722
A103A06014	TA21 MDA-U-DP IDW Char. Analysis				
ES 29JUL96	EF 20FEB97	LS 7FEB06	LF 23AUG06	OD 139	BC 3160
A103A06010	TA21 MDA-U-DP Data Tracking Ph1				
ES 29JUL96	EF 20MAR97	LS 17MAR05	LF 31OCT05	OD 159	BC 11721
A103A06013	TA21 MDA-U-DP IDW Monitoring				
ES 29JUL96	EF 20MAR97	LS 14FEB06	LF 28SEP06	OD 159	BC 1659
A103A06012	TA21 MDA-U-DP IDW Mgt				
ES 29JUL96	EF 27MAR97	LS 14FEB06	LF 28SEP06	OD 164	BC 0
A103A06001	TA21 Ph1 Subs. Agg. 12.5: MDA-U-DP				
ES 29JUL96	EF 27FEB98	LS 10MAR05	LF 28SEP06	OD 393	BC 0
A103A06004	TA21 MDA-U-DP Document Locations Ph1				
ES 9AUG96	EF 9AUG96	LS 31OCT05	LF 31OCT05	OD 1	BC 1713
A103A06005	TA21 MDA-U-DP Log/Test Ph1				
ES 9AUG96	EF 20AUG96	LS 21SEP05	LF 30SEP05	OD 8	BC 58250
A103A06007	TA21 MDA-U-DP Geo-Hydro Analysis Ph1				
ES 9AUG96	EF 5DEC96	LS 8JUL05	LF 31OCT05	OD 80	BC 22380
A103A06008	TA21 MDA-U-DP Geo Logging Analysis Ph1				
ES 21AUG96	EF 18SEP96	LS 30CT05	LF 31OCT05	OD 20	BC 15100
A103A06015	TA21 MDA-U-DP Prepare IDW Disposal Documentation				
ES 21FEB97	EF 13MAR97	LS 24AUG06	LF 14SEP06	OD 15	BC 8160
A103A06016	TA21 MDA-U-DP IDW Disposal				
ES 14MAR97	EF 27MAR97	LS 15SEP06	LF 28SEP06	OD 10	BC 12149
A103A06009	TA21 MDA-U-DP Data Quality Assurance Ph1				
ES 21MAR97	EF 27MAR97	LS 25OCT05	LF 31OCT05	OD 5	BC 1997
A103A06011	TA21 MDA-U-DP Data Assessment Ph1				
ES 28MAR97	EF 30MAY97	LS 1NOV05	LF 6JAN06	OD 45	BC 66355
A103A06018	TA21 MDA-U-DP Risk Assessment				
ES 2JUN97	EF 13JUN97	LS 9JAN06	LF 23JAN06	OD 10	BC 13022
A104A06001	TA21 MDA-U-DP RFI Report Prep. Ph1				
ES 2JUN97	EF 25AUG97	LS 9JAN06	LF 4APR06	OD 60	BC 0
A103A06017	TA21 MDA-U-DP Decision Analysis				
ES 16JUN97	EF 20JUN97	LS 24JAN06	LF 30JAN06	OD 5	BC 7849
A104A06004	TA21 MDA-U-DP Write RFI Report				
ES 23JUN97	EF 25AUG97	LS 31JAN06	LF 4APR06	OD 45	BC 71320
A104A06005	TA21 MDA-U-DP LANL/DOE Review Ph1				
ES 26AUG97	EF 23SEP97	LS 5APR06	LF 2MAY06	OD 20	BC 1534
A104A06006	TA21 MDA-U-DP Incl. LANL/DOE Comments Ph1				
ES 24SEP97	EF 22OCT97	LS 3MAY06	LF 31MAY06	OD 20	BC 15786
A104A06007	TA21 MDA-U-DP Issue EPA Draft Ph1				
ES 23OCT97	EF 5NOV97	LS 1JUN06	LF 14JUN06	OD 10	BC 4257
A104A06008	TA21 MDA-U-DP EPA Draft Complete Ph1				
	EF 5NOV97		LF 14JUN06	OD 0	BC 0
A104A06009	TA21 MDA-U-DP EPA Review Ph1				
ES 6NOV97	EF 14JAN98	LS 15JUN06	LF 16AUG06	OD 44	BC 793
A104A06010	TA21 MDA-U-DP Incl. EPA Comments Ph1				
ES 15JAN98	EF 12FEB98	LS 17AUG06	LF 14SEP06	OD 20	BC 6780
A104A06011	TA21 MDA-U-DP Issue Final Rpt./WP Mod. Ph1				
ES 13FEB98	EF 27FEB98	LS 15SEP06	LF 28SEP06	OD 10	BC 1922
A104A07012	TA21 MDA-T-DP START RFI REPORT				
ES 30CT94		LS 29SEP06	OD 0	BC	0
A103A07501	TA21 Surf. Agg. 12.6: Quarterly Water Sample Ph1				
ES 3JAN95	EF 7MAR00	LS 31JUL01	LF 28SEP06	OD 1289	BC 0
A103A07002	TA21 MDA-T-DP Drill/Sample Ph1				
ES 22MAY95	EF 2JUN95	LS 17AUG95	LF 29AUG95	OD 9	BC 55133
A103A07003	TA21 MDA-T-DP Field Analysis Ph1				
ES 22MAY95	EF 2JUN95	LS 4APR96	LF 16APR96	OD 9	BC 18000
A103A07006	TA21 MDA-T-DP Laboratory Analysis Ph1				
ES 22MAY95	EF 11DEC95	LS 17AUG95	LF 12MAR96	OD 139	BC 14722
A103A07010	TA21 MDA-T-DP Data Tracking Ph1				
ES 22MAY95	EF 11JAN96	LS 24AUG95	LF 16APR96	OD 159	BC 11721
A103A07014	TA21 MDA-T-DP IDW Char. Analysis				
ES 22MAY95	EF 11JAN96	LS 9JAN06	LF 23AUG06	OD 159	BC 3160
A103A07013	TA21 MDA-T-DP IDW Monitoring				
ES 22MAY95	EF 19JAN96	LS 7FEB06	LF 28SEP06	OD 164	BC 1659
A103A07012	TA21 MDA-T-DP IDW Mgt				
ES 22MAY95	EF 16FEB96	LS 7FEB06	LF 28SEP06	OD 184	BC 0



A103A07001	TA21 Ph1 Subs. Agg. 12.5: MDA-T-DP					
ES 22MAY95	EF 17DEC96	LS 17AUG95	LF 28SEP06	OD 393	BC	0
A103A07004	TA21 MDA-T-DP Document Locations Ph1					
ES 5JUN95	EF 5JUN95	LS 16APR96	LF 16APR96	OD 1	BC	1713
A103A07005	TA21 MDA-T-DP Log/Test Ph1					
ES 5JUN95	EF 14JUN95	LS 8MAR96	LF 19MAR96	OD 8	BC	58250
A103A07007	TA21 MDA-T-DP Geo-Hydro Analysis Ph1					
ES 5JUN95	EF 26SEP95	LS 20DEC95	LF 16APR96	OD 80	BC	22380
A103A07008	TA21 MDA-T-DP Geo Logging Analysis Ph1					
ES 15JUN95	EF 13JUL95	LS 20MAR96	LF 16APR96	OD 20	BC	15100
A103A07009	TA21 MDA-T-DP Data Quality Assurance Ph1					
ES 12JAN96	EF 19JAN96	LS 10APR96	LF 16APR96	OD 5	BC	1661
A103A07015	TA21 MDA-T-DP Prepare IDW Disposal Documentation					
ES 12JAN96	EF 2FEB96	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A07011	TA21 MDA-T-DP Data Assessment Ph1					
ES 22JAN96	EF 25MAR96	LS 17APR96	LF 19JUN96	OD 45	BC	66355
A103A07016	TA21 MDA-T-DP IDW Disposal					
ES 5FEB96	EF 16FEB96	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A07018	TA21 MDA-T-DP Risk Assessment					
ES 26MAR96	EF 8APR96	LS 20JUN96	LF 3JUL96	OD 10	BC	13022
A104A07001	TA21 MDA-T-DP RFI Report Prep. Ph1					
ES 26MAR96	EF 18JUN96	LS 20JUN96	LF 13SEP96	OD 60	BC	0
A103A07017	TA21 MDA-T-DP Decision Analysis					
ES 9APR96	EF 15APR96	LS 5JUL96	LF 11JUL96	OD 5	BC	7849
A104A07004	TA21 MDA-T-DP Write RFI Report					
ES 16APR96	EF 18JUN96	LS 12JUL96	LF 13SEP96	OD 45	BC	71320
A104A07005	TA21 MDA-T-DP LANL/DOE Review Ph1					
ES 19JUN96	EF 17JUL96	LS 16SEP96	LF 11OCT96	OD 20	BC	1534
A104A07006	TA21 MDA-T-DP Incl. LANL/DOE Comments Ph1					
ES 18JUL96	EF 14AUG96	LS 15OCT96	LF 12NOV96	OD 20	BC	15786
A104A07007	TA21 MDA-T-DP Issue EPA Draft Ph1					
ES 15AUG96	EF 28AUG96	LS 13NOV96	LF 26NOV96	OD 10	BC	4257
A104A07008	TA21 MDA-T-DP EPA Draft Complete Ph1					
	EF 28AUG96		LF 26NOV96	OD 0	BC	0
A104A07009	TA21 MDA-T-DP EPA Review Ph1					
ES 29AUG96	EF 31OCT96	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A07010	TA21 MDA-T-DP Incl. EPA Comments Ph1					
ES 1NOV96	EF 3DEC96	LS 17AUG06	LF 14SEP06	OD 20	BC	6780
A104A07011	TA21 MDA-T-DP Issue Final Rpt./WP Mod. Ph1					
ES 4DEC96	EF 17DEC96	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A07503	Winter Sampling					
ES 3JAN95	EF 4JAN95	LS 31JUL01	LF 1AUG01	OD 2	BC	3190
A103A07502	Field Work: Year 3					
ES 3JAN95	EF 12JUL95	LS 31JUL01	LF 13FEB02	OD 133	BC	0
A103A07507	Winter Laboratory Analysis					
ES 3JAN95	EF 18AUG95	LS 24JAN06	LF 8SEP06	OD 160	BC	64150
A103A07506	Sample Analysis Year 3					
ES 3JAN95	EF 19MAR96	LS 24JAN06	LF 28SEP06	OD 302	BC	0
A103A07504	Spring Sampling					
ES 6APR95	EF 7APR95	LS 1NOV01	LF 2NOV01	OD 2	BC	3190
A103A07508	Spring Laboratory Analysis					
ES 6APR95	EF 22NOV95	LS 25JAN06	LF 11SEP06	OD 160	BC	64150
A103A07505	Summer Sampling					
ES 7JUL95	EF 12JUL95	LS 8FEB02	LF 13FEB02	OD 4	BC	4778
A103A07509	Summer Laboratory Analysis					
ES 7JUL95	EF 1MAR96	LS 25JAN06	LF 12SEP06	OD 161	BC	40610
A103A07510	Winter Data Quality Assurance					
ES 5SEP95	EF 5SEP95	LS 25SEP06	LF 25SEP06	OD 1	BC	400
A103A07514	Fall Sampling					
ES 20CT95	EF 5OCT95	LS 6MAY02	LF 9MAY02	OD 4	BC	4778
A103A07519	Fall Laboratory Analysis					
ES 20CT95	EF 24MAY96	LS 17JAN06	LF 1SEP06	OD 161	BC	35902
A103A07513	Field Work: Year 4					
ES 20CT95	EF 2JUL96	LS 6MAY02	LF 5FEB03	OD 187	BC	0
A103A07518	Sample Analysis Year 4					
ES 20CT95	EF 11MAR97	LS 17JAN06	LF 28SEP06	OD 356	BC	0
A103A07511	Spring Data Quality Assurance					
ES 11DEC95	EF 11DEC95	LS 26SEP06	LF 26SEP06	OD 1	BC	400
A103A07515	Winter Sampling					
ES 28DEC95	EF 3JAN96	LS 26JUL02	LF 31JUL02	OD 4	BC	4778
A103A07520	Winter Laboratory Analysis					
ES 28DEC95	EF 15AUG96	LS 19JAN06	LF 6SEP06	OD 161	BC	35902
A103A07512	Summer Data Quality Assurance					
ES 18MAR96	EF 19MAR96	LS 27SEP06	LF 28SEP06	OD 2	BC	808



A103A07516	Spring Sampling							
ES 29MAR96	EF 3APR96	LS 25OCT02	LF 30OCT02	OD	4	BC	4778
A103A07521	Spring Laboratory Analysis							
ES 29MAR96	EF 15NOV96	LS 23JAN06	LF 8SEP06	OD	161	BC	64150
A103A07523	Fall Data Quality Assurance							
ES 11JUN96	EF 12JUN96	LS 19SEP06	LF 20SEP06	OD	2	BC	808
A103A07517	Summer Sampling							
ES 27JUN96	EF 2JUL96	LS 31JAN03	LF 5FEB03	OD	4	BC	4778
A103A07522	Summer Laboratory Analysis							
ES 27JUN96	EF 21FEB97	LS 25JAN06	LF 12SEP06	OD	161	BC	40610
A103A07524	Winter Data Quality Assurance							
ES 30AUG96	EF 3SEP96	LS 21SEP06	LF 22SEP06	OD	2	BC	808
A103A07528	Fall Sampling							
ES 25SEP96	EF 30SEP96	LS 30APR03	LF 5MAY03	OD	4	BC	4778
A103A07533	Fall Laboratory Analysis							
ES 25SEP96	EF 20MAY97	LS 17JAN06	LF 1SEP06	OD	161	BC	35902
A103A07527	Field Work: Year 5							
ES 25SEP96	EF 24JUN97	LS 30APR03	LF 28JAN04	OD	185	BC	0
A103A07532	Sample Analysis Year 5							
ES 25SEP96	EF 3MAR98	LS 17JAN06	LF 28SEP06	OD	354	BC	0
A103A07525	Spring Data Quality Assurance							
ES 4DEC96	EF 5DEC96	LS 25SEP06	LF 26SEP06	OD	2	BC	808
A103A07529	Winter Sampling							
ES 19DEC96	EF 24DEC96	LS 22JUL03	LF 25JUL03	OD	4	BC	4778
A103A07534	Winter Laboratory Analysis							
ES 19DEC96	EF 11AUG97	LS 19JAN06	LF 6SEP06	OD	161	BC	35902
A103A07526	Summer Data Quality Assurance							
ES 10MAR97	EF 11MAR97	LS 27SEP06	LF 28SEP06	OD	2	BC	808
A103A07530	Spring Sampling							
ES 19MAR97	EF 24MAR97	LS 15OCT03	LF 20OCT03	OD	4	BC	4778
A103A07535	Spring Laboratory Analysis							
ES 19MAR97	EF 4NOV97	LS 23JAN06	LF 8SEP06	OD	161	BC	64150
A103A07537	Fall Data Quality Assurance							
ES 5JUN97	EF 6JUN97	LS 19SEP06	LF 20SEP06	OD	2	BC	808
A103A07531	Summer Sampling							
ES 19JUN97	EF 24JUN97	LS 23JAN04	LF 28JAN04	OD	4	BC	4778
A103A07536	Summer Laboratory Analysis							
ES 19JUN97	EF 12FEB98	LS 25JAN06	LF 12SEP06	OD	161	BC	40610
A103A07538	Winter Data Quality Assurance							
ES 26AUG97	EF 27AUG97	LS 21SEP06	LF 22SEP06	OD	2	BC	808
A103A07542	Fall Sampling							
ES 17SEP97	EF 22SEP97	LS 21APR04	LF 26APR04	OD	4	BC	4778
A103A07547	Fall Laboratory Analysis							
ES 17SEP97	EF 12MAY98	LS 13JAN06	LF 31AUG06	OD	161	BC	40610
A103A07541	Field Work: Year 6							
ES 17SEP97	EF 23JUN98	LS 21APR04	LF 26JAN05	OD	190	BC	0
A103A07546	Sample Analysis Year 6							
ES 17SEP97	EF 2MAR99	LS 13JAN06	LF 28SEP06	OD	359	BC	0
A103A07539	Spring Data Quality Assurance							
ES 20NOV97	EF 21NOV97	LS 25SEP06	LF 26SEP06	OD	2	BC	808
A103A07543	Winter Sampling							
ES 12DEC97	EF 17DEC97	LS 14JUL04	LF 19JUL04	OD	4	BC	4778
A103A07548	Winter Laboratory Analysis							
ES 12DEC97	EF 4AUG98	LS 19JAN06	LF 6SEP06	OD	161	BC	35902
A103A07540	Summer Data Quality Assurance							
ES 2MAR98	EF 3MAR98	LS 27SEP06	LF 28SEP06	OD	2	BC	808
A103A07544	Spring Sampling							
ES 25MAR98	EF 30MAR98	LS 20OCT04	LF 25OCT04	OD	4	BC	4778
A103A07549	Spring Laboratory Analysis							
ES 25MAR98	EF 11NOV98	LS 23JAN06	LF 8SEP06	OD	161	BC	64150
A103A07551	Fall Data Quality Assurance							
ES 29MAY98	EF 1JUN98	LS 19SEP06	LF 20SEP06	OD	2	BC	808
A103A07545	Summer Sampling							
ES 18JUN98	EF 23JUN98	LS 21JAN05	LF 26JAN05	OD	4	BC	4778
A103A07550	Summer Laboratory Analysis							
ES 18JUN98	EF 11FEB99	LS 25JAN06	LF 12SEP06	OD	161	BC	40610
A103A07552	Winter Data Quality Assurance							
ES 19AUG98	EF 20AUG98	LS 21SEP06	LF 22SEP06	OD	2	BC	808
A103A07556	Fall Sampling							
ES 21SEP98	EF 24SEP98	LS 25APR05	LF 28APR05	OD	4	BC	4778
A103A07561	Fall Laboratory Analysis							
ES 21SEP98	EF 14MAY99	LS 13JAN06	LF 31AUG06	OD	161	BC	40610
A103A07555	Field Work: Year 7							
ES 21SEP98	EF 29JUN99	LS 25APR05	LF 30JAN06	OD	192	BC	0
A103A07560	Sample Analysis Year 7							
ES 21SEP98	EF 7MAR00	LS 13JAN06	LF 28SEP06	OD	361	BC	0



A103A07553	Spring Data Quality Assurance						
ES 30NOV98	EF 1DEC98	LS 25SEP06	LF 26SEP06	OD	2	BC	808
A103A07557	Winter Sampling						
ES 21DEC98	EF 24DEC98	LS 21JUL05	LF 26JUL05	OD	4	BC	4778
A103A07562	Winter Laboratory Analysis						
ES 21DEC98	EF 11AUG99	LS 19JAN06	LF 6SEP06	OD	161	BC	36217
A103A07554	Summer Data Quality Assurance						
ES 1MAR99	EF 2MAR99	LS 27SEP06	LF 28SEP06	OD	2	BC	808
A103A07558	Spring Sampling						
ES 29MAR99	EF 1APR99	LS 24OCT05	LF 27OCT05	OD	4	BC	4778
A103A07563	Spring Laboratory Analysis						
ES 29MAR99	EF 15NOV99	LS 23JAN06	LF 8SEP06	OD	161	BC	60626
A103A07565	Fall Data Quality Assurance						
ES 2JUN99	EF 3JUN99	LS 19SEP06	LF 20SEP06	OD	2	BC	808
A103A07559	Summer Sampling						
ES 24JUN99	EF 29JUN99	LS 25JAN06	LF 30JAN06	OD	4	BC	4778
A103A07564	Summer Laboratory Analysis						
ES 24JUN99	EF 17FEB00	LS 25JAN06	LF 12SEP06	OD	161	BC	40477
A103A07566	Winter Data Quality Assurance						
ES 26AUG99	EF 27AUG99	LS 21SEP06	LF 22SEP06	OD	2	BC	808
A103A07567	Spring Data Quality Assurance						
ES 2DEC99	EF 3DEC99	LS 25SEP06	LF 26SEP06	OD	2	BC	808
A103A07568	Summer Data Quality Assurance						
ES 6MAR00	EF 7MAR00	LS 27SEP06	LF 28SEP06	OD	2	BC	808
A103A08017	TA21 LAUZ 1&2 RFI FIELD WORK COMPLETE						
	EF 30SEP94		LF 14JUN06	OD	0	BC	0
A104A08012	TA21 LAUZ 1&2 START RFI REPORT			SM	1		
ES 30CT94		LS 29SEP06		OD	0	BC	0
A103A08005	TA21 LAUZ 1&2 Laboratory Analysis-DP Wells Ph1						
ES 3JAN95	EF 27MAR95	LS 5JUL05	LF 23SEP05	OD	58	BC	29042
A103A08006	TA21 LAUZ 1&2 Laboratory Analysis-GW Ph1						
ES 3JAN95	EF 27MAR95	LS 5JUL05	LF 23SEP05	OD	58	BC	19497
A103A08012	TA21 LAUZ 1&2 IDW Char. Analysis						
ES 3JAN95	EF 27MAR95	LS 2JUN06	LF 23AUG06	OD	58	BC	3160
A103A08010	TA21 LAUZ 1&2 IDW Mgt						
ES 3JAN95	EF 1MAY95	LS 25MAY06	LF 28SEP06	OD	83	BC	0
A103A08008	TA21 LAUZ 1&2 Data Tracking Ph1						
ES 3JAN95	EF 8MAY95	LS 25MAY06	LF 28SEP06	OD	88	BC	7986
A103A08011	TA21 LAUZ 1&2 IDW Monitoring						
ES 3JAN95	EF 8MAY95	LS 25MAY06	LF 28SEP06	OD	88	BC	1569
A103A08013	TA21 LAUZ 1&2 Prepare IDW Disposal Documentation						
ES 28MAR95	EF 17APR95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A08014	TA21 LAUZ 1&2 IDW Disposal						
ES 18APR95	EF 1MAY95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A08007	TA21 LAUZ 1&2 Data Qual. Assurance DP Wells Ph1						
ES 25APR95	EF 1MAY95	LS 25OCT05	LF 31OCT05	OD	5	BC	2065
A103A08003	TA21 LAUZ 1&2 Complete/Instrument Ph1						
ES 1JUN95	EF 12JUN95	LS 19SEP06	LF 28SEP06	OD	8	BC	13846
A103A08002	TA21 Ph1 Surf. Agg. 12.6: LAUZ 1&2						
ES 1JUN95	EF 7MAR96	LS 19SEP06	LF 18SEP06	OD	190	BC	0
A103A08009	TA21 LAUZ 1&2 Data Assessment Ph1						
ES 20CT95	EF 7DEC95	LS 1NOV05	LF 6JAN06	OD	45	BC	66355
A103A08016	TA21 LAUZ 1&2 Risk Assessment						
ES 8DEC95	EF 21DEC95	LS 9JAN06	LF 23JAN06	OD	10	BC	13022
A104A08001	TA21 LAUZ 1&2 RFI Report Prep., Ph1						
ES 8DEC95	EF 7MAR96	LS 9JAN06	LF 4APR06	OD	60	BC	0
A103A08015	TA21 LAUZ 1&2 Decision Analysis						
ES 22DEC95	EF 2JAN96	LS 24JAN06	LF 30JAN06	OD	5	BC	7849
A104A08004	TA21 LAUZ 1&2 Write RFI Report						
ES 3JAN96	EF 7MAR96	LS 31JAN06	LF 4APR06	OD	45	BC	71320
A104A08005	TA21 LAUZ 1&2 LANL/DOE Review Ph1						
ES 8MAR96	EF 4APR96	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A08006	TA21 LAUZ 1&2 Incl. LANL/DOE Comments Ph1						
ES 5APR96	EF 2MAY96	LS 3MAY06	LF 31MAY06	OD	20	BC	15786
A104A08007	TA21 LAUZ 1&2 Issue EPA Draft Ph1						
ES 3MAY96	EF 16MAY96	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A08008	TA21 LAUZ 1&2 EPA Draft Complete Ph1						
	EF 16MAY96		LF 14JUN06	OD	0	BC	0
A104A08009	TA21 LAUZ 1&2 EPA Review Ph1						
ES 17MAY96	EF 19JUL96	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A08010	TA21 LAUZ 1&2 Incl. EPA Comments Ph1						
ES 22JUL96	EF 16AUG96	LS 17AUG06	LF 14SEP06	OD	20	BC	6780
A104A08011	TA21 LAUZ 1&2 Issue Final Rpt./WP Mod. Ph1						
ES 19AUG96	EF 30AUG96	LS 15SEP06	LF 28SEP06	OD	10	BC	1922



A103A08004	TA21 LAUZ 1&2 Tracer Study Ph1				
ES 10CT97	EF 2JUN99 LS 8FEB05 LF 28SEP06	OD	414	BC	158630
A103A09017	TA21 14.2 RFI FIELD WORK COMPLETE				
	EF 30SEP94 LF 14JUN06	OD	0	BC	0
A103A09002	TA21 14.2 Laboratory Analysis Ph1				
ES 3JAN95	EF 14APR95 LS 29MAR06 LF 10JUL06	OD	72	BC	67557
A103A09004	TA21 14.2 Data Tracking Ph1				
ES 3JAN95	EF 26MAY95 LS 5MAY06 LF 28SEP06	OD	102	BC	9258
A103A09008	TA21 14.2 IDW Char. Analysis				
ES 3JAN95	EF 31MAY95 LS 29MAR06 LF 23AUG06	OD	104	BC	1580
A103A09007	TA21 14.2 IDW Monitoring				
ES 3JAN95	EF 26JUN95 LS 7APR06 LF 28SEP06	OD	122	BC	1569
A103A09001	TA21 Ph1 Surf. Agg. 14.2: 21-003 (PCB Area)				
ES 3JAN95	EF 6JUL95 LS 29MAR06 LF 28SEP06	OD	129	BC	0
A103A09006	TA21 14.2 IDW Mgt				
ES 3JAN95	EF 6JUL95 LS 7APR06 LF 28SEP06	OD	129	BC	0
A103A09003	TA21 14.2 Data Quality Assurance Ph1				
ES 15MAY95	EF 19MAY95 LS 24AUG06 LF 30AUG06	OD	5	BC	1907
A103A09005	TA21 14.2 Data Assessment Ph1				
ES 22MAY95	EF 19JUN95 LS 31AUG06 LF 28SEP06	OD	20	BC	22331
A103A09009	TA21 14.2 Prepare IDW Disposal Documentation				
ES 1JUN95	EF 21JUN95 LS 24AUG06 LF 14SEP06	OD	15	BC	8160
A103A09010	TA21 14.2 IDW Disposal				
ES 22JUN95	EF 6JUL95 LS 15SEP06 LF 28SEP06	OD	10	BC	12149
A103A10017	TA21 14.2 RFI FIELD WORK COMPLETE				
	EF 30SEP94 LF 14JUN06	OD	0	BC	0
A103A10018	TA21 14.2 START RFI FIELD WORK PH2				
ES 30CT94	LS 29SEP06	OD	0	BC	0
A104A10012	TA21 14.2 START RFI REPORT Ph2				
ES 30CT94	LS 29SEP06	OD	0	BC	0
A103A10002	TA21 14.2 Drill/Sample Ph2				
ES 2MAY96	EF 3MAY96 LS 20OCT97 LF 21OCT97	OD	2	BC	11154
A103A10003	TA21 14.2 Field Analysis Ph2				
ES 2MAY96	EF 3MAY96 LS 20JAN06 LF 23JAN06	OD	2	BC	4000
A103A10005	TA21 14.2 Laboratory Analysis Ph2				
ES 2MAY96	EF 7NOV96 LS 7JUN05 LF 13DEC05	OD	132	BC	34291
A103A10011	TA21 14.2 IDW Char. Analysis				
ES 2MAY96	EF 7NOV96 LS 16FEB06 LF 23AUG06	OD	132	BC	3160
A103A10007	TA21 14.2 Data Tracking Ph2				
ES 2MAY96	EF 10DEC96 LS 24FEB06 LF 28SEP06	OD	152	BC	11079
A103A10010	TA21 14.2 IDW Monitoring				
ES 2MAY96	EF 10DEC96 LS 24FEB06 LF 28SEP06	OD	152	BC	1569
A103A10009	TA21 14.2 IDW Mgt				
ES 2MAY96	EF 17DEC96 LS 24FEB06 LF 28SEP06	OD	157	BC	0
A103A10001	TA21 Ph2 Surf. Agg. 14.2: 21-003 (PCB Area)				
ES 2MAY96	EF 27AUG97 LS 20OCT97 LF 28SEP06	OD	331	BC	0
A103A10004	TA21 14.2 Document Locations Ph2				
ES 6MAY96	EF 6MAY96 LS 23JAN06 LF 23JAN06	OD	1	BC	1713
A103A10012	TA21 14.2 Prepare IDW Disposal Documentation				
ES 8NOV96	EF 30DEC96 LS 24AUG06 LF 14SEP06	OD	15	BC	8160
A103A10013	TA21 14.2 IDW Disposal				
ES 4DEC96	EF 17DEC96 LS 15SEP06 LF 28SEP06	OD	10	BC	12149
A103A10006	TA21 14.2 Data Quality Assurance Ph2				
ES 11DEC96	EF 17DEC96 LS 17JAN06 LF 23JAN06	OD	5	BC	1644
A103A10008	TA21 14.2 Data Assessment Ph2				
ES 18DEC96	EF 20JAN97 LS 24JAN06 LF 21FEB06	OD	20	BC	22331
A103A10014	TA21 14.2 Risk Assessment				
ES 21JAN97	EF 3FEB97 LS 22FEB06 LF 7MAR06	OD	10	BC	13022
A104A10001	TA21 14.2 RFI Report Prep. Ph2				
ES 21JAN97	EF 4MAR97 LS 22FEB06 LF 4APR06	OD	30	BC	0
A103A10015	TA21 14.2 Decision Analysis				
ES 4FEB97	EF 10FEB97 LS 8MAR06 LF 14MAR06	OD	5	BC	7849
A104A10004	TA21 14.2 Write RFI Report				
ES 11FEB97	EF 4MAR97 LS 15MAR06 LF 4APR06	OD	15	BC	31839
A104A10005	TA21 14.2 LANL/DOE Review Ph2				
ES 5MAR97	EF 1APR97 LS 5APR06 LF 2MAY06	OD	20	BC	1534
A104A10006	TA21 14.2 Incl. LANL/DOE Comments Ph2				
ES 2APR97	EF 29APR97 LS 3MAY06 LF 31MAY06	OD	20	BC	22061
A104A10007	TA21 14.2 Issue EPA Draft Ph2				
ES 30APR97	EF 13MAY97 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A104A10008	TA21 14.2 EPA Draft Complete Ph2				
	EF 13MAY97 LF 14JUN06	OD	0	BC	0



A104A10009	TA21 14.2 EPA Review Ph2						
ES 14MAY97	EF 16JUL97	LS 15JUN06	LF 16AUG06	OD 44	BC	793	
A104A10010	TA21 14.2 Incl. EPA Comments Ph2						
ES 17JUL97	EF 13AUG97	LS 17AUG06	LF 14SEP06	OD 20	BC	22061	
A104A10011	TA21 14.2 Issue Final Rpt./WP Mod. Ph2						
ES 14AUG97	EF 27AUG97	LS 15SEP06	LF 28SEP06	OD 10	BC	1922	
A112A10012	TA21 EC 14.2: 21-003 (PCB Area)						
ES 10CT98	EF 30SEP99	LS 30CT05	LF 28SEP06	OD 249	BC	750000	
A103A11017	TA21 14.3 RFI FIELD WORK COMPLETE PH1						
	EF 30SEP94		LF 14JUN06	OD 0	BC	0	
A103A11002	TA21 14.3 Laboratory Analysis Ph1						
ES 3JAN95	EF 10APR95	LS 3APR06	LF 7JUL06	OD 68	BC	7399	
A103A11004	TA21 14.3 Data Tracking Ph1						
ES 3JAN95	EF 22MAY95	LS 11MAY06	LF 28SEP06	OD 98	BC	8900	
A103A11008	TA21 14.3 IDW Char. Analysis						
ES 3JAN95	EF 25MAY95	LS 3APR06	LF 23AUG06	OD 101	BC	1580	
A103A11007	TA21 14.3 IDW Monitoring						
ES 3JAN95	EF 26JUN95	LS 7APR06	LF 28SEP06	OD 122	BC	1569	
A103A11001	TA21 Ph1 Surf. Agg. 14.3: 21-004a-c (A.G. Tanks)						
ES 3JAN95	EF 30JUN95	LS 3APR06	LF 28SEP06	OD 126	BC	0	
A103A11006	TA21 14.3 IDW Mgt						
ES 3JAN95	EF 30JUN95	LS 7APR06	LF 28SEP06	OD 126	BC	0	
A103A11003	TA21 14.3 Data Qualtiy Assurance Ph1						
ES 9MAY95	EF 15MAY95	LS 31AUG06	LF 7SEP06	OD 5	BC	1661	
A103A11005	TA21 14.3 Data Assessment Ph1						
ES 16MAY95	EF 6JUN95	LS 8SEP06	LF 28SEP06	OD 15	BC	16746	
A103A11009	TA21 14.3 Prepare IDW Disposal Documentation						
ES 26MAY95	EF 16JUN95	LS 24AUG06	LF 14SEP06	OD 15	BC	8160	
A103A11010	TA21 14.3 IDW Disposal						
ES 19JUN95	EF 30JUN95	LS 15SEP06	LF 28SEP06	OD 10	BC	12149	
A103A12017	TA21 14.4 RFI FIELD WORK COMPLETE PH1						
	EF 30SEP94		LF 14JUN06	OD 0	BC	0	
A103A12002	TA21 14.4 Laboratory Analysis Ph1						
ES 3JAN95	EF 10APR95	LS 3APR06	LF 7JUL06	OD 68	BC	36159	
A103A12004	TA21 14.4 Data Tracking Ph1						
ES 3JAN95	EF 22MAY95	LS 11MAY06	LF 28SEP06	OD 98	BC	8900	
A103A12008	TA21 14.4 IDW Char. Analysis						
ES 3JAN95	EF 25MAY95	LS 3APR06	LF 23AUG06	OD 101	BC	1580	
A103A12007	TA21 14.4 IDW Monitoring						
ES 3JAN95	EF 26JUN95	LS 7APR06	LF 28SEP06	OD 122	BC	1569	
A103A12001	TA21 Ph1 Surf. Agg. 14.4: 21-028d/e (ACT. CSAs)						
ES 3JAN95	EF 30JUN95	LS 3APR06	LF 28SEP06	OD 126	BC	0	
A103A12006	TA21 14.4 IDW Mgt						
ES 3JAN95	EF 30JUN95	LS 7APR06	LF 28SEP06	OD 126	BC	0	
A103A12003	TA21 14.4 Data Quality Assurance Ph1						
ES 9MAY95	EF 15MAY95	LS 24AUG06	LF 30AUG06	OD 5	BC	1621	
A103A12005	TA21 14.4 Data Assessment Ph1						
ES 16MAY95	EF 13JUN95	LS 31AUG06	LF 28SEP06	OD 20	BC	22331	
A103A12009	TA21 14.4 Prepare IDW Disposal Documentation						
ES 26MAY95	EF 16JUN95	LS 24AUG06	LF 14SEP06	OD 15	BC	8160	
A103A12010	TA21 14.4 IDW Disposal						
ES 19JUN95	EF 30JUN95	LS 15SEP06	LF 28SEP06	OD 10	BC	12149	
A103A13021	TA21 14.5 RFI FIELD WORK COMPLETE PH1						
	EF 30SEP94		LF 14JUN06	OD 0	BC	0	
A103A13022	TA21 14.5 RFI FIELD WORK COMPLETE Ph1A						
	EF 30SEP94		LF 14JUN06	OD 0	BC	0	
A103A13002	TA21 14.5 Laboratory Analysis Ph1						
ES 3JAN95	EF 13MAR95	LS 3APR06	LF 8JUN06	OD 48	BC	77406	
A103A13004	TA21 14.5 Data Tracking Ph1						
ES 3JAN95	EF 24APR95	LS 9JUN06	LF 28SEP06	OD 78	BC	7082	
A103A13008	TA21 14.5 IDW Char. Analysis						
ES 3JAN95	EF 25MAY95	LS 3APR06	LF 23AUG06	OD 101	BC	6320	
A103A13007	TA21 14.5 IDW Monitoring						
ES 3JAN95	EF 26JUN95	LS 7APR06	LF 28SEP06	OD 122	BC	1569	
A103A13006	TA21 14.5 IDW Mgt						
ES 3JAN95	EF 30JUN95	LS 7APR06	LF 28SEP06	OD 126	BC	0	
A103A13001	TA21 Ph1 Surf. Agg. 14.5: 21-029 (DP Tank)						
ES 3JAN95	EF 28SEP06	LS 3APR06	LF 28SEP06	OD 2928	BC	0	
A103A13012	TA21 14.5 Soil Sampling Ph1A						
ES 1MAR95	EF 1MAR95	LS 12MAY06	LF 12MAY06	OD 1	BC	2380	



A103A13015	TA21 14.5 Field Analysis Ph1A						
ES 1MAR95	EF 8MAR95	LS 21SEP06	LF 28SEP06	OD	6	BC	12000
A103A13018	TA21 14.5 Laboratory Analysis Ph1A						
ES 1MAR95	EF 21JUN95	LS 12MAY06	LF 5SEP06	OD	80	BC	66070
A103A13013	TA21 14.5 Geophysical Survey Ph1A						
ES 2MAR95	EF 3MAR95	LS 27SEP06	LF 28SEP06	OD	2	BC	4227
A103A13014	TA21 14.5 Drill/Sample Ph1A						
ES 2MAR95	EF 8MAR95	LS 20SEP06	LF 26SEP06	OD	5	BC	30400
A103A13017	TA21 14.5 Field Data Assessment Ph1A						
ES 8MAR95	EF 8MAR95	LS 28SEP06	LF 28SEP06	OD	1	BC	2736
A103A13016	TA21 14.5 Document Locations Ph1A						
ES 9MAR95	EF 10MAR95	LS 27SEP06	LF 28SEP06	OD	2	BC	2854
A103A13003	TA21 14.5 Data Quality Assurance Ph1						
ES 11APR95	EF 17APR95	LS 17AUG06	LF 23AUG06	OD	5	BC	1755
A103A13005	TA21 14.5 Data Assessment Ph1						
ES 18APR95	EF 22MAY95	LS 24AUG06	LF 28SEP06	OD	25	BC	50378
A103A13009	TA21 14.5 Prepare IDW Disposal Documentation						
ES 26MAY95	EF 16JUN95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A13010	TA21 14.5 IDW Disposal						
ES 19JUN95	EF 30JUN95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A13019	TA21 14.5 Data Quality Assurance Ph1A						
ES 22JUN95	EF 23JUN95	LS 6SEP06	LF 7SEP06	OD	2	BC	647
A103A13020	TA21 14.5 Data Assessment Ph1A						
ES 26JUN95	EF 17JUL95	LS 8SEP06	LF 28SEP06	OD	15	BC	30240
A103A13011	TA21 Ph2 Surf. Agg. 14.5: 21-029 (DP Tank)						
ES 10CT96	EF 2FEB98	LS 8JUN05	LF 28SEP06	OD	330	BC	700000
A112A13012	TA21 EC Agg. 14.5: 21-029 (DP Tank)						
ES 10CT98	EF 11MAY00	LS 1MAR05	LF 28SEP06	OD	400	BC	1000000
A103A14012	TA21 14.6 RFI FIELD WORK COMPLETE						
	EF 30SEP94		LF 14JUN06	OD	0	BC	0
A103A14002	TA21 14.6 Laboratory Analysis Ph1						
ES 3JAN95	EF 7APR95	LS 3APR06	LF 6JUL06	OD	67	BC	36159
A103A14004	TA21 14.6 Data Tracking Ph1						
ES 3JAN95	EF 19MAY95	LS 12MAY06	LF 28SEP06	OD	97	BC	8808
A103A14008	TA21 14.6 IDW Char. Analysis						
ES 3JAN95	EF 25MAY95	LS 3APR06	LF 23AUG06	OD	101	BC	1580
A103A14007	TA21 14.6 IDW Monitoring						
ES 3JAN95	EF 26JUN95	LS 7APR06	LF 28SEP06	OD	122	BC	1569
A103A14001	TA21 Ph1 Surf. Agg. 14.6: 21-002b (Inact. CSA)						
ES 3JAN95	EF 30JUN95	LS 3APR06	LF 28SEP06	OD	126	BC	0
A103A14006	TA21 14.6 IDW Mgt						
ES 3JAN95	EF 30JUN95	LS 7APR06	LF 28SEP06	OD	126	BC	0
A103A14003	TA21 14.6 Data Quality Asssurance Ph1						
ES 8MAY95	EF 12MAY95	LS 24AUG06	LF 30AUG06	OD	5	BC	1621
A103A14005	TA21 14.6 Data Assessment Ph1						
ES 15MAY95	EF 12JUN95	LS 31AUG06	LF 28SEP06	OD	20	BC	22331
A103A14009	TA21 14.6 Prepare IDW Disposal Documentation						
ES 26MAY95	EF 16JUN95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A14010	TA21 14.6 IDW Disposal						
ES 19JUN95	EF 30JUN95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A15012	TA21 14.7 RFI FIELD WORK COMPLETE						
	EF 30SEP94		LF 14JUN06	OD	0	BC	0
A103A15002	TA21 14.7 Laboratory Analysis Ph1						
ES 3JAN95	EF 18APR95	LS 14MAR06	LF 26JUN06	OD	74	BC	207212
A103A15004	TA21 14.7 Data Tracking Ph1						
ES 3JAN95	EF 31MAY95	LS 3MAY06	LF 28SEP06	OD	104	BC	10447
A103A15008	TA21 14.7 IDW Char. Analysis						
ES 3JAN95	EF 15JUN95	LS 14MAR06	LF 23AUG06	OD	115	BC	3160
A103A15007	TA21 14.7 IDW Monitoring						
ES 3JAN95	EF 26JUN95	LS 7APR06	LF 28SEP06	OD	122	BC	1569
A103A15001	TA21 Ph1 Surf. Agg. 14.7: 21-013a-g (SDAs)						
ES 3JAN95	EF 21JUL95	LS 14MAR06	LF 28SEP06	OD	140	BC	0
A103A15006	TA21 14.7 IDW Mgt						
ES 3JAN95	EF 21JUL95	LS 7APR06	LF 28SEP06	OD	140	BC	0
A103A15003	TA21 14.7 Data Quality Assurance Ph1						
ES 17MAY95	EF 23MAY95	LS 17AUG06	LF 23AUG06	OD	5	BC	1661
A103A15005	TA21 14.7 Data Assessment Ph1						
ES 24MAY95	EF 28JUN95	LS 24AUG06	LF 28SEP06	OD	25	BC	27912
A103A15009	TA21 14.7 Prepare IDW Disposal Documentation						
ES 16JUN95	EF 7JUL95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A15010	TA21 14.7 IDW Disposal						
ES 10JUL95	EF 21JUL95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149



A103A16012	TA21 14.8 RFI FIELD WORK COMPLETE EF 30SEP94 LF 14JUN06	OD	0	BC	0
A103A16002 ES 3JAN95	TA21 14.8 Laboratory Analysis Ph1 EF 21MAR95 LS 31MAR06 LF 15JUN06	OD	54	BC	60814
A103A16004 ES 3JAN95	TA21 14.8 Data Tracking Ph1 EF 2MAY95 LS 1JUN06 LF 28SEP06	OD	84	BC	7633
A103A16008 ES 3JAN95	TA21 14.8 IDW Char. Analysis EF 26MAY95 LS 31MAR06 LF 23AUG06	OD	102	BC	3160
A103A16007 ES 3JAN95	TA21 14.8 IDW Monitoring EF 26JUN95 LS 7APR06 LF 28SEP06	OD	122	BC	1569
A103A16001 ES 3JAN95	TA21 Ph1 Subs. Agg. 14.8: 21-026a-c (STP) EF 3JUL95 LS 31MAR06 LF 28SEP06	OD	127	BC	0
A103A16006 ES 3JAN95	TA21 14.8 IDW Mgt EF 3JUL95 LS 7APR06 LF 28SEP06	OD	127	BC	0
A103A16003 ES 19APR95	TA21 14.8 Data Quality Assurance Ph1 EF 25APR95 LS 24AUG06 LF 30AUG06	OD	5	BC	1796
A103A16005 ES 26APR95	TA21 14.8 Data Assessment Ph1 EF 23MAY95 LS 31AUG06 LF 28SEP06	OD	20	BC	22331
A103A16009 ES 30MAY95	TA21 14.8 Prepare IDW Disposal Documentation EF 19JUN95 LS 24AUG06 LF 14SEP06	OD	15	BC	8160
A103A16010 ES 20JUN95	TA21 14.8 IDW Disposal EF 3JUL95 LS 15SEP06 LF 28SEP06	OD	10	BC	12149
A112A17003 ES 1FEB95	TA21 24i/d EC Prepare EC Plan Draft EF 29MAR95 LS 8FEB95 LF 5APR95	OD	40	BC	29030
A112A17002 ES 1FEB95	TA21 Prepare 21-024i/d EC Plan EF 8JUN95 LS 8FEB95 LF 15JUN95	OD	90	BC	0
A112A17001 ES 1FEB95	TA21 EC Agg. 15.3: 21-024i/d (Rad Only) EF 12DEC96 LS 8FEB95 LF 28SEP06	OD	467	BC	0
A112A17004 ES 30MAR95	TA21 24i/d EC LANL/DOE Review EF 26APR95 LS 6APR95 LF 3MAY95	OD	20	BC	1534
A112A17005 ES 27APR95	TA21 24i/d EC Incl. LANL/DOE Comments EF 24MAY95 LS 4MAY95 LF 1JUN95	OD	20	BC	22061
A112A17006 ES 25MAY95	TA21 24i/d EC Issue EPA Draft EF 8JUN95 LS 2JUN95 LF 15JUN95	OD	10	BC	4257
A112A17008 ES 9JUN95	TA21 24i/d EC Notify EPA LS 16JUN95	OD	0	BC	0
A112A17007 ES 9JUN95	TA21 24i/d EC Initiate EC Approvals EF 7NOV95 LS 16JUN95 LF 28SEP06	OD	105	BC	0
A112A17009 ES 14AUG95	TA21 24i/d EC EPA Temp. Authorization LS 21AUG95	OD	0	BC	0
A112A17012 ES 26SEP95	TA21 24i/d EC Rad Survey EF 26SEP95 LS 30CT95 LF 30CT95	OD	1	BC	1363
A112A17013 ES 27SEP95	TA21 24i/d EC Remove Soil EF 110CT95 LS 40CT95 LF 180CT95	OD	10	BC	30036
A112A17020 ES 27SEP95	TA21 24i/d EC IDW Monitoring EF 7MAY96 LS 27FEB06 LF 28SEP06	OD	151	BC	1554
A112A17019 ES 27SEP95	TA21 24i/d EC IDW Mgt EF 30MAY96 LS 27FEB06 LF 14SEP06	OD	167	BC	0
A112A17014 ES 120CT95	TA21 24i/d EC Rad Survey EF 120CT95 LS 190CT95 LF 190CT95	OD	1	BC	1408
A112A17015 ES 130CT95	TA21 24i/d EC Verification Sampling EF 130CT95 LS 200CT95 LF 200CT95	OD	1	BC	2629
A112A17016 ES 130CT95	TA21 24i/d EC Laboratory Analysis EF 24APR96 LS 200CT95 LF 1MAY96	OD	131	BC	63118
A112A17021 ES 130CT95	TA21 24i/d EC IDW Char. Analysis EF 24APR96 LS 3FEB06 LF 9AUG06	OD	131	BC	3160
A112A17017 ES 130CT95	TA21 24i/d EC Data Tracking EF 22MAY96 LS 31MAY96 LF 9JAN97	OD	151	BC	10982
A112A17011	TA21 24i/d EC EPA Class III Mod. Approval EF 7NOV95 LF 28SEP06	OD	0	BC	0
A112A17022 ES 25APR96	TA21 24i/d EC Prepare IDW Disposal Documentation EF 15MAY96 LS 10AUG06 LF 30AUG06	OD	15	BC	8160
A112A17010	TA21 24i/d EC Required Completion EF 3MAY96 LF 28SEP06	OD	0	BC	0
A112A17023 ES 16MAY96	TA21 24i/d EC IDW Disposal EF 30MAY96 LS 31AUG06 LF 14SEP06	OD	10	BC	12149
A112A17018 ES 23MAY96	TA21 24i/d EC Data Quality Assurance EF 30MAY96 LS 31MAY96 LF 6JUN96	OD	5	BC	1621
A112A17024 ES 31MAY96	TA21 24i/d EC Report Prep. EF 27JUN96 LS 7JUN96 LF 5JUL96	OD	20	BC	21660
A112A17025 ES 28JUN96	TA21 24i/d EC LANL/DOE Review EF 26JUL96 LS 8JUL96 LF 2AUG96	OD	20	BC	1534
A112A17026 ES 29JUL96	TA21 24i/d EC Incl. LANL/DOE Comments EF 9AUG96 LS 5AUG96 LF 16AUG96	OD	10	BC	4749



A112A17027	TA21 24i/d EC Issue EPA Draft						
ES 12AUG96	EF 23AUG96	LS 19AUG96	LF 30AUG96	OD	10	BC	4257
A112A17028	TA21 24i/d EC EPA Draft Complete						
	EF 23AUG96		LF 30AUG96	OD	0	BC	0
A112A17029	TA21 24i/d EC EPA Review						
ES 26AUG96	EF 28OCT96	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A112A17030	TA21 24i/d EC Incl. EPA Comments						
ES 29OCT96	EF 26NOV96	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A112A17031	TA21 24i/d EC Issue Final EC Rpt.						
ES 27NOV96	EF 12DEC96	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A112A17032	TA21 24i/d EC COMPLETE						
	EF 12DEC96		LF 28SEP06	OD	0	BC	1922
A112A18003	TA21 24c EC Prepare EC Plan Draft						
ES 1FEB95	EF 29MAR95	LS 2NOV04	LF 4JAN05	OD	40	BC	29030
A112A18002	TA21 Prepare 21-024c EC Plan						
ES 1FEB95	EF 8JUN95	LS 2NOV04	LF 17MAR05	OD	90	BC	0
A112A18001	TA21 EC Agg. 15.3: 21-024c						
ES 1FEB95	EF 30DEC96	LS 2NOV04	LF 28SEP06	OD	477	BC	0
A112A18004	TA21 24c EC LANL/DOE Review						
ES 30MAR95	EF 26APR95	LS 5JAN05	LF 2FEB05	OD	20	BC	1534
A112A18005	TA21 24c EC Incl. LANL/DOE Comments						
ES 27APR95	EF 24MAY95	LS 3FEB05	LF 3MAR05	OD	20	BC	22061
A112A18006	TA21 24c EC Issue EPA Draft						
ES 25MAY95	EF 8JUN95	LS 4MAR05	LF 17MAR05	OD	10	BC	4257
A112A18008	TA21 24c EC Notify EPA						
ES 9JUN95		LS 18MAR05		OD	0	BC	0
A112A18007	TA21 24c EC Initiate EC Approvals						
ES 9JUN95	EF 13JUN96	LS 18MAR05	LF 28SEP06	OD	253	BC	0
A112A18009	TA21 24c EC EPA Temp. Authorization						
	EF 11AUG95		LF 19MAY05	OD	0	BC	0
A112A18012	TA21 24c EC Rad Survey						
ES 11OCT95	EF 11OCT95	LS 19JUL05	LF 19JUL05	OD	1	BC	1408
A112A18013	TA21 24c EC Remove Soil						
ES 12OCT95	EF 25OCT95	LS 20JUL05	LF 2AUG05	OD	10	BC	29579
A112A18020	TA21 24c EC IDW Monitoring						
ES 12OCT95	EF 21MAY96	LS 27FEB06	LF 28SEP06	OD	151	BC	1554
A112A18019	TA21 24c EC IDW Mgt						
ES 12OCT95	EF 13JUN96	LS 27FEB06	LF 28SEP06	OD	167	BC	0
A112A18014	TA21 24c EC Rad Survey						
ES 26OCT95	EF 26OCT95	LS 3AUG05	LF 3AUG05	OD	1	BC	1408
A112A18015	TA21 24c EC Verification Sampling						
ES 27OCT95	EF 27OCT95	LS 4AUG05	LF 4AUG05	OD	1	BC	2629
A112A18016	TA21 24c EC Laboratory Analysis						
ES 27OCT95	EF 8MAY96	LS 4AUG05	LF 13FEB06	OD	131	BC	31559
A112A18021	TA21 24c EC IDW Char. Analysis						
ES 27OCT95	EF 8MAY96	LS 17FEB06	LF 23AUG06	OD	131	BC	1580
A112A18017	TA21 24c EC Data Tracking						
ES 27OCT95	EF 6JUN96	LS 4AUG05	LF 14MAR06	OD	151	BC	10982
A112A18011	TA21 24c EC EPA Class III Mod. Approval						
	EF 7NOV95		LF 28SEP06	OD	0	BC	0
A112A18022	TA21 24c EC Prepare IDW Disposal Documentation						
ES 9MAY96	EF 30MAY96	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A112A18023	TA21 24c EC IDW Disposal						
ES 31MAY96	EF 13JUN96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A112A18018	TA21 24c EC Data Quality Assurance						
ES 7JUN96	EF 13JUN96	LS 15MAR06	LF 21MAR06	OD	5	BC	1621
A112A18010	TA21 24c EC Required Completion						
	EF 13JUN96		LF 28SEP06	OD	0	BC	0
A112A18032	TA21 24c EC COMPLETE						
	EF 13JUN96		LF 28SEP06	OD	0	BC	0
A112A18024	TA21 24c EC Report Prep.						
ES 14JUN96	EF 12JUL96	LS 22MAR06	LF 18APR06	OD	20	BC	21660
A112A18025	TA21 24c EC LANL/DOE Review						
ES 15JUL96	EF 9AUG96	LS 19APR06	LF 16MAY06	OD	20	BC	1534
A112A18026	TA21 24c EC Incl. LANL/DOE Comments						
ES 12AUG96	EF 23AUG96	LS 17MAY06	LF 31MAY06	OD	10	BC	4961
A112A18027	TA21 24c EC Issue EPA Draft						
ES 26AUG96	EF 9SEP96	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A112A18028	TA21 24c EC EPA Draft Complete						
	EF 9SEP96		LF 28SEP06	OD	0	BC	0
A112A18029	TA21 24c EC EPA Review						
ES 10SEP96	EF 12NOV96	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A112A18030	TA21 24c EC Incl. EPA Comments						
ES 13NOV96	EF 12DEC96	LS 17AUG06	LF 14SEP06	OD	20	BC	22061



A112A18031	TA21 24c EC Issue Final EC Rpt.						
ES 13DEC96	EF 30DEC96	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A19003	TA21 15.2/4 Develop Ph2 DQOs						
ES 1FEB95	EF 7FEB95	LS 23AUG04	LF 27AUG04	OD	5	BC	2319
A103A19002	TA21 Prepare Ph2 Sampling Plan						
ES 1FEB95	EF 8SEP95	LS 23AUG04	LF 7APR05	OD	154	BC	0
A103A19001	TA21 Ph2 Surf Agg 15.2/4: 21-011k/023c (Rad Only)						
ES 1FEB95	EF 12MAR97	LS 23AUG04	LF 28SEP06	OD	526	BC	0
A103A19004	TA21 15.2/4 Develop Ph2 Sampling Approach						
ES 8FEB95	EF 14FEB95	LS 30AUG04	LF 3SEP04	OD	5	BC	2487
A103A19005	TA21 15.2/4 Write Ph2 Sampling Plan						
ES 15FEB95	EF 15MAR95	LS 7SEP04	LF 4OCT04	OD	20	BC	14516
A103A19006	TA21 15.2/4 LANL/DOE Review Ph2						
ES 16MAR95	EF 12APR95	LS 5OCT04	LF 2NOV04	OD	20	BC	1534
A103A19007	TA21 15.2/4 Incl. LANL/DOE Comments Ph2						
ES 13APR95	EF 10MAY95	LS 3NOV04	LF 3DEC04	OD	20	BC	22061
A103A19008	TA21 15.2/4 Issue EPA Draft Ph2						
ES 11MAY95	EF 24MAY95	LS 6DEC04	LF 17DEC04	OD	10	BC	4257
A104A19012	TA21 15.2/4 EPA Draft Complete Ph2 Sampling Plan						
	EF 24MAY95		LF 28SEP06	OD	0	BC	0
A103A19010	TA21 15.2/4 EPA Review Ph2						
ES 25MAY95	EF 27JUL95	LS 20DEC04	LF 24FEB05	OD	44	BC	793
A103A19011	TA21 15.2/4 Incl. EPA Comments Ph2						
ES 28JUL95	EF 24AUG95	LS 25FEB05	LF 24MAR05	OD	20	BC	22061
A103A19012	TA21 15.2/4 Issue Final Ph2 Sampling Plan						
ES 25AUG95	EF 8SEP95	LS 25MAR05	LF 7APR05	OD	10	BC	1922
A103A19013	TA21 15.2/4 Identify Locations Ph2						
ES 10OCT95	EF 13OCT95	LS 6MAY05	LF 11MAY05	OD	4	BC	6852
A103A19014	TA21 15.2/4 Rad Survey Ph2						
ES 16OCT95	EF 19OCT95	LS 12MAY05	LF 17MAY05	OD	4	BC	5626
A103A19015	TA21 15.2/4 Soil Sampling Ph2						
ES 20OCT95	EF 2NOV95	LS 18MAY05	LF 1JUN05	OD	10	BC	26274
A103A19016	TA21 15.2/4 Field Analysis Ph2						
ES 20OCT95	EF 2NOV95	LS 30DEC05	LF 13JAN06	OD	10	BC	20000
A103A19018	TA21 15.2/4 Laboratory Analysis Ph2						
ES 20OCT95	EF 14MAY96	LS 18MAY05	LF 6DEC05	OD	140	BC	111720
A103A19024	TA21 15.2/4 IDW Char. Analysis						
ES 20OCT95	EF 14MAY96	LS 6FEB06	LF 23AUG06	OD	140	BC	1580
A103A19020	TA21 15.2/4 Data Tracking Ph2						
ES 20OCT95	EF 12JUN96	LS 13FEB06	LF 28SEP06	OD	160	BC	13567
A103A19023	TA21 15.2/4 IDW Monitoring						
ES 20OCT95	EF 12JUN96	LS 13FEB06	LF 28SEP06	OD	160	BC	1950
A103A19022	TA21 15.2/4 IDW Mgt						
ES 20OCT95	EF 19JUN96	LS 13FEB06	LF 28SEP06	OD	165	BC	0
A103A19017	TA21 15.2/4 Document Locations Ph2						
ES 3NOV95	EF 8NOV95	LS 10JAN06	LF 13JAN06	OD	4	BC	6852
A103A19025	TA21 15.2/4 Prepare IDW Disposal Documentation						
ES 15MAY96	EF 5JUN96	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A19026	TA21 15.2/4 IDW Disposal						
ES 6JUN96	EF 19JUN96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A19019	TA21 15.2/4 Data Quality Assurance Ph2						
ES 13JUN96	EF 19JUN96	LS 9JAN06	LF 13JAN06	OD	5	BC	1661
A103A19021	TA21 15.2/4 Data Assessment Ph2						
ES 20JUN96	EF 25JUL96	LS 17JAN06	LF 21FEB06	OD	25	BC	27912
A103A19027	TA21 15.2/4 Risk Assessment						
ES 26JUL96	EF 8AUG96	LS 22FEB06	LF 7MAR06	OD	10	BC	13022
A104A19001	TA21 15.2/4 RFI Report Prep. Ph2						
ES 26JUL96	EF 6SEP96	LS 22FEB06	LF 4APR06	OD	30	BC	0
A103A19028	TA21 15.2/4 Decision Analysis						
ES 9AUG96	EF 15AUG96	LS 8MAR06	LF 14MAR06	OD	5	BC	7849
A104A19028	TA21 15.2/4 RFI FIELD WORK COMPLETE PH2						
	EF 15AUG96		LF 28SEP06	OD	0	BC	0
A104A19004	TA21 15.2/4 Write RFI Report						
ES 16AUG96	EF 6SEP96	LS 15MAR06	LF 4APR06	OD	15	BC	31839
A104A19005	TA21 15.2/4 LANL/DOE Review Ph2						
ES 9SEP96	EF 4OCT96	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A19006	TA21 15.2/4 Incl. LANL/DOE Comments Ph2						
ES 7OCT96	EF 4NOV96	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A19007	TA21 15.2/4 Issue EPA Draft Ph2						
ES 5NOV96	EF 19NOV96	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A19008	TA21 15.2/4 EPA Draft Complete Ph2						
	EF 19NOV96		LF 14JUN06	OD	0	BC	0
A104A19009	TA21 15.2/4 EPA Review Ph2						
ES 20NOV96	EF 28JAN97	LS 15JUN06	LF 16AUG06	OD	44	BC	793



A104A19010	TA21 15.2/4 Incl. EPA Comments Ph2						
ES 29JAN97	EF 26FEB97	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A19011	TA21 15.2/4 Issue Final Rpt./WP Mod. Ph2						
ES 27FEB97	EF 12MAR97	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A112A19001	TA21 EC 15.2/4: 21-011k/023c (Rad Only)						
ES 10CT98	EF 16DEC99	LS 21JUL05	LF 28SEP06	OD	300	BC	2500000
A103A20003	TA21 15.5 Develop Ph2 DQOs						
ES 1FEB95	EF 7FEB95	LS 16SEP04	LF 22SEP04	OD	5	BC	2319
A103A20002	TA21 15.5 Prepare Ph2 Sampling Plan						
ES 1FEB95	EF 8SEP95	LS 16SEP04	LF 2MAY05	OD	154	BC	0
A103A20001	TA21 Ph2 Surf. Agg. 15.5: 21-027a						
ES 1FEB95	EF 14FEB97	LS 16SEP04	LF 28SEP06	OD	509	BC	0
A103A20004	TA21 15.5 Develop Ph2 Sampling Approach						
ES 8FEB95	EF 14FEB95	LS 23SEP04	LF 29SEP04	OD	5	BC	2487
A103A20005	TA21 15.5 Write Ph2 Sampling Plan						
ES 15FEB95	EF 15MAR95	LS 30SEP04	LF 28OCT04	OD	20	BC	14516
A103A20006	TA21 15.5 LANL/DOE Review Ph2						
ES 16MAR95	EF 12APR95	LS 29OCT04	LF 30NOV04	OD	20	BC	1534
A103A20007	TA21 15.5 Incl. LANL/DOE Comments Ph2						
ES 13APR95	EF 10MAY95	LS 1DEC04	LF 30DEC04	OD	20	BC	22061
A104A20012	TA21 15.5 START RFI REPORT PH2						
ES 10MAY95		LS 29SEP06		OD	0	BC	0
A103A20008	TA21 15.5 Issue EPA Draft Ph2						
ES 11MAY95	EF 24MAY95	LS 3JAN05	LF 14JAN05	OD	10	BC	4257
A103A20009	TA21 15.5 EPA Draft Complete Ph2						
	EF 24MAY95		LF 28SEP06	OD	0	BC	0
A103A20010	TA21 15.5 EPA Review Ph2						
ES 25MAY95	EF 27JUL95	LS 18JAN05	LF 21MAR05	OD	44	BC	766
A103A20011	TA21 15.5 Incl. EPA Comments Ph2						
ES 28JUL95	EF 24AUG95	LS 22MAR05	LF 18APR05	OD	20	BC	22061
A103A20012	TA21 15.5 Issue Final Ph2 Sampling Plan						
ES 25AUG95	EF 8SEP95	LS 19APR05	LF 2MAY05	OD	10	BC	1922
A103A20027	TA21 15.5 START RFI FIELD WORK PH 2						
ES 10OCT95		LS 29SEP06		OD	0	BC	0
A103A20013	TA21 15.5 Rad Survey Ph2						
ES 10OCT95	EF 11OCT95	LS 1JUN05	LF 2JUN05	OD	2	BC	2807
A103A20014	TA21 15.5 Soil Sampling Ph2						
ES 12OCT95	EF 17OCT95	LS 3JUN05	LF 8JUN05	OD	4	BC	10510
A103A20015	TA21 15.5 Field Analysis Ph2						
ES 12OCT95	EF 17OCT95	LS 18JAN06	LF 23JAN06	OD	4	BC	8000
A103A20017	TA21 15.5 Laboratory Analysis Ph2						
ES 12OCT95	EF 26APR96	LS 3JUN05	LF 13DEC05	OD	134	BC	55860
A103A20023	TA21 15.2/4 IDW Char. Analysis						
ES 12OCT95	EF 26APR96	LS 14FEB06	LF 23AUG06	OD	134	BC	1580
A103A20019	TA21 15.5 Data Tracking Ph2						
ES 12OCT95	EF 24MAY96	LS 22FEB06	LF 28SEP06	OD	154	BC	11256
A103A20022	TA21 15.2/4 IDW Monitoring						
ES 12OCT95	EF 24MAY96	LS 22FEB06	LF 28SEP06	OD	154	BC	1893
A103A20021	TA21 15.5 IDW Mgt						
ES 12OCT95	EF 3JUN96	LS 22FEB06	LF 28SEP06	OD	159	BC	0
A103A20016	TA21 15.5 Document Locations Ph2						
ES 18OCT95	EF 19OCT95	LS 20JAN06	LF 23JAN06	OD	2	BC	3426
A103A20024	TA21 15.2/4 Prepare IDW Disposal Documentation						
ES 29APR96	EF 17MAY96	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A20025	TA21 15.2/4 IDW Disposal						
ES 20MAY96	EF 3JUN96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A20018	TA21 15.5 Data Quality Assurance Ph2						
ES 28MAY96	EF 3JUN96	LS 17JAN06	LF 23JAN06	OD	5	BC	1621
A103A20020	TA21 15.5 Data Assessment Ph2						
ES 4JUN96	EF 9JUL96	LS 24JAN06	LF 28FEB06	OD	25	BC	27912
A104A20002	TA21 15.2/4 Risk Assessment						
ES 10JUL96	EF 23JUL96	LS 1MAR06	LF 14MAR06	OD	10	BC	13022
A104A20001	TA21 15.5 RFI Report Prep. Ph2						
ES 10JUL96	EF 13AUG96	LS 1MAR06	LF 4APR06	OD	25	BC	0
A104A20003	TA21 15.2/4 Decision Analysis						
ES 24JUL96	EF 30JUL96	LS 15MAR06	LF 21MAR06	OD	5	BC	7849
A103A20028	TA21 15.5 RFI FIELD WORK COMPLETE PH2						
	EF 30JUL96		LF 28SEP06	OD	0	BC	0
A104A20004	TA21 15.2/4 Write RFI Report						
ES 31JUL96	EF 13AUG96	LS 22MAR06	LF 4APR06	OD	10	BC	21228
A104A20005	TA21 15.5 LANL/DOE Review Ph2						
ES 14AUG96	EF 11SEP96	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A20006	TA21 15.5 Incl. LANL/DOE Comments Ph2						
ES 12SEP96	EF 9OCT96	LS 3MAY06	LF 31MAY06	OD	20	BC	22061



A104A20007 ES 10OCT96	TA21 15.5 Issue EPA Draft Ph2 EF 24OCT96	LS 1JUN06	LF 14JUN06	OD 10	BC	4257	
A104A20008	TA21 15.5 EPA Draft Complete Ph2 Smpl Plan EF 24OCT96		LF 14JUN06	OD 0	BC	0	
A104A20009 ES 25OCT96	TA21 15.5 EPA Review Ph2 Phase 2 Smple Plan EF 2JAN97	LS 15JUN06	LF 16AUG06	OD 44	BC	793	
A104A20010 ES 3JAN97	TA21 15.5 Incl. EPA Comments Ph2 EF 31JAN97	LS 17AUG06	LF 14SEP06	OD 20	BC	22061	
A104A20011 ES 3FEB97	TA21 15.5 Issue Final Rpt./WP Mod. Ph2 EF 14FEB97	LS 15SEP06	LF 28SEP06	OD 10	BC	1922	
A103A21013	TA21 16.1 RFI FIELD WORK COMPLETE EF 30SEP94		LF 28SEP06	OD 0	BC	0	
A103A21002 ES 3JAN95	TA21 16.1 Laboratory Analysis Ph1 EF 15FEB95	LS 6JUN06	LF 19JUL06	OD 31	BC	229747	
A103A21008 ES 3JAN95	TA21 16.1 IDW Char. Analysis EF 15FEB95	LS 12JUL06	LF 23AUG06	OD 31	BC	1580	
A103A21006 ES 3JAN95	TA21 16.1 IDW Mgt EF 23MAR95	LS 5JUL06	LF 28SEP06	OD 56	BC	0	
A103A21004 ES 3JAN95	TA21 16.1 Data Tracking Ph1 EF 30MAR95	LS 5JUL06	LF 28SEP06	OD 61	BC	11721	
A103A21007 ES 3JAN95	TA21 16.1 IDW Monitoring EF 30MAR95	LS 5JUL06	LF 28SEP06	OD 61	BC	1659	
A103A21001 ES 3JAN95	TA21 Ph1 Surf. Agg. 16.1: MDA Drainages EF 27APR95	LS 6JUN06	LF 28SEP06	OD 81	BC	0	
A103A21009 ES 16FEB95	TA21 16.1 Prepare IDW Disposal Documentation EF 9MAR95	LS 24AUG06	LF 14SEP06	OD 15	BC	8160	
A103A21010 ES 10MAR95	TA21 16.1 IDW Disposal EF 23MAR95	LS 15SEP06	LF 28SEP06	OD 10	BC	12149	
A103A21003 ES 17MAR95	TA21 16.1 Data Quality Assurance Ph1 EF 23MAR95	LS 17AUG06	LF 23AUG06	OD 5	BC	1907	
A103A21005 ES 24MAR95	TA21 16.1 Data Assessment Ph1 EF 27APR95	LS 24AUG06	LF 28SEP06	OD 25	BC	27912	
A104A22015 ES 30CT94	TA21 16.2 START RFI REPORT Ph1 SM 1	LS 29SEP06		OD 0	BC	0	
A103A22002 ES 3JAN95	TA21 16.2 Laboratory Analysis Ph1 EF 30JAN95	LS 23JUN95	LF 20JUL95	OD 19	BC	220587	
A103A22008 ES 3JAN95	TA21 16.2 IDW Char. Analysis EF 30JAN95	LS 28JUL06	LF 23AUG06	OD 19	BC	1580	
A103A22006 ES 3JAN95	TA21 16.2 IDW Mgt EF 7MAR95	LS 21JUL06	LF 28SEP06	OD 44	BC	0	
A103A22004 ES 3JAN95	TA21 16.2 Data Tracking Ph1 EF 14MAR95	LS 21JUL06	LF 28SEP06	OD 49	BC	4445	
A103A22007 ES 3JAN95	TA21 16.2 IDW Monitoring EF 14MAR95	LS 21JUL06	LF 28SEP06	OD 49	BC	627	
A103A22001 ES 3JAN95	TA21 Ph1 Surf. Agg. 16.2: 21-015 (MDA B) EF 6DEC95	LS 23JUN95	LF 28SEP06	OD 233	BC	0	
A103A22009 ES 31JAN95	TA21 16.2 Prepare IDW Disposal Documentation EF 21FEB95	LS 24AUG06	LF 14SEP06	OD 15	BC	8160	
A103A22010 ES 22FEB95	TA21 16.2 IDW Disposal EF 7MAR95	LS 15SEP06	LF 28SEP06	OD 10	BC	12149	
A103A22003 ES 1MAR95	TA21 16.2 Surface Data Quality Assurance Ph1 EF 7MAR95	LS 18AUG95	LF 24AUG95	OD 5	BC	1880	
A103A22005 ES 8MAR95	TA21 16.2 Data Assessment Ph1 EF 11APR95	LS 25AUG95	LF 29SEP95	OD 25	BC	27912	
A103A22011 ES 12APR95	TA21 16.2 Risk Assessment EF 2MAY95	LS 20CT95	LF 23OCT95	OD 15	BC	19524	
A104A22001 ES 12APR95	TA21 16.2 RFI Report Prep. Ph1 EF 7JUN95	LS 20CT95	LF 30NOV95	OD 40	BC	0	
A103A22012 ES 3MAY95	TA21 16.2 Decision Analysis EF 9MAY95	LS 24OCT95	LF 30OCT95	OD 5	BC	7849	
A103A22017	TA21 16.2 FIELD WORK COMPLETE Ph1 SURF AGG EF 9MAY95		LF 14FEB96	OD 0	BC	0	
A104A22005 ES 10MAY95	TA21 16.2 Dev. Ph2 DQOs EF 11MAY95	LS 31OCT95	LF 1NOV95	OD 2	BC	928	
A104A22004 ES 10MAY95	TA21 16.2 Write RFI Report EF 7JUN95	LS 31OCT95	LF 30NOV95	OD 20	BC	42454	
A104A22006 ES 12MAY95	TA21 16.2 Dev. Ph2 Sampling Approach EF 16MAY95	LS 2NOV95	LF 6NOV95	OD 3	BC	1486	
A104A22007 ES 17MAY95	TA21 16.2 Write Ph2 Sampling Plan EF 7JUN95	LS 7NOV95	LF 30NOV95	OD 15	BC	10886	
A104A22008 ES 8JUN95	TA21 16.2 LANL/DOE Review Ph1 EF 6JUL95	LS 1DEC95	LF 2JAN96	OD 20	BC	1534	



A104A22009	TA21 16.2 Incl. LANL/DOE Comments Ph1					
ES 7JUL95	EF 3AUG95	LS 3JAN96	LF 31JAN96	OD 20	BC	22061
A104A22010	TA21 16.2 Issue EPA Draft Ph1					
ES 4AUG95	EF 17AUG95	LS 1FEB96	LF 14FEB96	OD 10	BC	4257
A104A22011	TA21 16.2 EPA Draft Complete Ph1 SURF AGG					
	EF 17AUG95		LF 14FEB96	OD 0	BC	0
A104A22012	TA21 16.2 EPA Review Ph1					
ES 18AUG95	EF 20OCT95	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A22013	TA21 16.2 Incl. EPA Comments Ph1					
ES 23OCT95	EF 20NOV95	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A22014	TA21 16.2 Issue Final Rpt./WP Mod. Ph1					
ES 21NOV95	EF 6DEC95	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A23019	TA21 16.2 FIELD WORK COMPLETE Ph1 SURS AGG					
	EF 15APR97		LF 28SEP06	OD 0	BC	0
A104A23015	TA21 16.2 START RFI REPORT Ph1 SM 1					
ES 3OCT94		LS 29SEP06		OD 0	BC	0
A103A23002	TA21 16.2 Drill/Sample Ph1					
ES 6MAY96	EF 24JUN96	LS 22OCT97	LF 12DEC97	OD 35	BC	711641
A103A23003	TA21 16.2 Field Analysis Ph1					
ES 6MAY96	EF 24JUN96	LS 8NOV05	LF 29DEC05	OD 35	BC	70000
A103A23005	TA21 16.2 Laboratory Analysis Ph1					
ES 6MAY96	EF 3JAN97	LS 30MAR05	LF 22NOV05	OD 165	BC	89523
A103A23012	TA21 16.2 IDW Char. Analysis					
ES 6MAY96	EF 3JAN97	LS 29DEC05	LF 23AUG06	OD 165	BC	6320
A103A23008	TA21 16.2 Data Tracking Ph1					
ES 6MAY96	EF 3FEB97	LS 6JAN06	LF 28SEP06	OD 185	BC	15838
A103A23011	TA21 16.2 IDW Monitoring					
ES 6MAY96	EF 3FEB97	LS 6JAN06	LF 28SEP06	OD 185	BC	2270
A103A23010	TA21 16.2 IDW Mgt					
ES 6MAY96	EF 10FEB97	LS 6JAN06	LF 28SEP06	OD 190	BC	0
A103A23001	TA21 Ph1 Subs. Agg. 16.2: 21-015 (MDA B)					
ES 6MAY96	EF 7NOV97	LS 22OCT97	LF 28SEP06	OD 379	BC	0
A103A23004	TA21 16.2 Document Locations Ph1					
ES 25JUN96	EF 25JUN96	LS 29DEC05	LF 29DEC05	OD 1	BC	1713
A103A23006	TA21 16.2 Geo-Hydro Analysis Ph1					
ES 25JUN96	EF 17OCT96	LS 25SEP05	LF 29DEC05	OD 80	BC	0
A103A23013	TA21 16.2 Prepare IDW Disposal Documentation					
ES 6JAN97	EF 27JAN97	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A23014	TA21 16.2 IDW Disposal					
ES 28JAN97	EF 10FEB97	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A23007	TA21 16.2 Data Qualtiy Assurance Ph1					
ES 4FEB97	EF 10FEB97	LS 21DEC05	LF 29DEC05	OD 5	BC	1880
A103A23009	TA21 16.2 Data Assessment Ph1					
ES 11FEB97	EF 18MAR97	LS 30DEC05	LF 6FEB06	OD 25	BC	27912
A103A23015	TA21 16.2 Risk Assessment					
ES 19MAR97	EF 8APR97	LS 7FEB06	LF 28FEB06	OD 15	BC	19524
A104A23001	TA21 16.2 RFI Report Prep. Ph1					
ES 19MAR97	EF 13MAY97	LS 7FEB06	LF 4APR06	OD 40	BC	0
A103A23016	TA21 16.2 Decision Analysis					
ES 9APR97	EF 15APR97	LS 1MAR06	LF 7MAR06	OD 5	BC	7849
A104A23005	TA21 16.2 Dev. Ph2 DQOs					
ES 16APR97	EF 17APR97	LS 8MAR06	LF 9MAR06	OD 2	BC	928
A104A23004	TA21 16.2 Write RFI Report					
ES 16APR97	EF 13MAY97	LS 8MAR06	LF 4APR06	OD 20	BC	42454
A103A23017	TA21 16.2 Dev. Ph2 Sampling Approach					
ES 18APR97	EF 22APR97	LS 10MAR06	LF 14MAR06	OD 3	BC	1486
A103A23018	TA21 16.2 Write Ph2 Sampling Plan					
ES 23APR97	EF 13MAY97	LS 15MAR06	LF 4APR06	OD 15	BC	10886
A104A23008	TA21 16.2 LANL/DOE Review Ph1					
ES 14MAY97	EF 11JUN97	LS 5APR06	LF 2MAY06	OD 20	BC	1534
A104A23009	TA21 16.2 Incl. LANL/DOE Comments Ph1					
ES 12JUN97	EF 10JUL97	LS 3MAY06	LF 31MAY06	OD 20	BC	22061
A104A23010	TA21 16.2 Issue EPA Draft Ph1					
ES 11JUL97	EF 24JUL97	LS 1JUN06	LF 14JUN06	OD 10	BC	4257
A104A23011	TA21 16.2 EPA Draft Complete Ph1 SUB AGG.					
	EF 24JUL97		LF 14JUN06	OD 0	BC	0
A104A23012	TA21 16.2 EPA Review Ph1					
ES 25JUL97	EF 25SEP97	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A23013	TA21 16.2 Incl. EPA Comments Ph1					
ES 26SEP97	EF 24OCT97	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A23014	TA21 16.2 Issue Final Rpt./WP Mod. Ph1					
ES 27OCT97	EF 7NOV97	LS 15SEP06	LF 28SEP06	OD 10	BC	1922



A104A24012	TA21 16.2 START RFI REPORT Ph2 SM 1				
ES 30CT94	LS 29SEP06	OD	0	BC	0
A103A24002	TA21 16.2 Identify Locations Ph2				
ES 23APR96	EF 23APR96 LS 23MAY97 LF 23MAY97	OD	1	BC	1713
A103A24001	TA21 Ph2 Surf. Agg. 16.2: 21-015 (MDA B)				
ES 23APR96	EF 19JUN00 LS 23MAY97 LF 28SEP06	OD	1036	BC	0
A103A24003	TA21 16.2 Rad Survey Ph2				
ES 24APR96	EF 24APR96 LS 27MAY97 LF 27MAY97	OD	1	BC	1408
A103A24004	TA21 16.2 Soil Sampling Ph2				
ES 25APR96	EF 26APR96 LS 28MAY97 LF 29MAY97	OD	2	BC	5249
A103A24005	TA21 16.2 Field Analysis Ph2				
ES 25APR96	EF 26APR96 LS 28DEC05 LF 29DEC05	OD	2	BC	4000
A103A24006	TA21 16.2 Laboratory Analysis Ph2				
ES 25APR96	EF 31OCT96 LS 16MAY05 LF 22NOV05	OD	132	BC	101445
A103A24008	TA21 16.2 Data Tracking Ph2				
ES 25APR96	EF 3DEC96 LS 24FEB06 LF 28SEP06	OD	152	BC	11079
A103A24012	TA21 16.2 IDW Char. Analysis				
ES 25APR96	EF 3DEC96 LS 19JAN06 LF 23AUG06	OD	152	BC	3160
A103A24011	TA21 16.2 IDW Monitoring				
ES 25APR96	EF 10DEC96 LS 16FEB06 LF 28SEP06	OD	157	BC	1569
A103A24010	TA21 16.2 IDW Mgt				
ES 25APR96	EF 10JAN97 LS 16FEB06 LF 28SEP06	OD	177	BC	0
A103A24007	TA21 16.2 Surface Data Quality Assurance Ph2				
ES 4DEC96	EF 10DEC96 LS 21DEC05 LF 29DEC05	OD	5	BC	1779
A103A24013	TA21 16.2 Prepare IDW Disposal Documentation				
ES 4DEC96	EF 24DEC96 LS 24AUG06 LF 14SEP06	OD	15	BC	8160
A103A24009	TA21 16.2 Data Assessment Ph2				
ES 11DEC96	EF 20JAN97 LS 30DEC05 LF 6FEB06	OD	25	BC	27912
A103A24014	TA21 16.2 IDW Disposal				
ES 27DEC96	EF 10JAN97 LS 15SEP06 LF 28SEP06	OD	10	BC	12149
A103A24015	TA21 16.2 Risk Assessment				
ES 21JAN97	EF 10FEB97 LS 7FEB06 LF 28FEB06	OD	15	BC	19524
A104A24001	TA21 16.2 RFI Report Prep. Ph2				
ES 21JAN97	EF 18MAR97 LS 7FEB06 LF 4APR06	OD	40	BC	0
A103A24016	TA21 16.2 Decision Analysis				
ES 11FEB97	EF 18FEB97 LS 1MAR06 LF 7MAR06	OD	5	BC	7849
A104A24004	TA21 16.2 Write RFI Report				
ES 19FEB97	EF 18MAR97 LS 8MAR06 LF 4APR06	OD	20	BC	42454
A104A24005	TA21 16.2 LANL/DOE Review Ph2				
ES 19MAR97	EF 15APR97 LS 5APR06 LF 2MAY06	OD	20	BC	1534
A104A24006	TA21 16.2 Incl. LANL/DOE Comments Ph2				
ES 16APR97	EF 13MAY97 LS 3MAY06 LF 31MAY06	OD	20	BC	22061
A104A24007	TA21 16.2 Issue EPA Draft Ph2				
ES 14MAY97	EF 28MAY97 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A103A24017	TA21 16.2 RFI FIELD WORK COMPLETE PH 2 SURF AGG				
	EF 6MAR00 LF 14JUN06	OD	0	BC	0
A104A24008	TA21 16.2 EPA Draft Complete Ph2 SURF AGG				
	EF 6MAR00 LF 14JUN06	OD	0	BC	0
A104A24009	TA21 16.2 EPA Review Ph2				
ES 7MAR00	EF 5MAY00 LS 15JUN06 LF 16AUG06	OD	44	BC	793
A104A24010	TA21 16.2 Incl. EPA Comments Ph2				
ES 8MAY00	EF 5JUN00 LS 17AUG06 LF 14SEP06	OD	20	BC	22061
A104A24011	TA21 16.2 Issue Final Rpt./WP Mod. Ph2				
ES 6JUN00	EF 19JUN00 LS 15SEP06 LF 28SEP06	OD	10	BC	1922
A103A25016	TA21 16.2 START RFI FIELD WORK				
ES 30CT94	LS 29SEP06	OD	0	BC	0
A104A25012	TA21 16.2 START RFI REPORT Ph2				
ES 30CT94	LS 29SEP06	OD	0	BC	0
A103A25002	TA21 16.2 Drill/Sample Ph2				
ES 23APR99	EF 13MAY99 LS 27APR05 LF 17MAY05	OD	15	BC	75135
A103A25003	TA21 16.2 Field Analysis Ph2				
ES 23APR99	EF 13MAY99 LS 7DEC05 LF 29DEC05	OD	15	BC	30000
A103A25005	TA21 16.2 Laboratory Analysis Ph2				
ES 23APR99	EF 18NOV99 LS 27APR05 LF 22NOV05	OD	145	BC	278927
A103A25011	TA21 16.2 IDW Char. Analysis				
ES 23APR99	EF 18NOV99 LS 30JAN06 LF 23AUG06	OD	145	BC	3160
A103A25007	TA21 16.2 Data Tracking Ph2				
ES 23APR99	EF 20DEC99 LS 4MAY05 LF 29DEC05	OD	165	BC	14030
A103A25010	TA21 16.2 IDW Monitoring				
ES 23APR99	EF 20DEC99 LS 6FEB06 LF 28SEP06	OD	165	BC	2013
A103A25009	TA21 16.2 IDW Mgt				
ES 23APR99	EF 29DEC99 LS 6FEB06 LF 28SEP06	OD	170	BC	0
A103A25001	TA21 Ph2 Subs. Agg. 16.2: 21-015 (MDA B)				
ES 23APR99	EF 27SEP00 LS 27APR05 LF 28SEP06	OD	359	BC	0



A103A25004	TA21 16.2 Document Locations Ph2						
ES 14MAY99	EF 14MAY99	LS 29DEC05	LF 29DEC05	OD	1	BC	1932
A103A25012	TA21 16.2 Prepare IDW Disposal Documentation						
ES 19NOV99	EF 13DEC99	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A25013	TA21 16.2 IDW Disposal						
ES 14DEC99	EF 29DEC99	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A25006	TA21 16.2 Data Qualtiy Assurance Ph2						
ES 21DEC99	EF 29DEC99	LS 21DEC05	LF 29DEC05	OD	5	BC	1880
A103A25008	TA21 16.2 Data Assessment Ph2						
ES 30DEC99	EF 4FEB00	LS 30DEC05	LF 6FEB06	OD	25	BC	27912
A103A25014	TA21 16.2 Risk Assessment						
ES 7FEB00	EF 28FEB00	LS 7FEB06	LF 28FEB06	OD	15	BC	19524
A104A25001	TA21 16.2 RFI Report Prep. Ph2						
ES 7FEB00	EF 3APR00	LS 7FEB06	LF 4APR06	OD	40	BC	0
A103A25015	TA21 16.2 Decision Analysis						
ES 29FEB00	EF 6MAR00	LS 1MAR06	LF 7MAR06	OD	5	BC	7849
A103A25017	TA21 16.2 RFI FIELD WORK COMPLETE PH2 SUB AGG						
	EF 6MAR00		LF 14JUN06	OD	0	BC	0
A104A25004	TA21 16.2 Write RFI Report						
ES 7MAR00	EF 3APR00	LS 8MAR06	LF 4APR06	OD	20	BC	42454
A104A25005	TA21 16.2 LANL/DOE Review Ph2						
ES 4APR00	EF 1MAY00	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A25006	TA21 16.2 Incl. LANL/DOE Comments Ph2						
ES 2MAY00	EF 30MAY00	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A25007	TA21 16.2 Issue EPA Draft Ph2						
ES 31MAY00	EF 13JUN00	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A25008	TA21 16.2 EPA Draft Complete Ph2 SUBS AGG.						
	EF 13JUN00		LF 14JUN06	OD	0	BC	0
A104A25009	TA21 16.2 EPA Review Ph2						
ES 14JUN00	EF 15AUG00	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A25010	TA21 16.2 Incl. EPA Comments Ph2						
ES 16AUG00	EF 13SEP00	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A25011	TA21 16.2 Issue Final Rpt./WP Mod. Ph2						
ES 14SEP00	EF 27SEP00	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A26002	TA21 16.3/15.10 Data Assessment Ph1						
ES 3JAN95	EF 7FEB95	LS 24AUG06	LF 28SEP06	OD	25	BC	27912
A103A26001	TA21 Ph1 Surf Ag 16.3/15.10: 21-016a-c/028a/NPDES						
ES 3JAN95	EF 28SEP06	LS 24AUG06	LF 28SEP06	OD	2928	BC	0
A103A27020	TA21 16.3 START RFI FIELD WORK PH1						
ES 5JUN95		LS 3JAN95		OD	0	BC	0
A103A27002	TA21 16.3 Drill/Sample Ph1						
ES 20CT95	EF 3NOV95	LS 30APR97	LF 3JUN97	OD	24	BC	124390
A103A27003	TA21 16.3 Field Analysis Ph1						
ES 20CT95	EF 3NOV95	LS 12DEC97	LF 20JAN98	OD	24	BC	48000
A103A27005	TA21 16.3 Laboratory Analysis Ph1						
ES 20CT95	EF 15MAY96	LS 30APR97	LF 10DEC97	OD	154	BC	59464
A103A27012	TA21 16.3 IDW Char. Analysis						
ES 20CT95	EF 15MAY96	LS 17JAN06	LF 23AUG06	OD	154	BC	6320
A103A27008	TA21 16.3 Data Tracking Ph1						
ES 20CT95	EF 13JUN96	LS 7MAY97	LF 20JAN98	OD	174	BC	13079
A103A27011	TA21 16.3 IDW Monitoring						
ES 20CT95	EF 13JUN96	LS 24JAN06	LF 28SEP06	OD	174	BC	1853
A103A27010	TA21 16.3 IDW Mgt						
ES 20CT95	EF 20JUN96	LS 24JAN06	LF 28SEP06	OD	179	BC	0
A103A27001	TA21 Ph1 Subs. Agg. 16.3: 21-016a-c/011c (MDA T)						
ES 20CT95	EF 27MAR97	LS 30APR97	LF 28SEP06	OD	368	BC	0
A103A27004	TA21 16.3 Document Locations Ph1						
ES 6NOV95	EF 6NOV95	LS 20JAN98	LF 20JAN98	OD	1	BC	1713
A103A27006	TA21 16.3 Geo-Hydro Analysis Ph1						
ES 6NOV95	EF 6MAR96	LS 19SEP97	LF 20JAN98	OD	80	BC	16080
A103A27013	TA21 16.3 Prepare IDW Disposal Documentation						
ES 16MAY96	EF 6JUN96	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A27014	TA21 16.3 IDW Disposal						
ES 7JUN96	EF 20JUN96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A27007	TA21 16.3 Data Quality Assurance Ph1						
ES 14JUN96	EF 20JUN96	LS 13JAN98	LF 20JAN98	OD	5	BC	2771
A103A27009	TA21 16.3 Data Assessment Ph1						
ES 21JUN96	EF 26JUL96	LS 21JAN98	LF 25FEB98	OD	25	BC	27912
A103A27015	TA21 16.3 Risk Assessment						
ES 29JUL96	EF 16AUG96	LS 26FEB98	LF 18MAR98	OD	15	BC	19524
A104A27001	TA21 16.3 RFI Report Prep. Ph1						
ES 29JUL96	EF 23SEP96	LS 26FEB98	LF 22APR98	OD	40	BC	0



						TA21 Ph2 Surf. Agg. 16.3: 21-016a-c/028a (MDA T)
A104A28009 ES 3JUN97	TA21 16.3 EPA Review Ph2 EF 4AUG97 LS 15JUN06 LF 16AUG06	OD	44	BC	793	
A104A28010 ES 5AUG97	TA21 16.3 Incl. EPA Comments Ph2 EF 25SEP97 LS 17AUG06 LF 14SEP06	OD	20	BC	22061	
A104A28011 ES 3SEP97	TA21 16.3 Issue Final Rpt./WP Mod. Ph2 EF 16SEP97 LS 15SEP06 LF 28SEP06	OD	10	BC	1922	
A104A28015 ES 21JUL98	TA21 16.3 START AFI REPORT Ph2 LS 29SEP06	OD	0	BC	0	
						TA21 Ph2 Subs.Agg. 16.3: 21-016a-c/011-c (MDA T)
A104A29012 ES 30CT94	TA21 16.3 START AFI REPORT Ph2 SM 1 LS 29SEP06	OD	0	BC	0	
A103A29002 ES 28MAY97	TA21 16.3 Drill/Sample Ph2 EF 26SEP97 LS 14DEC04 LF 19APR05	OD	86	BC	465574	
A103A29003 ES 28MAY97	TA21 16.3 Field Analysis Ph2 EF 26SEP97 LS 25AUG05 LF 29DEC05	OD	86	BC	172000	
A103A29005 ES 28MAY97	TA21 16.3 Laboratory Analysis Ph2 EF 9APR98 LS 14JAN05 LF 22NOV05	OD	216	BC	191533	
A103A29011 ES 28MAY97	TA21 16.3 IDW Char. Analysis EF 9APR98 LS 14OCT05 LF 23AUG06	OD	216	BC	6320	
A103A29007 ES 28MAY97	TA21 16.3 Data Tracking Ph2 EF 7MAY98 LS 24JAN05 LF 29DEC05	OD	236	BC	18713	
A103A29010 ES 28MAY97	TA21 16.3 IDW Monitoring EF 7MAY98 LS 21OCT05 LF 28SEP06	OD	236	BC	2648	
A103A29009 ES 28MAY97	TA21 16.3 IDW Mgt EF 14MAY98 LS 21OCT05 LF 28SEP06	OD	241	BC	0	
A103A29001 ES 28MAY97	TA21 Ph2 Subs. Agg 16.3: 21-016a-c/011-c (MDA T) EF 19FEB99 LS 14DEC04 LF 28SEP06	OD	430	BC	0	
A103A29004 ES 29SEP97	TA21 16.3 Document Locations Ph2 EF 29SEP97 LS 29DEC05 LF 29DEC05	OD	1	BC	1713	
A103A29012 ES 10APR98	TA21 16.3 Prepare IDW Disposal Documentation EF 30APR98 LS 24AUG06 LF 14SEP06	OD	15	BC	8160	
A103A29013 ES 1MAY98	TA21 16.3 IDW Disposal EF 14MAY98 LS 15SEP06 LF 28SEP06	OD	10	BC	12149	
A103A29006 ES 8MAY98	TA21 16.3 Data Quality Assurance Ph2 EF 14MAY98 LS 21DEC05 LF 29DEC05	OD	5	BC	1880	
A103A29008 ES 15MAY98	TA21 16.3 Data Assessment Ph2 EF 19JUN98 LS 30DEC05 LF 6FEB06	OD	25	BC	27912	
A103A29014 ES 22JUN98	TA21 16.3 Risk Assessment EF 13JUL98 LS 7FEB06 LF 28FEB06	OD	15	BC	19524	
A104A29001 ES 22JUN98	TA21 16.3 AFI Report Prep. Ph2 EF 17AUG98 LS 7FEB06 LF 4APR06	OD	40	BC	0	
A103A29015 ES 14JUL98	TA21 16.3 Decision Analysis EF 20JUL98 LS 1MAR06 LF 7MAR06	OD	5	BC	7849	
A103A29016	TA21 16.3 AFI FIELD WORK COMPLETE EF 20JUL98 LF 3JAN95	OD	0	BC	0	
A104A29004 ES 21JUL98	TA21 16.3 Write AFI Report EF 17AUG98 LS 8MAR06 LF 4APR06	OD	20	BC	42454	
A104A29005 ES 18AUG98	TA21 16.3 LANL/DOE Review Ph2 EF 15SEP98 LS 5APR06 LF 2MAY06	OD	20	BC	1534	
A104A29006 ES 16SEP98	TA21 16.3 Incl. LANL/DOE Comments Ph2 EF 14OCT98 LS 3MAY06 LF 31MAY06	OD	20	BC	22061	
A104A29007 ES 15OCT98	TA21 16.3 Issue EPA Draft Ph2 EF 28OCT98 LS 1JUN06 LF 14JUN06	OD	10	BC	4257	
A104A29008	TA21 16.3 EPA Draft Complete Ph2 EF 28OCT98 LF 14JUN06	OD	0	BC	0	
A104A29009 ES 29OCT98	TA21 16.3 EPA Review Ph2 EF 6JAN99 LS 15JUN06 LF 16AUG06	OD	44	BC	793	
A104A29010 ES 7JAN99	TA21 16.3 Incl. EPA Comments Ph2 EF 4FEB99 LS 17AUG06 LF 14SEP06	OD	20	BC	22061	
A104A29011 ES 5FEB99	TA21 16.3 Issue Final Rpt./WP Mod. Ph2 EF 19FEB99 LS 15SEP06 LF 28SEP06	OD	10	BC	1922	
						TA21 Ph1 Surf. Agg. 16.4: 21-10a-h (21-35)
A103A30017	TA21 16.4 AFI FIELD WORK COMPLETE EF 30SEP94 LF 14JUN06	OD	0	BC	0	
A103A30002 ES 3JAN95	TA21 16.4 Laboratory Analysis Ph1 EF 6MAR95 LS 18MAY06 LF 19JUL06	OD	43	BC	74313	
A103A30008 ES 3JAN95	TA21 16.4 IDW Char. Analysis EF 6MAR95 LS 23JUN06 LF 23AUG06	OD	43	BC	3160	
A103A30006 ES 3JAN95	TA21 16.4 IDW Mgt EF 10APR95 LS 16JUN06 LF 28SEP06	OD	68	BC	0	
A103A30004 ES 3JAN95	TA21 16.4 Data Tracking Ph1 EF 17APR95 LS 18MAY06 LF 30AUG06	OD	73	BC	6629	
A103A30007 ES 3JAN95	TA21 16.4 IDW Monitoring EF 17APR95 LS 16JUN06 LF 28SEP06	OD	73	BC	1569	



A103A27016 ES 19AUG96	TA21 16.3 Decision Analysis EF 23AUG96	LS 19MAR98	LF 25MAR98	OD	5	BC	7849
A103A27019	TA21 16.3 RFI FIELD WORK COMPLETE PH1 EF 23AUG96		LF 28SEP06	OD	0	BC	0
A104A27015 ES 26AUG96	TA21 16.3 START RFI REPORT Ph1	LS 29SEP06		OD	0	BC	0
A104A27005 ES 26AUG96	TA21 16.3 Dev. Ph2 DQOs EF 27AUG96	LS 26MAR98	LF 27MAR98	OD	2	BC	928
A104A27004 ES 26AUG96	TA21 16.3 Write RFI Report EF 23SEP96	LS 26MAR98	LF 22APR98	OD	20	BC	42454
A103A27017 ES 28AUG96	TA21 16.3 Dev. Ph2 Sampling Approach EF 30AUG96	LS 30MAR98	LF 1APR98	OD	3	BC	1486
A103A27018 ES 3SEP96	TA21 16.3 Write Ph2 Sampling Plan EF 23SEP96	LS 2APR98	LF 22APR98	OD	15	BC	10886
A104A27008 ES 24SEP96	TA21 16.3 LANL/DOE Review Ph1 EF 22OCT96	LS 23APR98	LF 20MAY98	OD	20	BC	1534
A104A27009 ES 23OCT96	TA21 16.3 Incl. LANL/DOE Comments Ph1 EF 20NOV96	LS 21MAY98	LF 18JUN98	OD	20	BC	22061
A104A27010 ES 21NOV96	TA21 16.3 Issue EPA Draft Ph1 EF 6DEC96	LS 19JUN98	LF 2JUL98	OD	10	BC	4257
A104A27011	TA21 16.3 EPA Draft Complete Ph1 EF 6DEC96		LF 2JUL98	OD	0	BC	0
A104A27012 ES 9DEC96	TA21 16.3 EPA Review Ph1 EF 12FEB97	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A27013 ES 13FEB97	TA21 16.3 Incl. EPA Comments Ph1 EF 13MAR97	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A27014 ES 14MAR97	TA21 16.3 Issue Final Rpt./WP Mod. Ph1 EF 27MAR97	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A28002 ES 23APR96	TA21 16.3 Identify Locations Ph2 EF 24APR96	LS 23MAY97	LF 27MAY97	OD	2	BC	3426
A103A28001 ES 23APR96	TA21 Ph2 Surf. Agg. 16.3: 21-016a-c/028a (MDA T) EF 16SEP97	LS 23MAY97	LF 28SEP06	OD	351	BC	0
A103A28003 ES 25APR96	TA21 16.3 Rad Surveys Ph2 EF 26APR96	LS 28MAY97	LF 29MAY97	OD	2	BC	2807
A103A28004 ES 29APR96	TA21 16.3 Soil Sampling Ph2 EF 1MAY96	LS 30MAY97	LF 3JUN97	OD	3	BC	7882
A103A28005 ES 29APR96	TA21 16.3 Field Analysis Ph2 EF 1MAY96	LS 15JAN98	LF 20JAN98	OD	3	BC	6000
A103A28006 ES 29APR96	TA21 16.3 Laboratory Analysis Ph2 EF 5NOV96	LS 30MAY97	LF 10DEC97	OD	133	BC	130298
A103A28012 ES 29APR96	TA21 16.3 IDW Char. Analysis EF 5NOV96	LS 15FEB06	LF 23AUG06	OD	133	BC	1580
A103A28008 ES 29APR96	TA21 16.3 Data Tracking Ph2 EF 6DEC96	LS 6JUN97	LF 20JAN98	OD	153	BC	11171
A103A28011 ES 29APR96	TA21 16.3 IDW Monitoring EF 6DEC96	LS 23FEB06	LF 28SEP06	OD	153	BC	1569
A103A28010 ES 29APR96	TA21 16.3 IDW Mgt EF 13DEC96	LS 23FEB06	LF 28SEP06	OD	158	BC	0
A103A28017	TA21 16.3 RFI FIELD WORK COMPLETE PH2 EF 26JUL96		LF 28SEP06	OD	0	BC	0
A103A28013 ES 6NOV96	TA21 16.3 Prepare IDW Disposal Documentation EF 27NOV96	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A28014 ES 2DEC96	TA21 16.3 IDW Disposal EF 13DEC96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A28007 ES 9DEC96	TA21 16.3 Surface Data Quality Assurance Ph2 EF 13DEC96	LS 13JAN98	LF 20JAN98	OD	5	BC	1822
A103A28009 ES 16DEC96	TA21 16.3 Data Assessment Ph2 EF 23JAN97	LS 21JAN98	LF 25FEB98	OD	25	BC	27912
A103A28015 ES 24JAN97	TA21 16.3 Risk Assessment EF 13FEB97	LS 26FEB98	LF 18MAR98	OD	15	BC	19524
A104A28001 ES 24JAN97	TA21 16.3 RFI Report Prep. Ph2 EF 21MAR97	LS 26FEB98	LF 22APR98	OD	40	BC	0
A103A28016 ES 14FEB97	TA21 16.3 Decision Analysis PH2 EF 21FEB97	LS 19MAR98	LF 25MAR98	OD	5	BC	7849
A104A28004 ES 24FEB97	TA21 16.3 Write RFI Report EF 21MAR97	LS 26MAR98	LF 22APR98	OD	20	BC	42454
A104A28005 ES 24MAR97	TA21 16.3 LANL/DOE Review Ph2 EF 18APR97	LS 23APR98	LF 20MAY98	OD	20	BC	1534
A104A28006 ES 21APR97	TA21 16.3 Incl. LANL/DOE Comments Ph2 EF 16MAY97	LS 21MAY98	LF 18JUN98	OD	20	BC	22061
A104A28007 ES 19MAY97	TA21 16.3 Issue EPA Draft Ph2 EF 2JUN97	LS 19JUN98	LF 2JUL98	OD	10	BC	4257
A104A28008	TA21 16.3 EPA Draft Complete Ph2 EF 2JUN97		LF 2JUL98	OD	0	BC	0



A103A30001	TA21 Ph1 Surf. Agg. 16.4: 21-10a-h (21-35)					
ES 3JAN95	EF 28SEP06	LS 18MAY06	LF 28SEP06	OD 2928	BC	0
A103A30009	TA21 16.4 Prepare IDW Disposal Documentation					
ES 7MAR95	EF 27MAR95	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A30010	TA21 16.4 IDW Disposal					
ES 28MAR95	EF 10APR95	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A30003	TA21 16.4 Data Qualtiy Assurance Ph1					
ES 4APR95	EF 10APR95	LS 24AUG06	LF 30AUG06	OD 5	BC	1728
A103A30005	TA21 16.4 Data Assessment Ph1					
ES 18APR95	EF 15MAY95	LS 31AUG06	LF 28SEP06	OD 20	BC	22331
A103A31017	TA21 16.4 RFI FIELD WORK COMPLETE Ph2					
	EF 30SEP94		LF 14JUN06	OD 0	BC	0
A104A31012	TA21 16.4 START RFI REPORT Ph2			SM		
ES 30CT94		LS 15JUN06		OD 0	BC	0
A104A31017	TA21 16.4 START RFI REPORT Ph2					
ES 30CT94		LS 15JUN06		OD 0	BC	0
A103A31020	TA21 16.4 START RFI FIELD WORK PH2					
ES 19MAY97		LS 3JAN95		OD 0	BC	0
A103A31002	TA21 16.4 Drill/Sample Ph2					
ES 19MAY97	EF 23MAY97	LS 6DEC04	LF 10DEC04	OD 5	BC	27617
A103A31003	TA21 16.4 Field Analysis Ph2					
ES 19MAY97	EF 23MAY97	LS 17JAN06	LF 23JAN06	OD 5	BC	10000
A103A31005	TA21 16.4 Laboratory Analysis Ph2					
ES 19MAY97	EF 20EC97	LS 2JUN05	LF 13DEC05	OD 135	BC	51961
A103A31011	TA21 16.4 IDW Char. Analysis					
ES 19MAY97	EF 20EC97	LS 13FEB06	LF 23AUG06	OD 135	BC	3160
A103A31007	TA21 16.4 Data Tracking Ph2					
ES 19MAY97	EF 2JAN98	LS 9JUN05	LF 23JAN06	OD 155	BC	14075
A103A31010	TA21 16.4 IDW Monitoring					
ES 19MAY97	EF 2JAN98	LS 21FEB06	LF 28SEP06	OD 155	BC	1992
A103A31009	TA21 16.4 IDW Mgt					
ES 19MAY97	EF 9JAN98	LS 21FEB06	LF 28SEP06	OD 160	BC	0
A103A31001	TA21 Ph2 Surf. Agg. 16.4 PRS 21-10a-h (21-35)					
ES 19MAY97	EF 17SEP98	LS 6DEC04	LF 28SEP06	OD 334	BC	0
A103A31004	TA21 16.4 Document Locations Ph2					
ES 27MAY97	EF 27MAY97	LS 23JAN06	LF 23JAN06	OD 1	BC	1713
A103A31012	TA21 16.4 Prepare IDW Disposal Documentation					
ES 3DEC97	EF 23DEC97	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A31013	TA21 16.4 IDW Disposal					
ES 24DEC97	EF 9JAN98	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A31006	TA21 16.4 Data Quality Assurance Ph2					
ES 5JAN98	EF 9JAN98	LS 17JAN06	LF 23JAN06	OD 5	BC	1712
A103A31008	TA21 16.4 Data Assessment Ph2					
ES 12JAN98	EF 9FEB98	LS 24JAN06	LF 21FEB06	OD 20	BC	22331
A103A31014	TA21 16.4 Risk Assessment					
ES 10FEB98	EF 24FEB98	LS 22FEB06	LF 7MAR06	OD 10	BC	13022
A104A31001	TA21 16.4 RFI Report Prep. Ph2					
ES 10FEB98	EF 24MAR98	LS 22FEB06	LF 4APR06	OD 30	BC	0
A103A31015	TA21 16.4 Decision Analysis Ph2					
ES 25FEB98	EF 3MAR98	LS 8MAR06	LF 14MAR06	OD 5	BC	7849
A104A31004	TA21 16.4 Write RFI Report					
ES 4MAR98	EF 24MAR98	LS 15MAR06	LF 4APR06	OD 15	BC	31839
A104A31005	TA21 16.4 LANL/DOE Review Ph2					
ES 25MAR98	EF 21APR98	LS 5APR06	LF 2MAY06	OD 20	BC	1534
A104A31006	TA21 16.4 Incl. LANL/DOE Comments Ph2					
ES 22APR98	EF 19MAY98	LS 3MAY06	LF 31MAY06	OD 20	BC	22061
A104A31007	TA21 16.4 Issue EPA Draft Ph2					
ES 20MAY98	EF 3JUN98	LS 1JUN06	LF 14JUN06	OD 10	BC	4257
A104A31008	TA21 16.4 EPA Draft Complete Ph2					
	EF 3JUN98		LF 14JUN06	OD 0	BC	0
A104A31009	TA21 16.4 EPA Review Ph2					
ES 4JUN98	EF 5AUG98	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A31010	TA21 16.4 Incl. EPA Comments Ph2					
ES 6AUG98	EF 2SEP98	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A31011	TA21 16.4 Issue Final Rpt./WP Mod. Ph2					
ES 3SEP98	EF 17SEP98	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A32020	TA21 16.5 RFI FIELD WORK COMPLETE					
ES 3JAN95	EF 28JUL98	LS 3JAN95	LF 3JAN95	OD 891	BC	0
A103A32002	TA21 16.5 Rad Surveys Ph1					
ES 26SEP97	EF 26SEP97	LS 19APR05	LF 19APR05	OD 1	BC	1414
A103A32001	TA21 Ph1 Surf. Agg. 16.5: 21-011a-j (21-257)					
ES 26SEP97	EF 1MAR99	LS 19APR05	LF 28SEP06	OD 351	BC	0



A103A32003	TA21 16.5 Soil Sampling Ph1						
ES 29SEP97	EF 30SEP97	LS 20APR05	LF 21APR05	OD	2	BC	5249
A103A32005	TA21 16.5 Field Analysis Ph1						
ES 29SEP97	EF 6OCT97	LS 20DEC05	LF 29DEC05	OD	6	BC	12000
A103A32007	TA21 16.5 Laboratory Analysis Ph1						
ES 29SEP97	EF 17APR98	LS 10MAY05	LF 22NOV05	OD	136	BC	103143
A103A32013	TA21 16.5 IDW Char. Analysis						
ES 29SEP97	EF 17APR98	LS 10FEB06	LF 23AUG06	OD	136	BC	6320
A103A32009	TA21 16.5 Data Tracking Ph1						
ES 29SEP97	EF 15MAY98	LS 17MAY05	LF 29DEC05	OD	156	BC	11256
A103A32012	TA21 16.5 IDW Monitoring						
ES 29SEP97	EF 15MAY98	LS 17FEB06	LF 28SEP06	OD	156	BC	1621
A103A32011	TA21 16.5 IDW Mgt						
ES 29SEP97	EF 22MAY98	LS 17FEB06	LF 28SEP06	OD	161	BC	0
A103A32004	TA21 16.5 Drill/Sample Ph1						
ES 1OCT97	EF 6OCT97	LS 22APR05	LF 27APR05	OD	4	BC	22555
A103A32006	TA21 16.5 Document Locations Ph1						
ES 7OCT97	EF 7OCT97	LS 29DEC05	LF 29DEC05	OD	1	BC	1713
A103A32014	TA21 16.5 Prepare IDW Disposal Documentation						
ES 20APR98	EF 8MAY98	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A32015	TA21 16.5 IDW Disposal						
ES 11MAY98	EF 22MAY98	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A32008	TA21 16.5 Data Quality Assurance Ph1						
ES 18MAY98	EF 22MAY98	LS 21DEC05	LF 29DEC05	OD	5	BC	1796
A103A32010	TA21 16.5 Data Assessment Ph1						
ES 26MAY98	EF 29JUN98	LS 30DEC05	LF 6FEB06	OD	25	BC	27912
A103A32016	TA21 16.5 Risk Assessment						
ES 30JUN98	EF 21JUL98	LS 7FEB06	LF 28FEB06	OD	15	BC	19524
A104A32001	TA21 16.5 AFI Report Prep. Ph1						
ES 30JUN98	EF 25AUG98	LS 7FEB06	LF 4APR06	OD	40	BC	0
A103A32017	TA21 16.5 Decision Analysis						
ES 22JUL98	EF 28JUL98	LS 1MAR06	LF 7MAR06	OD	5	BC	7849
A104A32015	TA21 16.5 START AFI REPORT Ph1						
ES 29JUL98		LS 29SEP06		OD	0	BC	0
A104A32005	TA21 16.5 Dev. Ph2 DQOs						
ES 29JUL98	EF 30JUL98	LS 8MAR06	LF 9MAR06	OD	2	BC	928
A104A32004	TA21 16.5 Write AFI Report						
ES 29JUL98	EF 25AUG98	LS 8MAR06	LF 4APR06	OD	20	BC	42454
A103A32018	TA21 16.5 Dev. Ph2 Sampling Approach						
ES 31JUL98	EF 4AUG98	LS 10MAR06	LF 14MAR06	OD	3	BC	1486
A103A32019	TA21 16.5 Write Ph2 Sampling Plan						
ES 5AUG98	EF 25AUG98	LS 15MAR06	LF 4APR06	OD	15	BC	10886
A104A32008	TA21 16.5 LANL/DOE Review Ph1						
ES 26AUG98	EF 23SEP98	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A32009	TA21 16.5 Incl. LANL/DOE Comments Ph1						
ES 24SEP98	EF 22OCT98	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A32010	TA21 16.5 Issue EPA Draft Ph1						
ES 23OCT98	EF 5NOV98	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A32011	TA21 16.5 EPA Draft Complete Ph1						
	EF 5NOV98		LF 14JUN06	OD	0	BC	0
A104A32012	TA21 16.5 EPA Review Ph1						
ES 6NOV98	EF 14JAN99	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A32013	TA21 16.5 Incl. EPA Comments Ph1						
ES 15JAN99	EF 12FEB99	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A32014	TA21 16.5 Issue Final Rpt./WP Mod. Ph1						
ES 16FEB99	EF 1MAR99	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A33016	TA21 16.5 COMPLETE AFI FIELD WORK PH1						
	EF 28JUL98		LF 28SEP06	OD	0	BC	0
A103A33002	TA21 16.5 Drill/Sample Ph2						
ES 7APR99	EF 13APR99	LS 25MAR05	LF 31MAR05	OD	5	BC	29613
A103A33003	TA21 16.5 Field Analysis Ph2						
ES 7APR99	EF 13APR99	LS 17JAN06	LF 23JAN06	OD	5	BC	10000
A103A33005	TA21 16.5 Laboratory Analysis Ph2						
ES 7APR99	EF 18OCT99	LS 2JUN05	LF 13DEC05	OD	135	BC	64456
A103A33011	TA21 16.5 IDW Char. Analysis						
ES 7APR99	EF 18OCT99	LS 13FEB06	LF 23AUG06	OD	135	BC	6320
A103A33007	TA21 16.5 Data Tracking Ph2						
ES 7APR99	EF 16NOV99	LS 9JUN05	LF 23JAN06	OD	155	BC	14075
A103A33010	TA21 16.5 IDW Monitoring						
ES 7APR99	EF 16NOV99	LS 21FEB06	LF 28SEP06	OD	155	BC	1992
A103A33009	TA21 16.5 IDW Mgt						
ES 7APR99	EF 23NOV99	LS 21FEB06	LF 28SEP06	OD	160	BC	0
A103A33001	TA21 Ph2 Surf. Agg. 16.5: 21-011a-j (21-257)						
ES 7APR99	EF 4AUG00	LS 25MAR05	LF 28SEP06	OD	334	BC	0



A103A33004	TA21 16.5 Document Locations Ph2							
ES 14APR99	EF 14APR99	LS 23JAN06	LF 23JAN06	OD	1	BC	1713
A103A33012	TA21 16.5 Prepare IDW Disposal Documentation						
ES 19OCT99	EF 8NOV99	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A33013	TA21 16.5 IDW Disposal						
ES 9NOV99	EF 23NOV99	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A33006	TA21 16.5 Data Quality Assurance Ph2						
ES 17NOV99	EF 23NOV99	LS 17JAN06	LF 23JAN06	OD	5	BC	1712
A103A33008	TA21 16.5 Data Assessment Ph2						
ES 24NOV99	EF 23DEC99	LS 24JAN06	LF 21FEB06	OD	20	BC	22331
A103A33014	TA21 16.5 Risk Assessment						
ES 28DEC99	EF 11JAN00	LS 22FEB06	LF 7MAR06	OD	10	BC	13022
A104A33001	TA21 16.5 AFI Report Prep. Ph2						
ES 28DEC99	EF 9FEB00	LS 22FEB06	LF 4APR06	OD	30	BC	0
A103A33015	TA21 16.5 Decision Analysis						
ES 12JAN00	EF 19JAN00	LS 8MAR06	LF 14MAR06	OD	5	BC	7849
A103A33020	TA21 16.5 AFI FIELD WORK COMPLETE Ph2						
	EF 19JAN00		LF 3JAN95	OD	0	BC	0
A104A33012	TA21 16.5 COMPLETE AFI FIELD WORK Ph2				S		
	EF 19JAN00		LF 28SEP06	OD	0	BC	0
A104A33004	TA21 16.5 Write AFI Report						
ES 20JAN00	EF 9FEB00	LS 15MAR06	LF 4APR06	OD	15	BC	31839
A104A33005	TA21 16.5 LANL/DOE Review Ph2						
ES 10FEB00	EF 9MAR00	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A33006	TA21 16.5 Incl. LANL/DOE Comments Ph2						
ES 10MAR00	EF 6APR00	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A33007	TA21 16.5 Issue EPA Draft Ph2						
ES 7APR00	EF 20APR00	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A33008	TA21 16.5 EPA Draft Complete Ph2						
	EF 20APR00		LF 14JUN06	OD	0	BC	0
A104A33009	TA21 16.5 EPA Review Ph2						
ES 21APR00	EF 22JUN00	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A33010	TA21 16.5 Incl. EPA Comments Ph2						
ES 23JUN00	EF 21JUL00	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A33011	TA21 16.5 Issue Final Rpt./WP Mod. Ph2						
ES 24JUL00	EF 4AUG00	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A34017	TA21 16.6 AFI FIELD WORK COMPLETE FM 1						
	EF 30SEP94		LF 14JUN06	OD	0	BC	0
A103A34002	TA21 16.6 Laboratory Analysis Ph1						
ES 3JAN95	EF 31MAR95	LS 14APR06	LF 12JUL06	OD	62	BC	191921
A103A34008	TA21 16.6 IDW Char. Analysis						
ES 3JAN95	EF 31MAR95	LS 26MAY06	LF 23AUG06	OD	62	BC	3160
A103A34006	TA21 16.6 IDW Mgt						
ES 3JAN95	EF 5MAY95	LS 19MAY06	LF 28SEP06	OD	87	BC	0
A103A34004	TA21 16.6 Data Tracking Ph1						
ES 3JAN95	EF 12MAY95	LS 14APR06	LF 23AUG06	OD	92	BC	8355
A103A34007	TA21 16.6 IDW Monitoring						
ES 3JAN95	EF 12MAY95	LS 19MAY06	LF 28SEP06	OD	92	BC	1569
A103A34001	TA21 Ph1 Surf. Agg. 16.6: 21-017a-c (MDA U)						
ES 3JAN95	EF 28SEP06	LS 14APR06	LF 28SEP06	OD	2928	BC	0
A103A34009	TA21 16.6 Prepare IDW Disposal Documentation						
ES 3APR95	EF 21APR95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A34010	TA21 16.6 IDW Disposal						
ES 24APR95	EF 5MAY95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A34003	TA21 16.6 Surface Data Quality Assurance Ph1						
ES 1MAY95	EF 5MAY95	LS 17AUG06	LF 23AUG06	OD	5	BC	1974
A103A34005	TA21 16.6 Data Assessment Ph1						
ES 15MAY95	EF 19JUN95	LS 24AUG06	LF 28SEP06	OD	25	BC	27912
A104A35015	TA21 16.6 START AFI REPORT Ph1 SM 1						
ES 30OCT94		LS 29SEP06		OD	0	BC	0
A103A35019	TA21 16.6 START AFI FIELD WORK PH1						
ES 9AUG96		LS 3JAN95		OD	0	BC	0
A103A35002	TA21 16.6 Drill/Sample Ph1						
ES 9AUG96	EF 23AUG96	LS 3MAY05	LF 17MAY05	OD	11	BC	49667
A103A35003	TA21 16.6 Field Analysis Ph1						
ES 9AUG96	EF 23AUG96	LS 13DEC05	LF 29DEC05	OD	11	BC	22000
A103A35005	TA21 16.6 Laboratory Analysis Ph1						
ES 9AUG96	EF 7MAR97	LS 3MAY05	LF 22NOV05	OD	141	BC	223587
A103A35012	TA21 16.6 IDW Char. Analysis						
ES 9AUG96	EF 7MAR97	LS 3FEB06	LF 23AUG06	OD	141	BC	6320
A103A35008	TA21 16.6 Data Tracking Ph1						
ES 9AUG96	EF 4APR97	LS 10MAY05	LF 29DEC05	OD	161	BC	11900



A103A35011	TA21 16.6 IDW Monitoring					
ES 9AUG96	EF 4APR97	LS 10FEB06	LF 28SEP06	OD 161	BC	1683
A103A35010	TA21 16.6 IDW Mgt					
ES 9AUG96	EF 11APR97	LS 10FEB06	LF 28SEP06	OD 166	BC	0
A103A35001	TA21 Ph1 Subs. Agg. 16.6: 21-017a-c (MDA U)					
ES 9AUG96	EF 15JAN98	LS 3MAY05	LF 28SEP06	OD 355	BC	0
A103A35004	TA21 16.6 Document Locations Ph1					
ES 26AUG96	EF 26AUG96	LS 29DEC05	LF 29DEC05	OD 1	BC	1713
A103A35006	TA21 16.6 Geo-Hydro Analysis Ph1					
ES 26AUG96	EF 20DEC96	LS 2SEP05	LF 29DEC05	OD 80	BC	0
A103A35013	TA21 16.6 Prepare IDW Disposal Documentation					
ES 10MAR97	EF 28MAR97	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A35014	TA21 16.6 IDW Disposal					
ES 31MAR97	EF 11APR97	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A35007	TA21 16.6 Data Quality Assurance Ph1					
ES 7APR97	EF 11APR97	LS 21DEC05	LF 29DEC05	OD 5	BC	1880
A103A35009	TA21 16.6 Data Assessment Ph1					
ES 14APR97	EF 16MAY97	LS 30DEC05	LF 6FEB06	OD 25	BC	27912
A103A35015	TA21 16.6 Risk Assessment					
ES 19MAY97	EF 9JUN97	LS 7FEB06	LF 28FEB06	OD 15	BC	19524
A104A35001	TA21 16.6 RFI Report Prep. Ph1					
ES 19MAY97	EF 15JUL97	LS 7FEB06	LF 4APR06	OD 40	BC	0
A103A35016	TA21 16.6 Decision Analysis					
ES 10JUN97	EF 16JUN97	LS 1MAR06	LF 7MAR06	OD 5	BC	7849
A103A35020	TA21 16.6 RFI FIELD WORK COMPLETE PH1					
	EF 16JUN97		LF 3JAN95	OD 0	BC	0
A104A35005	TA21 16.6 Dev. Ph2 DQOs					
ES 17JUN97	EF 18JUN97	LS 8MAR06	LF 9MAR06	OD 2	BC	928
A104A35004	TA21 16.6 Write RFI Report					
ES 17JUN97	EF 15JUL97	LS 8MAR06	LF 4APR06	OD 20	BC	42454
A103A35017	TA21 16.6 Dev. Ph2 Sampling Approach					
ES 19JUN97	EF 23JUN97	LS 10MAR06	LF 14MAR06	OD 3	BC	1486
A103A35018	TA21 16.6 Write Ph2 Sampling Plan					
ES 24JUN97	EF 15JUL97	LS 15MAR06	LF 4APR06	OD 15	BC	10886
A104A35008	TA21 16.6 LANL/DOE Review Ph1					
ES 16JUL97	EF 12AUG97	LS 5APR06	LF 2MAY06	OD 20	BC	1534
A104A35009	TA21 16.6 Incl. LANL/DOE Comments Ph1					
ES 13AUG97	EF 10SEP97	LS 3MAY06	LF 31MAY06	OD 20	BC	22061
A104A35010	TA21 16.6 Issue EPA Draft Ph1					
ES 11SEP97	EF 24SEP97	LS 1JUN06	LF 14JUN06	OD 10	BC	4257
A104A35011	TA21 16.6 EPA Draft Complete Ph1					
	EF 24SEP97		LF 14JUN06	OD 0	BC	0
A104A35012	TA21 16.6 EPA Review Ph1					
ES 25SEP97	EF 1DEC97	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A35013	TA21 16.6 Incl. EPA Comments Ph1					
ES 2DEC97	EF 31DEC97	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A35014	TA21 16.6 Issue Final Rpt./WP Mod. Ph1					
ES 2JAN98	EF 15JAN98	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A36017	TA21 16.6 START RFI FIELD WORK					
ES 30CT94		LS 29SEP06		OD 0	BC	0
A104A36012	TA21 16.6 START RFI REPORT Ph2			SM		
ES 30CT94		LS 29SEP06		OD 0	BC	0
A103A36002	TA21 16.6 Identify Locations Ph2					
ES 18APR96	EF 18APR96	LS 20MAY97	LF 20MAY97	OD 1	BC	1713
A103A36001	TA21 Ph2 Surf. Agg. 16.6: 21-017a-c (MDA U)					
ES 18APR96	EF 25AUG97	LS 20MAY97	LF 28SEP06	OD 339	BC	0
A103A36003	TA21 16.6 Rad Survey Ph2					
ES 19APR96	EF 22APR96	LS 21MAY97	LF 22MAY97	OD 2	BC	2807
A103A36004	TA21 16.6 Soil Sampling Ph2					
ES 23APR96	EF 24APR96	LS 23MAY97	LF 27MAY97	OD 2	BC	5249
A103A36005	TA21 16.6 Field Analysis Ph2					
ES 23APR96	EF 24APR96	LS 12JAN06	LF 13JAN06	OD 2	BC	4000
A103A36006	TA21 16.6 Laboratory Analysis Ph2					
ES 23APR96	EF 29OCT96	LS 31MAY05	LF 6DEC05	OD 132	BC	79134
A103A36012	TA21 16.6 IDW Char. Analysis					
ES 23APR96	EF 29OCT96	LS 16FEB06	LF 23AUG06	OD 132	BC	1580
A103A36008	TA21 16.6 Data Tracking Ph2					
ES 23APR96	EF 27NOV96	LS 7JUN05	LF 13JAN06	OD 152	BC	11079
A103A36011	TA21 16.6 IDW Monitoring					
ES 23APR96	EF 27NOV96	LS 24FEB06	LF 28SEP06	OD 152	BC	1569
A103A36010	TA21 16.6 IDW Mgt					
ES 23APR96	EF 6DEC96	LS 24FEB06	LF 28SEP06	OD 157	BC	0
A103A36013	TA21 16.6 Prepare IDW Disposal Documentation					
ES 30OCT96	EF 20NOV96	LS 24AUG06	LF 14SEP06	OD 15	BC	8160



A103A36014	TA21 16.6 IDW Disposal						
ES 21NOV96	EF 6DEC96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A36007	TA21 16.6 Surface Data Quality Assurance Ph2						
ES 2DEC96	EF 6DEC96	LS 9JAN06	LF 13JAN06	OD	5	BC	1755
A103A36009	TA21 16.6 Data Assessment Ph2						
ES 9DEC96	EF 16JAN97	LS 17JAN06	LF 21FEB06	OD	25	BC	27912
A103A36015	TA21 16.6 Risk Assessment						
ES 17JAN97	EF 30JAN97	LS 22FEB06	LF 7MAR06	OD	10	BC	13022
A104A36001	TA21 16.6 AFI Report Prep. Ph2						
ES 17JAN97	EF 28FEB97	LS 22FEB06	LF 4APR06	OD	30	BC	0
A103A36016	TA21 16.6 Decision Analysis						
ES 31JAN97	EF 6FEB97	LS 8MAR06	LF 14MAR06	OD	5	BC	7849
A103A36020	TA21 16.6 AFI FIELD WORK COMPLETE PH2						
	EF 6FEB97		LF 3JAN95	OD	0	BC	0
A104A36004	TA21 16.6 Write AFI Report						
ES 7FEB97	EF 28FEB97	LS 15MAR06	LF 4APR06	OD	15	BC	31839
A104A36005	TA21 16.6 LANL/DOE Review Ph2						
ES 3MAR97	EF 28MAR97	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A36006	TA21 16.6 Incl. LANL/DOE Comments Ph2						
ES 31MAR97	EF 25APR97	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A36007	TA21 16.6 Issue EPA Draft Ph2						
ES 28APR97	EF 9MAY97	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A36008	TA21 16.6 EPA Draft Complete Ph2						
	EF 9MAY97		LF 14JUN06	OD	0	BC	0
A104A36009	TA21 16.6 EPA Review Ph2						
ES 12MAY97	EF 14JUL97	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A36010	TA21 16.6 Incl. EPA Comments Ph2						
ES 15JUL97	EF 11AUG97	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A36011	TA21 16.6 Issue Final Rpt./WP Mod. Ph2						
ES 12AUG97	EF 25AUG97	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A37017	TA21 16.6 START AFI FIELD WORK PH2						
ES 30CT94		LS 29SEP06		OD	0	BC	0
A104A37015	TA21 16.6 START AFI REPORT Ph2			SM			
ES 30CT94		LS 29SEP06		OD	0	BC	0
A103A37002	TA21 16.6 Drill/Sample Ph2						
ES 19MAY97	EF 12JUN97	LS 17AUG98	LF 10SEP98	OD	18	BC	283478
A103A37003	TA21 16.6 Field Analysis Ph2						
ES 19MAY97	EF 12JUN97	LS 5APR99	LF 28APR99	OD	18	BC	36000
A103A37005	TA21 16.6 Laboratory Analysis Ph2						
ES 19MAY97	EF 19DEC97	LS 17AUG98	LF 24MAR99	OD	148	BC	435878
A103A37011	TA21 16.6 IDW Char. Analysis						
ES 19MAY97	EF 19DEC97	LS 25JAN06	LF 23AUG06	OD	148	BC	6320
A103A37007	TA21 16.6 Data Tracking Ph2						
ES 19MAY97	EF 22JAN98	LS 24AUG98	LF 28APR99	OD	168	BC	12528
A103A37010	TA21 16.6 IDW Monitoring						
ES 19MAY97	EF 22JAN98	LS 1FEB06	LF 28SEP06	OD	168	BC	1774
A103A37009	TA21 16.6 IDW Mgt						
ES 19MAY97	EF 29JAN98	LS 1FEB06	LF 28SEP06	OD	173	BC	0
A103A37001	TA21 Ph2 Subs. Agg. 16.6: 21-017a-c (MDA U)						
ES 19MAY97	EF 28OCT98	LS 17AUG98	LF 28SEP06	OD	362	BC	0
A103A37004	TA21 16.6 Document Locations Ph2						
ES 13JUN97	EF 13JUN97	LS 28APR99	LF 28APR99	OD	1	BC	1713
A103A37012	TA21 16.6 Prepare IDW Disposal Documentation						
ES 22DEC97	EF 14JAN98	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A37013	TA21 16.6 IDW Disposal						
ES 15JAN98	EF 29JAN98	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A37006	TA21 16.6 Data Quality Assurance Ph2						
ES 23JAN98	EF 29JAN98	LS 22APR99	LF 28APR99	OD	5	BC	2486
A103A37008	TA21 16.6 Data Assessment Ph2						
ES 30JAN98	EF 6MAR98	LS 29APR99	LF 3JUN99	OD	25	BC	27912
A103A37014	TA21 16.6 Risk Assessment						
ES 9MAR98	EF 27MAR98	LS 4JUN99	LF 24JUN99	OD	15	BC	19524
A104A37001	TA21 16.6 AFI Report Prep. Ph2						
ES 9MAR98	EF 1MAY98	LS 4JUN99	LF 30JUL99	OD	40	BC	0
A103A37015	TA21 16.6 Decision Analysis						
ES 30MAR98	EF 3APR98	LS 25JUN99	LF 1JUL99	OD	5	BC	7849
A103A37020	TA21 16.6 AFI FIELD WORK COMPLETE PH2						
	EF 3APR98		LF 3JAN95	OD	0	BC	0
A104A37004	TA21 16.6 Write AFI Report						
ES 6APR98	EF 1MAY98	LS 2JUL99	LF 30JUL99	OD	20	BC	42454
A104A37005	TA21 16.6 LANL/DOE Review Ph2						
ES 4MAY98	EF 1JUN98	LS 2AUG99	LF 27AUG99	OD	20	BC	1534
A104A37006	TA21 16.6 Incl. LANL/DOE Comments Ph2						
ES 2JUN98	EF 29JUN98	LS 30AUG99	LF 27SEP99	OD	20	BC	22061



A104A37007	TA21 16.6 Issue EPA Draft Ph2						
ES 30JUN98	EF 14JUL98	LS 28SEP99	LF 12OCT99	OD	10	BC	4257
A104A37008	TA21 16.6 EPA Draft Complete Ph2						
	EF 14JUL98		LF 12OCT99	OD	0	BC	0
A104A37009	TA21 16.6 EPA Review Ph2						
ES 15JUL98	EF 15SEP98	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A37010	TA21 16.6 Incl. EPA Comments Ph2						
ES 16SEP98	EF 14OCT98	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A37011	TA21 16.6 Issue Final Rpt./WP Mod. Ph2						
ES 15OCT98	EF 28OCT98	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A104A38015	TA21 16.7 START RFI Report	SM	1				
ES 30CT94		LS 29SEP06		OD	0	BC	0
A103A38002	TA21 16.7 Laboratory Analysis Ph1						
ES 3JAN95	EF 6APR95	LS 18MAR05	LF 20JUN05	OD	66	BC	48607
A103A38008	TA21 16.7 IDW Char. Analysis						
ES 3JAN95	EF 6APR95	LS 22MAY06	LF 23AUG06	OD	66	BC	6320
A103A38006	TA21 16.7 IDW Mgt						
ES 3JAN95	EF 11MAY95	LS 15MAY06	LF 28SEP06	OD	91	BC	0
A103A38004	TA21 16.7 Data Tracking Ph1						
ES 3JAN95	EF 18MAY95	LS 18MAR05	LF 2AUG05	OD	96	BC	9488
A103A38007	TA21 16.7 IDW Monitoring						
ES 3JAN95	EF 18MAY95	LS 15MAY06	LF 28SEP06	OD	96	BC	1319
A103A38001	TA21 Ph1 Subs. Agg. 16.7: 21-018a (MDA V)						
ES 3JAN95	EF 18JUL96	LS 18MAR05	LF 28SEP06	OD	387	BC	0
A103A38009	TA21 16.7 Prepare IDW Disposal Documentation						
ES 7APR95	EF 27APR95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A38010	TA21 16.7 IDW Disposal						
ES 28APR95	EF 11MAY95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A38003	TA21 16.7 Data Quality Assurance Ph1						
ES 5MAY95	EF 11MAY95	LS 27JUL05	LF 2AUG05	OD	5	BC	2502
A103A38005	TA21 16.7 Data Assessment Ph1						
ES 19MAY95	EF 23JUN95	LS 3AUG05	LF 7SEP05	OD	25	BC	27912
A103A38011	TA21 16.7 Risk Assessment						
ES 26JUN95	EF 19SEP95	LS 8SEP05	LF 2DEC05	OD	60	BC	77568
A104A38001	TA21 16.7 RFI Report Prep. Ph1						
ES 26JUN95	EF 16FEB96	LS 8SEP05	LF 28APR06	OD	160	BC	0
A103A38012	TA21 16.7 Decision Analysis						
ES 20SEP95	EF 18OCT95	LS 5DEC05	LF 4JAN06	OD	20	BC	31332
A103A38013	TA21 16.7 Dev. Ph2 DQOs						
ES 19OCT95	EF 30OCT95	LS 5JAN06	LF 17JAN06	OD	8	BC	928
A104A38004	TA21 16.7 Write RFI Report						
ES 19OCT95	EF 16FEB96	LS 5JAN06	LF 28APR06	OD	80	BC	169550
A103A38017	TA21 16.7 RFI FIELD WORK COMPLETE PH1						
	EF 23OCT95		LF 3JAN95	OD	0	BC	0
A103A38014	TA21 16.7 Dev. Ph2 Sampling Approach						
ES 31OCT95	EF 16NOV95	LS 18JAN06	LF 2FEB06	OD	12	BC	2486
A103A38015	TA21 16.7 Write Ph2 Sampling Plan						
ES 17NOV95	EF 16FEB96	LS 3FEB06	LF 28APR06	OD	60	BC	43384
A104A38008	TA21 16.7 LANL/DOE Review Ph1						
ES 20FEB96	EF 18MAR96	LS 1MAY06	LF 26MAY06	OD	20	BC	1534
A104A38009	TA21 16.7 Incl. LANL/DOE Comments Ph1						
ES 19MAR96	EF 20MAR96	LS 30MAY06	LF 31MAY06	OD	2	BC	22061
A104A38010	TA21 16.7 Issue EPA Draft Ph1						
ES 21MAR96	EF 3APR96	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A38011	TA21 16.7 EPA Draft Complete Ph1						
	EF 3APR96		LF 14JUN06	OD	0	BC	0
A104A38012	TA21 16.7 EPA Review Ph1						
ES 4APR96	EF 5JUN96	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A38013	TA21 16.7 Incl. EPA Comments Ph1						
ES 6JUN96	EF 3JUL96	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A38014	TA21 16.7 Issue Final Rpt./WP Mod. Ph1						
ES 5JUL96	EF 18JUL96	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A39017	TA21 16.7 START RFI FIELD WORK						
ES 30CT94		LS 29SEP06		OD	0	BC	0
A104A39025	TA21 16.7 START RFI REPORT	Ph2	SM	1			
ES 30CT94		LS 29SEP06		OD	0	BC	0
A104A39012	TA21 Ph1 Subs. Agg. 16.7: 21-018b (MDA V Laundry						
ES 1MAR95	EF 30CT95	LS 24FEB06	LF 28SEP06	OD	152	BC	0
A103A39002	TA21 16.7 Drill/Sample Ph2						
ES 1FEB99	EF 30MAR99	LS 3FEB05	LF 1APR05	OD	41	BC	731163
A103A39003	TA21 16.7 Field Analysis Ph2						
ES 1FEB99	EF 30MAR99	LS 31OCT05	LF 29DEC05	OD	41	BC	82000



A103A39005	TA21 16.7 Laboratory Analysis Ph2						
ES 1FEB99	EF 10CT99	LS 22MAR05	LF 22NOV05	OD	171	BC	106830
A103A39011	TA21 16.7 IDW Char. Analysis						
ES 1FEB99	EF 10CT99	LS 19DEC05	LF 23AUG06	OD	171	BC	6320
A103A39007	TA21 16.7 Data Tracking Ph2						
ES 1FEB99	EF 1NOV99	LS 29MAR05	LF 29DEC05	OD	191	BC	14620
A103A39010	TA21 16.7 IDW Monitoring						
ES 1FEB99	EF 1NOV99	LS 28DEC05	LF 28SEP06	OD	191	BC	2071
A103A39009	TA21 16.7 IDW Mgt						
ES 1FEB99	EF 8NOV99	LS 28DEC05	LF 28SEP06	OD	196	BC	0
A103A39001	TA21 Ph2 Subs. Agg. 16.7: 21-018a (MDA V)						
ES 1FEB99	EF 11AUG00	LS 3FEB05	LF 28SEP06	OD	385	BC	0
A103A39004	TA21 16.7 Document Locations Ph2						
ES 31MAR99	EF 31MAR99	LS 29DEC05	LF 29DEC05	OD	1	BC	1713
A103A39012	TA21 16.7 Prepare IDW Disposal Documentation						
ES 4OCT99	EF 25OCT99	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A39013	TA21 16.7 IDW Disposal						
ES 26OCT99	EF 8NOV99	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A39006	TA21 16.7 Data Qualtiy Assurance Ph2						
ES 2NOV99	EF 8NOV99	LS 21DEC05	LF 29DEC05	OD	5	BC	3709
A103A39008	TA21 16.7 Data Assessment Ph2						
ES 9NOV99	EF 16DEC99	LS 30DEC05	LF 6FEB06	OD	25	BC	28714
A103A39014	TA21 16.7 Risk Assessment						
ES 17DEC99	EF 11JAN00	LS 7FEB06	LF 28FEB06	OD	15	BC	19524
A104A39001	TA21 16.7 RFI Report Prep. Ph2						
ES 17DEC99	EF 16FEB00	LS 7FEB06	LF 4APR06	OD	40	BC	0
A103A39015	TA21 16.7 Decision Analysis						
ES 12JAN00	EF 19JAN00	LS 1MAR06	LF 7MAR06	OD	5	BC	7849
A103A39020	TA21 16.7 RFI FIELD WORK COMPLETE						
	EF 19JAN00		LF 3JAN95	OD	0	BC	0
A104A39004	TA21 16.7 Write RFI Report						
ES 20JAN00	EF 16FEB00	LS 8MAR06	LF 4APR06	OD	20	BC	42454
A104A39005	TA21 16.7 LANL/DOE Review Ph2						
ES 17FEB00	EF 16MAR00	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A39006	TA21 16.7 Incl. LANL/DOE Comments Ph2						
ES 17MAR00	EF 13APR00	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A39007	TA21 16.7 Issue EPA Draft Ph2						
ES 14APR00	EF 27APR00	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A39008	TA21 16.7 EPA Draft Complete Ph2						
	EF 27APR00		LF 14JUN06	OD	0	BC	0
A104A39009	TA21 16.7 EPA Review Ph2						
ES 28APR00	EF 29JUN00	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A39010	TA21 16.7 Incl. EPA Comments Ph2						
ES 30JUN00	EF 28JUL00	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A39011	TA21 16.7 Issue Final Rpt./WP Mod. Ph2						
ES 31JUL00	EF 11AUG00	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A40015	TA21 16.8 RFI FIELD WORK COMPLETE						
	EF 30SEP94		LF 14JUN06	OD	0	BC	0
A103A40002	TA21 16.8 Laboratory Analysis Ph1						
ES 3JAN95	EF 16MAR95	LS 4DEC96	LF 19FEB97	OD	51	BC	179281
A103A40008	TA21 16.8 IDW Char. Analysis						
ES 3JAN95	EF 16MAR95	LS 13JUN06	LF 23AUG06	OD	51	BC	3160
A103A40006	TA21 16.8 IDW Mgt						
ES 3JAN95	EF 20APR95	LS 6JUN06	LF 28SEP06	OD	76	BC	0
A103A40004	TA21 16.8 Data Tracking Ph1						
ES 3JAN95	EF 27APR95	LS 4DEC96	LF 2APR97	OD	81	BC	7358
A103A40007	TA21 16.8 IDW Monitoring						
ES 3JAN95	EF 27APR95	LS 6JUN06	LF 28SEP06	OD	81	BC	1569
A103A40001	TA21 Ph1 Surf. Agg. 16.8: 21-014 (MDA A)						
ES 3JAN95	EF 28SEP06	LS 4DEC96	LF 28SEP06	OD	2928	BC	0
A103A40009	TA21 16.8 Prepare IDW Disposal Documentation						
ES 17MAR95	EF 6APR95	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A40010	TA21 16.8 IDW Disposal						
ES 7APR95	EF 20APR95	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A40003	TA21 16.8 Surface Data Quality Assurance Ph1						
ES 14APR95	EF 20APR95	LS 27MAR97	LF 2APR97	OD	5	BC	1930
A103A40005	TA21 16.8 Data Assessment Ph1						
ES 28APR95	EF 2JUN95	LS 3APR97	LF 7MAY97	OD	25	BC	27912
A103A41017	TA21 16.8 RFI FIELD WORK COMPLETE						
	EF 30SEP94		LF 14JUN06	OD	0	BC	0
A104A41012	TA21 16.8 START RFI REPORT Ph2			SM	1		
ES 30CT94		LS 29SEP06		OD	0	BC	0



A103A41018	TA21 16.8 START RFI FIELD WORK PH2						
ES 26MAY95		LS 3JAN95		OD	0	BC	0
A103A41002	TA21 16.8 Identify Locations Ph2						
ES 8APR96	EF 8APR96	LS 8MAY97	LF 8MAY97	OD	1	BC	1713
A103A41001	TA21 Ph2 Surf. Agg. 16.8: 21-014 (MDA A)						
ES 8APR96	EF 13SEP96	LS 8MAY97	LF 19JUL05	OD	112	BC	0
A103A41003	TA21 16.8 Rad Survey Ph2						
ES 9APR96	EF 10APR96	LS 9MAY97	LF 12MAY97	OD	2	BC	2807
A103A41004	TA21 16.8 Soil Sampling Ph2						
ES 11APR96	EF 12APR96	LS 13MAY97	LF 14MAY97	OD	2	BC	5249
A103A41005	TA21 16.8 Field Analysis Ph2						
ES 11APR96	EF 12APR96	LS 14FEB05	LF 15FEB05	OD	2	BC	4000
A103A41011	TA21 16.8 IDW Monitoring						
ES 11APR96	EF 20CT96	LS 20AUG98	LF 19FEB99	OD	122	BC	1569
A103A41010	TA21 16.8 IDW Mgt						
ES 11APR96	EF 26NOV96	LS 20AUG98	LF 28SEP06	OD	159	BC	0
A103A41006	TA21 16.8 Laboratory Analysis Ph2						
ES 15APR96	EF 6SEP96	LS 16FEB05	LF 12JUL05	OD	102	BC	79134
A103A41012	TA21 16.8 IDW Char. Analysis						
ES 15APR96	EF 21OCT96	LS 16FEB06	LF 23AUG06	OD	132	BC	1580
A103A41007	TA21 16.8 Surface Data Quality Assurance Ph2						
ES 9SEP96	EF 13SEP96	LS 13JUL05	LF 19JUL05	OD	5	BC	1755
A103A41008	TA21 16.8 Data Tracking Ph2						
ES 16SEP96	EF 17MAR97	LS 20JUL05	LF 13JAN06	OD	122	BC	11079
A103A41013	TA21 16.8 Prepare IDW Disposal Documentation						
ES 22OCT96	EF 12NOV96	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A41014	TA21 16.8 IDW Disposal						
ES 13NOV96	EF 26NOV96	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A41009	TA21 16.8 Data Assessment Ph2						
ES 18MAR97	EF 21APR97	LS 17JAN06	LF 21FEB06	OD	25	BC	27912
A103A41015	TA21 16.8 Risk Assessment						
ES 22APR97	EF 5MAY97	LS 22FEB06	LF 7MAR06	OD	10	BC	13022
A104A41001	TA21 16.8 RFI Report Prep. Ph2						
ES 22APR97	EF 3JUN97	LS 22FEB06	LF 4APR06	OD	30	BC	0
A103A41016	TA21 16.8 Decision Analysis						
ES 6MAY97	EF 12MAY97	LS 8MAR06	LF 14MAR06	OD	5	BC	7849
A104A41004	TA21 16.8 Write RFI Report						
ES 13MAY97	EF 3JUN97	LS 15MAR06	LF 4APR06	OD	15	BC	31839
A104A41005	TA21 16.8 LANL/DOE Review Ph2						
ES 4JUN97	EF 1JUL97	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A41006	TA21 16.8 Incl. LANL/DOE Comments Ph2						
ES 2JUL97	EF 30JUL97	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A41007	TA21 16.8 Issue EPA Draft Ph2						
ES 31JUL97	EF 13AUG97	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A41008	TA21 16.8 EPA Draft Complete Ph2						
	EF 13AUG97		LF 14JUN06	OD	0	BC	0
A104A41009	TA21 16.8 EPA Review Ph2						
ES 14AUG97	EF 16OCT97	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A41010	TA21 16.8 Incl. EPA Comments Ph2						
ES 17OCT97	EF 14NOV97	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A41011	TA21 16.8 Issue Final Rpt./WP Mod. Ph2						
ES 17NOV97	EF 2DEC97	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A104A42015	TA21 16.8 START RFI REPORT Ph1			SM			
ES 3OCT94		LS 29SEP06		OD	0	BC	0
A103A42002	TA21 16.8 Drill/Sample Ph1						
ES 26JUN96	EF 26JUL96	LS 16DEC97	LF 20JAN98	OD	22	BC	186200
A103A42003	TA21 16.8 Field Analysis Ph1						
ES 26JUN96	EF 26JUL96	LS 30JUL98	LF 28AUG98	OD	22	BC	44000
A103A42005	TA21 16.8 Laboratory Analysis Ph1						
ES 26JUN96	EF 6FEB97	LS 16DEC97	LF 24JUL98	OD	152	BC	557088
A103A42012	TA21 16.8 IDW Char. Analysis						
ES 26JUN96	EF 6FEB97	LS 19JAN06	LF 23AUG06	OD	152	BC	6320
A103A42008	TA21 16.8 Data Tracking Ph1						
ES 26JUN96	EF 7MAR97	LS 23DEC97	LF 28AUG98	OD	172	BC	12896
A103A42011	TA21 16.8 IDW Monitoring						
ES 26JUN96	EF 7MAR97	LS 26JAN06	LF 28SEP06	OD	172	BC	1826
A103A42010	TA21 16.8 IDW Mgt						
ES 26JUN96	EF 14MAR97	LS 26JAN06	LF 28SEP06	OD	177	BC	0
A103A42001	TA21 Ph1 Subs. Agg. 16.8: 21-014 (MDA A)						
ES 26JUN96	EF 15DEC97	LS 16DEC97	LF 28SEP06	OD	366	BC	0
A103A42004	TA21 16.8 Document Locations Ph1						
ES 29JUL96	EF 29JUL96	LS 28AUG98	LF 28AUG98	OD	1	BC	1713
A103A42006	TA21 16.8 Geo-Hydro Analysis Ph1						
ES 29JUL96	EF 9OCT96	LS 17JUN98	LF 28AUG98	OD	52	BC	0



A103A42013	TA21 16.8 Prepare IDW Disposal Documentation					
ES 7FEB97	EF 28FEB97	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A42014	TA21 16.8 IDW Disposal					
ES 3MAR97	EF 14MAR97	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A42007	TA21 16.8 Data Quality Assurance Ph1					
ES 10MAR97	EF 14MAR97	LS 24AUG98	LF 28AUG98	OD 5	BC	2732
A103A42009	TA21 16.8 Data Assessment Ph1					
ES 17MAR97	EF 18APR97	LS 31AUG98	LF 5OCT98	OD 25	BC	27912
A103A42015	TA21 16.8 Risk Assessment					
ES 21APR97	EF 9MAY97	LS 6OCT98	LF 27OCT98	OD 15	BC	19524
A104A42001	TA21 16.8 RFI Report Prep. Ph1					
ES 21APR97	EF 16JUN97	LS 6OCT98	LF 4DEC98	OD 40	BC	0
A103A42016	TA21 16.8 Decision Analysis					
ES 12MAY97	EF 16MAY97	LS 28OCT98	LF 3NOV98	OD 5	BC	7849
A103A42020	TA21 16.8 RFI FIELD WORK COMPLETE					
	EF 16MAY97		LF 3JAN95	OD 0	BC	0
A104A42005	TA21 16.8 Dev. Ph2 DQOs					
ES 19MAY97	EF 20MAY97	LS 4NOV98	LF 5NOV98	OD 2	BC	928
A104A42004	TA21 16.8 Write RFI Report					
ES 19MAY97	EF 16JUN97	LS 4NOV98	LF 4DEC98	OD 20	BC	42454
A103A42017	TA21 16.8 Dev. Ph2 Sampling Approach					
ES 21MAY97	EF 23MAY97	LS 6NOV98	LF 11NOV98	OD 3	BC	1486
A103A42018	TA21 16.8 Write Ph2 Sampling Plan					
ES 27MAY97	EF 16JUN97	LS 12NOV98	LF 4DEC98	OD 15	BC	10886
A104A42008	TA21 16.8 LANL/DOE Review Ph1					
ES 17JUN97	EF 15JUL97	LS 7DEC98	LF 6JAN99	OD 20	BC	1534
A104A42009	TA21 16.8 Incl. LANL/DOE Comments Ph1					
ES 16JUL97	EF 12AUG97	LS 7JAN99	LF 4FEB99	OD 20	BC	22061
A104A42010	TA21 16.8 Issue EPA Draft Ph1					
ES 13AUG97	EF 26AUG97	LS 5FEB99	LF 19FEB99	OD 10	BC	4257
A104A42011	TA21 16.8 EPA Draft Complete Ph1					
	EF 26AUG97		LF 19FEB99	OD 0	BC	0
A104A42012	TA21 16.8 EPA Review Ph1					
ES 27AUG97	EF 29OCT97	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A42013	TA21 16.8 Incl. EPA Comments Ph1					
ES 30OCT97	EF 1DEC97	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A42014	TA21 16.8 Issue Final Rpt./WP Mod. Ph1					
ES 2DEC97	EF 15DEC97	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A43017	TA21 16.8 RFI FIELD WORK COMPLETE					
	EF 30SEP94		LF 28SEP06	OD 0	BC	0
A103A43018	TA21 16.8 START RFI FIELD WORK					
ES 3OCT94		LS 29SEP06		OD 0	BC	0
A104A43012	TA21 16.8 START RFI REPORT Ph2					
ES 3OCT94		LS 29SEP06		OD 0	BC	0
A103A43002	TA21 16.8 Drill/Sample Ph2					
ES 1APR99	EF 22APR99	LS 5APR05	LF 26APR05	OD 16	BC	73107
A103A43003	TA21 16.8 Field Analysis Ph2					
ES 1APR99	EF 22APR99	LS 6DEC05	LF 29DEC05	OD 16	BC	32000
A103A43005	TA21 16.8 Laboratory Analysis Ph2					
ES 1APR99	EF 27OCT99	LS 26APR05	LF 22NOV05	OD 146	BC	359312
A103A43011	TA21 16.8 IDW Char. Analysis					
ES 1APR99	EF 27OCT99	LS 27JAN06	LF 23AUG06	OD 146	BC	6320
A103A43007	TA21 16.8 Data Tracking Ph2					
ES 1APR99	EF 29NOV99	LS 3MAY05	LF 29DEC05	OD 166	BC	12350
A103A43010	TA21 16.8 IDW Monitoring					
ES 1APR99	EF 29NOV99	LS 3FEB06	LF 28SEP06	OD 166	BC	1749
A103A43009	TA21 16.8 IDW Mgt					
ES 1APR99	EF 6DEC99	LS 3FEB06	LF 28SEP06	OD 171	BC	0
A103A43001	TA21 Ph2 Subs. Agg. 16.8: 21-014 (MDA A)					
ES 1APR99	EF 6SEP00	LS 5APR05	LF 28SEP06	OD 360	BC	0
A103A43004	TA21 16.8 Document Locations Ph2					
ES 23APR99	EF 23APR99	LS 29DEC05	LF 29DEC05	OD 1	BC	1713
A103A43012	TA21 16.8 Prepare IDW Disposal Documentation					
ES 28OCT99	EF 18NOV99	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A43013	TA21 16.8 IDW Disposal					
ES 19NOV99	EF 6DEC99	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A43006	TA21 16.8 Data Quality Assurance Ph2					
ES 30NOV99	EF 6DEC99	LS 21DEC05	LF 29DEC05	OD 5	BC	1880
A103A43008	TA21 16.8 Data Assessment Ph2					
ES 7DEC99	EF 13JAN00	LS 30DEC05	LF 6FEB06	OD 25	BC	27912
A103A43014	TA21 16.8 Risk Assessment					
ES 14JAN00	EF 4FEB00	LS 7FEB06	LF 28FEB06	OD 15	BC	19524
A104A43001	TA21 16.8 RFI Report Prep. Ph2					
ES 14JAN00	EF 13MAR00	LS 7FEB06	LF 4APR06	OD 40	BC	0



A103A43015 ES 7FEB00	TA21 16.8 Decision Analysis Ph2 EF 11FEB00 LS 1MAR06 LF 7MAR06	OD	5	BC	7849
A104A43004 ES 14FEB00	TA21 16.8 Write RFI Report Ph2 EF 13MAR00 LS 8MAR06 LF 4APR06	OD	20	BC	42454
A104A43005 ES 14MAR00	TA21 16.8 LANL/DOE Review Ph2 EF 10APR00 LS 5APR06 LF 2MAY06	OD	20	BC	1534
A104A43006 ES 11APR00	TA21 16.8 Incl. LANL/DOE Comments Ph2 EF 8MAY00 LS 3MAY06 LF 31MAY06	OD	20	BC	22061
A104A43007 ES 9MAY00	TA21 16.8 Issue EPA Draft Ph2 EF 22MAY00 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A104A43008	TA21 16.8 EPA Draft Complete Ph2 EF 22MAY00 LF 14JUN06	OD	0	BC	0
A104A43009 ES 23MAY00	TA21 16.8 EPA Review Ph2 EF 25JUL00 LS 15JUN06 LF 16AUG06	OD	44	BC	793
A104A43010 ES 26JUL00	TA21 16.8 Incl. EPA Comments Ph2 EF 22AUG00 LS 17AUG06 LF 14SEP06	OD	20	BC	22061
A104A43011 ES 23AUG00	TA21 16.8 Issue Final Rpt./WP Mod. Ph2 EF 6SEP00 LS 15SEP06 LF 28SEP06	OD	10	BC	1922
A104A44015 ES 30CT94	TA21 17.2 START RFI REPORT Ph1 LS 29SEP06	SM OD	0	BC	0
A103A44002 ES 20CT97	TA21 17.2 Identify Locations Ph1 EF 30CT97 LS 25APR05 LF 26APR05	OD	2	BC	3421
A103A44001 ES 20CT97	TA21 Ph1 Subs. Agg. 17.2: 21-006b EF 2FEB99 LS 25APR05 LF 28SEP06	OD	329	BC	0
A103A44003 ES 60CT97	TA21 17.2 Geophysical Survey Ph1 EF 60CT97 LS 27APR05 LF 27APR05	OD	1	BC	1682
A103A44004 ES 70CT97	TA21 17.2 Drill/Sample Ph1 EF 80CT97 LS 28APR05 LF 29APR05	OD	2	BC	8992
A103A44005 ES 70CT97	TA21 17.2 Field Analysis Ph1 EF 80CT97 LS 27JAN06 LF 30JAN06	OD	2	BC	4000
A103A44007 ES 70CT97	TA21 17.2 Laboratory Analysis Ph1 EF 21APR98 LS 14JUN05 LF 20DEC05	OD	132	BC	27531
A103A44013 ES 70CT97	TA21 17.2 IDW Char. Analysis EF 21APR98 LS 16FEB06 LF 23AUG06	OD	132	BC	1580
A103A44009 ES 70CT97	TA21 17.2 Data Tracking Ph1 EF 19MAY98 LS 21JUN05 LF 30JAN06	OD	152	BC	11079
A103A44012 ES 70CT97	TA21 17.2 IDW Monitoring EF 19MAY98 LS 24FEB06 LF 28SEP06	OD	152	BC	1569
A103A44011 ES 70CT97	TA21 17.2 IDW Mgt EF 27MAY98 LS 24FEB06 LF 28SEP06	OD	157	BC	0
A103A44006 ES 90CT97	TA21 17.2 Document Locations Ph1 EF 90CT97 LS 30JAN06 LF 30JAN06	OD	1	BC	1713
A103A44014 ES 22APR98	TA21 17.2 Prepare IDW Disposal Documentation EF 12MAY98 LS 24AUG06 LF 14SEP06	OD	15	BC	8160
A103A44015 ES 13MAY98	TA21 17.2 IDW Disposal EF 27MAY98 LS 15SEP06 LF 28SEP06	OD	10	BC	12149
A103A44008 ES 20MAY98	TA21 17.2 Data Qualtiy Assurance Ph1 EF 27MAY98 LS 24JAN06 LF 30JAN06	OD	5	BC	1621
A103A44010 ES 28MAY98	TA21 17.2 Data Assessment Ph1 EF 17JUN98 LS 31JAN06 LF 21FEB06	OD	15	BC	16746
A103A44016 ES 18JUN98	TA21 17.2 Risk Assessment EF 1JUL98 LS 22FEB06 LF 7MAR06	OD	10	BC	13022
A104A44001 ES 18JUN98	TA21 17.2 RFI Report Prep. Ph1 EF 30JUL98 LS 22FEB06 LF 4APR06	OD	30	BC	0
A103A44017 ES 2JUL98	TA21 17.2 Decision Analysis EF 9JUL98 LS 8MAR06 LF 14MAR06	OD	5	BC	7849
A103A44020	TA21 17.2 RFI FIELD WORK COMPLETE PH1 EF 9JUL98 LF 3JAN95	OD	0	BC	0
A104A44005 ES 10JUL98	TA21 17.2 Dev. Ph2 DQOs EF 13JUL98 LS 15MAR06 LF 16MAR06	OD	2	BC	928
A104A44004 ES 10JUL98	TA21 17.2 Write RFI Report EF 30JUL98 LS 15MAR06 LF 4APR06	OD	15	BC	31839
A103A44018 ES 14JUL98	TA21 17.2 Dev. Ph2 Sampling Approach EF 16JUL98 LS 17MAR06 LF 21MAR06	OD	3	BC	1486
A103A44019 ES 17JUL98	TA21 17.2 Write Ph2 Sampling Plan EF 30JUL98 LS 22MAR06 LF 4APR06	OD	10	BC	7256
A104A44008 ES 31JUL98	TA21 17.2 LANL/DOE Review Ph1 EF 27AUG98 LS 5APR06 LF 2MAY06	OD	20	BC	1534
A104A44009 ES 28AUG98	TA21 17.2 Incl. LANL/DOE Comments Ph1 EF 25SEP98 LS 3MAY06 LF 31MAY06	OD	20	BC	22061
A104A44010 ES 28SEP98	TA21 17.2 Issue EPA Draft Ph1 EF 90CT98 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A104A44011	TA21 17.2 EPA Draft Complete Ph1 EF 90CT98 LF 14JUN06	OD	0	BC	0



A104A44012	TA21 17.2 EPA Review Ph1						
ES 13OCT98	EF 16DEC98	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A44013	TA21 17.2 Incl. EPA Comments Ph1						
ES 17DEC98	EF 19JAN99	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A44014	TA21 17.2 Issue Final Rpt./WP Mod. Ph1						
ES 20JAN99	EF 2FEB99	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A45017	TA21 17.2 RFI FIELD WORK COMPLETE FM				1		
	EF 30SEP94		LF 28SEP06	OD	0	BC	0
A104A45012	TA21 17.2 START RFI RPT WP Mod. Ph2			SM	1		
ES 3OCT94		LS 29SEP06		OD	0	BC	0
A103A45002	TA21 17.2 Drill/Sample Ph2						
ES 15APR99	EF 28APR99	LS 4APR05	LF 15APR05	OD	10	BC	58286
A103A45003	TA21 17.2 Field Analysis Ph2						
ES 15APR99	EF 28APR99	LS 14DEC05	LF 29DEC05	OD	10	BC	20000
A103A45005	TA21 17.2 Laboratory Analysis Ph2						
ES 15APR99	EF 2NOV99	LS 4MAY05	LF 22NOV05	OD	140	BC	143500
A103A45011	TA21 17.2 IDW Char. Analysis						
ES 15APR99	EF 2NOV99	LS 6FEB06	LF 23AUG06	OD	140	BC	1580
A103A45007	TA21 17.2 Data Tracking Ph2						
ES 15APR99	EF 3DEC99	LS 11MAY05	LF 29DEC05	OD	160	BC	13567
A103A45010	TA21 17.2 IDW Monitoring						
ES 15APR99	EF 3DEC99	LS 13FEB06	LF 28SEP06	OD	160	BC	1950
A103A45009	TA21 17.2 IDW Mgt						
ES 15APR99	EF 10DEC99	LS 13FEB06	LF 28SEP06	OD	165	BC	0
A103A45001	TA21 Ph2 Subs. Agg. 17.2: 21-006b						
ES 15APR99	EF 12SEP00	LS 4APR05	LF 28SEP06	OD	354	BC	0
A103A45004	TA21 17.2 Document Locations Ph2						
ES 29APR99	EF 29APR99	LS 29DEC05	LF 29DEC05	OD	1	BC	1713
A103A45012	TA21 17.2 Prepare IDW Disposal Documentation						
ES 3NOV99	EF 24NOV99	LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A45013	TA21 17.2 IDW Disposal						
ES 29NOV99	EF 10DEC99	LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A45006	TA21 17.2 Data Quality Assurance Ph2						
ES 6DEC99	EF 10DEC99	LS 21DEC05	LF 29DEC05	OD	5	BC	1880
A103A45008	TA21 17.2 Data Assessment Ph2						
ES 13DEC99	EF 20JAN00	LS 30DEC05	LF 6FEB06	OD	25	BC	27912
A103A45014	TA21 17.2 Risk Assessment						
ES 21JAN00	EF 10FEB00	LS 7FEB06	LF 28FEB06	OD	15	BC	19524
A104A45001	TA21 17.2 RFI Report Prep. Ph2						
ES 21JAN00	EF 17MAR00	LS 7FEB06	LF 4APR06	OD	40	BC	0
A103A45015	TA21 17.2 Decision Analysis						
ES 11FEB00	EF 17FEB00	LS 1MAR06	LF 7MAR06	OD	5	BC	7849
A104A45004	TA21 17.2 Write RFI Report						
ES 18FEB00	EF 17MAR00	LS 8MAR06	LF 4APR06	OD	20	BC	42454
A104A45005	TA21 17.2 LANL/DOE Review Ph2						
ES 20MAR00	EF 14APR00	LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A45006	TA21 17.2 Incl. LANL/DOE Comments Ph2						
ES 17APR00	EF 12MAY00	LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A45007	TA21 17.2 Issue EPA Draft Ph2						
ES 15MAY00	EF 26MAY00	LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A45008	TA21 17.2 EPA Draft Complete Ph2						
	EF 26MAY00		LF 14JUN06	OD	0	BC	0
A104A45009	TA21 17.2 EPA Review Ph2						
ES 30MAY00	EF 31JUL00	LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A45010	TA21 17.2 Incl. EPA Comments Ph2						
ES 1AUG00	EF 28AUG00	LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A45011	TA21 17.2 Issue Final Rpt./WP Mod. Ph2						
ES 29AUG00	EF 12SEP00	LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A104A46015	TA21 17.3 START RFI REPORT PH1			SM	1		
ES 3OCT94		LS 29SEP06		OD	0	BC	0
A103A46002	TA21 17.3 Identify Locations Ph1						
ES 7OCT97	EF 8OCT97	LS 28APR05	LF 29APR05	OD	2	BC	3426
A103A46001	TA21 Ph1 Subs. Agg. 17.3: 21-009						
ES 7OCT97	EF 5FEB99	LS 28APR05	LF 28SEP06	OD	329	BC	0
A103A46003	TA21 17.3 Excavate/Sample Ph1						
ES 9OCT97	EF 9OCT97	LS 2MAY05	LF 2MAY05	OD	1	BC	4815
A103A46006	TA21 17.3 Field Analysis Ph1						
ES 9OCT97	EF 14OCT97	LS 26JAN06	LF 30JAN06	OD	3	BC	6000
A103A46008	TA21 17.3 Laboratory Analysis Ph1						
ES 9OCT97	EF 24APR98	LS 13JUN05	LF 20DEC05	OD	133	BC	30755
A103A46014	TA21 17.3 IDW Char. Analysis						
ES 9OCT97	EF 24APR98	LS 15FEB06	LF 23AUG06	OD	133	BC	3160



A103A46010	TA21 17.3 Data Tracking Ph1					
ES 9OCT97	EF 22MAY98	LS 20JUN05	LF 30JAN06	OD 153	BC	11171
A103A46013	TA21 17.3 IDW Monitoring					
ES 9OCT97	EF 22MAY98	LS 23FEB06	LF 28SEP06	OD 153	BC	1583
A103A46012	TA21 17.3 IDW Mgt					
ES 9OCT97	EF 1JUN98	LS 23FEB06	LF 28SEP06	OD 158	BC	0
A103A46004	TA21 17.3 Soil Sampling Ph1					
ES 10OCT97	EF 10OCT97	LS 3MAY05	LF 3MAY05	OD 1	BC	2629
A103A46005	TA21 17.3 Drill/Sample Ph1					
ES 14OCT97	EF 14OCT97	LS 4MAY05	LF 4MAY05	OD 1	BC	5191
A103A46007	TA21 17.3 Document Locations Ph1					
ES 15OCT97	EF 15OCT97	LS 30JAN06	LF 30JAN06	OD 1	BC	1713
A103A46015	TA21 17.3 Prepare IDW Disposal Documentation					
ES 27APR98	EF 15MAY98	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A46016	TA21 17.3 IDW Disposal					
ES 18MAY98	EF 1JUN98	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A46009	TA21 17.3 Data Quality Assurance Ph1					
ES 26MAY98	EF 1JUN98	LS 24JAN06	LF 30JAN06	OD 5	BC	1621
A103A46011	TA21 17.3 Data Assessment Ph1					
ES 2JUN98	EF 22JUN98	LS 31JAN06	LF 21FEB06	OD 15	BC	16746
A103A46017	TA21 17.3 Risk Assessment					
ES 23JUN98	EF 7JUL98	LS 22FEB06	LF 7MAR06	OD 10	BC	13022
A104A46001	TA21 17.3 RFI Report Prep. Ph1					
ES 23JUN98	EF 4AUG98	LS 22FEB06	LF 4APR06	OD 30	BC	0
A103A46018	TA21 17.3 Decision Analysis					
ES 8JUL98	EF 14JUL98	LS 8MAR06	LF 14MAR06	OD 5	BC	7849
A103A46021	TA21 17.3 RFI FIELD WORK COMPLETE PH1					
	EF 14JUL98		LF 3JAN95	OD 0	BC	0
A104A46005	TA21 17.3 Dev. Ph2 DQOs					
ES 15JUL98	EF 16JUL98	LS 15MAR06	LF 16MAR06	OD 2	BC	928
A104A46004	TA21 17.3 Write RFI Report					
ES 15JUL98	EF 4AUG98	LS 15MAR06	LF 4APR06	OD 15	BC	31839
A103A46019	TA21 17.3 Dev. Ph2 Sampling Approach					
ES 17JUL98	EF 21JUL98	LS 17MAR06	LF 21MAR06	OD 3	BC	1486
A103A46020	TA21 17.3 Write Ph2 Sampling Plan					
ES 22JUL98	EF 4AUG98	LS 22MAR06	LF 4APR06	OD 10	BC	7256
A104A46008	TA21 17.3 LANL/DOE Review Ph1					
ES 5AUG98	EF 1SEP98	LS 5APR06	LF 2MAY06	OD 20	BC	1534
A104A46009	TA21 17.3 Incl. LANL/DOE Comments Ph1					
ES 2SEP98	EF 30SEP98	LS 3MAY06	LF 31MAY06	OD 20	BC	22061
A104A46010	TA21 17.3 Issue EPA Draft Ph1					
ES 10OCT98	EF 15OCT98	LS 1JUN06	LF 14JUN06	OD 10	BC	4257
A104A46011	TA21 17.3 EPA Draft Complete Ph1					
	EF 15OCT98		LF 14JUN06	OD 0	BC	0
A104A46012	TA21 17.3 EPA Review Ph1					
ES 16OCT98	EF 21DEC98	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A46013	TA21 17.3 Incl. EPA Comments Ph1					
ES 22DEC98	EF 22JAN99	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A46014	TA21 17.3 Issue Final Apt./WP Mod. Ph1					
ES 25JAN99	EF 5FEB99	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A47017	TA21 17.3 RFI FIELD WORK COMPLETE FM 1					
	EF 30SEP94		LF 14JUN06	OD 0	BC	0
A103A47018	TA21 17.3 START RFI FIELD WORK PH2 SM 1					
ES 30CT94		LS 29SEP06		OD 0	BC	0
A104A47012	TA21 17.3 START RFI REPORT PH2 SM					
ES 30CT94		LS 29SEP06		OD 0	BC	0
A103A47002	TA21 17.3 Drill/Sample Ph2					
ES 30APR99	EF 3MAY99	LS 19APR05	LF 20APR05	OD 2	BC	9356
A103A47003	TA21 17.3 Field Analysis Ph2					
ES 30APR99	EF 3MAY99	LS 27JAN06	LF 30JAN06	OD 2	BC	4000
A103A47005	TA21 17.3 Laboratory Analysis Ph2					
ES 30APR99	EF 5NOV99	LS 14JUN05	LF 20DEC05	OD 132	BC	22655
A103A47011	TA21 17.3 IDW Char. Analysis					
ES 30APR99	EF 5NOV99	LS 16FEB06	LF 23AUG06	OD 132	BC	1580
A103A47007	TA21 17.3 Data Tracking Ph2					
ES 30APR99	EF 8DEC99	LS 21JUN05	LF 30JAN06	OD 152	BC	11079
A103A47010	TA21 17.3 IDW Monitoring					
ES 30APR99	EF 8DEC99	LS 24FEB06	LF 28SEP06	OD 152	BC	1569
A103A47009	TA21 17.3 IDW Mgt					
ES 30APR99	EF 15DEC99	LS 24FEB06	LF 28SEP06	OD 157	BC	0
A103A47001	TA21 Ph2 Subs. Agg. 17.3: 21-009					
ES 30APR99	EF 17AUG00	LS 19APR05	LF 28SEP06	OD 326	BC	0
A103A47004	TA21 17.3 Document Locations Ph2					
ES 4MAY99	EF 4MAY99	LS 30JAN06	LF 30JAN06	OD 1	BC	1713



A103A47012	TA21 17.3 Prepare IDW Disposal Documentation							
ES 8NOV99	EF 1DEC99	LS 24AUG06	LF 14SEP06	OD	15	BC	8160	
A103A47013	TA21 17.3 IDW Disposal							
ES 2DEC99	EF 15DEC99	LS 15SEP06	LF 28SEP06	OD	10	BC	12149	
A103A47006	TA21 17.3 Data Quality Assurance Ph2							
ES 9DEC99	EF 15DEC99	LS 24JAN06	LF 30JAN06	OD	5	BC	1621	
A103A47008	TA21 17.3 Data Assessment Ph2							
ES 16DEC99	EF 10JAN00	LS 31JAN06	LF 21FEB06	OD	15	BC	16746	
A103A47014	TA21 17.3 Risk Assessment							
ES 11JAN00	EF 25JAN00	LS 22FEB06	LF 7MAR06	OD	10	BC	13022	
A104A47001	TA21 17.3 RFI Report Prep. Ph2							
ES 11JAN00	EF 23FEB00	LS 22FEB06	LF 4APR06	OD	30	BC	0	
A103A47015	TA21 17.3 Decision Analysis							
ES 26JAN00	EF 1FEB00	LS 8MAR06	LF 14MAR06	OD	5	BC	7849	
A104A47004	TA21 17.3 Write RFI Report							
ES 2FEB00	EF 23FEB00	LS 15MAR06	LF 4APR06	OD	15	BC	31839	
A104A47005	TA21 17.3 LANL/DOE Review Ph2							
ES 24FEB00	EF 22MAR00	LS 5APR06	LF 2MAY06	OD	20	BC	1534	
A104A47006	TA21 17.3 Incl. LANL/DOE Comments Ph2							
ES 23MAR00	EF 19APR00	LS 3MAY06	LF 31MAY06	OD	20	BC	22061	
A104A47007	TA21 17.3 Issue EPA Draft Ph2							
ES 20APR00	EF 3MAY00	LS 1JUN06	LF 14JUN06	OD	10	BC	4257	
A104A47008	TA21 17.3 EPA Draft Complete Ph2							
	EF 3MAY00		LF 14JUN06	OD	0	BC	0	
A104A47009	TA21 17.3 EPA Review Ph2							
ES 4MAY00	EF 6JUL00	LS 15JUN06	LF 16AUG06	OD	44	BC	793	
A104A47010	TA21 17.3 Incl. EPA Comments Ph2							
ES 7JUL00	EF 3AUG00	LS 17AUG06	LF 14SEP06	OD	20	BC	22061	
A104A47011	TA21 17.3 Issue Final Rpt./WP Mod. Ph2							
ES 4AUG00	EF 17AUG00	LS 15SEP06	LF 28SEP06	OD	10	BC	1922	
A103A48018	TA21 17.4 START RFI FIELD WORK			SM	1			
ES 30CT94		LS 29SEP06		OD	0	BC	0	
A104A48012	TA21 17.4 START RFI REPORT Ph1			SM	1			
ES 30CT94		LS 29SEP06		OD	0	BC	0	
A103A48002	TA21 17.4 Identify Locations Ph1							
ES 10OCT97	EF 14OCT97	LS 3MAY05	LF 4MAY05	OD	2	BC	3426	
A103A48001	TA21 Ph1 Subs. Agg. 17.4: 21-012b							
ES 10OCT97	EF 11FEB99	LS 3MAY05	LF 28SEP06	OD	330	BC	0	
A103A48003	TA21 17.4 Drill/Sample Ph1							
ES 15OCT97	EF 20OCT97	LS 5MAY05	LF 10MAY05	OD	4	BC	22555	
A103A48004	TA21 17.4 Field Analysis Ph1							
ES 15OCT97	EF 20OCT97	LS 25JAN06	LF 30JAN06	OD	4	BC	8000	
A103A48006	TA21 17.4 Laboratory Analysis Ph1							
ES 15OCT97	EF 30APR98	LS 10JUN05	LF 20DEC05	OD	134	BC	32398	
A103A48008	TA21 17.4 Data Tracking Ph1							
ES 15OCT97	EF 29MAY98	LS 17JUN05	LF 30JAN06	OD	154	BC	11256	
A103A48012	TA21 17.4 IDW Char. Analysis							
ES 15OCT97	EF 29MAY98	LS 18JUL05	LF 28FEB06	OD	154	BC	3160	
A103A48011	TA21 17.4 IDW Monitoring							
ES 15OCT97	EF 5JUN98	LS 14FEB06	LF 28SEP06	OD	159	BC	1592	
A103A48010	TA21 17.4 IDW Mgt							
ES 15OCT97	EF 6JAN99	LS 14FEB06	LF 28SEP06	OD	303	BC	0	
A103A48005	TA21 17.4 Document Locations Ph1							
ES 21OCT97	EF 21OCT97	LS 30JAN06	LF 30JAN06	OD	1	BC	1713	
A103A48007	TA21 17.4 Data Quality Assurance Ph1							
ES 1JUN98	EF 5JUN98	LS 24JAN06	LF 30JAN06	OD	5	BC	1712	
A103A48013	TA21 17.4 Prepare IDW Disposal Documentation							
ES 1JUN98	EF 11DEC98	LS 1MAR06	LF 7SEP06	OD	134	BC	8160	
A103A48009	TA21 17.4 Data Assessment Ph1							
ES 8JUN98	EF 26JUN98	LS 31JAN06	LF 21FEB06	OD	15	BC	16746	
A103A48015	TA21 17.4 Risk Assessment							
ES 29JUN98	EF 13JUL98	LS 22FEB06	LF 7MAR06	OD	10	BC	13022	
A104A48001	TA21 17.4 RFI Report Prep. Ph1							
ES 29JUN98	EF 10AUG98	LS 22FEB06	LF 4APR06	OD	30	BC	0	
A103A48016	TA21 17.4 Decision Analysis							
ES 14JUL98	EF 20JUL98	LS 8MAR06	LF 14MAR06	OD	5	BC	7849	
A104A48004	TA21 17.4 Write RFI Report							
ES 21JUL98	EF 10AUG98	LS 15MAR06	LF 4APR06	OD	15	BC	31839	
A103A48020	TA21 17.4 RFI FIELD WORK COMPLETE PH1							
	EF 22JUL98		LF 3JAN95	OD	0	BC	0	
A104A48005	TA21 17.4 LANL/DOE Review Ph1							
ES 11AUG98	EF 8SEP98	LS 5APR06	LF 2MAY06	OD	20	BC	1534	
A104A48006	TA21 17.4 Incl. LANL/DOE Comments Ph1							
ES 9SEP98	EF 6OCT98	LS 3MAY06	LF 31MAY06	OD	20	BC	22061	



A104A48007 ES 7OCT98	TA21 17.4 Issue EPA Draft Ph1 EF 21OCT98 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A104A48008	TA21 17.4 EPA Draft Complete Ph1 EF 21OCT98 LF 14JUN06	OD	0	BC	0
A104A48009 ES 22OCT98	TA21 17.4 EPA Review Ph1 EF 29DEC98 LS 15JUN06 LF 16AUG06	OD	44	BC	793
A103A48014 ES 14DEC98	TA21 17.4 IDW Disposal EF 6JAN99 LS 8SEP06 LF 28SEP06	OD	15	BC	12149
A104A48010 ES 30DEC98	TA21 17.4 Incl. EPA Comments Ph1 EF 28JAN99 LS 17AUG06 LF 14SEP06	OD	20	BC	22061
A104A48011 ES 29JAN99	TA21 17.4 Issue Final Rpt./WP Mod. Ph1 EF 11FEB99 LS 15SEP06 LF 28SEP06	OD	10	BC	1922
A104A49015 ES 30CT94	TA21 17.5 START RFI REPORT Ph1 LS 29SEP06	SM OD	0	BC	0
A103A49002 ES 20OCT97	TA21 17.5 Identify Locations Ph1 EF 20OCT97 LS 10MAY05 LF 10MAY05	OD	1	BC	1713
A103A49001 ES 20OCT97	TA21 Ph1 Subs. Agg. 17.5: 21-022a/f EF 19MAR99 LS 10MAY05 LF 28SEP06	OD	350	BC	0
A103A49003 ES 21OCT97	TA21 17.5 Drill/Sample Ph1 EF 27OCT97 LS 11MAY05 LF 17MAY05	OD	5	BC	29137
A103A49004 ES 21OCT97	TA21 17.5 Field Analysis Ph1 EF 27OCT97 LS 21DEC05 LF 29DEC05	OD	5	BC	10000
A103A49006 ES 21OCT97	TA21 17.5 Laboratory Analysis Ph1 EF 7MAY98 LS 11MAY05 LF 22NOV05	OD	135	BC	108675
A103A49012 ES 21OCT97	TA21 17.5 IDW Char. Analysis EF 7MAY98 LS 13FEB06 LF 23AUG06	OD	135	BC	3160
A103A49008 ES 21OCT97	TA21 17.5 Data Tracking Ph1 EF 5JUN98 LS 18MAY05 LF 29DEC05	OD	155	BC	14075
A103A49011 ES 21OCT97	TA21 17.5 IDW Monitoring EF 5JUN98 LS 21FEB06 LF 28SEP06	OD	155	BC	1992
A103A49010 ES 21OCT97	TA21 17.5 IDW Mgt EF 12JUN98 LS 21FEB06 LF 28SEP06	OD	160	BC	0
A103A49005 ES 28OCT97	TA21 17.5 Document Locations Ph1 EF 28OCT97 LS 29DEC05 LF 29DEC05	OD	1	BC	1713
A103A49013 ES 8MAY98	TA21 17.5 Prepare IDW Disposal Documentation EF 29MAY98 LS 24AUG06 LF 14SEP06	OD	15	BC	8160
A103A49014 ES 1JUN98	TA21 17.5 IDW Disposal EF 12JUN98 LS 15SEP06 LF 28SEP06	OD	10	BC	12149
A103A49007 ES 8JUN98	TA21 17.5 Data Quality Assurance Ph1 EF 12JUN98 LS 21DEC05 LF 29DEC05	OD	5	BC	1755
A103A49009 ES 15JUN98	TA21 17.5 Data Assessment Ph1 EF 20JUL98 LS 30DEC05 LF 6FEB06	OD	25	BC	27912
A103A49015 ES 21JUL98	TA21 17.5 Risk Assessment EF 10AUG98 LS 7FEB06 LF 28FEB06	OD	15	BC	19524
A104A49001 ES 21JUL98	TA21 17.5 RFI Report Prep. Ph1 EF 15SEP98 LS 7FEB06 LF 4APR06	OD	40	BC	0
A103A49016 ES 11AUG98	TA21 17.5 Decision Analysis EF 17AUG98 LS 1MAR06 LF 7MAR06	OD	5	BC	7849
A104A49005 ES 18AUG98	TA21 17.5 Dev. Ph2 DQOs EF 19AUG98 LS 8MAR06 LF 9MAR06	OD	2	BC	928
A104A49004 ES 18AUG98	TA21 17.5 Write RFI Report EF 15SEP98 LS 8MAR06 LF 4APR06	OD	20	BC	42454
A103A49020	TA21 17.5 RFI FIELD WORK COMPLETE PH1 EF 19AUG98 LF 3JAN95	OD	0	BC	0
A103A49017 ES 20AUG98	TA21 17.5 Dev. Ph2 Sampling Approach EF 24AUG98 LS 10MAR06 LF 14MAR06	OD	3	BC	1486
A103A49018 ES 25AUG98	TA21 17.5 Write Ph2 Sampling Plan EF 15SEP98 LS 15MAR06 LF 4APR06	OD	15	BC	10886
A104A49008 ES 16SEP98	TA21 17.5 LANL/DOE Review Ph1 EF 14OCT98 LS 5APR06 LF 2MAY06	OD	20	BC	1534
A104A49009 ES 15OCT98	TA21 17.5 Incl. LANL/DOE Comments Ph1 EF 12NOV98 LS 3MAY06 LF 31MAY06	OD	20	BC	22061
A104A49010 ES 13NOV98	TA21 17.5 Issue EPA Draft Ph1 EF 30NOV98 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A104A49011	TA21 17.5 EPA Draft Complete Ph1 EF 30NOV98 LF 14JUN06	OD	0	BC	0
A104A49012 ES 1DEC98	TA21 17.5 EPA Review Ph1 EF 4FEB99 LS 15JUN06 LF 16AUG06	OD	44	BC	793
A104A49013 ES 5FEB99	TA21 17.5 Incl. EPA Comments Ph1 EF 5MAR99 LS 17AUG06 LF 14SEP06	OD	20	BC	22061
A104A49014 ES 8MAR99	TA21 17.5 Issue Final Rpt./WP Mod. Ph1 EF 19MAR99 LS 15SEP06 LF 28SEP06	OD	10	BC	1922



A104A50012 ES 30CT94	TA21 17.5 START AFI REPORT Ph2 LS 29SEP06		SM OD	0	BC	0
A103A50002 ES 5MAY99	TA21 17.5 Drill/Sample Ph2 EF 28MAY99 LS 22APR05	LF 17MAY05	OD	18	BC	104898
A103A50003 ES 5MAY99	TA21 17.5 Field Analysis Ph2 EF 28MAY99 LS 2DEC05	LF 29DEC05	OD	18	BC	36000
A103A50005 ES 5MAY99	TA21 17.5 Laboratory Analysis Ph2 EF 7DEC99 LS 22APR05	LF 22NOV05	OD	148	BC	205455
A103A50011 ES 5MAY99	TA21 17.5 IDW Char. Analysis EF 7DEC99 LS 25JAN06	LF 23AUG06	OD	148	BC	6320
A103A50007 ES 5MAY99	TA21 17.5 Data Tracking Ph2 EF 7JAN00 LS 29APR05	LF 29DEC05	OD	168	BC	12528
A103A50010 ES 5MAY99	TA21 17.5 IDW Monitoring EF 7JAN00 LS 1FEB06	LF 28SEP06	OD	168	BC	1774
A103A50009 ES 5MAY99	TA21 17.5 IDW Mgt EF 14JAN00 LS 1FEB06	LF 28SEP06	OD	173	BC	0
A103A50001 ES 5MAY99	TA21 Ph2 Subs. Agg. 17.5: 21-022a/f EF 13OCT00 LS 22APR05	LF 28SEP06	OD	362	BC	0
A103A50004 ES 1JUN99	TA21 17.5 Document Locations Ph2 EF 1JUN99 LS 29DEC05	LF 29DEC05	OD	1	BC	1713
A103A50012 ES 8DEC99	TA21 17.5 Prepare IDW Disposal Documentation EF 30DEC99 LS 24AUG06	LF 14SEP06	OD	15	BC	8160
A103A50013 ES 3JAN00	TA21 17.5 IDW Disposal EF 14JAN00 LS 15SEP06	LF 28SEP06	OD	10	BC	12149
A103A50006 ES 10JAN00	TA21 17.5 Data Quality Assurance Ph2 EF 14JAN00 LS 21DEC05	LF 29DEC05	OD	5	BC	1880
A103A50008 ES 18JAN00	TA21 17.5 Data Assessment Ph2 EF 22FEB00 LS 30DEC05	LF 6FEB06	OD	25	BC	27912
A103A50014 ES 23FEB00	TA21 17.5 Risk Assessment EF 14MAR00 LS 7FEB06	LF 28FEB06	OD	15	BC	19524
A104A50001 ES 23FEB00	TA21 17.5 AFI Report Prep. Ph2 EF 18APR00 LS 7FEB06	LF 4APR06	OD	40	BC	0
A103A50015 ES 15MAR00	TA21 17.5 Decision Analysis EF 21MAR00 LS 1MAR06	LF 7MAR06	OD	5	BC	7849
A103A50020	TA21 17.5 AFI FIELD WORK COMPLETE PH2 EF 21MAR00	LF 3JAN95	OD	0	BC	0
A104A50004 ES 22MAR00	TA21 17.5 Write AFI Report EF 18APR00 LS 8MAR06	LF 4APR06	OD	20	BC	42454
A104A50005 ES 19APR00	TA21 17.5 LANL/DOE Review Ph2 EF 16MAY00 LS 5APR06	LF 2MAY06	OD	20	BC	1534
A104A50006 ES 17MAY00	TA21 17.5 Incl. LANL/DOE Comments Ph2 EF 14JUN00 LS 3MAY06	LF 31MAY06	OD	20	BC	22061
A104A50007 ES 15JUN00	TA21 17.5 Issue EPA Draft Ph2 EF 28JUN00 LS 1JUN06	LF 14JUN06	OD	10	BC	4257
A104A50008	TA21 17.5 EPA Draft Complete Ph2 EF 28JUN00	LF 14JUN06	OD	0	BC	0
A104A50009 ES 29JUN00	TA21 17.5 EPA Review Ph2 EF 30AUG00 LS 15JUN06	LF 16AUG06	OD	44	BC	793
A104A50010 ES 31AUG00	TA21 17.5 Incl. EPA Comments Ph2 EF 28SEP00 LS 17AUG06	LF 14SEP06	OD	20	BC	22061
A104A50011 ES 29SEP00	TA21 17.5 Issue Final Rpt./WP Mod. Ph2 EF 13OCT00 LS 15SEP06	LF 28SEP06	OD	10	BC	1922
A103A51017	TA21 17.6 AFI FIELD WORK COMPLETE EF 30SEP94	LF 28SEP06	OD	0	BC	0
A103A51002 ES 7APR99	TA21 17.6 Identify Locations Ph1 EF 8APR99 LS 26APR05	LF 27APR05	OD	2	BC	3426
A103A51001 ES 7APR99	TA21 Ph1 Subs. Agg. 17.6: 21-005 EF 26JUL00 LS 26APR05	LF 28SEP06	OD	327	BC	0
A103A51003 ES 9APR99	TA21 17.6 Drill/Sample Ph1 EF 9APR99 LS 28APR05	LF 28APR05	OD	1	BC	3550
A103A51004 ES 9APR99	TA21 17.6 Field Analysis Ph1 EF 9APR99 LS 30JAN06	LF 30JAN06	OD	1	BC	2000
A103A51006 ES 9APR99	TA21 17.6 Laboratory Analysis Ph1 EF 14OCT99 LS 15JUN05	LF 20DEC05	OD	131	BC	15512
A103A51012 ES 9APR99	TA21 17.6 IDW Char. Analysis EF 14OCT99 LS 17FEB06	LF 23AUG06	OD	131	BC	1580
A103A51008 ES 9APR99	TA21 17.6 Data Tracking Ph1 EF 11NOV99 LS 22JUN05	LF 30JAN06	OD	151	BC	10982
A103A51011 ES 9APR99	TA21 17.6 IDW Monitoring EF 11NOV99 LS 27FEB06	LF 28SEP06	OD	151	BC	1554
A103A51010 ES 9APR99	TA21 17.6 IDW Mgt EF 19NOV99 LS 27FEB06	LF 28SEP06	OD	156	BC	0
A103A51005 ES 12APR99	TA21 17.6 Document Locations Ph1 EF 12APR99 LS 30JAN06	LF 30JAN06	OD	1	BC	1713



A103A51013	TA21 17.6 Prepare IDW Disposal Documentation					
ES 15OCT99	EF 4NOV99	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A51014	TA21 17.6 IDW Disposal					
ES 5NOV99	EF 19NOV99	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A51007	TA21 17.6 Data Quality Assurance Ph1					
ES 15NOV99	EF 19NOV99	LS 24JAN06	LF 30JAN06	OD 5	BC	1593
A103A51009	TA21 17.6 Data Assessment Ph1					
ES 22NOV99	EF 14DEC99	LS 31JAN06	LF 21FEB06	OD 15	BC	16746
A103A51015	TA21 17.6 Risk Assessment					
ES 15DEC99	EF 30DEC99	LS 22FEB06	LF 7MAR06	OD 10	BC	13022
A104A51001	TA21 17.6 RFI Report Prep. Ph1					
ES 15DEC99	EF 31JAN00	LS 22FEB06	LF 4APR06	OD 30	BC	0
A103A51016	TA21 17.6 Decision Analysis					
ES 3JAN00	EF 7JAN00	LS 8MAR06	LF 14MAR06	OD 5	BC	7849
A104A51004	TA21 17.6 Write RFI Report Ph1					
ES 10JAN00	EF 31JAN00	LS 15MAR06	LF 4APR06	OD 15	BC	31839
A104A51005	TA21 17.6 LANL/DOE Review Ph1					
ES 1FEB00	EF 29FEB00	LS 5APR06	LF 2MAY06	OD 20	BC	1534
A104A51006	TA21 17.6 Incl. LANL/DOE Comments Ph1					
ES 1MAR00	EF 28MAR00	LS 3MAY06	LF 31MAY06	OD 20	BC	22061
A104A51007	TA21 17.6 Issue EPA Draft Ph1					
ES 29MAR00	EF 11APR00	LS 1JUN06	LF 14JUN06	OD 10	BC	4257
A104A51008	TA21 17.6 EPA Draft Complete Ph1					
	EF 11APR00		LF 14JUN06	OD 0	BC	0
A104A51009	TA21 17.6 EPA Review Ph1					
ES 12APR00	EF 13JUN00	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A51010	TA21 17.6 Incl. EPA Comments Ph1					
ES 14JUN00	EF 12JUL00	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A51012	TA21 17.6 START RFI Rpt./WP Mod. Ph1					
ES 13JUL00		LS 15SEP06		OD 0	BC	1922
A104A51011	TA21 17.6 Issue Final Rpt./WP Mod. Ph1					
ES 13JUL00	EF 26JUL00	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A101A53020	TA21 D&D Verification Sampling Ph1					
ES 30CT94	EF 28SEP06	LS 30CT94	LF 28SEP06	OD 2987	BC	0
A103A53513	TA21 D&D Verification Soil Sampling					
ES 20CT95	EF 6OCT95	LS 21MAR06	LF 27MAR06	OD 5	BC	14396
A103A53514	TA21 D&D Field Analysis					
ES 20CT95	EF 6OCT95	LS 22SEP06	LF 28SEP06	OD 5	BC	10000
A103A53515	TA21 D&D Laboratory Analysis					
ES 20CT95	EF 18APR96	LS 21MAR06	LF 28SEP06	OD 135	BC	100660
A104A53013	TA21 D&D VERIFICATION Sampling Ph1					
ES 20CT95	EF 18APR96	LS 21MAR06	LF 28SEP06	OD 135	BC	100660
A103110667	TA21 18.2-7 Group					
ES 10CT96	EF 5OCT00	LS 26SEP02	LF 28SEP06	OD 1000	BC	0
A103A51501	TA21 Ph1 Subs. Agg. 18.2-7: See Note for SWMUs					
ES 10CT96	EF 5OCT00	LS 26SEP02	LF 28SEP06	OD 1000	BC	0
A103A51502	TA21 Ph1 Subs. Agg. 18.2-7: See Note for SWMUs					
ES 10CT96	EF 5OCT00	LS 26SEP02	LF 28SEP06	OD 1000	BC	5000000
A104A52012	TA21 18.8 START RFI REPORT Ph1			SM		
ES 30CT94		LS 15JUN06		OD 0	BC	0
A103A52002	TA21 18.8 Identify Locations Ph1					
ES 8APR99	EF 9APR99	LS 27APR05	LF 28APR05	OD 2	BC	3426
A103A52001	TA21 Ph1 Subs. Agg. 18.8: 21-022b-e/g					
ES 8APR99	EF 12SEP00	LS 27APR05	LF 28SEP06	OD 359	BC	0
A103A52003	TA21 18.8 Excavate/Sample Ph1					
ES 12APR99	EF 16APR99	LS 29APR05	LF 5MAY05	OD 5	BC	18065
A103A52005	TA21 18.8 Field Analysis Ph1					
ES 12APR99	EF 5MAY99	LS 2DEC05	LF 29DEC05	OD 18	BC	36000
A103A52007	TA21 18.8 Laboratory Analysis Ph1					
ES 12APR99	EF 9NOV99	LS 29APR05	LF 29NOV05	OD 148	BC	209535
A103A52013	TA21 18.8 IDW Char. Analysis					
ES 12APR99	EF 9NOV99	LS 25JAN06	LF 23AUG06	OD 148	BC	6320
A103A52009	TA21 18.8 Data Tracking Ph1					
ES 12APR99	EF 10DEC99	LS 29APR05	LF 29DEC05	OD 168	BC	12528
A103A52012	TA21 18.8 IDW Monitoring					
ES 12APR99	EF 10DEC99	LS 1FEB06	LF 28SEP06	OD 168	BC	1774
A103A52011	TA21 18.8 IDW Mgt					
ES 12APR99	EF 17DEC99	LS 1FEB06	LF 28SEP06	OD 173	BC	0
A103A52004	TA21 18.8 Drill/Sample Ph1					
ES 19APR99	EF 5MAY99	LS 12MAY05	LF 31MAY05	OD 13	BC	72722
A103A52006	TA21 18.8 Document Locations Ph1					
ES 6MAY99	EF 6MAY99	LS 29DEC05	LF 29DEC05	OD 1	BC	1713



A103A52008	TA21 18.8 Data Quality Assurance Ph1					
ES 10NOV99	EF 17NOV99	LS 21DEC05	LF 29DEC05	OD 5	BC	1880
A103A52014	TA21 18.8 Prepare IDW Disposal Documentation					
ES 10NOV99	EF 3DEC99	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A52015	TA21 18.8 IDW Disposal					
ES 6DEC99	EF 17DEC99	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A52010	TA21 18.8 Data Assessment Ph1					
ES 13DEC99	EF 20JAN00	LS 30DEC05	LF 6FEB06	OD 25	BC	27912
A103A52016	TA21 18.8 Risk Assessment					
ES 21JAN00	EF 10FEB00	LS 7FEB06	LF 28FEB06	OD 15	BC	19524
A104A52001	TA21 18.8 RFI Report Prep. Ph1					
ES 21JAN00	EF 17MAR00	LS 7FEB06	LF 4APR06	OD 40	BC	0
A103A52017	TA21 18.8 Decision Analysis					
ES 11FEB00	EF 17FEB00	LS 1MAR06	LF 7MAR06	OD 5	BC	7849
A103A52020	TA21 18.8 RFI FIELD WORK COMPLETE PH1					
	EF 17FEB00		LF 3JAN95	OD 0	BC	0
A104A52004	TA21 18.8 Write RFI Report					
ES 18FEB00	EF 17MAR00	LS 8MAR06	LF 4APR06	OD 20	BC	42454
A104A52005	TA21 18.8 LANL/DOE Review Ph1					
ES 20MAR00	EF 14APR00	LS 5APR06	LF 2MAY06	OD 20	BC	1534
A104A52006	TA21 18.8 Incl. LANL/DOE Comments Ph1					
ES 17APR00	EF 12MAY00	LS 3MAY06	LF 31MAY06	OD 20	BC	22061
A104A52007	TA21 18.8 Issue EPA Draft Ph1					
ES 15MAY00	EF 26MAY00	LS 1JUN06	LF 14JUN06	OD 10	BC	4257
A104A52008	TA21 18.8 EPA Draft Complete Ph1					
	EF 26MAY00		LF 14JUN06	OD 0	BC	0
A104A52009	TA21 18.8 EPA Review Ph1					
ES 30MAY00	EF 31JUL00	LS 15JUN06	LF 16AUG06	OD 44	BC	793
A104A52010	TA21 18.8 Incl. EPA Comments Ph1					
ES 1AUG00	EF 28AUG00	LS 17AUG06	LF 14SEP06	OD 20	BC	22061
A104A52011	TA21 18.8 Issue Final Rpt./WP Mod. Ph1					
ES 29AUG00	EF 12SEP00	LS 15SEP06	LF 28SEP06	OD 10	BC	1922
A103A53017	TA21 18.9 RFI FIELD WORK COMPLETE FM 1					
	EF 30SEP94		LF 14JUN06	OD 0	BC	0
A103A53016	TA21 18.8 START RFI FIELD WORK PH1					
ES 30CT94		LS 29SEP06		OD 0	BC	0
A104A53016	TA21 18.9 START RFI REPORT Ph1			SM		
ES 30CT94		LS 29SEP06		OD 0	BC	0
A103A53002	TA21 18.9 Drill/Sample Ph1					
ES 7MAY99	EF 13MAY99	LS 2JUN05	LF 8JUN05	OD 5	BC	28377
A103A53003	TA21 18.9 Field Analysis Ph1					
ES 7MAY99	EF 13MAY99	LS 17JAN06	LF 23JAN06	OD 5	BC	10000
A103A53005	TA21 18.9 Laboratory Analysis Ph1					
ES 7MAY99	EF 18NOV99	LS 2JUN05	LF 13DEC05	OD 135	BC	86945
A103A53011	TA21 18.9 IDW Char. Analysis					
ES 7MAY99	EF 18NOV99	LS 13FEB06	LF 23AUG06	OD 135	BC	3160
A103A53007	TA21 18.9 Data Tracking Ph1					
ES 7MAY99	EF 20DEC99	LS 9JUN05	LF 23JAN06	OD 155	BC	14075
A103A53010	TA21 18.9 IDW Monitoring					
ES 7MAY99	EF 20DEC99	LS 21FEB06	LF 28SEP06	OD 155	BC	1992
A103A53009	TA21 18.9 IDW Mgt					
ES 7MAY99	EF 29DEC99	LS 21FEB06	LF 28SEP06	OD 160	BC	0
A103A53001	TA21 Ph1 Subs. Agg. 18.9: 21-022h-j					
ES 7MAY99	EF 6SEP00	LS 2JUN05	LF 28SEP06	OD 334	BC	0
A103A53004	TA21 18.9 Document Locations Ph1					
ES 14MAY99	EF 14MAY99	LS 23JAN06	LF 23JAN06	OD 1	BC	1713
A103A53012	TA21 18.9 Prepare IDW Disposal Documentation					
ES 19NOV99	EF 13DEC99	LS 24AUG06	LF 14SEP06	OD 15	BC	8160
A103A53013	TA21 18.9 IDW Disposal					
ES 14DEC99	EF 29DEC99	LS 15SEP06	LF 28SEP06	OD 10	BC	12149
A103A53006	TA21 18.9 Data Quality Assurance Ph1					
ES 21DEC99	EF 29DEC99	LS 17JAN06	LF 23JAN06	OD 5	BC	1971
A103A53008	TA21 18.9 Data Assessment Ph1					
ES 30DEC99	EF 28JAN00	LS 24JAN06	LF 21FEB06	OD 20	BC	22331
A103A53014	TA21 18.9 Risk Assessment					
ES 31JAN00	EF 11FEB00	LS 22FEB06	LF 7MAR06	OD 10	BC	13022
A104A53001	TA21 18.9 RFI Report Prep. Ph1					
ES 31JAN00	EF 13MAR00	LS 22FEB06	LF 4APR06	OD 30	BC	0
A103A53015	TA21 18.9 Decision Analysis					
ES 14FEB00	EF 18FEB00	LS 8MAR06	LF 14MAR06	OD 5	BC	7849
A104A53004	TA21 18.9 Write RFI Report					
ES 22FEB00	EF 13MAR00	LS 15MAR06	LF 4APR06	OD 15	BC	31839
A104A53005	TA21 18.9 LANL/DOE Review Ph1					
ES 14MAR00	EF 10APR00	LS 5APR06	LF 2MAY06	OD 20	BC	1534



A104A53006 ES 11APR00	TA21 18.9 Incl. LANL/DOE Comments Ph1 EF 8MAY00 LS 3MAY06 LF 31MAY06	OD	20	BC	22061
A104A53007 ES 9MAY00	TA21 18.9 Issue EPA Draft Ph1 EF 22MAY00 LS 1JUN06 LF 14JUN06	OD	10	BC	4257
A104A53008	TA21 18.9 EPA Draft Complete Ph1 EF 22MAY00 LF 14JUN06	OD	0	BC	0
A104A53009 ES 23MAY00	TA21 18.9 EPA Review Ph1 EF 25JUL00 LS 15JUN06 LF 16AUG06	OD	44	BC	793
A104A53010 ES 26JUL00	TA21 18.9 Incl. EPA Comments Ph1 EF 22AUG00 LS 17AUG06 LF 14SEP06	OD	20	BC	22061
A104A53011 ES 23AUG00	TA21 18.9 Issue Final Rpt./WP Mod. Ph1 EF 6SEP00 LS 15SEP06 LF 28SEP06	OD	10	BC	1922
A103110670 ES 1FEB95	TA21 Subcontract FY95 EF 13APR95 LS 15FEB95 LF 27APR95	OD	51	BC	85115
A102110610 ES 1FEB95	TA21 FY95 Subs. Subcont/Mobilize EF 5MAY95 LS 15FEB95 LF 19MAY95	OD	67	BC	0
A103110671 ES 31MAR95	TA21 Write SSHASP FY95 EF 13APR95 LS 15SEP06 LF 28SEP06	OD	10	BC	11338
A103110672 ES 7APR95	TA21 Write SSWMP FY95 EF 13APR95 LS 21APR95 LF 27APR95	OD	5	BC	7082
A103110673 ES 7APR95	TA21 Write Field Imp. Plan FY95 EF 13APR95 LS 22SEP06 LF 28SEP06	OD	5	BC	5137
A103110674 ES 14APR95	TA21 Training FY95 EF 20APR95 LS 28APR95 LF 4MAY95	OD	5	BC	19603
A103110675 ES 21APR95	TA21 Readiness Review FY95 EF 24APR95 LS 5MAY95 LF 8MAY95	OD	2	BC	1776
A103110676 ES 21APR95	TA21 Drill Rig Mobilization FY95 EF 5MAY95 LS 5MAY95 LF 19MAY95	OD	11	BC	28500
A103110677 ES 1FEB96	TA21 Subcontract FY96 EF 14MAR96 LS 5MAR97 LF 15APR97	OD	30	BC	7419
A102110617 ES 1FEB96	TA21 FY96 Surf./Subs. Subcont/Mob EF 5APR96 LS 5MAR97 LF 7MAY97	OD	46	BC	0
A103110678 ES 1MAR96	TA21 Write SSHASP FY96 EF 14MAR96 LS 15SEP06 LF 28SEP06	OD	10	BC	11338
A103110679 ES 8MAR96	TA21 Write SSWMP FY96 EF 14MAR96 LS 9APR97 LF 15APR97	OD	5	BC	7082
A103110680 ES 8MAR96	TA21 Write Field Imp. Plan FY96 EF 14MAR96 LS 22SEP06 LF 28SEP06	OD	5	BC	5137
A103110681 ES 15MAR96	TA21 Training FY96 EF 21MAR96 LS 16APR97 LF 22APR97	OD	5	BC	19603
A103110682 ES 22MAR96	TA21 Readiness Review FY96 EF 25MAR96 LS 23APR97 LF 24APR97	OD	2	BC	1776
A103110683 ES 22MAR96	TA21 Drill Rig Mobilization FY96 EF 5APR96 LS 23APR97 LF 7MAY97	OD	11	BC	7000
A103110684 ES 3FEB97	TA21 Subcontract FY97 EF 25APR97 LS 1MAY98 LF 24JUL98	OD	59	BC	14587
A102110624 ES 3FEB97	TA21 FY97 Subs. Subcont/Mobilize EF 16MAY97 LS 1MAY98 LF 14AUG98	OD	74	BC	0
A103110685 ES 14APR97	TA21 Write SSHASP FY97 EF 25APR97 LS 15SEP06 LF 28SEP06	OD	10	BC	11338
A103110686 ES 21APR97	TA21 Write SSWMP FY97 EF 25APR97 LS 20JUL98 LF 24JUL98	OD	5	BC	7082
A103110687 ES 21APR97	TA21 Write Field Imp. Plan FY97 EF 25APR97 LS 22SEP06 LF 28SEP06	OD	5	BC	5137
A103110688 ES 28APR97	TA21 Training FY97 EF 2MAY97 LS 27JUL98 LF 31JUL98	OD	5	BC	19603
A103110689 ES 5MAY97	TA21 Readiness Review FY97 EF 6MAY97 LS 3AUG98 LF 4AUG98	OD	2	BC	1776
A103110690 ES 5MAY97	TA21 Drill Rig Mobilization FY97 EF 16MAY97 LS 3AUG98 LF 14AUG98	OD	10	BC	7000
A103110691 ES 2FEB98	TA21 Subcontract FY98 EF 15APR98 LS 21OCT04 LF 10JAN05	OD	52	BC	12862
A102110631 ES 2FEB98	TA21 FY 98 Subs. Subcont/Mobilize EF 7MAY98 LS 21OCT04 LF 2FEB05	OD	68	BC	0
A103110692 ES 2APR98	TA21 Write SSHASP FY98 EF 15APR98 LS 15SEP06 LF 28SEP06	OD	10	BC	11338
A103110693 ES 9APR98	TA21 Write SSWMP FY98 EF 15APR98 LS 4JAN05 LF 10JAN05	OD	5	BC	7082
A103110694 ES 9APR98	TA21 Write Field Imp. Plan FY98 EF 15APR98 LS 22SEP06 LF 28SEP06	OD	5	BC	5137
A103110695 ES 16APR98	TA21 Training FY98 EF 22APR98 LS 11JAN05 LF 18JAN05	OD	5	BC	19603
A103110696 ES 23APR98	TA21 Readiness Review FY98 EF 24APR98 LS 19JAN05 LF 20JAN05	OD	2	BC	1776



Mobilization							
A103110697	TA21 Drill Rig Mobilization FY98						
ES 23APR98	EF 7MAY98	LS 19JAN05	LF 2FEB05	OD 11	BC	7000	
A103110698	TA21 Subcontract FY99						
ES 1FEB99	EF 15MAR99	LS 19JAN05	LF 2MAR05	OD 30	BC	7419	
A102110638	TA21 FY99 Subs. Subcont/Mobilize						
ES 1FEB99	EF 6APR99	LS 19JAN05	LF 24MAR05	OD 46	BC	0	
A103110699	TA21 Write SSHASP FY99						
ES 2MAR99	EF 15MAR99	LS 15SEP06	LF 28SEP06	OD 10	BC	11338	
A103110601	TA21 Write SSWMP FY99						
ES 9MAR99	EF 15MAR99	LS 24FEB05	LF 2MAR05	OD 5	BC	7050	
A103110602	TA21 Write Field Imp. Plan FY99						
ES 9MAR99	EF 15MAR99	LS 22SEP06	LF 28SEP06	OD 5	BC	5137	
A103110603	TA21 Training FY99						
ES 16MAR99	EF 22MAR99	LS 3MAR05	LF 9MAR05	OD 5	BC	19603	
A103110604	TA21 Readiness Review FY99						
ES 23MAR99	EF 24MAR99	LS 10MAR05	LF 11MAR05	OD 2	BC	1776	
A103110605	TA21 Drill Rig Mobilization FY99						
ES 23MAR99	EF 6APR99	LS 10MAR05	LF 24MAR05	OD 11	BC	7000	
A103110606	TA21 Subcontract FY00						
ES 1FEB00	EF 13APR00	LS 23JUN06	LF 6SEP06	OD 52	BC	12862	
A102110645	TA21 FY00 Subs. Subcont/Mobilize						
ES 1FEB00	EF 5MAY00	LS 23JUN06	LF 28SEP06	OD 68	BC	0	
A103110607	TA21 Write SSHASP FY00						
ES 31MAR00	EF 13APR00	LS 15SEP06	LF 28SEP06	OD 10	BC	11338	
A103110609	TA21 Write SSWMP FY00						
ES 7APR00	EF 13APR00	LS 30AUG06	LF 6SEP06	OD 5	BC	7082	
A103110610	TA21 Write Field Imp. Plan FY00						
ES 7APR00	EF 13APR00	LS 22SEP06	LF 28SEP06	OD 5	BC	5137	
A103110611	TA21 Training FY00						
ES 14APR00	EF 20APR00	LS 7SEP06	LF 13SEP06	OD 5	BC	19603	
A103110613	TA21 Readiness Review FY00						
ES 21APR00	EF 24APR00	LS 14SEP06	LF 15SEP06	OD 2	BC	1776	
A103110615	TA21 Drill Rig Mobilization FY00						
ES 21APR00	EF 5MAY00	LS 14SEP06	LF 28SEP06	OD 11	BC	7000	
D&D Work Plan Modification							
A102110602	TA21 D&D WP Mod. Ph1						
ES 20CT95	EF 7DEC95	LS 15MAR06	LF 16MAY06	OD 45	BC	43633	
A102110660	TA21 RFI Work Plan (D&D Mod.)						
ES 20CT95	EF 24APR96	LS 15MAR06	LF 28SEP06	OD 139	BC	0	
A102110603	TA21 LANL Review D&D WP Mod. Ph1						
ES 8DEC95	EF 21DEC95	LS 17MAY06	LF 31MAY06	OD 10	BC	768	
A102110604	TA21 Incl. LANL Comments D&D WP Mod. Ph1						
ES 22DEC95	EF 9JAN96	LS 1JUN06	LF 14JUN06	OD 10	BC	11031	
A102110605	TA21 D&D WP Mod. Issue EPA Draft Ph1						
ES 10JAN96	EF 24JAN96	LS 15JUN06	LF 28JUN06	OD 10	BC	4257	
A102110606	TA21 DELIVER D&D WP Mod. to EPA Ph1						
	EF 24JAN96		LF 28JUN06	OD 0	BC	0	
A102110607	TA21 EPA Review D&D WP Mod. Ph1						
ES 25JAN96	EF 27MAR96	LS 29JUN06	LF 30AUG06	OD 44	BC	793	
A102110608	TA21 Incl. EPA/NMED Comment D&D WP Ph1						
ES 28MAR96	EF 10APR96	LS 31AUG06	LF 14SEP06	OD 10	BC	3395	
A102110609	TA21 Issue Final D&D WP Mod. Ph1						
ES 11APR96	EF 24APR96	LS 15SEP06	LF 28SEP06	OD 10	BC	1922	
Bench Pilot Studies							
A106110604	TA21 11.2 MDA B Data Eval. FY95						
ES 3JAN95	EF 3MAY95	LS 31MAY06	LF 28SEP06	OD 85	BC	38973	
A106110602	TA21 11.2 Pilot Studies FY95						
ES 3JAN95	EF 29SEP95	LS 3JAN02	LF 28SEP06	OD 189	BC	0	
A106110603	TA21 11.2 MDA B Pilot Study FY95						
ES 3JAN95	EF 29SEP95	LS 3JAN02	LF 10CT02	OD 189	BC	113501	
A106110605	TA21 11.2 Risk Based Cover Design FY95						
ES 3JAN95	EF 29SEP95	LS 30DEC05	LF 28SEP06	OD 189	BC	34326	
A106110606	TA21 11.2 MDA V Cover Design FY95						
ES 3JAN95	EF 29SEP95	LS 30DEC05	LF 28SEP06	OD 189	BC	0	
A106110607	TA21 11.2 21-027a Soil Washing FY95						
ES 3JAN95	EF 29SEP95	LS 30DEC05	LF 28SEP06	OD 189	BC	95566	
A106110608	TA21 11.2 21-011k Stabilization FY95						
ES 3JAN95	EF 29SEP95	LS 30DEC05	LF 28SEP06	OD 189	BC	95566	
A105110602	Bench Pilot Studies						
ES 3JAN95	EF 30SEP99	LS 3JAN02	LF 28SEP06	OD 1185	BC	0	
A106110609	TA21 11.2 Pilot Studies FY96						
ES 20CT95	EF 30SEP96	LS 20CT02	LF 28SEP06	OD 249	BC	0	
A106110610	TA21 11.2 MDA B Pilot Study FY96						
ES 20CT95	EF 30SEP96	LS 20CT02	LF 10CT03	OD 249	BC	73402	



A106110611	TA21 11.2 MDA V Closure Plan FY96								
ES 20CT95	EF 30SEP96	LS 30CT05	LF 28SEP06	OD	249	BC	58160		
A106110612	TA21 11.2 Pilot Studies FY97								
ES 10CT96	EF 30SEP97	LS 20CT03	LF 30SEP04	OD	249	BC	0		
A106110613	TA21 11.2 MDA B Pilot Study FY97								
ES 10CT96	EF 30SEP97	LS 20CT03	LF 30SEP04	OD	249	BC	73402		
A106110614	TA21 11.2 MDA V Closure Plan Implementation FY97								
ES 1APR97	EF 30SEP97	LS 1APR04	LF 30SEP04	OD	128	BC	42612		
A106110615	TA21 11.2 Pilot Studies FY98								
ES 10CT97	EF 30SEP98	LS 10CT04	LF 30SEP05	OD	249	BC	0		
A106110616	TA21 11.2 MDA B Pilot Study FY98								
ES 10CT97	EF 30SEP98	LS 10CT04	LF 30SEP05	OD	249	BC	73402		
A106110617	TA21 11.2 MDA V Closure Plan Implementation FY98								
ES 10CT97	EF 30SEP98	LS 10CT04	LF 30SEP05	OD	249	BC	73212		
A106110618	TA21 11.2 MDA B Pilot Study FY99								
ES 10CT98	EF 30SEP99	LS 30CT05	LF 28SEP06	OD	249	BC	73402		
A105110654	TA21 CMS								
ES 3JAN95	EF 28SEP06	LS 3JAN02	LF 28SEP06	OD	2928	BC	0		
A106110650	TA21 Start CMS Plan								
ES 20CT00		LS 30CT05		OD	0	BC	796129		
A106110652	TA21 CMS Plan								
ES 20CT00	EF 10CT01	LS 30CT05	LF 28SEP06	OD	249	BC	796129		
A111110674	TA21 CM Implementation								
ES 10CT01	EF 28SEP06	LS 10CT01	LF 28SEP06	OD	1246	BC	3715189		
A107110673	TA21 CMS Report								
ES 10CT02	EF 29SEP03	LS 4OCT05	LF 28SEP06	OD	248	BC	812940		
A104A39013	TA21 16.7 21-018b Research								
ES 1MAR95	EF 2MAY95	LS 24FEB06	LF 27APR06	OD	45	BC	5725		
A104A39014	TA21 16.7 RFI Report Prep. Ph1								
ES 3MAY95	EF 3MAY95	LS 16MAY06	LF 16MAY06	OD	1	BC	0		
A104A39015	TA21 16.7 Risk Assessment								
ES 3MAY95	EF 4MAY95	LS 28APR06	LF 1MAY06	OD	2	BC	2757		
A104A39016	TA21 16.7 Decision Analysis								
ES 5MAY95	EF 5MAY95	LS 2MAY06	LF 2MAY06	OD	1	BC	1590		
A104A39017	TA21 16.7 Write RFI Report								
ES 8MAY95	EF 19MAY95	LS 3MAY06	LF 16MAY06	OD	10	BC	13432		
A104A39018	TA21 16.7 LANL/DOE Review Ph1								
ES 22MAY95	EF 19JUN95	LS 17MAY06	LF 14JUN06	OD	20	BC	1534		
A104A39019	TA21 16.7 Incl. LANL/DOE Comments Ph1								
ES 20JUN95	EF 26JUN95	LS 15JUN06	LF 21JUN06	OD	5	BC	5582		
A104A39020	TA21 16.7 Issue EPA Draft Ph1								
ES 27JUN95	EF 11JUL95	LS 22JUN06	LF 6JUL06	OD	10	BC	4257		
A104A39021	TA21 16.7 EPA Draft Complete Ph1								
	EF 11JUL95		LF 28SEP06	OD	0	BC	0		
A104A39022	TA21 16.7 EPA Review Ph1								
ES 12JUL95	EF 12SEP95	LS 7JUL06	LF 7SEP06	OD	44	BC	793		
A104A39023	TA21 16.7 Incl. EPA Comments Ph1								
ES 13SEP95	EF 19SEP95	LS 8SEP06	LF 14SEP06	OD	5	BC	5582		
A104A39024	TA21 16.7 Issue Final Rpt./WP Mod. Ph1								
ES 20SEP95	EF 30CT95	LS 15SEP06	LF 28SEP06	OD	10	BC	1922