

FEB 28 2006

<p><b>SEND COMPLETED FORM TO:</b></p> <p>The Appropriate State or EPA Regional Office</p>	<p>United States Environmental Protection Agency  <b>ENTERED</b></p> <p><b>RCRA SUBTITLE C SITE IDENTIFICATION FORM (2007)</b></p>
<p><b>1. Reason for Submittal</b></p> <p>MARK ALL BOX(ES) THAT APPLY</p>	<p><b>Reason for Submittal:</b></p> <p><input type="checkbox"/> To provide initial Notification of Regulated Waste Activity (to obtain an EPA ID Number for hazardous waste, Universal waste, or used oil activities).</p> <p><input type="checkbox"/> To provide Subsequent Notification of Regulated Waste Activity (to update site identification information).</p> <p><input type="checkbox"/> As a component of a First RCRA Hazardous Waste Part A Permit Application.</p> <p><input type="checkbox"/> As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment # _____)</p> <p><input checked="" type="checkbox"/> As a component of the Hazardous Waste Report.</p>
<p><b>2. Site EPA ID Number</b></p>	<p>EPA ID Number: <b>NMD002208627</b></p>
<p><b>3. Site Name</b></p>	<p>Name: <b>RINCHEM COMPANY INC.,</b></p>
<p><b>4. Site Location Information</b></p>	<p>Street Address: <b>6133 EDITH BLVD NE</b></p> <p>City, Town, or Village: <b>ALBUQUERQUE</b> State: <b>NM</b></p> <p>County Name: <b>BERNALILLO</b> Zip Code: <b>87107</b></p>
<p><b>5. Site Land Type</b></p>	<p>Site Land Type:</p> <p><input checked="" type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other</p>
<p><b>6. NAICS Code(s) for the Site</b></p>	<p>A. <b>562998</b> B. C. D.</p>
<p><b>7. Site Mailing Address</b></p>	<p>Street or P. O. Box: <b>6133 EDITH BLVD NE</b></p> <p>City, Town, or Village: <b>ALBUQUERQUE</b> State: <b>NM</b></p> <p>Country: <b>UNITED STATES</b> Zip Code: <b>87107</b></p>
<p><b>8. Site Contact Person</b></p>	<p>First Name: <b>POLLY</b> MI: <b>J</b> Last Name: <b>WAGNER</b></p> <p>Phone Number: <b>9984143</b> Extension:</p> <p>Email Address: <b>pwagner@rinchem.com</b></p>
<p><b>9. Operator and Legal Owner of the Site</b></p>	<p>A. Name of Site's Operator: <b>WILLIAM W MOORE</b> Date Became Operator: <b>7/30/1976</b></p> <p>Operator Type:</p> <p><input checked="" type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other</p>
	<p>B. Name of Site's Legal Owner: <b>WILLIAM W MOORE</b> Date Became Owner: <b>7/30/1970</b></p> <p>Owner Type:</p> <p><input checked="" type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other</p>

9. Legal Owner Address (continued)	Street or P. O. Box: 6133 EDITH BLVD NE	
	City: ALBUQUERQUE	State: NM
	Country: UNITED STATES	Zip Code: 87107

10. Type of Regulated Waste Activity  
Mark Yes or No for all activities; complete any additional boxes as instructed.

A. Hazardous Waste Activities

Complete all parts for 1 through 6.

1. Generator of Hazardous Waste

If Yes, choose only one of the following - a, b, or c.

- a. LQG: Greater than 1,000 kg/mo (2,200 lbs./mo.) of non-acute hazardous waste; or
- b. SQG: 100 to 1,000 kg/mo (220 - 2,200 lbs./mo.) of non-acute hazardous waste; or
- c. CESQG: Less than 100 kg/mo (220 lbs./mo.) of non-acute hazardous waste

In addition, indicate other generator activities.

d. United States Importer of Hazardous Waste

e. Mixed Waste (hazardous and radioactive) Generator

2. Transporter of Hazardous Waste

3. Treater, Storer, or Disposer of Hazardous Waste (at your site)

Note: A hazardous waste permit is required for this activity.

4. Recycler of Hazardous Waste (at your site)

5. Exempt Boiler and/or Industrial Furnace

If Yes, mark each that applies.

- a. Small Quantity On-site Burner Exemption
- b. Smelting, Melting, and Refining Furnace

6. Underground Injection Control

B. Universal Waste Activities

1. Large Quantity Handler of Universal Waste (accumulate 5,000 kg or more) [refer to your State regulations to determine what is regulated]. Indicate types of universal waste that apply:

Generate      Managed

- a. Batteries
- b. Pesticides
- c. Mercury containing equipment
- d. Lamps
- e. Other (specify)
- f. Other (specify)
- g. Other (specify)

2. Destination Facility for Universal Waste

Note: A hazardous waste permit may be required for this activity.

C. Used Oil Activities

Mark all boxes that apply

1. Used Oil Transporter  
If Yes, mark each that applies.

- a. Transporter
- b. Transfer Facility

2. Used Oil Processor and/or Re-refiner  
If Yes, mark each that applies.

- a. Processor
- b. Re-refiner

3. Off-Specification Used Oil Burner

4. Used Oil Fuel Marketer

If Yes, mark each that applies.

- a. Marketer Who Directs Shipment of Off-Specification Used Oil to Off-Specification Used Oil Burner
- b. Marketer Who First Claims the Used Oil Meets the Specifications

11. Description of Hazardous Wastes

**A. Waste Codes for Federally Regulated Hazardous Wastes.**

Please list the waste codes of the Federal hazardous wastes handled at your site. List them in the order they are presented in the regulations (e.g., D001, D003, F007, U112). Use an additional page if more spaces are needed.

D001 D002 D003 D004 D005 D006 D007 D008 D009 D010 D011 D012 D013 D014 D015 D016 D017 D018 D019 D020 D021 D022  
 D023 D024 D025 D026 D027 D028 D029 D030 D031 D032 D033 D034 D035 D036 D037 D038 D039 D040 D041 D042 D043 F001  
 F002 F003 F005 F008 F037 K050 K051 K171 LABP P021 P022 P030 P039 P042 P044 P050 P089 P098 P105 P106 P127 U001  
 U002 U003 U007 U012 U044 U056 U057 U072 U077 U122 U123 U124 U133 U134 U135 U138 U144 U154 U159 U165 U185 U188  
 U196 U201 U211 U213 U219 U220 U223 U239 U246 U279


**B. Waste Codes for State-Regulated (i.e., non-Federal) Hazardous Wastes.**

Please list the waste codes of the State-regulated hazardous wastes handled at your site. List them in the order they are presented in the regulations. Use an additional page if more spaces are needed for waste codes.

12. Comments

13. Certification

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature of Operator, Owner, or an Authorized Representative	Name and Official Title (type or print)	Date Signed (mm/dd/yyyy)
	LISE V. GORGONE, VICE PRESIDENT OF OPERATIONS	02/18/2008

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description FLAMMABLE LIQUIDS, PAINTS AND SOLVENTS		
	B. EPA hazardous waste code D001 D004 D007 D008 D011 D018 D019 D026 D028 D035 F001 F002 F003 F005		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	KSD980633259	H061	391427.0
<b>SITE 2</b>	COD980591184	H141	796.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CHROME TANK SLUDGE		
B. EPA hazardous waste code D007 D008		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25		E. Form code W609	F. Quantity generated in 2007  0.0
		G. UOM 1	Density └─ 1 lbs/gal └─ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H132	2145.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

**US ENVIRONMENTAL  
PROTECTION AGENCY**  
2007 HAZARDOUS WASTE REPORT  
**WASTE GENERATION AND  
MANAGEMENT**

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description GRAPHITE PLATTERS WITH ARSENIC		
	B. EPA hazardous waste code D004	C. State hazardous waste code	
D. Source code G61	E. Form code W319	F. Quantity generated in 2007 0.0	G. UOM 1 Density 1 lbs/gal 2 sg
Management method code for source code G25			
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	1542.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description OIL REFINERY SLUDGE		
	B. EPA hazardous waste code K050		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W603	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	1925.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SPENT FILTERS		
B. EPA hazardous waste code D005 D006 D007 D008 D018 D035		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	8.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description LABORATORY SOLVENT CONTAMINATED DEBRIS		
B. EPA hazardous waste code F003		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25		E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	1460.0
<b>SITE 2</b>	COD980591184	H141	5853.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description GLYCOL W/BENZENE		
	B. EPA hazardous waste code D018		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density  <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	2748.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description DEBRIS CONTAMINATED WITH LEAD		
	B. EPA hazardous waste code D008		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	49446.0
<b>SITE 2</b>	UTD991301748	H132	16355.0
<b>SITE 3</b>	COD980591184	H141	217.0
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOIL CONTAMINATED WITH LEAD		
	B. EPA hazardous waste code D008		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W301	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	20720.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOLIDS CONTAINING FLAMMABLE LIQUIDS		
	B. EPA hazardous waste code D001 F003 F005		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	1873.0
<b>SITE 2</b>	COD980591184	H141	7982.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOIL CONTAMINATED WITH MERCURY CHROMIUM		
	B. EPA hazardous waste code D007 D009 F037		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W409	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	77354.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOIL CONTAMINATED WITH CHROMIUM AND ARSNIK		
	B. EPA hazardous waste code D004 D007		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W301	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	635.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CONTAMINATED SOIL		
B. EPA hazardous waste code D008 D018 F037		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W301	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	10449.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SODIUM HYDROXIDE, LEAD CONTAMINATED DEBRIS		
	B. EPA hazardous waste code D002 D008	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	637.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description LIME STRIPPER		
B. EPA hazardous waste code D002		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
ON-SITE PROCESS 1			
ON-SITE PROCESS 2			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
SITE 1	UTD981552177	H141	16.0
SITE 2			
SITE 3			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CALCIUM NITRATE		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	1062.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description HAZARDOUS LIQUID		
B. EPA hazardous waste code D005 D007 D008 D009 D010 D011		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	139.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description HAZARDOUS LIQUID		
	B. EPA hazardous waste code D011 D038 F002		C. State hazardous waste code
	D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	54.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ZINC CHROMATE PUTTY		
	B. EPA hazardous waste code D007	C. State hazardous waste code	
D. Source code G61	E. Form code W319	F. Quantity generated in 2007 0.0	G. UOM 1 Density 1 lbs/gal 2 sg
Management method code for source code G25			
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
		B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to
	D. Total Quantity Shipped in 2007		
<b>SITE 1</b>	UTD981552177	H040	6.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ADHESIVE		
B. EPA hazardous waste code D035		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W319	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	14.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ACID ETCH SOLUTION		
	B. EPA hazardous waste code D002 D004		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	3609.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description PHOTO FIXER		
	B. EPA hazardous waste code D002 D011		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	2977.0
<b>SITE 2</b>	COD980591184	H141	1014.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description USED LAPPING SLURRY		
B. EPA hazardous waste code D004		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	62.0
<b>SITE 2</b>	COD980591184	H141	512.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CORROSIVE LIQUID		
B. EPA hazardous waste code D002		C. State hazardous waste code	
D. Source code G61	E. Form code W119	F. Quantity generated in 2007 0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
Management method code for source code G25			
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	1810.0
<b>SITE 2</b>	COD980591184	H141	27329.0
<b>SITE 3</b>	AZD009015389	H141	4771.0
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description		
B. EPA hazardous waste code		C. State hazardous waste code	
D. Source code	E. Form code	F. Quantity generated in 2007	G. UOM      Density
Management method code for source code G25			<input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 3</b>			
<b>ON-SITE PROCESS 4</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 4</b>	AZD049318009	H141	41958.0
<b>SITE 5</b>			
<b>SITE 6</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description BLAST MEDIA		
B. EPA hazardous waste code D007 D008 D011		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	674.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ARSENIC CONTAMINATED DEBRIS		
	B. EPA hazardous waste code D004	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	648.0
<b>SITE 2</b>	AZD009015389	H141	515.0
<b>SITE 3</b>	COD980591184	H141	267.0
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CONTAMINATED DEBRIS		
B. EPA hazardous waste code D004 D005 D006 D007 D008 D010 D011		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	939.0
<b>SITE 2</b>	COD980591184	H141	285.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description HAZARDOUS LIQUID		
	B. EPA hazardous waste code D005 D006 D007 D010		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density  <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	76.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SILVER CONTAMINATED WATER		
	B. EPA hazardous waste code D011	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	880.0
<b>SITE 2</b>	COD980591184	H141	8070.0
<b>SITE 3</b>	AZD009015389	H141	3790.0
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description		
	B. EPA hazardous waste code		C. State hazardous waste code
	D. Source code  Management method code for source code G25	E. Form code	F. Quantity generated in 2007
		G. UOM	Density  ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
<b>ON-SITE PROCESS 3</b>			
<b>ON-SITE PROCESS 4</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 4</b>	AZD049318009	H141	5428.0
<b>SITE 5</b>			
<b>SITE 6</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**



US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description RADIATOR SLUDGE FILTER CAKE		
B. EPA hazardous waste code D008		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W609	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	13736.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SEPERATOR SLUDGE		
	B. EPA hazardous waste code K051		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W603	F. Quantity generated in 2007  0.0
		G. UOM 1	Density ↓ 1 lbs/gal   ↓ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	16260.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MERCURY CONTAMINATED DEBRIS		
	B. EPA hazardous waste code D009	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H141	12.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ACID CONTAMINATED DEBRIS		
	B. EPA hazardous waste code D007		C. State hazardous waste code
	D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	150.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CONTAMINATED RAGS		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	769.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CORROSIVE LIQUIDS		
B. EPA hazardous waste code D002 D007		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	1049.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOIL CONTAMINATED WITH GAS/DIESEL		
	B. EPA hazardous waste code D001 D018		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W301	F. Quantity generated in 2007 0.0
		G. UOM 1	Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	206.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CREOSOTE		
	B. EPA hazardous waste code D026	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	14.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description PAINT FILTERS CONTAMINATED WITH CHROMATE		
	B. EPA hazardous waste code D007		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
	<b>ON-SITE PROCESS 1</b>		
	<b>ON-SITE PROCESS 2</b>		
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
		B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to
	<b>SITE 1</b>	COD980591184	H061
	<b>SITE 2</b>		
	<b>SITE 3</b>		
D. Total Quantity Shipped in 2007  4511.0			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER  
 SITE NAME: RINCHEM COMPANY INC.,  
 EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
 2007 HAZARDOUS WASTE REPORT  
 WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ABSORBENT CONTAMINATED WITH FUELS		
	B. EPA hazardous waste code D018		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density  <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	11.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description PERCHLOROETHYLENE		
B. EPA hazardous waste code D039 F002		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	54.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description POTASSIUM HYDROXIDE SOLUTION		
	B. EPA hazardous waste code D002	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	2312.0
<b>SITE 2</b>	AZD009015389	H141	928.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND  
MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CONTAMINATED RAGS AND PPE		
	B. EPA hazardous waste code D001	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density └ 1 lbs/gal └ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	1648.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description BARIUM CONTAMINATED WATER		
B. EPA hazardous waste code D005		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	7696.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description DEBRIS CONTAMINATED WITH TOLUENE DIISOCYANATE		
B. EPA hazardous waste code U223		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	1112.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TETRACHLOROETHYLENE		
B. EPA hazardous waste code D039		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	498.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOLVENT CONTAMINATED WATER		
B. EPA hazardous waste code D004 D008 D018 F001 F002 F003 F005		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	452.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CORROSIVE OXIDIZING LIQUID		
B. EPA hazardous waste code D001 D002 D006 D007 D008 D011		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	410.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CORROSIVE TOXIC LIQUIDS		
B. EPA hazardous waste code D002 D007		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	555.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description AEROSOLS		
B. EPA hazardous waste code D001 D003 D035		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	484.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SODIUM CYANIDE		
B. EPA hazardous waste code D003 P106		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W312	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	892.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description FLAMMABLE LIQUIDS		
	B. EPA hazardous waste code D001 U002 U159 U213		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density ┆ 1 lbs/gal    ┆ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? ┆ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┆ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	51.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CYANIDE CONTAMINATED DEBRIS		
B. EPA hazardous waste code F008		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	45.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description DEBRIS CONTAMINATED WITH LEAD AND METHYL ETHYL KETONE		
	B. EPA hazardous waste code D008 D035		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W002	F. Quantity generated in 2007  0.0
		G. UOM 1	Density └ 1 lbs/gal └ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? └ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      └ 2 No (FORM IS COMPLETE)		
		B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to
<b>SITE 1</b>	COD980591184	H141	82.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER  
 SITE NAME: RINCHEM COMPANY INC.,  
 EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
 2007 HAZARDOUS WASTE REPORT  
 WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ALKALINE CLEANING COMPOUND		
B. EPA hazardous waste code D002		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	2291.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description POTASSIUM CYANDIE		
	B. EPA hazardous waste code D003 P098		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W319	F. Quantity generated in 2007  0.0
		G. UOM 1	Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	48.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description DIPHENYLMETHANE DIISOCYANATE		
	B. EPA hazardous waste code D003	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007 0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	238.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MAGNESIUM PERCHLORATE		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W319	F. Quantity generated in 2007  0.0	G. UOM 1 Density └ 1 lbs/gal └ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	2.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description POTASSIUM PERMANGANATE		
	B. EPA hazardous waste code D001	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W319	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	52.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description BARIUM COMPOUNDS		
B. EPA hazardous waste code D005		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	3215.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description KEROSENE		
	B. EPA hazardous waste code D018		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	71.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description BATTERY FLUID		
B. EPA hazardous waste code D002 D006		C. State hazardous waste code	
D. Source code G61  Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	88.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description 2-DIISOPROYLAMINOETHANOL		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	50.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description BENZENE		
B. EPA hazardous waste code D018		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	46.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description EPINEPHRINE		
	B. EPA hazardous waste code P042		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W409	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	8.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description PAINT SOLID		
B. EPA hazardous waste code D001 D004 D005 D006 D007 D008 D009 D010 D011 D012 D013 D014 D015 D016 D017 D018 D019 D020 D021 D022 D023 D024 D025 D026 D027 D028 D029 D030 D031 D032 D033 D034 D035 D036 D037 D038 D039 D040 D041 D042 D043		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25		E. Form code W209	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
ON-SITE PROCESS 1			
ON-SITE PROCESS 2			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
SITE 1	COD980591184	H141	1310.0
SITE 2			
SITE 3			
Comments:			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description FLAMMABLE LIQUIDS, TOXIC		
	B. EPA hazardous waste code D001 D004 D011 D018 D043		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	400.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TOXIC LIQUIDS		
	B. EPA hazardous waste code D004		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	11097.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CONTAMINATED DEBRIS		
B. EPA hazardous waste code D007 D008 D011 F003 F005		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0	G. UOM 1 Density └─ 1 lbs/gal └─ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	14943.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CONTAMINATED DEBRIS		
	B. EPA hazardous waste code D001 D007 D008 D018 D035 F002 F003 F005		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W409	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	19729.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description PARATHION ETHYL SOLUTION		
	B. EPA hazardous waste code D001 P089		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	1174.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description FLAMMABLE LIQUIDS (TOLUENE,XYLENE)		
	B. EPA hazardous waste code D001 F003 F005		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W209	F. Quantity generated in 2007  0.0
		G. UOM 1	Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	202.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description HYDROFLUORIC ACID		
	B. EPA hazardous waste code D002 U154		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	35.0
<b>SITE 2</b>	AZD009015389	H141	120359.0
<b>SITE 3</b>	AZD049318009	H141	75150.0
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SODIUM HYDROXIDE SOLID		
B. EPA hazardous waste code D003		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	15.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			



BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TOXIC LIQUID INORGANIC		
B. EPA hazardous waste code D002 D004		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	2501.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CHLOROFORM SOLUTIONS		
	B. EPA hazardous waste code D022	C. State hazardous waste code	
D. Source code G61	E. Form code W219	F. Quantity generated in 2007 0.0	G. UOM 1 Density 1 lbs/gal 2 sg
Management method code for source code G25			
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
		B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to
<b>SITE 1</b>	COD980591184	H141	852.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SOIL CONTAMINATED WITH MERCURY		
B. EPA hazardous waste code D009		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25		E. Form code W301	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
ON-SITE PROCESS 1			
ON-SITE PROCESS 2			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
SITE 1	COD980591184	H141	43.0
SITE 2			
SITE 3			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TOXIC SOLIDS		
B. EPA hazardous waste code D005 D011		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	93.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TOXIC LIQUIDS		
	B. EPA hazardous waste code D005 D011		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W219	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	165.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CALCIUM CARBIDE		
B. EPA hazardous waste code D003		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? ┐ 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B)      ┐ 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	3.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description CORROSIVE LIQUIDS TOXIC (ARSENIC, CITRIC ACID)		
B. EPA hazardous waste code D002 D004		C. State hazardous waste code	
D. Source code G61  Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	957.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TOLUENE DIISOCYANATE		
B. EPA hazardous waste code D003 U223		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W403	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	A. Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	564.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description RESIN		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W403	F. Quantity generated in 2007  0.0	G. UOM 1 Density ┐ 1 lbs/gal    ┐ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	3575.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description PHOSPHOROUS TRIBROMIDE		
	B. EPA hazardous waste code D003	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	16.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description ADHESIVES WITH SILVER		
	B. EPA hazardous waste code D011	C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	92.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MERCURY COMPOUNDS		
B. EPA hazardous waste code D009		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W117	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZ0000337360	H010	1099.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description LEAD ACID BATTERIES		
	B. EPA hazardous waste code D002 D008		C. State hazardous waste code
	D. Source code G61 Management method code for source code G25	E. Form code W409	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZ0000337360	H010	81.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MERCURY CONTAMINATED DEBRIS		
B. EPA hazardous waste code D009		C. State hazardous waste code	
D. Source code G61	E. Form code W002	F. Quantity generated in 2007 0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
Management method code for source code G25			
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZ0000337360	H010	108.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MERCURY CONTAINED IN MANUFACTURED ARTICLES		
B. EPA hazardous waste code D009		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W002	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZ0000337360	H010	428.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MERCURY		
B. EPA hazardous waste code D009		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W117	F. Quantity generated in 2007  0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZ0000337360	H010	151.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description NICAD BATTERIES		
B. EPA hazardous waste code D006		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W319	F. Quantity generated in 2007  0.0	G. UOM 1 Density └ 1 lbs/gal    └ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZ0000337360	H141	41.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SULFURIC ACID, LEAD, CONTAMINATED WATER		
	B. EPA hazardous waste code D002 D008		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZD009015389	H141	1167.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description NITRATES		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZD009015389	H141	18443.0
<b>SITE 2</b>	AZD049318009	H141	1681.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description MIXED ACIDS AND NITRATES		
	B. EPA hazardous waste code D001 D002 D011		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZD009015389	H141	2357.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description OXIDIZING LIQUID		
	B. EPA hazardous waste code D001 D005	C. State hazardous waste code	
D. Source code G61	E. Form code W119	F. Quantity generated in 2007 0.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
Management method code for source code G25			
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZD009015389	H141	7605.0
<b>SITE 2</b>	AZD049318009	H141	5225.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description OXIDIZING CORROSIVE SOLUTION		
B. EPA hazardous waste code D001 D002		C. State hazardous waste code	
D. Source code G61 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  0.0	G. UOM 1 Density └─ 1 lbs/gal └─ 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZD009015389	H141	15574.0
<b>SITE 2</b>	AZD049318009	H141	41858.0
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SODIUM HYDDROXIDE LIQUID		
	B. EPA hazardous waste code D002		C. State hazardous waste code
D. Source code G61 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	UTD981552177	H040	41370.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description LABPACKS		
B. EPA hazardous waste code D001 D002 D003 D004 D005 D006 D007 D008 D009 D010 D011 D013 D016 D018 D019 D020 D021 D022 D035 D040 F003 F005 LABP P021 P022 P030 P039 P044 P050 P089 P098 P105 P106 P127 U001 U007 U012 U044 U056 U057 U072 U077 U122 U123 U124 U133 U134 U135 U138 U144 G11		C. State hazardous waste code	
D. Source code G11		E. Form code W004	F. Quantity generated in 2007 0.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
		On-site management method code	Quantity treated, disposed, or recycled on site in 2007
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	20478.00
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b> SOME LABPACKS SENT WERE ACUTE			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description RESIN LABPACK		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G11 Management method code for source code G25	E. Form code W606	F. Quantity generated in 2007  127.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	127.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description RESIN		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G11 Management method code for source code G25	E. Form code W606	F. Quantity generated in 2007  3575.0	G. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	3575.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description SULFURIC ACID		
B. EPA hazardous waste code D002		C. State hazardous waste code	
D. Source code G11 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007  17100.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	COD980591184	H141	17100.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description TETRAMETHYLAMMONIUM HYDROXIDE		
	B. EPA hazardous waste code D002		C. State hazardous waste code
D. Source code G11 Management method code for source code G25		E. Form code W119	F. Quantity generated in 2007 41333.0
		G. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	AZD009015389	H141	41333.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description FLAMMABLE LIQUIDS		
B. EPA hazardous waste code D001		C. State hazardous waste code	
D. Source code G11 Management method code for source code G25	E. Form code W219	F. Quantity generated in 2007  2447.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	KSD980633259	H061	2447.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
GM**

US ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 19 of the instructions and forms booklet before completing this form

<b>SEC. 1</b>	A. Waste description HYDROGEN PEROXIDE		
	B. EPA hazardous waste code D001	C. State hazardous waste code	
D. Source code G11 Management method code for source code G25	E. Form code W119	F. Quantity generated in 2007  67024.0	G. UOM 1 Density 1 lbs/gal 2 sg
<b>SEC. 2</b>	Was any of this waste managed on site? <input type="checkbox"/> 1. Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> 2. No (SKIP TO SEC.3)		
	On-site management method code	Quantity treated, disposed, or recycled on site in 2007	
<b>ON-SITE PROCESS 1</b>			
<b>ON-SITE PROCESS 2</b>			
<b>SEC. 3</b>	A. Was any of this waste shipped off site in 2007 for treatment, disposal, or recycling? <input checked="" type="checkbox"/> 1 Yes (CONTINUE TO BOX B) <input type="checkbox"/> 2 No (FORM IS COMPLETE)		
	B. EPA ID No. of facility to which waste was shipped	C. Off-site management method code shipped to	D. Total Quantity Shipped in 2007
<b>SITE 1</b>	NVT330010000	H132	63720.0
<b>SITE 2</b>			
<b>SITE 3</b>			
<b>Comments:</b>			

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

FORM  
WR

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 1</b>	A. Description of hazardous waste CITRISUF205 RC7664		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 379.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 2</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC7710		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 446.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 3</b>	A. Description of hazardous waste WASTE DIESEL, GASOLINE MIX RC7801		
B. EPA hazardous waste code D001 D018			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 466.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 1

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 4</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC7805		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1044.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 5</b>	A. Description of hazardous waste HYDROCHLORIC ACID RC7815		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 366.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 6</b>	A. Description of hazardous waste POLYESTER RESIN/ACETONE RC2609		
	B. EPA hazardous waste code D001 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number AZD982442246	E. Quantity received in 2007 20660.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W403	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 2

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

FORM  
WR

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 7</b>	A. Description of hazardous waste SOLVENT/TOLUENE RC2075		
B. EPA hazardous waste code D001 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 468.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 8</b>	A. Description of hazardous waste THINNERS,SOLVENTS, STAINS RC2110		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 386.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 9</b>	A. Description of hazardous waste PAINT WASTE RC2254		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 439.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 3

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER  
 SITE NAME: RINCHEM COMPANY INC.,  
 EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
 2007 HAZARDOUS WASTE REPORT  
 WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 10</b>	A. Description of hazardous waste PAINT WASTE RC2411		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 104.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 11</b>	A. Description of hazardous waste TOXIC LIQUIDS RC3145		
	B. EPA hazardous waste code D005 D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 165.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 12</b>	A. Description of hazardous waste WIPES, GLOVES CONTAMINATED WITH BARIUM AND SILVER		
	B. EPA hazardous waste code D005 D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 93.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 13</b>	A. Description of hazardous waste PAINT WASTE RC4082		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1415.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 14</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC5116		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1532.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 15</b>	A. Description of hazardous waste CORROSIVE ACID LIQUID RC5515		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 492.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
Comments:			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 16</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC5538		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 514.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 17</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC5548		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 525.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 18</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC5540		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 933.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 19</b>	A. Description of hazardous waste FLAMMABLES RC5627		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1491.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 20</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC5660		
	B. EPA hazardous waste code D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 535.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 21</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC5712		
	B. EPA hazardous waste code D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 805.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

WR Page 7

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 22</b>	A. Description of hazardous waste PHOTO FIXER RC5752		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 532.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 23</b>	A. Description of hazardous waste SOLVENTS RC5801		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 228.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 24</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC5812		
B. EPA hazardous waste code D002 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 450.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 25</b>	A. Description of hazardous waste PAINT WATE RC5897		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 455.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 26</b>	A. Description of hazardous waste SOLVENT/LAQUER THINNER RC5920		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 945.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 27</b>	A. Description of hazardous waste FURNITURE STRIPPER RC5942		
B. EPA hazardous waste code D001 F002 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 2373.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 28</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC6091		
	B. EPA hazardous waste code D001 D019 F002 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1000.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>WASTE 29</b>	A. Description of hazardous waste CORROSIVE OXIDIZING LIQUID RC6092		
	B. EPA hazardous waste code D001 D002 D005 D007		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 210.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>WASTE 30</b>	A. Description of hazardous waste WATER WITH SOLVENTS AND PETROLEUM PRODUCTS RC6137		
	B. EPA hazardous waste code D004 D008 D018 F001 F002 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 153.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 31</b>	A. Description of hazardous waste ACETONITRILE RC6138		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 125.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 32</b>	A. Description of hazardous waste PAINT THINNERS RC6170		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 441.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 33</b>	A. Description of hazardous waste DEBRIS CONTAMINATED WITH SOLVENTS RC6717		
	B. EPA hazardous waste code D008 D011 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 543.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 34</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC7049		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 505.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 35</b>	A. Description of hazardous waste PAINTS AND SOLVENTS RC7073		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 2275.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 36</b>	A. Description of hazardous waste PETROLEUM NAPHTHA RC7177		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 301.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 37</b>	A. Description of hazardous waste GASOLINE AND WATER RC7178		
B. EPA hazardous waste code D001 D018			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 95.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 38</b>	A. Description of hazardous waste SULFURIC ACID RC7179		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 19.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 39</b>	A. Description of hazardous waste ELEMENTAL MERCURY RC7180		
B. EPA hazardous waste code D002 D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 24.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 40</b>	A. Description of hazardous waste LATEX AND OIL BASED PAINT RC7187		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 222.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 41</b>	A. Description of hazardous waste WASTE PAINT AND THINNERS RC7216		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 859.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 42</b>	A. Description of hazardous waste ALCOHOL RC7394		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1974.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 14

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 43</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7441		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 212.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 44</b>	A. Description of hazardous waste ACETONITRILE RC7546		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 463.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 45</b>	A. Description of hazardous waste SOIL CONTAMINATED WITH GAS AND DIESEL RC7547		
B. EPA hazardous waste code D001 D018			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 179.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 15

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 46</b>	A. Description of hazardous waste SOIL CONTAMINATD WITH METALS RC7551		
B. EPA hazardous waste code D004 D005 D006 D007 D008 D009 D010 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 188.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 47</b>	A. Description of hazardous waste STANDARD VIALS RC7552		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 288.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 48</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7620		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 794.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 49</b>	A. Description of hazardous waste SULFONIC ACID RC7645		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 80.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 50</b>	A. Description of hazardous waste AEROSOLS RC7797		
	B. EPA hazardous waste code D001 D003		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 9.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 51</b>	A. Description of hazardous waste PAINT RC7834		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 830.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 52</b>	A. Description of hazardous waste PAINTS AND STAINS RC7835		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1191.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 53</b>	A. Description of hazardous waste OLD GASOLINE RC7836		
B. EPA hazardous waste code D001 D018			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 108.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 54</b>	A. Description of hazardous waste AEROSOLS RC7844		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 10.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 55</b>	A. Description of hazardous waste PAINT RC7847		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 570.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 56</b>	A. Description of hazardous waste MERCURY CONTAINED IN ARTICLES RC7913		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 20.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 57</b>	A. Description of hazardous waste MERCURY OXIDE RC7934		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 6.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 58</b>	A. Description of hazardous waste AEROSOLS RC7951		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 19.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 59</b>	A. Description of hazardous waste POLYMERIC DIPHENYLMETHANE DIISOCYANATE RC7952		
B. EPA hazardous waste code D003			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 238.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W403	H. Management method code H141
<b>WASTE 60</b>	A. Description of hazardous waste MERCURY COMPOUNDS RC7956		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 157.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 61</b>	A. Description of hazardous waste AEROSOLS RC7960		
B. EPA hazardous waste code D001 D035			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 23.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 62</b>	A. Description of hazardous waste LEAD DEBRIS RC7961		
B. EPA hazardous waste code D008 D035			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 82.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 63</b>	A. Description of hazardous waste MERCURIC CHLORIDE RC8002		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 16.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 64</b>	A. Description of hazardous waste PAINT RC8006		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 407.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 65</b>	A. Description of hazardous waste PAINT WASTE RC8007		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 744.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 66</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC8017		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 223.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 67</b>	A. Description of hazardous waste PAINT RC8033		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 560.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 68</b>	A. Description of hazardous waste FORMALDEHYDE SOLUTIONS RC8036		
	B. EPA hazardous waste code D001 U122		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 175.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 69</b>	A. Description of hazardous waste MERCURY DEBRIS RC8038		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 6.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 70</b>	A. Description of hazardous waste EHTANOL AND SODIUM CYANIDE RC8043		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 16.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 71</b>	A. Description of hazardous waste PAINT RC8052		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 955.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 72</b>	A. Description of hazardous waste PAINT RC8059		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1810.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 24

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 73</b>	A. Description of hazardous waste MERCURY CONTAMINATED DIRT RC8063		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 45.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 74</b>	A. Description of hazardous waste PAINT RC8065		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 1595.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 75</b>	A. Description of hazardous waste AEROSOLS RC8086		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 12.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 76</b>	A. Description of hazardous waste PAINTS RC8087		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 238.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 77</b>	A. Description of hazardous waste PAINT RC8088		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 494.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 78</b>	A. Description of hazardous waste AEROSOLS RC8090		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 80.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 79</b>	A. Description of hazardous waste AEROSOLS RC8095		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 206.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 80</b>	A. Description of hazardous waste AEROSOLS-CORROSIVE RC8096		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 16.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 81</b>	A. Description of hazardous waste PAINT RC8111		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 544.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 82</b>	A. Description of hazardous waste TECH SPRAY RC8114		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 26.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 83</b>	A. Description of hazardous waste SOLDER FLUX RC8117		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 392.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 84</b>	A. Description of hazardous waste WATER WITH SILVER RC8123		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 345.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 85</b>	A. Description of hazardous waste PAINT RC8124		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 257.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 86</b>	A. Description of hazardous waste AEROSOLS RC8125		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 42.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 87</b>	A. Description of hazardous waste PAINT RC8127		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 394.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 88</b>	A. Description of hazardous waste MERCURIC COMPOUNDS RC8130		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 10.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>WASTE 89</b>	A. Description of hazardous waste XYLENES RC8131		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 827.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 90</b>	A. Description of hazardous waste EHTANOL AND CHLOROFORM RC8134		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 67.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 91</b>	A. Description of hazardous waste THINNER RC8144		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 220.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 92</b>	A. Description of hazardous waste AEROSOLS RC8176		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 32.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 93</b>	A. Description of hazardous waste PAINT RC8177		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 231.00
	F. UOM 1 Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 94</b>	A. Description of hazardous waste MAP GAS CYLINDER RC8178		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 8.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W801	H. Management method code H141
<b>WASTE 95</b>	A. Description of hazardous waste PAINT RC8180		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 518.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 96</b>	A. Description of hazardous waste MERCURY LAMPS RC7850		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NM750311508	E. Quantity received in 2007 5.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W320	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 97</b>	A. Description of hazardous waste MERCURY CONTAINED IN MANUFACTURED ARTICLES RC7851		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NM750311508	E. Quantity received in 2007 57.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W320
H. Management method code H141			
<b>WASTE 98</b>	A. Description of hazardous waste FLAMMABLE PAINTS RC7852		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NM750311508	E. Quantity received in 2007 311.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>WASTE 99</b>	A. Description of hazardous waste MIXED SOLVENTS RC1026		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 1639.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 100</b>	A. Description of hazardous waste CHLOROFORM SOLUTIONS RC6834		
B. EPA hazardous waste code D022			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 852.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 101</b>	A. Description of hazardous waste AEROSOLS RC6866		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 136.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 102</b>	A. Description of hazardous waste EHTANOL/ACETONITRILE RC6986		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 28.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 103</b>	A. Description of hazardous waste FORMIC ACID RC7266		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 351.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 104</b>	A. Description of hazardous waste PHOTO FIXER RC7367		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 300.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 105</b>	A. Description of hazardous waste HYDROCHLORIC ACID SOLUTION RC7630		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 1141.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 106</b>	A. Description of hazardous waste FORMIC ACID RC7790		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 217.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 107</b>	A. Description of hazardous waste PHOSPHORIC ACID RC7795		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 264.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 108</b>	A. Description of hazardous waste SODIUM HYDROXIDE RC7796		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 86.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

WR Page 36

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 109</b>	A. Description of hazardous waste SPENT HD CATALYST RC1093		
B. EPA hazardous waste code K171			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 876.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 110</b>	A. Description of hazardous waste OIL REFINERY SLUDGE RC5562		
B. EPA hazardous waste code K050			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 1925.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W603	H. Management method code H141
<b>WASTE 111</b>	A. Description of hazardous waste SEWER SLUDGE RC5666		
B. EPA hazardous waste code F037			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 75567.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER  
 SITE NAME: RINCHEM COMPANY INC.,  
 EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
 2007 HAZARDOUS WASTE REPORT  
 WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 112</b>	A. Description of hazardous waste API SEPERATOR SLUDGE RC5959		
	B. EPA hazardous waste code K051		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 18155.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 113</b>	A. Description of hazardous waste SOIL CONTAMINATED WITH LEAD RC7762		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 20720.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 114</b>	A. Description of hazardous waste SLUDGE RC7763		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 26243.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 115</b>	A. Description of hazardous waste PROCESS SEWER SLUDGE RC7764		
B. EPA hazardous waste code D007 D009 F037			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 1022.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 116</b>	A. Description of hazardous waste SOIL CONTAMINATED WITH CHROMIUM AND ARSENIC RC7791		
B. EPA hazardous waste code D004 D007			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 635.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 117</b>	A. Description of hazardous waste SOIL CONTAMINATED WITH XYLENE AND TOLUENE RC7792		
B. EPA hazardous waste code F037			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 2034.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 118</b>	A. Description of hazardous waste SOIL CONTAMINATED WITH BENZENE AND LEAD RC7793		
	B. EPA hazardous waste code D008 D018 F037		
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 1961.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 119</b>	A. Description of hazardous waste CONTAMINATED SOIL RC7794		
	B. EPA hazardous waste code F037		
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 6454.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 120</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC7885		
	B. EPA hazardous waste code D001		
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 3360.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 121</b>	A. Description of hazardous waste MERCURY SWITCHES RC7886		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 59.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W320	H. Management method code H141
<b>WASTE 122</b>	A. Description of hazardous waste SOIL WITH MERCURY AND BENZENE RC7970		
B. EPA hazardous waste code D009 D018 F003 K050			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 6935.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 123</b>	A. Description of hazardous waste SOIL WITH BENZENE RC8149		
B. EPA hazardous waste code D001 D018			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 927.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 124</b>	A. Description of hazardous waste SOIL CONTAMINATED WITH CHLORIDE, FLOURID AND BENZENE RC8150		
	B. EPA hazardous waste code D001 D018		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 197.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>WASTE 125</b>	A. Description of hazardous waste SOLID SEWER SLUDGE RC8154		
	B. EPA hazardous waste code F037		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 9801.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 126</b>	A. Description of hazardous waste CHLORIDE GUARD WASTE RC8163		
	B. EPA hazardous waste code D001 D003 D018		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 27767.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 42

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 127</b>	A. Description of hazardous waste <b>BENZENE CONTAMINATED CATALYST RC8179</b>		
B. EPA hazardous waste code <b>D018</b>			
C. State hazardous waste code		D. Off-site handler EPA ID number <b>NMD000333211</b>	E. Quantity received in 2007 <b>3390.00</b>
F. UOM <b>1</b>	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code <b>W519</b>	H. Management method code <b>H141</b>
<b>WASTE 128</b>	A. Description of hazardous waste <b>BROKEN FLUORSCENT LIGHT TUBES RC5644</b>		
B. EPA hazardous waste code <b>D009</b>			
C. State hazardous waste code		D. Off-site handler EPA ID number <b>NMD000610303</b>	E. Quantity received in 2007 <b>99.00</b>
F. UOM <b>1</b>	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code <b>W002</b>	H. Management method code <b>H141</b>
<b>WASTE 129</b>	A. Description of hazardous waste <b>DEBRIS CONTAMINATED WITH MERCURY RC6278</b>		
B. EPA hazardous waste code <b>D009</b>			
C. State hazardous waste code		D. Off-site handler EPA ID number <b>NMD000610303</b>	E. Quantity received in 2007 <b>4.00</b>
F. UOM <b>1</b>	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code <b>W002</b>	H. Management method code <b>H141</b>
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

FORM  
WR

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 130</b>	A. Description of hazardous waste SULFAMIC ACID RC7707		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 429.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 131</b>	A. Description of hazardous waste COMPRESSED CYLINDERS RC8188		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 12.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W801	H. Management method code H141
<b>WASTE 132</b>	A. Description of hazardous waste MERCURY RC8121		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 11.00
	F. UOM 1      Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 44

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 133</b>	A. Description of hazardous waste CHROME TANK SLUDGE RC7184		
	B. EPA hazardous waste code D007 D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD035740950	E. Quantity received in 2007 2145.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 134</b>	A. Description of hazardous waste SOLID PAINT RC2045		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD061268819	E. Quantity received in 2007 9215.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W409	H. Management method code H141
<b>WASTE 135</b>	A. Description of hazardous waste PAINT RC2049		
	B. EPA hazardous waste code D001 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD061268819	E. Quantity received in 2007 3679.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 136</b>	A. Description of hazardous waste AEROSOLS RC6789		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD061268819	E. Quantity received in 2007 21.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 137</b>	A. Description of hazardous waste PAINT SOLIDS RC7879		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD061268819	E. Quantity received in 2007 196.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W409	H. Management method code H141
<b>WASTE 138</b>	A. Description of hazardous waste ACETONE RC2068		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD064912348	E. Quantity received in 2007 1125.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 46

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 139</b>	A. Description of hazardous waste BLAST MEDIA WITH LEAD CRHOME AND SILVER RC2253		
B. EPA hazardous waste code D007 D008 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD064912348	E. Quantity received in 2007 674.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W409	H. Management method code H141
<b>WASTE 140</b>	A. Description of hazardous waste PAINTS AND SOLVENTS RC7964		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD080376346	E. Quantity received in 2007 865.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 141</b>	A. Description of hazardous waste AEROSOLS RC5481		
B. EPA hazardous waste code D001 D003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD980744551	E. Quantity received in 2007 20.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 142</b>	A. Description of hazardous waste LEAD CONTAMINATED DEBRIS RC7677		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD980744551	E. Quantity received in 2007 65801.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
<b>WASTE 143</b>	A. Description of hazardous waste BARIUM CARBONATE RC7820		
	B. EPA hazardous waste code D005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD980744551	E. Quantity received in 2007 3215.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319
<b>WASTE 144</b>	A. Description of hazardous waste PAINTS AND THINNERS RC7821		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD980744551	E. Quantity received in 2007 273.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 145</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC8139		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD980744551	E. Quantity received in 2007 31.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 146</b>	A. Description of hazardous waste SULFURIC ACID RC8140		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD980744551	E. Quantity received in 2007 736.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 147</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC2094		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD980872105	E. Quantity received in 2007 443.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 148</b>	A. Description of hazardous waste PAINT RC7840		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD980872105	E. Quantity received in 2007 459.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 149</b>	A. Description of hazardous waste PAINT RC5860		
	B. EPA hazardous waste code D001 D035 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD981610090	E. Quantity received in 2007 2524.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 150</b>	A. Description of hazardous waste TOXIC LIQUIDS ORGANIC RC8012		
	B. EPA hazardous waste code D003		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD981610090	E. Quantity received in 2007 1797.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 150</b>		A. Description of hazardous waste		
B. EPA hazardous waste code				
C. State hazardous waste code		D. Off-site handler EPA ID number		E. Quantity received in 2007
F. UOM	Density	G. Form code		H. Management method code
	<input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg			
<b>Comments:</b>				

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 151</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7207		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD981610181	E. Quantity received in 2007 513.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 152</b>	A. Description of hazardous waste MERCURY COMPOUNDS RC8034		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD982306110	E. Quantity received in 2007 5.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117
<b>WASTE 153</b>	A. Description of hazardous waste PAINT WASTE RC2305		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD986675940	E. Quantity received in 2007 3935.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 154</b>	A. Description of hazardous waste WASTE INK RC2048		
	B. EPA hazardous waste code D001 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD986675965	E. Quantity received in 2007 77.00
	F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 155</b>	A. Description of hazardous waste PAINT RC7338		
	B. EPA hazardous waste code D001 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD986682466	E. Quantity received in 2007 1052.00
	F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 156</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC2315		
	B. EPA hazardous waste code D001 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD986683092	E. Quantity received in 2007 936.00
	F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 157</b>	A. Description of hazardous waste LEAD ACID DEBRIS RC7838		
B. EPA hazardous waste code D002 D008			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD986683092	E. Quantity received in 2007 226.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 158</b>	A. Description of hazardous waste PAINT RC5819		
B. EPA hazardous waste code D001 D035 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011126	E. Quantity received in 2007 10231.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 159</b>	A. Description of hazardous waste PAINT RC6610		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011261	E. Quantity received in 2007 1550.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 160</b>	A. Description of hazardous waste AEROSOL RC7817		
B. EPA hazardous waste code D001 D003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011264	E. Quantity received in 2007 51.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 161</b>	A. Description of hazardous waste PETROLEUM NAPHTHA RC7855		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011268	E. Quantity received in 2007 668.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 162</b>	A. Description of hazardous waste PESTICIDE SOLID RC7899		
B. EPA hazardous waste code U279			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011269	E. Quantity received in 2007 390.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W401	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: **NMD002208627**

**FORM  
WR**

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 163</b>	A. Description of hazardous waste    PAINT/THINNER RC7901		
B. EPA hazardous waste code    D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011269	E. Quantity received in 2007 474.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 164</b>	A. Description of hazardous waste    RESIN LOOSEPACKD RC7902		
B. EPA hazardous waste code    D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011269	E. Quantity received in 2007 840.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W606	H. Management method code H141
<b>WASTE 165</b>	A. Description of hazardous waste    PARATHION RC7904		
B. EPA hazardous waste code    D001 P089			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011269	E. Quantity received in 2007 1174.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 166</b>	A. Description of hazardous waste LAQUER THINNER RC7971		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011271	E. Quantity received in 2007 133.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 167</b>	A. Description of hazardous waste AMMONIUM HYDROXIDE RC8021		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011275	E. Quantity received in 2007 1627.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 168</b>	A. Description of hazardous waste ACETIC ACID RC8022		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011275	E. Quantity received in 2007 989.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 169</b>	A. Description of hazardous waste FLAMMABLE LIQUID RC8026		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011275	E. Quantity received in 2007 859.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 170</b>	A. Description of hazardous waste MERCURY COMPOUNDS RC8056		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011276	E. Quantity received in 2007 5.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>WASTE 171</b>	A. Description of hazardous waste MERCURY COMPOUNDS SOLID RC8057		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011276	E. Quantity received in 2007 7.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 172</b>	A. Description of hazardous waste AEROSOLS RC8081		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMP360011279	E. Quantity received in 2007 25.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 173</b>	A. Description of hazardous waste PAINTS RC8082		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMP360011279	E. Quantity received in 2007 1441.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 174</b>	A. Description of hazardous waste LEAD PAINT CHIPS RC8083		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMP360011279	E. Quantity received in 2007 156.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W409
H. Management method code H141			
Comments:			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 175</b>	A. Description of hazardous waste PAINT EMULSIFIER RC8084		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011279	E. Quantity received in 2007 920.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 176</b>	A. Description of hazardous waste MERCURIC COMPOUNDS RC8136		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011282	E. Quantity received in 2007 8.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117	H. Management method code H141
<b>WASTE 177</b>	A. Description of hazardous waste MERCURY CONTAMINATED SOIL RC8182		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011283	E. Quantity received in 2007 137.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 178</b>	A. Description of hazardous waste FLAMMABLE SOLVENTS RC8183		
	B. EPA hazardous waste code D001 D018		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMP360011283	E. Quantity received in 2007 325.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>WASTE 179</b>	A. Description of hazardous waste DEBRIS CONTAMINATED WITH LEAD RC0049		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 113.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
H. Management method code H141			
<b>WASTE 180</b>	A. Description of hazardous waste LABORATORY SOLVENTS RC2122		
	B. EPA hazardous waste code D001 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 237515.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

WR Page 60

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 181</b>	A. Description of hazardous waste SOLVENT CONAMINATED DEBRIS		
B. EPA hazardous waste code F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 6469.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 182</b>	A. Description of hazardous waste ARSENIC WASTE RC2124		
B. EPA hazardous waste code D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 3108.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 183</b>	A. Description of hazardous waste COPPER SULFATE AND WATER WASTE RC2126		
B. EPA hazardous waste code D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 5635.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 61

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 184</b>	A. Description of hazardous waste ARSENIC DEBRIS RC5482		
B. EPA hazardous waste code D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 750.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 185</b>	A. Description of hazardous waste CHARCOL WITH ACETONE RC5537		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 3432.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 186</b>	A. Description of hazardous waste USED LAPPING SLURRY RC5550		
B. EPA hazardous waste code D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 420.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 187</b>		A. Description of hazardous waste ACID ETCH SOLUTION	
B. EPA hazardous waste code D002 D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 3091.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 188</b>		A. Description of hazardous waste AMMONIUM HYDROXIDE SOLUTION RC5571	
B. EPA hazardous waste code D002 D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 2111.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 189</b>		A. Description of hazardous waste SOLVENTS RC5888	
B. EPA hazardous waste code D001 D026 D035 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 8568.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 190</b>	A. Description of hazardous waste ADHESIVES CONTAMINATED WITH SILVER RC6123		
	B. EPA hazardous waste code D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 95.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519
<b>WASTE 191</b>	A. Description of hazardous waste CITRIC ACID SOLUTION RC6856		
	B. EPA hazardous waste code D002 D004		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 1483.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 192</b>	A. Description of hazardous waste GRAPHITE PLATTERS WITH ARSENIC RC7478		
	B. EPA hazardous waste code D004		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 1439.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
H. Management method code H141			
Comments:			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 193</b>	A. Description of hazardous waste TGA CARBON-ARSENIC WASTE RC8077		
B. EPA hazardous waste code D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 18160.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 194</b>	A. Description of hazardous waste TGA PPE WASTE RC8078		
B. EPA hazardous waste code D004			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000002816	E. Quantity received in 2007 197.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 195</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC2044		
B. EPA hazardous waste code D001 D035			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000003012	E. Quantity received in 2007 7230.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 196</b>	A. Description of hazardous waste ARSENIC CONTAMINATED DEBRIS RC6988		
	B. EPA hazardous waste code D004		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000003418	E. Quantity received in 2007 132.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
<b>WASTE 197</b>	A. Description of hazardous waste ACID WATER MIXTURE RC6989		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000003418	E. Quantity received in 2007 7933.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 198</b>	A. Description of hazardous waste POTASSIUM HYDROXIDE SOLUTION RC6990		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000003418	E. Quantity received in 2007 1371.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 199</b>	A. Description of hazardous waste FLAMMABLE SOLVENTS RC6992		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000003418	E. Quantity received in 2007 976.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 200</b>	A. Description of hazardous waste CONTAMINATED PPE RC6995		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000003418	E. Quantity received in 2007 746.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 201</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC3192		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000003640	E. Quantity received in 2007 4746.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 202</b>	A. Description of hazardous waste LEAD CONTAMINATED DEBRIS RC5707		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000003640	E. Quantity received in 2007 98.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 203</b>	A. Description of hazardous waste CLEANER WITH INK RC2143		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000004952	E. Quantity received in 2007 357.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 204</b>	A. Description of hazardous waste SOLVENT CONTAMINATED DEBRIS RC7021		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000005835	E. Quantity received in 2007 2969.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 205</b>	A. Description of hazardous waste PAINT PRODUCTION DEBRIS RC7376		
B. EPA hazardous waste code D001 D007 D008 D035 F002 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000007435	E. Quantity received in 2007 1079.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 206</b>	A. Description of hazardous waste SOLVENTS RC5823		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000008516	E. Quantity received in 2007 94.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 207</b>	A. Description of hazardous waste POLISH RINSE WATER RC5824		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000008516	E. Quantity received in 2007 1061.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 208</b>	A. Description of hazardous waste AEROSOLS RC7465		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000008516	E. Quantity received in 2007 11.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 209</b>	A. Description of hazardous waste CYANIDE CONTAMINATED DEBRIS RC7991		
B. EPA hazardous waste code F008			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000008516	E. Quantity received in 2007 45.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 210</b>	A. Description of hazardous waste PAINT PRODUCTION DEBRIS RC7375		
B. EPA hazardous waste code D001 D007 D035 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009134	E. Quantity received in 2007 3269.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 211</b>	A. Description of hazardous waste PAINT FILTERS RC7569		
	B. EPA hazardous waste code D007		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009134	E. Quantity received in 2007 913.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
<b>WASTE 212</b>	A. Description of hazardous waste CHROMIUM CONTAMINATED SORBENT PADS RC7788		
	B. EPA hazardous waste code D007		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009134	E. Quantity received in 2007 77.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
<b>WASTE 213</b>	A. Description of hazardous waste PAINT RC8001		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009134	E. Quantity received in 2007 2175.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

WR Page 71

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 214</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC6964		
	B. EPA hazardous waste code D001 D011 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 14113.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 215</b>	A. Description of hazardous waste SILVER DEBRIS RC7077		
	B. EPA hazardous waste code D008 D011 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 5062.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
<b>WASTE 216</b>	A. Description of hazardous waste OXIDIZING CORROSIVE SOLUTION RC7502		
	B. EPA hazardous waste code D001 D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 60799.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 217</b>	A. Description of hazardous waste SILVER AND WATER RC7565		
	B. EPA hazardous waste code D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 9115.00
	F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 218</b>	A. Description of hazardous waste MIXED ACIDS AND NITRATES RC7600		
	B. EPA hazardous waste code D001 D002 D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 2044.00
	F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 219</b>	A. Description of hazardous waste COPPER NITRATE NICKEL NITRATE RC7657		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 20124.00
	F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

FORM  
WR

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 220</b>	A. Description of hazardous waste YTRIIUM NITRATE BARIUM NITRATE RC7676		
B. EPA hazardous waste code D001 D005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 12830.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 221</b>	A. Description of hazardous waste SILVER AND WATER RC7709		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 888.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 222</b>	A. Description of hazardous waste SILVER AND WATER RC7771		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 4964.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 74

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 223</b>	A. Description of hazardous waste BARIUM OXIDE RINSATE RC7773		
	B. EPA hazardous waste code D005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 7696.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>WASTE 224</b>	A. Description of hazardous waste MERCURY RC7807		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 13.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117
H. Management method code H141			
<b>WASTE 225</b>	A. Description of hazardous waste MERCURY SPILL KIT RC7926		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 6.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 226</b>	A. Description of hazardous waste YTTRIUM NITRATE AND YTTERBIUM NITRATE RC8054		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 1613.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 227</b>	A. Description of hazardous waste CORROSIVE OXIDIZING LIQUIDS RC8074		
	B. EPA hazardous waste code D001 D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 2079.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 228</b>	A. Description of hazardous waste OXIDIZING LIQUID RC8093		
	B. EPA hazardous waste code D001 D007 D011		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 6403.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 229</b>	A. Description of hazardous waste FLAMMABLE LIQUID RC8184		
B. EPA hazardous waste code D001 D008 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 230.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 230</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7009		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009431	E. Quantity received in 2007 3550.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 231</b>	A. Description of hazardous waste DEBRIS CONTAMINATED WITH SOLVENTS AND LEAD RC7011		
B. EPA hazardous waste code D008 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009431	E. Quantity received in 2007 733.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 232</b>	A. Description of hazardous waste NICAD BATTERIES RC7012		
	B. EPA hazardous waste code D006		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000009431	E. Quantity received in 2007 41.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319
<b>WASTE 233</b>	A. Description of hazardous waste PAINT PRODUCTION DEBRIS RC7374		
	B. EPA hazardous waste code D001 D007 D035 F003		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000010074	E. Quantity received in 2007 8060.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002
<b>WASTE 234</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC7615		
	B. EPA hazardous waste code D001 D007 D035 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000010074	E. Quantity received in 2007 3038.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 235</b>	A. Description of hazardous waste PAINT FILTERS RC7616		
B. EPA hazardous waste code D007			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000010074	E. Quantity received in 2007 3631.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 236</b>	A. Description of hazardous waste TOLUENE DIISOCYANATE RC8103		
B. EPA hazardous waste code D003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000010967	E. Quantity received in 2007 1108.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W519	H. Management method code H141
<b>WASTE 237</b>	A. Description of hazardous waste CONTAMINATED DEBRIS RC8166		
B. EPA hazardous waste code D008 D011 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000010967	E. Quantity received in 2007 58.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 79

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 238</b>	A. Description of hazardous waste SOLVENT CONTAMINATED DEBRIS RC7715		
B. EPA hazardous waste code D008 D011 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000011841	E. Quantity received in 2007 7641.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 239</b>	A. Description of hazardous waste HYDROFLUORIC ACID RC7745		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000011841	E. Quantity received in 2007 187950.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 240</b>	A. Description of hazardous waste CONTAMINATED DEBRIS RC7770		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000011841	E. Quantity received in 2007 86.00
F. UOM 1	Density <input checked="" type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

FORM  
WR

U.S. ENVIRONMENTAL  
PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 241</b>	A. Description of hazardous waste HYDROFLUORIC ACID RC7778		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000011841	E. Quantity received in 2007 29.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 242</b>	A. Description of hazardous waste POTASSIUM HYDROXIDE RC7780		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000011841	E. Quantity received in 2007 160.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 243</b>	A. Description of hazardous waste POTASSIUM HYDROXIDE RC8051		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000011841	E. Quantity received in 2007 6650.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 81

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 244</b>	A. Description of hazardous waste RADIATOR SLUDGE FILTERCAKE RC7749		
	B. EPA hazardous waste code D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000011981	E. Quantity received in 2007 11116.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W603
H. Management method code H141			
<b>WASTE 245</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7782		
	B. EPA hazardous waste code D001 D028 D035		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012153	E. Quantity received in 2007 458.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>WASTE 246</b>	A. Description of hazardous waste AEROSOLS RC7783		
	B. EPA hazardous waste code D001		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012153	E. Quantity received in 2007 8.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 247</b>	A. Description of hazardous waste CHROMIC ACID/HYDROFLUORIC ACID RC7785		
B. EPA hazardous waste code D002 D007			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012153	E. Quantity received in 2007 555.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 248</b>	A. Description of hazardous waste PAINT/PRODUCTION DEBRIS RC7988		
B. EPA hazardous waste code D001 D007 D008 D035 F002 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012377	E. Quantity received in 2007 343.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 249</b>	A. Description of hazardous waste CONTAMINATED DEBRIS RC8098		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012567	E. Quantity received in 2007 742.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 250</b>	A. Description of hazardous waste PAINT THINNERS RC8156		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012567	E. Quantity received in 2007 1263.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 251</b>	A. Description of hazardous waste HYDROFLUORIC ACID LABPACK RC7916		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 10.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001
<b>WASTE 252</b>	A. Description of hazardous waste ELEMENTAL MERCURY RC7917		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 73.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

WR Page 84

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 253</b>	A. Description of hazardous waste INORGANIC ACIDS RC7919		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 1033.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 254</b>	A. Description of hazardous waste SODIUM HYDROXIDE SOLUTION RC7920		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 395.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 255</b>	A. Description of hazardous waste HYDROGEN PEROXIDE RC7921		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 440.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 256</b>	A. Description of hazardous waste SODIUM CYANIDE SOLID RC7923		
B. EPA hazardous waste code D003 P106			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 242.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 257</b>	A. Description of hazardous waste LEAD CONTAMINATED SLAG RC7924		
B. EPA hazardous waste code D008			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 4773.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 258</b>	A. Description of hazardous waste OXIDIZING/CORROSIVE SOLID RC7976		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 1123.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 259</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7977		
	B. EPA hazardous waste code D001 F003 F005		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 418.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219
<b>WASTE 260</b>	A. Description of hazardous waste ALKALINE CLEANING COMPOUNDS RC7978		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 2291.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119
<b>WASTE 261</b>	A. Description of hazardous waste ELEMENTAL MERCURY RC8107		
	B. EPA hazardous waste code D009		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 8.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W117
<b>Comments:</b>			

Submit Date:

WR Page 87

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 262</b>	A. Description of hazardous waste MERCURY COMPOUNDS SOLID RC8109		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 3.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 263</b>	A. Description of hazardous waste ZINC DUST RC7927		
B. EPA hazardous waste code D003			
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 1297.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 264</b>	A. Description of hazardous waste CALCIUM CARBIDE RC7928		
B. EPA hazardous waste code D003			
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 3.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 265</b>	A. Description of hazardous waste MAGNESIUM PERCHLORATE RC7929		
	B. EPA hazardous waste code D001		
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 2.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 266</b>	A. Description of hazardous waste SODIUM HYDROXIDE SOLID RC7930		
	B. EPA hazardous waste code D003		
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 15.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 267</b>	A. Description of hazardous waste SODIUM CYANIDE RC7931		
	B. EPA hazardous waste code D003 P106		
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 650.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 268</b>	A. Description of hazardous waste LABPACK POTASSIUM PERMANGANATE RC7932		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 51.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 269</b>	A. Description of hazardous waste POTASSIUM CYANIDE RC7936		
B. EPA hazardous waste code D003 P098			
C. State hazardous waste code		D. Off-site handler EPA ID number NV3890090001	E. Quantity received in 2007 48.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 270</b>	A. Description of hazardous waste AEROSOLS RC7937		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number TXR000020156	E. Quantity received in 2007 30.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 271</b>	A. Description of hazardous waste FLAMMABLE LIQUIDS RC7938		
B. EPA hazardous waste code D001 F003			
C. State hazardous waste code		D. Off-site handler EPA ID number TXR000020156	E. Quantity received in 2007 292.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 272</b>	A. Description of hazardous waste WATER CONTAMINATED WITH LEAD RC7962		
B. EPA hazardous waste code D008			
C. State hazardous waste code		D. Off-site handler EPA ID number TXR000020156	E. Quantity received in 2007 161.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 273</b>	A. Description of hazardous waste POTASSIUM HYDROXIDE RC8066		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number TXR000020156	E. Quantity received in 2007 510.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 274</b>	A. Description of hazardous waste FLOURESCENT LIGHT TUBES RC4039		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number UTD073008237	E. Quantity received in 2007 12.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W320	H. Management method code H141
<b>WASTE 275</b>	A. Description of hazardous waste BATTERIES RC4162		
B. EPA hazardous waste code D002 D008			
C. State hazardous waste code		D. Off-site handler EPA ID number UTD073008237	E. Quantity received in 2007 81.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W319	H. Management method code H141
<b>WASTE 276</b>	A. Description of hazardous waste PAINT RELATED MATERIAL RC4090		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number UTD988069860	E. Quantity received in 2007 4487.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 277</b>	A. Description of hazardous waste STAINS/MINERAL SPIRITS RC7060		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 1739.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>WASTE 278</b>	A. Description of hazardous waste SOLUTEK CONE FIXER RC7395		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 537.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 279</b>	A. Description of hazardous waste HG DEBRIS		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 2.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 280</b>	A. Description of hazardous waste LABPACK RC7787		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 6.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 281</b>	A. Description of hazardous waste LABPACK RC7808		
B. EPA hazardous waste code D001 D002 D005 D007 D011 U122 U165			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 166.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 282</b>	A. Description of hazardous waste LABPACK RC7832		
B. EPA hazardous waste code D001 U154			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 6.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 283</b>	A. Description of hazardous waste LABPACK RC7848		
B. EPA hazardous waste code D001 D005 D007 D008			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 38.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 284</b>	A. Description of hazardous waste LABPACK RC7872		
B. EPA hazardous waste code D001 D002			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 220.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 285</b>	A. Description of hazardous waste LABPACK RC7911		
B. EPA hazardous waste code D001 D002 D006 D009 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 336.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 286</b>	A. Description of hazardous waste LABPACK RC7933		
B. EPA hazardous waste code D001 D002 D005 D007 D008 U012			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 387.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 287</b>	A. Description of hazardous waste LABPACK RC7949		
B. EPA hazardous waste code D001 D002 U154			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 109.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 288</b>	A. Description of hazardous waste LABPACK RC7959		
B. EPA hazardous waste code D001 D008 D011 U220			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 106.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 289</b>	A. Description of hazardous waste LABPACK RC7984		
B. EPA hazardous waste code D016 D020 P021 P098			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 170.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 290</b>	A. Description of hazardous waste LABPACK RC7993		
B. EPA hazardous waste code D002 U134			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 227.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 291</b>	A. Description of hazardous waste LABPACK RC7999		
B. EPA hazardous waste code D001 D007 D009 U012 U072 U188 U239			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 179.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 292</b>	A. Description of hazardous waste LABPACK RC8000		
B. EPA hazardous waste code D001 D002 D003 D005 D008 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 72.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 293</b>	A. Description of hazardous waste LABPACK RC8014		
B. EPA hazardous waste code D001 U122			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 38.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 294</b>	A. Description of hazardous waste LABPACK RC8039		
B. EPA hazardous waste code D001 D002 D003 D006 D007 D008 P105 P106 U037 U072 U122 U220			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 723.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 295</b>	A. Description of hazardous waste LABPACK RC8045		
	B. EPA hazardous waste code D002 D003		
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 180.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 296</b>	A. Description of hazardous waste LABPACK RC8075		
	B. EPA hazardous waste code D002		
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 60.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 297</b>	A. Description of hazardous waste LABPACK RC8097		
	B. EPA hazardous waste code D001 D002		
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 68.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 298</b>	A. Description of hazardous waste LABPACK RC8105		
B. EPA hazardous waste code D001 D002 P030			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 21.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 299</b>	A. Description of hazardous waste LABPACK RC8152		
B. EPA hazardous waste code D001 D002 P030			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 63.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 300</b>	A. Description of hazardous waste LABPACK RC8122		
B. EPA hazardous waste code D001 D002 D005 D007 D008 D011 U154			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 63.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 301</b>	A. Description of hazardous waste LABPACK RC8126		
	B. EPA hazardous waste code D001 D002 D011		
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 66.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 302</b>	A. Description of hazardous waste LABPACK RC7845		
	B. EPA hazardous waste code D001 D002 D005 D008 D011 U154 U239		
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 253.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 303</b>	A. Description of hazardous waste LABPACK RC8016		
	B. EPA hazardous waste code D001		
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 154.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 101

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 304</b>	A. Description of hazardous waste LABPACK RC8089		
B. EPA hazardous waste code D001 D002			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 13.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 305</b>	A. Description of hazardous waste LABPACK RC8129		
B. EPA hazardous waste code D001 U012			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 56.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 306</b>	A. Description of hazardous waste LABPACK RC8155		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number CESQG	E. Quantity received in 2007 13.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 307</b>	A. Description of hazardous waste LABPACK RC7849		
	B. EPA hazardous waste code D001 D009 U154		
C. State hazardous waste code		D. Off-site handler EPA ID number NM075311508	E. Quantity received in 2007 657.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 308</b>	A. Description of hazardous waste LABPACK RC7985		
	B. EPA hazardous waste code D001 D002 D003 D007 D011 D022 P022 P098 P106 U044 U077 U122 U123 U134 U138		
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 880.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 309</b>	A. Description of hazardous waste LABPACK RC7859		
	B. EPA hazardous waste code D001 D010		
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 42.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 310</b>	A. Description of hazardous waste LABPACK RC7948		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 7.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 311</b>	A. Description of hazardous waste MERCURY VIALS RC8153		
B. EPA hazardous waste code D002 D007 D009 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 217.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W002	H. Management method code H141
<b>WASTE 312</b>	A. Description of hazardous waste MERCURY CONTAMINATED SOIL RC8172		
B. EPA hazardous waste code D009			
C. State hazardous waste code		D. Off-site handler EPA ID number NMCESQG	E. Quantity received in 2007 195.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W301	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 313</b>	A. Description of hazardous waste LABPACK RC7887		
	B. EPA hazardous waste code D001 D002 D003 D007 D008		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000333211	E. Quantity received in 2007 1591.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001
<b>WASTE 314</b>	A. Description of hazardous waste LABPACK RC7822		
	B. EPA hazardous waste code D002 D007		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 20.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001
<b>WASTE 315</b>	A. Description of hazardous waste LABPACK RC7861		
	B. EPA hazardous waste code D002		
	C. State hazardous waste code	D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 58.00
	F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001
H. Management method code H141			
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 316</b>	A. Description of hazardous waste LABPACK RC7987		
B. EPA hazardous waste code D001 D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 178.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 317</b>	A. Description of hazardous waste LABPACK RC8120		
B. EPA hazardous waste code D002 D007			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD000610303	E. Quantity received in 2007 17.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 318</b>	A. Description of hazardous waste LABPACK RC7880		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD061268819	E. Quantity received in 2007 20.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627



U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 319</b>	A. Description of hazardous waste LABPACK RC8012		
B. EPA hazardous waste code D001			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD981610090	E. Quantity received in 2007 50.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 320</b>	A. Description of hazardous waste LABPACK RC8018		
B. EPA hazardous waste code D001 D002 D005 D011 D019 D040 P105 U031 U122 U211 U228			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD982306110	E. Quantity received in 2007 232.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 321</b>	A. Description of hazardous waste LABPACK RC7858		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD986682466	E. Quantity received in 2007 100.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 322</b>	A. Description of hazardous waste LABPACK RC8019		
B. EPA hazardous waste code D001 D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMD986684165	E. Quantity received in 2007 254.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 323</b>	A. Description of hazardous waste LABPACK RC7818		
B. EPA hazardous waste code D001 D002 D003 D013			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011264	E. Quantity received in 2007 1157.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 324</b>	A. Description of hazardous waste LABPACK RC8020		
B. EPA hazardous waste code D001 D002 D003 D005 D006 D007 D008 D018 D019 P030 U001 U057 U122 U135 U154 U188 U201 U211 U220 U239			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011276	E. Quantity received in 2007 485.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 325</b>	A. Description of hazardous waste LABPACK RC8080		
B. EPA hazardous waste code D001 D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011279	E. Quantity received in 2007 83.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 326</b>	A. Description of hazardous waste LABPACK RC8135		
B. EPA hazardous waste code D001 D002 D005 D007 D008 D011 P030 P106 U134 U144			
C. State hazardous waste code		D. Off-site handler EPA ID number NMP360011282	E. Quantity received in 2007 1076.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 327</b>	A. Description of hazardous waste MIXED SOLVENTS RC6645		
B. EPA hazardous waste code D001 F003 F005			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000001529	E. Quantity received in 2007 1191.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W219	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

FORM  
WR

U.S. ENVIRONMENTAL  
PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED  
FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 328</b>	A. Description of hazardous waste PHOTOGRAPHIC FIXER RC7700		
B. EPA hazardous waste code D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000001529	E. Quantity received in 2007 558.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W119	H. Management method code H141
<b>WASTE 329</b>	A. Description of hazardous waste LABPACK RC7814		
B. EPA hazardous waste code D001 D002 D007 U003 U007 U122 U138 U188 U220			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000001529	E. Quantity received in 2007 100.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 330</b>	A. Description of hazardous waste LABPACK RC7824		
B. EPA hazardous waste code D001 D002 D022 U122 U154 U188 U246			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000001529	E. Quantity received in 2007 209.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

WR Page 110

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 331</b>	A. Description of hazardous waste LABPACK RC8010		
B. EPA hazardous waste code D001 D002 D035 U159			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000004952	E. Quantity received in 2007 216.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 332</b>	A. Description of hazardous waste LABPACK RC7804		
B. EPA hazardous waste code D001 D002 D003 D005 D008 D009 D011 U056 U123 U154			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 592.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 333</b>	A. Description of hazardous waste LABPACK RC7867		
B. EPA hazardous waste code D001 D002 D005 D008 D011 U123			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 928.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 334</b>	A. Description of hazardous waste LABPACK RC7925		
B. EPA hazardous waste code D001 D002 D005 D008 D009 D011 U196			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 410.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 335</b>	A. Description of hazardous waste LABPACK RC7997		
B. EPA hazardous waste code D001 D002 D005 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 576.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 336</b>	A. Description of hazardous waste LABPACK RC8076		
B. EPA hazardous waste code D001 D005 D008 D011			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000009191	E. Quantity received in 2007 331.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY

2007 HAZARDOUS WASTE REPORT

WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 337</b>	A. Description of hazardous waste LABPACK RC7784		
B. EPA hazardous waste code D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012153	E. Quantity received in 2007 64.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 338</b>	A. Description of hazardous waste LABPACK RC7915		
B. EPA hazardous waste code D001 D002 D003 D005 D006 D007 D008 D011 P106 U122 U123 U133 U219			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 563.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 339</b>	A. Description of hazardous waste LABPACK RC7965		
B. EPA hazardous waste code D001 D002			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012583	E. Quantity received in 2007 50.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER

SITE NAME: RINCHEM COMPANY INC.,

EPA ID NO: NMD002208627

**FORM  
WR**

U.S. ENVIRONMENTAL PROTECTION AGENCY  
2007 HAZARDOUS WASTE REPORT  
WASTE RECEIVED FROM OFF SITE

Instructions: Please see the detailed instructions beginning on page 27 of the instructions and forms booklet before completing this form

<b>WASTE 340</b>	A. Description of hazardous waste LABPACK RC8106		
B. EPA hazardous waste code D001 D002 D005 D007 D008 D011 P030 U002 U056 U122 U154 U220 U239			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 416.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W004	H. Management method code H141
<b>WASTE 341</b>	A. Description of hazardous waste LABPACK RC7975		
B. EPA hazardous waste code D001 D002 D016			
C. State hazardous waste code		D. Off-site handler EPA ID number NMR000012708	E. Quantity received in 2007 1143.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>WASTE 342</b>	A. Description of hazardous waste LABPACK RC7996		
B. EPA hazardous waste code D022			
C. State hazardous waste code		D. Off-site handler EPA ID number NM3890116129	E. Quantity received in 2007 48.00
F. UOM 1	Density <input type="checkbox"/> 1 lbs/gal <input type="checkbox"/> 2 sg	G. Form code W001	H. Management method code H141
<b>Comments:</b>			

Submit Date: