



DEPARTMENT OF THE AIR FORCE

HEADQUARTERS 27th FIGHTER WING (ACC)
CANNON AIR FORCE BASE, NEW MEXICO

15 APR 1994

William M. Guth, Brig Gen, USAF
Commander
100 S DL Ingram Blvd Ste 100
Cannon AFB NM 88103-5214

Mr. William K. Honker
U.S. EPA Region VI
Chief, RCRA Permits Branch
1445 Ross Avenue Suite 1200
Dallas TX 75202-2733



Dear Mr. Honker

XIII


On March 2, 1994, we uncovered a site of possible contamination on base. This site was uncovered by a contractor while preparing a site for a parking lot. As he was excavating soil, he realized it seemed to be contaminated with some sort of petroleum or solvent products. After filling in the excavation with clean fill, the work was stopped and Cannon AFB officials notified.

We have not yet located the source of this contamination. We have taken samples of the contaminated soil and will run a full TCLP suite, including pesticides. When these results are returned from the laboratory, we may be able to pinpoint the source of this contamination. Until these samples are returned, we will be calling this Area of Concern number 36.

We will inform your office upon receipt of sample results and determination of possible source. We are now pursuing funding to further investigate this site. We would like to enter directly into the Remedial Investigation phase of IRP program. We will continue to keep you up to date with all actions associated with this site.

The point of contact for this issue at Cannon AFB is Mr. John Ekhoﬀ at (505) 784-2739.

Sincerely


WILLIAM M. GUTH
Brigadier General, USAF
Commander

Attachment:
Site Map

cc:
Dave Morgan, NMED
Steve Pullen, NMED

Global Power for America

GENERAL AREA OF CONTAMINATED SOIL BY
BLDG. 214

→ APPX. 72.06' FROM BLDG. 214

↘ APPX. SOUTH 53.5 DEGREES WEST

