


FORT BLISS DIRECTORATE OF ENVIRONMENT

ATZC-DOE-M, MULTIMEDIA BRANCH

BLDG. 515B, CORNER OF PERSHING AND PLEASANTON ROADS

VOX: (915) 568-6959 (COMM); 978-6959 (DSN)

FAX: (915) 568-1333 (COMM); 978-1333 (DSN)



 ENTERED

FAX

TO:

Larry Bruckey - USEPA / Dave Morgan NMTED

FAX#:

(214) 665-6460 / (505) 827-2965

phone 665-8303

827-2754

FROM:

Yvette McKenna

DATE:

11/10/94

SUBJECT:

Summer info - per Col. Rued

PAGES:

1 + covers

NOTES:

I hope this gets Summers # 20 & 29 off the list. Let me know what you decide. Thanks

Rec'd 11/10/94
WmREPLY TO
ATTENTION OFDEPARTMENT OF THE ARMY
1ST COMBINED ARMS SUPPORT BATTALION (PROVISIONAL)
FORT BLISS, TEXAS 79916-9500

ATZC-B

November 2, 1994

MEMORANDUM FOR Director of Environment, ATTN: Mrs. McKennen, Fort Bliss
Texas 79916

SUBJECT: Solid Waste Management Unit (SWMU)

1. References:

- a. Inactive open detonation area, McGregor Range; SWMU #20
- b. Landfill #11 (Dona Ana) SWMU #29
- c. Landfill #12 (Dona Ana Rubble Pit) SWMU #27


2. References established three SWMUs. The following information is submitted to detail action taken against each reference.

3. SWMU #20; a through search has been made of the inactive open detonation area. A physical walk thru was made by personnel from 1st CAS Bn, EPA, DOE, and New Mexico State Environmental Inspectors which yielded no evidence. An aerial search was also conducted. All attempts have been fruitless to provide a single piece of evidence depicting a site location and/or activity of an open detonation area.

4. SWMU #29; an extensive search has been performed for the Dona Ana Landfill #11. The 1st CAS Bn personnel can't locate the site and we find no evidence it ever existed.

5. SWMU #27; (The Dona Ana Rubble Pit) Landfill #12 caught fire on approximately 15 June 1994. The estimated depth of the trench is 10 ft. It was covered with earth on approximately 30 August, 1994.

6. POC is Ms. Greta Couroux, 5-9302/9368.



REID K. LUND
LTC, AD
Commanding

Table 2: SWMUs REQUIRING AN RFI

Below is a list of the SWMUs requiring an RFI.

- SWMU 18 - McGregor "Rubble Pit" (Landfill No. 13)
- SWMU 19 - McGregor Range Oxidation Pond
- SWMU 20 - Inactive Open Detonation Area
- SWMU 25 - Oro Grande "Rubble Pit" (Landfill No. 14)
- SWMU 25B - Oro Grande Oxidation Pond
- SWMU 27 - Dona Ana "Rubble Pit" (Landfill No. 12)
- SWMU 27B - Dona Ana Oxidation Pond
- SWMU 29 - Landfill No. 11
- SWMU 76 - Meyer Range Oxidation Pond

SWMUs ided w RFA not included.

- #17 EAST MCGREGOR OBO
- + 21 MCGREGOR FIRE FIGHTING TRAINING AREA.
- + 22 MCGREGOR DRUM AREA.
- 23 MCGREGOR OIL/WATER SEPARATION SUMP.
- 24 MCGREGOR OIL/WATER SEPARATION.
- 16 DONA ANA OBO.
- ~~420 DONA ANA WASTE ACCUMULATION AREA.~~