



BRUCE KING  
GOVERNOR

State of New Mexico  
**ENVIRONMENT DEPARTMENT**  
Harold Runnels Building  
1190 St. Francis Drive, P.O. Box 26110  
Santa Fe, New Mexico 87502  
(505) 827-2850

JUDITH M. ESPINOSA  
SECRETARY

RON CURRY  
DEPUTY SECRETARY

MEMORANDUM

TO: File, <sup>GEAPP</sup> ~~GE~~/red/93

THROUGH: Edward Horst, RCRA Program Manager, and Steve Alexander, <sup>SAA</sup> Technical Section Supervisor

FROM: Ron Kern, <sup>RK</sup> Technical Program

DATE: February 25, 1993

SUBJECT: **Abandonment and Plugging of Wells/Piezometers at the General Electric Facility, Albuquerque**

Vincent Malott (EPA, Region VI) telephoned to indicate that EPA is overseeing the abandonment and plugging of some wells and piezometers at the General Electric (GE) facility. Wells and Piezometers will be plugged on March 8 and March 9.

Vince had telephoned on February 23 to determine if NMED had more strict guidelines than required by the State Engineer's Office for the plugging and abandonment of wells. I informed Vince that NMED was not more specific and that grout and capping were the only requirements.

PRC, contractor for the EPA, will be present to monitor the grout and capping procedure. Screened intervals will be pressure grouted.