

file



Confidential

FACSIMILE TRANSMITTAL

I

U.S. EPA REGION 6
HAZARDOUS WASTE MANAGEMENT DIVISION
1445 ROSS AVENUE
DALLAS, TEXAS 75202-2733

TO:	STEVE PULLEN - NMED	
MACHINE NUMBER:	(505) 827-4361	VERIFICATION NUMBER: ()
FROM:	Nancy Rinehart Morlock EPA Region 6 RCRA Permits Branch New Mexico and Federal Facilities Section	
PHONE:	(214) 665- 6650	MAIL CODE: 6H-PN
OFFICE:	10.085	
DATE:	11/23/94	PAGES, INCLUDING COVER SHEET: 7
PLEASE NUMBER ALL PAGES		
INFORMATION FOR SENDING FACSIMILE MESSAGES		
OUR EQUIPMENT	FACSIMILE NUMBER	
PANAFAX UF-766	(214) 665-6460 or (214) 665-6660	
COMMENTS: Steve- Attached is our draft letter on the NMERI site. Also attached is the site specific sampling plan for the Laundry Facility. Please call with any questions or comments on either document. The NMERI letter will probably be signed today or Monday. The Laundry Facility response should go out next week. Thanks, Nancy		
Copies to:		

KAFB1542



Christopher DeWitt, Acting Chief
Restoration Branch
Environmental Management Division
377 ABW/EM
2000 Wyoming Boulevard SE
Kirtland Air Force Base, NM 87117-5659

DRAFT

Dear Mr DeWitt:

The Environmental Protection Agency (EPA) has completed a review of your October 3, 1994 Solid Waste Management Unit (SMWU) Assessment Report on pits and surface anomalies located near the former New Mexico Engineering Research Institute site, Building 57000 area.

Based upon the sampling information and site descriptions provided, the EPA has concluded that the pits and surface anomalies are not SWMUs and should therefore not be added to Kirtland's RCRA/HSWA permit.

Please contact Nancy Morlock of my staff at (214) 665-6650 if you have any questions or need additional information.

Sincerely yours,

William K. Honker, P.E., Chief
RCRA Permits Branch

cc: Mr. Benito Garcia, Chief
Hazardous and Radioactive Materials Bureau
New Mexico Environment Department