



From: Bitner, Ludie W Jr Civ USAF AFMC 377 MSG/CEANR [mailto:Ludie.Bitner@kirtland.af.mil]
Sent: Thursday, March 24, 2011 4:03 PM
To: Bearzi, James, NMENV; Olson, Bill, NMENV; Moats, William, NMENV; McDonald, William, NMENV; Brandwein, Sid, NMENV
Cc: Wilson, Brent Civ USAF AFMC 377 MSG/CE; Bohannon, Herbert C Civ USAF AFMC 377 MSG/CE2; Agnew, Diane; Cooper, Thomas
Subject: Engine Replacement

Gentlemen

It was brought to my attention that we have a poorly performing engine on the SVE unit located on KAFB Well 1068. The engine was diagnosed yesterday afternoon with low compression pressure in 5 of 8 cylinders on engine number 2. Suggested remedy replace engine with engine on hand. The replacement will begin 25 March and take approximately one week for the unit to be brought back online. I will be sending another email with a detailed schedule of events associated with the engine replacement. We will also notify you when the unit is again fully functional. Thanks.

Wayne Bitner
Chief, Environmental Restoration
ludie.bitner@kirtland.af.mil
505-853-3484
DSN 263-3484

KAFB3711

