



BRUCE KING
GOVERNOR

State of New Mexico
ENVIRONMENT DEPARTMENT
DOE/LANL Oversight Program
P.O. Box 1663, MS/M-993
Los Alamos, New Mexico 87545

JUDITH M. ESPINOSA
SECRETARY

RON CURRY
DEPUTY SECRETARY

M E M O R A N D U M

To: Steve Alexander, Manager, RCRA Technical Enforcement Program

Through: Bruce Swanton, POC, AIP/LANL

From: Danny Katzman, AIP/LANL

Date: August 3, 1993

Re: **Comments on RFI Phase Report for OU 1071, SWMU Aggregate 0-G, Leakage from PCB Transformers**

The "Phase Report for OU 1071, SWMU Aggregate 0-G, Leakage from PCB Transformers" appears to satisfy the requirements for No Further Action status.

In general, however, the Phased Report contains the following minor deficiencies which should be addressed in future reports of this kind.

- 1). No details are given as to how deep the excavation went. Only the volume removed (20 cubic yards) was documented in the Report. More details of the remediation efforts will be necessary in future reports.

- 3). For the sake of succinct Phase Reports, sections such as "background", and "geology and hydrology" should be combined where possible into single, brief sections.

cc:

Barbara Driscoll, EPA Region 6
Benito J. Garcia, Chief, HRMB
Neil Weber, Chief, DOE Oversight Program
File, LANL, Red 93
File, AIP Program

rfi\1071\pcb



6733

TL