

LEN-HS

From: Andy Crowder <crowder@alice.lanl.gov>
To: LAAO.LAAO WPO(bkoch)
Date: 1/24/96 5:08pm
Subject: Response to 0-18 Questions

Bonnie~

The information you requested regarding the inactive Firing Range (0-018) is as follows:

1. SAMPLE COLLECTION: Bullets and lead fragments were not removed from the soil before compositing or homogenizing. If the sample was sieved at the lab as part of the procedure, then the larger fragments and whole bullets, if present, (slugs) would likely have been removed before analysis.

2. ANALYTICAL LABORATORY: The most recent samples were analyzed by Analytical Technologies, Inc., of Fort Collins, Colorado. The phone number is (303) 490-1511, and the contact is Lance Steere. It may be a good idea to keep John Miglio, SMO, informed of these events.

If you have any further questions, please contact me.

Thanks.

-Andy

.....
Andrew J. Crowder (crowder@alice.lanl.gov)
ERM/Golder Los Alamos Project Team
2237 Trinity Drive, Bldg 2, MS: M327

OFFICE: (505) 862-1338; FAX: 861-9699;
CELLULAR: 470-2497; PAGER: 820-4413

CC: Carl Newton <cnewton@lanl.gov>



6815

FL 170