



Department of Energy
Los Alamos Area Office
Albuquerque Operations Office
Los Alamos, New Mexico 87544

NEW MEXICO
ENVIRONMENTAL DEPARTMENT
1994 DEC -5 AM 11:25
OFFICE OF THE SECRETARY

NOV 18 1994

LAAL
OU 7114

Ron K
Barbara
file

William K. Honker, P. E., Chief
RCRA Permits Branch
U. S. Environmental Protection Agency
Region 6
1445 Ross Avenue, Suite 1200
Dallas, Texas 75202-2733

Dear Mr. Honker:

Subject: Schedule for Activities Associated with Solid Waste Management Unit
(SWMU) 3-010(a) Phase II Sampling Plan

This letter transmits the information you requested in your letter dated October 28, 1994, which was received at LAAO on November 2, 1994. The following schedule outlines the field and report activities associated with the Phase II Sampling Plan for SWMU 3-010(a).

Mobilize Phase II field activities	September 7, 1994
Complete Phase II field activities	January 27, 1995
Submit RFI report for Phase II activities	April 28, 1995

Should you have any questions, please feel free to contact Bonnie Koch of my staff at (505) 665-7202.

Sincerely,

Theodore J. Taylor
Program Manager
Environmental Restoration Program

LAAMEP:9BK-001

cc:
See page 2

R



5449

William K. Honker

2

-NOV 18 1994

CC:

Kathleen Sisneros

Water and Waste Management
Division
New Mexico Environment
Department
1190 St. Francis Drive
P. O. Box 26110
Santa Fe, New Mexico 87502
W. Spurgeon, EM-452, HQ
E. Merrill, EM-452, HQ
T. Taylor, AAMEP, LAAO
B. Koch, AAMEP, LAAO
K. Schenck, Sciencetech, LAAO
T. Baca, EM-DO, LANL, MS-J591
J. Jansen, EM/ER, LANL,
MS-M992
J. White, ESH-18, LANL,
MS-497
G. Allen, CST-18, LANL,
MS-J525
B. Swanton, NMED-AIP, LANL,
MS-J993
RPF, LANL, MS-M707
J. Levings, ERPO, AL