

LOS ALAMOS SCIENTIFIC LABORATORY WORK ORDER

LOCATION: TA- 10 STRUCTURE Bayo ROOM GROUP 5X-5

ENG. 4 ENGINEER Suchfarber or PHONE 8-5466 LASL I. O. 64554(47811)

HEALTH CLEARANCE REQ. Buckland 7-4127 S. C. D.

ESTIMATED COST W.O.R. BUDGET ITEM LAB. JOB

NOTE - SECURITY CLEARANCE, COORDINATION, CHANGES AND ACCEPTANCE OF COMPLETED WORK ON THIS ORDER MUST BE APPROVED BY THE ABOVE ENG. 4 ENGINEER.

1276 TA-10
G. S. H. H. H.

COST CODE		CRAFTS
8405-40	<p>SUBJECT: Burn and remove debris.</p> <p>PERFORM THE FOLLOWING WORK:</p> <p>Remove trash pile at Bayo Canyon. Separate in pile in half (approx) and make a burning pit. Burn all combustible material in pit under direction of Fire Department. Move all empty steel containers (approx 19) from west end of DP contaminated dump to Bayo Canyon and locate as directed. Construct ramp to steel containers. Locate water tanks (minimum 2,000 gallons) on hillside near burning pit. Place all ashes and small metal material in steel containers and take to dump located on Pajarito Road. Move all large pieces of non-combustible material to same dump in contaminated truck. Also move 2 small piles of trash located westward up the canyon to the burning pit. After completion of burning fill up pit, rake up and remove remaining debris.</p> <p>The above work is to be performed 24 hours per day, 7 days per week, until completed.</p>	Laborers Riggers Transp.



APPROVED BY: _____
ENG. 4 GROUP LEADER OR AUTHORIZED ALTERNATE

Memo Rutledge to Reynolds 7-17-56

RECEIVED 7-26-56	DISPATCHED 7-26-56	ACCEPTED	HAZARD CODE	WORK ORDER NO. 570387
---------------------	-----------------------	----------	-------------	--------------------------