

## V. FACILITY DRAWING (see page 4)

TA-14  
LIST OF FIGURES

6 Copies

1. Los Alamos Technical Areas.
2. Contour Map Showing the Location of the TA-54, Area L Treatment Tanks, Surface Impoundments, Waste packaging and Storage Pad, Shafts, and TA-54, Area G.
3. TA-54, Area L Waste Management Units.
4. TA-54, Area L Chemical Storage Facility Location Map.
5. TA-54, Area L Chemical Storage Facility Structural Drawing.
6. TA-54, Area L Waste Transfer, Packaging, and Storage Building.
7. Contour Map Showing the Location of TA-54, Area H, Shaft No. 9.
8. Contour Map Showing the Locations of the Batch Treatment System and Container Storage Area and the Waste Incinerator.
9. Locations of TA-50 Chemical Waste Incinerator and Container Storage Units.
10. Structural Diagram of the TA-50 Batch Waste Treatment Facility.
11. Treatment Development Facility Showing Locations of Chemical Waste Incinerator and Support Facilities.
12. Incinerator Process Diagram.
13. Chemical Storage TA-50.
14. Safety Storage Containers Brochure.
15. Contour Map Showing Location of TA-16 Open Burning Unit and TA-16-1150 Incinerator.
16. TA-16 Industrial Incinerator.
17. TA-16 Industrial Incinerator Structural Drawing.
18. TA-16 Pressure Vessel Structural Drawing.
19. TA-54, Area L Treatment Tanks Plan.
20. Contour Map Showing the Location of the TA-14 Firing Point and Burn Cage and the TA-40 Scrap Detonation Site.
21. Contour Map Showing the Location of the TA-15 and TA-36 Firing Points.
22. Contour Map Showing the Location of the TA-39 Firing Points.
23. Contour Map Showing the Locations of the TA-35-125 and TA-35-85 Surface Impoundments.
24. TA-54, Area L Conceptual Drawing of Container Storage Pad.



## V. FACILITY DRAWING (see page 4)

## LIST OF PHOTOGRAPHS

TA-14-23 and 35 - Building with firing point 35.

TA-15, Phermex - Firing point.

TA-16-387 - Burn Pad for Flashing Equipment.

TA-16-406 - Pressure Vessel for Dried HE Sludge and Associated Storage Area.

TA-16-394 - Burn Pads for HE Contaminated Oil.

TA-16-401 - Pressure Vessel for Dried HE Sludge and Associated Storage Area.

TA-16-399 - Burn Pad.

TA-16-388 - Burn Pad.

TA-36-57 - Kappa 8 - Firing Point.

TA-39-57 - Firing Point.

TA-39-6 - Firing Point.

TA-50-1 - Building Housing and Batch Waste Treatment Unit.

TA-50-1 - Batch Waste Treatment.

TA-50-1 - Batch Waste Treatment.

TA-50-114 - Hazardous Waste Treatment

TA-50-37 - Chemical Waste Incinerator Facility (east side).

TA-54, Area L - Front Gate

TA-54, Area L - Gas Cylinder Storage.

TA-54, Area L - Treatment Tanks.

TA-54, Area L - Nonliquid Hazardous Waste Storage.

TA-54, Area L - Hazardous Waste Storage Unit.

DRAWING 30121b J2 08 A5  
 NUMBER  
 10/23/77  
 10/24/88  
 CHECKED BY  
 APPROVED BY  
 KCT  
 10/11/88  
 By





FIGURE 1  
 LOS ALAMOS  
 TECHNICAL AREAS  
 PREPARED FOR  
 LOS ALAMOS  
 NATIONAL LABORATORY  
 LOS ALAMOS, NEW MEXICO

