

TA 16

Goering, Darlene, NMENV

From: Goering, Darlene, NMENV
Sent: Tuesday, March 06, 2007 11:11 AM
To: 'Don Hickmott'
Cc: Young, John, NMENV
Subject: SWMU 16-021(c) Outfall Drainage

Don,

During a meeting on 2/12/07, you requested that NMED determine if it was necessary to excavate several hot spot locations underneath the existing bentonite cap in the drainage channel. According to the Interim Measures Report for this site, several locations have RDX concentrations above 100 ppm, the cleanup level for the interim measures. Because the approved remedy for this component of the SWMU calls for complete removal of existing contamination, I feel we don't really have any option other than to remove the cap and excavate these areas. You should incorporate this activity into the Corrective Measures Implementation Plan.

Darlene Goering
Environmental Specialist
New Mexico Environment Department
2905 Rodeo Park Drive East, Bldg. 1
Santa Fe, NM 87505
505-476-6042
505-476-6030 Fax



6673

3/6/2007