


*Barbara
for K*

Los Alamos National Laboratory

UNIVERSITY OF CALIFORNIA



Environmental Restoration Project
MS M992
Los Alamos, New Mexico 87545
505-667-0808/FAX 505-665-4747

Date: April 1, 1996
Refer to: EM/ER:96-178



Ms. Barbara Driscoll
NM Federal Facilities Section
EPA, Region 6, 6PD-N
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733

SUBJECT: FIELD UNIT 3 SAMPLING AT FORMER OPERABLE UNIT (OU) 1122

Dear Ms. Driscoll:

Field Unit 3 is planning to start sampling at former OU 1122 on May 1, 1996 through approximately June 30, 1996. Sampling will be performed as part of the Resource Conservation and Recovery Act Facility Investigation efforts at OU 1122, Technical Area (TA) 33. Samples will be collected as shown in the enclosed table. In addition, a pilot project will be conducted at TA-33 to test remediation technologies. This work will commence on or about April 15, 1996 and finish on April 30, 1996.

The readiness review for this sampling activity and pilot project will be conducted on April 2, 1996. If you have any questions or concerns, please feel free to give me a call at (505) 667-0819.

Sincerely,

Dave McInroy
Environmental Restoration Project

DM/bp



16

Enclosures: Table

Cy: J. Jansen, EM/ER, MS M992
J. White, ESH-19, MS K490
R. Bohn, EM/ER, MS M992
B. Garcia NMED
L. Kidman, ICF KE, MS M892
B. Martin, CST-18, MS E525
R. Michelotti, CST-18, MS E525
T. Taylor, LAAO, MS A316
E. Trollinger, LAAO, MS A316
S. Yanicak, AIP, NMED, MS J993
EM/ER File, MS M992
RPF, MS M707

SAMPLING SCHEDULE

FIELD UNIT 3, FORMER OPERABLE UNIT 1122

Location	Number of Samples	Sample Type	PCOCs
010(a) VCA	0-2	debris/soil	Beryllium Lead Uranium
010(b) VCA	1-2	soil	Beryllium Lead Uranium
010(d) VCA	0-2	debris/soil	Beryllium Lead Uranium
011(b) VCA	0-2	debris/soil	Beryllium Other Metals Uranium
010(g) VCA	0-2	debris/soil	Beryllium Other Metals HE Uranium
004(k) Phase I	0-2	surface soil soil/tuff interface	Photo Processing Chemicals (SVOC, Metals, Cyanide)
004(b) Phase I	1	sediment	Photo Processing Chemicals (SVOC, Metals, Cyanide)
008(a) Phase I	16	8 soil 8 debris	Beryllium Lead HE Solvents (Metals, Uranium, TCLP, SVOC, HE)
008(b) Phase I	24	12 soil 12 debris	Beryllium Lead HE Solvents (Metals, Uranium, TCLP, SVOC)

FY96 SAMPLING SCHEDULE (continued)
FIELD UNIT 3, FORMER OPERABLE UNIT 1122

Location	Number of Samples	Sample Type	PCOCs
002(a) Phase II	10 (20 for Rad van)	tuff	Solvents Uranium Plutonium Tritium (Rad, VOC, SVOC, Metals)
002(b) Phase II	5	tuff	Ethanol Methanol TCE Benzene Acetone Beryllium Mercury Uranium Tritium (Rad, VOC, SVOC, Metals)
002(c) Phase II	5	tuff	TCE Methanol Ethanol Acetone Propanol Tritium (Rad, VOC, SVOC, Metals)