

COPY

TA-0-90
216

Listed Below

December 30, 1950

Carl Buckland, H-1 Monitoring Section

CONTAMINATED DUMP

H-1

AREA 'C'

A meeting was held on December 28, 1950, concerning the contaminated dump. It was decided at that time that H-1 Monitoring would be responsible for Rad-Safety of all persons entering the dump commencing January 5, 1951.

Our responsibilities are as follows:

1. Furnish full protective clothing including respirator to George Yates, Zia Co., who covers the trash every Friday. Yates has to be monitored after each job and nose swipes taken. He is scheduled for routine Health Pass test. By copy of this memo I'm requesting that Glenn Vogt write monthly work orders to cover the bulldozer work. The maintenance man of D-Bldg. formerly took care of this detail.
2. H-1 Monitoring will be notified upon arrival of highly active beta-gamma contaminants requiring a knowledge of tolerance times. We will also be notified upon arrival of hot filters from D.P. Site. This advance information will assist us in case of fire for which we are responsible.
3. Film badges and pocket chambers should be issued in cases of high beta-gamma activity.

CMR-Safety and CMR-12 will continue to dump chemicals in the proper place and contaminated items in another. Dean Meyer has stated that if at any time we feel that things are not dumped where we think they should, to contact him.

/s/ Carl Buckland
H-1 Monitoring Section

CB:pe

cc: Chas H. Perry
Glenn Vogt
Dean Meyer
Jack Aeby
Robert Barker
Chas. Blackwell
Ralph Gosline
Reynold Hoover
Files

COPY

C



8246