

TA54

**Description of Photos of TA-54, Area G, Pad 2
Drum Removal on
April 7, 1992
and
Photo of Overpack Drums as they Appear Currently
at TA-54, Area G, Dome 48**

1. TA-54, Area G, Pad 2 - two members of the Johnson Controls Inc. (JCI) crew remove swiped 55-gallon drums containing TRU wastes out of the pad. Streaking discoloration is a rust inhibitor sprayed on drums at the time they were placed in the pad.
2. A 55-gallon drum of waste is lowered into a 12-mil plastic liner onto a truck, which will be transported to MD-33.
3. Packaged 55-gallon drum of waste at TA-54, Area G, Pad 2 whose outer layer of paint is rusting and peeling off. Streaking discoloration is a rust inhibitor sprayed on drums at the time they were placed in the pad. Corrosion noted on surface of container at the rolling ring either caused by stress or paint scraped off during packaging.
4. Packaged 55-gallon drum of TRU waste at TA-54, Area G, Pad 2 whose outer layer of paint is rusting and peeling off, similar evidence of corrosion as cited in photo #4.
5. Overpacked drums in current storage array at TA-54, Area G, Dome 48.

Attachment

E



11254

Photo #1



Photo #2



Photo #3



Photo #4



Photo # 5

