

11:45

file 90 Red
Signetics

Telephone Personal Time 02/28/90 Date 02/28/90

Originating Party	Other Parties
Gary Murrakis	AG Gordon
Signetics	Haz Waste

Subject

Discussion
Tank 4+5; permission
removes 4+5 replace new tanks
is closure necessary

done over the phone with Kelley

can replace at any time;

RORA -

Conclusions or Agreements

Distribution Signed AG Gordon

- TKs 4 & 5 - located in lined concrete vaults
- used to store DOOZ (Corrosive wastes)
 - minimum Shell Thickness - .43"
 - corrosion barrier Veils - min thickness .0118"
 - ultrasonic testing every 2 yrs

- New 6/82

- TK 5 Hydrofluoric acid 5000 gal cap.

- TK 4 Buffered Acid waste

- vaults, underground, covered vaults - concrete & coated w/
chemically-resistant resins. pg 31 (E)

- Tanks UL labeled, flat bottom & top,
fiberglass, supported by 5/16" - pg 28 App E

- AH F pg 74 Closure Plan

- post-closure not required because this is not a
disposal facility

* 264.112(d) Notification required ✓

264.197 Closure & post closure care

at closure of [a tank system] - description

see 264.112
264.115

- closure description & cert. / \$

of tank system only (in permit only required for final closure)

- what, where rinsate & scrap.

no insp, test of new tank - tank identical to old one., ~~and~~
~~assume~~ cert req for installation