

WIPP Tour Approval

New Mexico Environment Department
Tuesday, January 8, 2012

Visit coordinator Rose B. Scott (575) 234-7512	Visit escort (s) Wes Boatwright, RES Rey Carrasco, NWP Randy Britain, NWP (surface only) Steve Travis, RES (surface only)	Visit requester George Basabilvazo/CBFO
---	--	--

Attendees:

1. Trais Kliphuis, NMED Hazardous Waste Bureau WIPP Group Leader
2. Ricardo Maestas, NMED Hazardous Waste Bureau
3. Steve Holmes, NMED Hazardous Waste Bureau
4. George Basabilvazo, CBFO
5. Anthony Stone, CBFO
6. Rick Chavez, RES
7. Ty Zimmerly, NWP
8. David Ganaway, RES

Areas to be toured: <input checked="" type="checkbox"/> Contact Handling Bay (WHB) <input checked="" type="checkbox"/> Underground <input checked="" type="checkbox"/> Remote Handling Bay <input type="checkbox"/> Emergency Operations Center <input type="checkbox"/> Central Monitoring Room <input type="checkbox"/> Fire Station <input type="checkbox"/> Surface Only	Special activities <input type="checkbox"/> Radiological Materials Area <input type="checkbox"/> UG blue area permit <input type="checkbox"/> Photographic Support <input checked="" type="checkbox"/> TLDs <input checked="" type="checkbox"/> Escort(s) will control Camera access
--	--

Tour classification:

High priority
 Work/Job specific
 Standard

Transportation plan: **Transportation provided by DOE**

Tour agenda: **See attached sheet.**

Purpose: **Enhance knowledge of facility and requirements.**

Security

Foreign nationals <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Foreign national host Name: Phone:	Foreign national escort Name: Phone:
--	---	---

Foreign visitor assignee request submitted: <input type="checkbox"/> Yes <input type="checkbox"/> No	Foreign visitor assignee request approved: <input type="checkbox"/> Yes <input type="checkbox"/> No
---	--

Carlsbad Field Office Approval:

December 20, 2012

Deb Gill, DOE Public Affairs Date

Photo ID Required

Prohibited attire: dresses, skirts, shorts, open-toe shoes, high-heeled shoes and sandals

Revised: 1/7/2013



**WIPP TOUR AGENDA
New Mexico Environment Department
Tuesday, January 8, 2012**

7:00 a.m.	Visitors arrive at Skeen Whitlock Building and meet CBFO and WTS representatives in the lobby area
7:20 a.m.	Transport to WIPP
8:05 a.m.	Visitors arrive on site -Security Office for visitor badges Auditorium Guard & Security Building - view safety briefing
9:00 a.m.	To Lamp Room for underground safety equipment and accountability tags Underground tour – Wes Boatwright, RES & Rey Carrasco, NWP ➤CH – TRU waste emplacement process ➤RH - TRU waste canister insertion equipment
11:00 a.m.	Return to Surface
11:15 a.m.	No host lunch site cafeteria
12:00 p.m.	Surface tour – Randy Britain Meet in lamproom and obtain TLDs for surface tour (escorts Randy Britain & Steve Travis) Waste Handling Building ➤CH Bay ➤RH Bay TRUPACT-III
1:30 p.m.	Tour concludes
2:00 p.m.	Depart site
2:45 p.m.	Arrive SWB/Meetings with RES & CBFO

Photo ID Required
Prohibited attire: dresses, skirts, shorts, open-toe shoes, high-heeled shoes and sandals
Revised: 1/7/2013