



**Allen, Pam, NMENV**

---

**From:** Maestas, Ricardo, NMENV  
**Sent:** Wednesday, December 17, 2014 4:18 PM  
**To:** Allen, Pam, NMENV  
**Subject:** FW: Accuracy of Request

May

**From:** Kouba, Steve - WRES [<mailto:Steve.Kouba@wipp.ws>]  
**Sent:** Thursday, May 01, 2014 2:44 PM  
**To:** Maestas, Ricardo, NMENV  
**Subject:** RE: Accuracy of Request

Ricardo

Thank you. I have incorporated your words into the action.

Steve

Steve Kouba  
Nuclear Waste Partnership LLC  
Regulatory Environmental Services  
Contractor to the Department of Energy  
4021 National Parks Hwy - MS GSA-109  
Carlsbad, NM 88220  
[steve.kouba@wipp.ws](mailto:steve.kouba@wipp.ws)  
575 234-7443  
575 302-3242 (Cell)

**From:** Maestas, Ricardo, NMENV [<mailto:Ricardo.Maestas@state.nm.us>]  
**Sent:** Thursday, May 01, 2014 2:18 PM  
**To:** Kouba, Steve - WRES; Kliphuis, Trais  
**Subject:** RE: Accuracy of Request

Hello Steve,

You got my email right.  
I just added the yellow highlight below.

Thanks Steve.

Ricardo

**From:** Kouba, Steve - WRES [<mailto:Steve.Kouba@wipp.ws>]  
**Sent:** Thursday, May 01, 2014 1:58 PM  
**To:** Kliphuis, Trais, NMENV; Maestas, Ricardo, NMENV  
**Subject:** Accuracy of Request

Ricardo and Trais



I want to verify I captured your request from today's phone call. I am guessing on Ricardo's email address so you may have to follow up with him.

*Requested site personnel by on 5/2 call to discuss observations from 4/30 entry photos/videos. Specifically dark spots and crease/dent that appear to be on the back bulkhead near the top of the waste stack, near the right (south) rib (~6:48 in the video). There was also a wire that appeared to be out of place.*

Steve

Steve Kouba, PMP  
Nuclear Waste Partnership LLC  
Regulatory Environmental Services  
Contractor to the Department of Energy  
4021 National Parks Hwy - MS GSA-109  
Carlsbad, NM 88220  
[steve.kouba@wipp.ws](mailto:steve.kouba@wipp.ws)  
575 234-7443  
575 302-3242 (Cell)