

Allen, Pam, NMENV

From: Maestas, Ricardo, NMENV
Sent: Wednesday, May 20, 2015 4:03 PM
To: Allen, Pam, NMENV
Subject: FW: Photos of stormwater ponds at WIPP
Attachments: Salt pile and E pond, looking N.JPG; Salt pile, closest pond, looking SW.JPG; Salt pile, E pond looking E at slumped salt.JPG; Salt pile, E pond looking east with salt in background.JPG; Salt pile, E pond, SW corner looking SE.JPG; Salt pile, N berm looking SW even further along road.JPG; Salt pile, N berm looking SW further along road.JPG; Salt pile, N berm looking SW.JPG; Salt pile, NW corner, unstable slope.JPG; Salt pile, spillway to closest pond, looking SW.JPG; Salt pile, surface (evap) texture.JPG; Salt pile, surface texture.JPG; Salt pile, SW corner looking N at lining between salt pile and pond 1.JPG; Salt pile, SW corner looking N at lining between salt pile and pond 2.JPG; Salt pile, SW corner looking N.JPG; Salt pile, SW corner looking SSE.JPG; Salt pile, SW corner.JPG; Salt pile, W end looking N.JPG; Salt pile, W pond looking W.JPG

Email and photos.

From: LucasKamat, Susan, NMENV
Sent: Tuesday, September 30, 2014 4:57 PM
To: Maestas, Ricardo, NMENV; Schoeppner, Jerry, NMENV
Cc: Kieling, John, NMENV; Johnson, Katrina, NMENV; Skibitski, Thomas, NMENV; Kliphuis, Trais, NMENV
Subject: RE: Photos of stormwater ponds at WIPP

Here you go, Ricardo (and Jerry).

All the photos were taken along the berm to the north of the salt pile and along the edges of the two (2) lagoons/ponds west of the salt pile. I don't know their official designations, so I called them E pond and W pond. The photo names include a description of where you are in relation to the salt pile, berms and lagoons and what direction you are facing.

Ms. Katrina Johnson took these photos. She observed a fair amount of sand, salt and other material covering the lining around the salt pile and between the salt pile and the ponds. She observed that it looked like there was a large flow from the salt piles to the ponds.

Ms. Johnson observed that the pond immediately south of the parking lot and the two (2) ponds south of the Waste Handling Building did not have large volumes of water at this time, and they did not look like they had overflowed.

If you have any questions, please feel free to contact Ms. Johnson.

Susan

From: Maestas, Ricardo, NMENV
Sent: Tuesday, September 30, 2014 4:41 PM
To: LucasKamat, Susan, NMENV; Schoeppner, Jerry, NMENV
Cc: Kieling, John, NMENV; Skibitski, Thomas, NMENV; Kliphuis, Trais, NMENV
Subject: RE: Photos of stormwater ponds at WIPP

That would be much appreciated.





30 11:51 AM



30 11:49AM



30 11:49 AM



30 11:47AM



30 11:49AM



30 11:46AM



30 11:46AM



30 11:47AM



30 11:50AM



30 11:45AM



30 11:47AM



30 11:47AM



30 11:50 AM





30 11:50AM



30 11:50AM



30 11:51AM



30 11:50AM



30 11:48AM