

State of New Mexico  
ENVIRONMENT DEPARTMENT  
Hazardous & Radioactive Materials Bureau  
2044-A Galisteo Street (87505)  
P.O. Box 26110  
Santa Fe, New Mexico 87502

Phone (505) 827-1561  
Fax (505) 827-1544

**FAX COVER SHEET**

Date: September 21, 1995

To: Ernest Preciado

cc: Craig Snider  
DOE/CAO

Company: ASI/WTAC

Telephone: 505/885-4730

Fax: 505/887-5494

Fax 234-7430

---

From: *SJB* Steve Zappe

Number of Pages (including this cover sheet): 2

---

**COMMENTS**

Please send one copy each of the documents listed on the following page to A.T. Kearney, our technical contractor reviewing the WIPP Part B application. Also, please send one copy of 1995(c) to me for our library. I am also faxing a copy of this request to Craig Snider (who I know is out of town this week) for his information. Thank you.

Connie Walker A.T. Kearney, Inc. One Tabor Center, Suite 950 1200 Seventeenth Street Denver, CO 80202 (303) 572-6180  1995(a) QAPP 1995(b) Methods Manual 1995(c) PDP	Steve Zappe NMED/HRMB 2044-A Galisteo Road Santa Fe, NM 87505 (505)827-1561  1995(c) PDP
--	--

950918



1 C-6 List of References

2

3 U.S. Department of Energy (DOE), 1995a, "Transuranic Waste Characterization Quality  
4 Assurance Program Plan," DOE/CAO 94-1010, U.S. Department of Energy, Washington, D.C.

5

6 U.S. Department of Energy (DOE), 1995b, "Transuranic Waste Characterization Sampling and  
7 Analysis Methods Manual," DOE/WIPP 91-043, Current Revision, Waste Isolation Pilot Plant,  
8 Carlsbad, New Mexico.

9

10 U.S. Department of Energy, (DOE), 1995c, "Transuranic Waste Characterization Performance  
11 Demonstration Program Plan," DOE/WIPP 91-016, Current Revision, Waste Isolation Pilot Plant,  
12 Carlsbad, New Mexico.

13