


**OFFICE OF REGULATORY COMPLIANCE
CARLSBAD AREA OFFICE
U.S. DEPT OF ENERGY
P.O. BOX 3090
CARLSBAD, NM 88221-3090**



NO. OF PAGES (excluding cover) 2

DATE 5/15/96

TO: Steve Zappe

LOCATION:

FAX # (505) 827-1544

FROM: Craig A. Snider

LOCATION: WOIC, 3rd Floor

PHONE/FAX #: 505-234-7452 / 505-234-7430

**MESSAGES: Steve: Here is the changes we talked about yesterday. I do not have a complete list yet of the potential changes to the Part A. I'll have this sent to you very soon. We anticipate that once we have the new codes, it would take approximately 1 1/2 weeks for a compatibility analysis to be run. I'll call you shortly. Thanks
Craig**

FAXBLANK

960516



Potential Changes to the WIPP RCRA Part B Permit Application

Page Number	Line Number	Change
C-14	28	§264.601(b) should be §264.601(c)
C-36	25	delete "discarded" ^{and then}
D-6	15	insert "or" before "sending" and delete "or emplacing the TRUPACT-II in the WIPP underground."
D-8	29	(3.5m ³) should be (43.5m ³)
D-64	44	delete "simply" and add a period. ?
D-73	28	delete "closing the regulator and constructing a chain link/brattice cloth barricade" and add "removing the air regulator bulkhead and constructing chain link/brattice cloth barricades at each end."
D-112	Table D-6	update values to be consistent with the NMVP Received 5/17 fax
D-131	Figure D-11	change caption "ventilation control point (typical)" to "location of room barricade (typical)" change caption "location of room air stoppage (typical)" to "location of room barricade (typical)"
F-30	Table F-1	reorder the rows so that the order of the inspections is consistent with Appendix F1
F-39 & F-40	Figures F-1 & F-2	replace with pictures that have the correct captions; only incorrect in the first 20 copies

Post-it™ Fax Note	7671	Date	5/15	# of pages	2
To	Craig Snider				
From	Karen G				
Co./Dept.	Co.				
Phone #	Phone #				
Fax #	Fax #				

<u>Page Number</u>	<u>Line Number</u>	<u>Change</u>
I-6	4	delete "mix of 60 percent drums and 40 percent SWBs is used" and add "maximum achievable volume is used."
Appendix D5		replace 1st page
Appendix D9		replace Table D9-8 with a table that includes values consistent with the NMVP
Appendix D11		copying error; replace complete appendix; only incorrect in the first 20 copies
Appendix D19		last few pages are copied on the wrong side of the paper
Appendix D20		insert pages 3-8 and 3-9; they are missing
Appendix F1		insert a form that is missing change table of contents to be consistent with Table F-1

*Received
5/17 fax*