



Note: No vertical exaggeration.
See Figure 4-3 for cross-section location map.

Revision Date: 08/25/12

2012 QUARTERLY REPORT 02
BULK FUELS FACILITY
KIRTLAND AIR FORCE BASE, NEW MEXICO

FIGURE 4-7

LITHOLOGY AND TOTAL VOC VAPOR CROSS-SECTIONS H-H'

H:\Kirtland_AFB\GIS_Documents\Project_Maps\2001BB_2012_QTR_Monitor_SVE_OM\2012_Q2\KAFB_061_VOC_vapor_cross_section_HH.mxd 08/25/12