

EPH



FACSIMILE TRANSMITTAL

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6
1445 ROSS AVENUE
DALLAS, TEXAS 75202-2733

MULTIMEDIA PLANNING AND PERMITTING DIVISION
NEW MEXICO AND FEDERAL FACILITIES SECTION

PLEASE PRINT IN BLACK INK ONLY

TO: **Dr. Robert S. (Stu) Dinwiddie, Ph.D., Program Manager**

MACHINE NUMBER:
505.827.1544

VERIFICATION NUMBER:

FROM: **James A. Harris, Jr., RCRA Facility Manager/Geologist** *JAH*

PHONE: (214) 665-8302

Mail Code: GPD-N

OFFICE: **New Mexico/Federal Facilities Section**

PAGES INCLUDING COVER SHEET: 3

DATE: **May 25, 1999**

PLEASE NUMBER ALL PAGES

INFORMATION FOR SENDING FACSIMILE MESSAGES

EQUIPMENT:

FACSIMILE NUMBER:

VERIFICATION NUMBER:

PANAFAX UF-766

(214) 665-7263

(214) 665-8302

COMMENTS

Stu,

Cornelius said you did not receive this. Here is a dated copy from our fileroom. If you have questions please call me at (214) 665-8302.



April 29, 1999



Dr. Robert S. (Stu) Dinwiddie, Ph.D., Program Manager
 RCRA Permits Management Program
 New Mexico Environment Department
 Hazardous and Radioactive Materials Bureau
 2044A Galisteo Street
 Santa Fe, NM 87505-2100

RE: Comments on Rinchem Company, Inc. Container Storage Unit, Draft RCRA Permit (Renewed), EPA ID No. NMD002208627-1

Dear Dr. Dinwiddie:

On April 14, 1999 the Environmental Protection Agency (EPA) received a copy of the Draft Permit Renewal Application for Rinchem Company, Inc. Container Storage Unit, EPA ID No. NMD002208627-1. The application also included your request to review and submit comments to the Hazardous and Radioactive Materials Bureau within thirty (30) days.

EPA has reviewed the draft permit application. Our comments are enclosed for your reference. If you have any questions or require additional information on EPA's review of the Draft Permit Renewal Application for the Rinchem Company, Inc. Container Storage Unit please contact me at (214) 665-6785 or James Harris of my staff at (214) 665-8302.

David Neleigh, Chief

Multi Media Permitting
 and Planning Division
 New Mexico and Federal
 Facilities Section (6PD-N)

6PD-N
 DNELEIGH
 PO 4/29

6PD-N
 SLANGLEY
 SL 4/29/99

6PD-N:JHARRIS:L:DRIVE\RINCHEM\Permit.WPD:x8302:04/29/99
 u/29

**RINCHEM COMPANY OPERATIONAL PERMIT RENEWAL APPLICATION,
EPA NO. NMD002208627**

This is a operating permit renewal application. Ten year duration effective 30 days from date of signature by the Secretary or Designee.

Facility consists of an approximately 23,000 sq-ft warehouse and office, loading/unloading dock, a back dock and two rainwater containment areas.

Units: Building containing the storage areas, the docks and the collection tank connected to the flammable storage area.

Rooms E&F Storage Areas (capacity 82,000 gallons); Rooms A&B (capacity 16,000 gallons) Controlled Temperature Storage Areas; Rooms C&D (capacity 80,000 and 74,000 gallons respectively) Storage Areas; Truck Loading Dock; Spill Drainage system; Spill collection Tank

Room floors are sealed with epoxy, expansion joints are caulked; separated from adjacent rooms by two and four-hour fire-walls.

Waste Types: Prepacked chemicals for distribution, spent wastes, wastes sensitive to temperature changes; "D", "F", "K", "P", "U"

Facility indicates wastes will not store more than 55,000 gallons of hazardous waste on-site at any one time for up to a year until economic quantity loads can be transported.

If it is determined that a release has occurred the facility is required to perform BLRA/CMS and CMI to protect human health and the environment (N/A at this time).

Director of NMED has determined no RFI is required.

SIC codes have not been included in the permit application

INTERESTING POINTS

Page 100 of the Part B Application: The entire facility is referenced as a SWMU yet under "ACTIVE PERMITTED OPERATIONAL UNIT AREAS/SOLID WASTE MANAGEMENT UNIT INFORMATION", page 93, the facility is separated into two areas: the active permitted operational unit area and the rain water impoundments and drainage areas within the fenced boundaries are referenced as "possible" SWMUs.

Page numbers are not continuous throughout the application.