



SUSANA MARTINEZ
Governor
JOHN A. SANCHEZ
Lieutenant Governor

 ENTERED

State of New Mexico
ENVIRONMENT DEPARTMENT
Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6313
Phone (505) 476-6000 Fax (505) 476-6030
www.env.nm.gov



BUTCH TONGATE
Cabinet Secretary
J. C. BORREGO
Deputy Secretary

CERTIFIED MAIL – RETURN RECEIPT REQUESTED

May 15, 2017

Mr. Jeffrey Smith
General Manager
Advanced Chemical Treatment
6137 Edith Boulevard N.E.
Albuquerque, NM 87107

**RE: DRUM SPILL AT LOADING DOCK – MARCH 9, 2017
ADVANCED CHEMICAL TREATMENT, INC.
EPA ID# NMD002208627
HWB-ACT-MISC**

Dear Mr. Smith:

The New Mexico Environment Department (NMED) received the Advanced Chemical Treatment (ACT) written Incident Report concerning the release of hazardous waste that occurred on March 9, 2017.

The NMED has reviewed the Incident Report and determined that it is missing information regarding the incident on March 9, 2017. Revise the Incident Report to include the following information:

1. Identify the exact location of the spill. Include:
 - a. if the spill was located within a trailer,
 - b. if the spill was contained by the trailer or if any contamination occurred outside the trailer,
 - c. if the spill was confined to the trailer, provide an explanation for the samples taken.

2. Include a map clearly showing the location of the spill as well as the sampling locations.


Mr. Smith
May 15, 2017
Page 2

3. The Incident Report lists the material spilled as D002 but the manifest lists both D002 and D004. Identify all constituents and applicable RCRA codes associated with the spill.
4. Identify the cause of the container leak and how long the container was at the facility before the leak was discovered.
5. Fully describe how and where this waste was managed and disposed. Note that this waste and any associated wash water must be included in the Facility's waste generation volume.
6. Include the laboratory chemical analyses conducted on the samples and the rationale for the selected analyses.
7. The Incident Report indicates that 7 to 10 gallons leaked from a drum; however, the volume recovered was not included. Include the total recovered volume.

The NMED is exercising its enforcement discretion by not issuing a Notice of Violation at this time. The Permittee must submit a revised and updated Incident Report to NMED no later than **June 15, 2017**.

If you have any questions, please contact Stacie Singleton of my staff at (505) 476-6056.

Sincerely,



John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
S. Singleton, NMED HWB
J. Kraemer, NMED HWB
P. Paduano, ACT
K. Harsono, ACT