

Please print or type with ELITE type (12 characters per inch) in the unshaded areas only

Please refer to the Instructions for Filing Notification before completing this form. The information requested here is required by law (Section 3010 of the Resource Conservation and Recovery Act).

**EPA**

**Notification of Regulated Waste Activity**

United States Environmental Protection Agency

2286

Date Received (For Official Use Only)  
**JUL 23 1997**

**I. Installation's EPA ID Number (Mark 'X' in the appropriate box)**

<input checked="" type="checkbox"/> A. First Notification	<input type="checkbox"/> B. Subsequent Notification (Complete item C)	C. Installation's EPA ID Number NM R 00000 2089
---	---	--

**II. Name of Installation (Include company and specific site name)**

Roswell Compressor Station

**III. Location of Installation (Physical address not P.O. Box or Route Number)**

Street

Approximately 20 miles North of Roswell, New Mexico.

Street (Continued)

City or Town

Roswell

State

NM

Zip Code

88201

County Code

County Name

Chaves

**IV. Installation Mailing Address (See Instructions)**

Street or P.O. Box

6 Petro Drive

P.O. Box 1492

City or Town

Roswell

State

EL Paso TX 79978

NM

Zip Code

88201-7479

**V. Installation Contact (Person to be contacted regarding waste activities at site)**

Name (Last)

Soltero

(First)

Martin

Job Title

Environmental Engineer

Phone Number (Area Code and Number)

915/496-3174

**VI. Installation Contact Address (See Instructions)**

A. Contract Address Location Mailing Other

B. Street or P.O. Box

100 North Stanton

City or Town

El Paso

State

TX

Zip Code

79901

**VII. Ownership (See Instructions)**

**A. Name of Installation's Legal Owner**

El Paso Natural Gas Company

Street, P.O. Box, of Route Number

100 North Stanton

City or Town

El Paso

State

TX

Zip Code

79901

Phone Number (Area Code and Number)

915/496-2600

B. Land Type

P

C. Owner Type

P

D. Change of Owner Indicator

Yes  No

(Date Changed) Month Day Year

thead gaged 7/24/97

ALL S. 11

1947  
APR 10 1947

1947/10/10

**ID - For Official Use Only**

**VIII. Type of Regulated Waste Activity (Mark 'X' in the appropriate boxes; Refer to instructions)**

**A. Hazardous Waste Activity**

- 1. Generator (See instructions)
  - a. Greater than 1000kg/mo (2,200 lbs.)
  - b. 100 to 1000 kg/mo (200-2,200 lbs.)
  - c. Less than 100 kg/mo (220 lbs)
- 2. Transporter (Indicate Mode in boxes 1-5 below)
  - a. For own waste only
  - b. For commercial purposes
- Mode of Transportation
  - 1. Air
  - 2. Rail
  - 3. Highway
  - 4. Water
  - 5. Other - specify
- 3. Treater, Storer, Disposer (at installation) Note: A permit is required for this activity; see instructions.
- 4. Hazardous Waste Fuel
  - a. Generator Marketing to Burner
  - b. Other Marketers
  - c. Boiler and/or Industrial Furnace
    - 1. Smelter Deferral
    - 2. Small Quantity Exemption
- Indicate Type of Combustion Device(s)
  - 1. Utility Boiler
  - 2. Industrial Boiler
  - 3. Industrial Furnace
- 5. Underground Injection Control

**B. Used Oil Recycling Activities**

- 1. Used Oil Fuel Marketer
  - a. Marketer Directs Shipment of Used Oil to Off-Specification Burner
  - b. Marketer Who First Claims the Used Oil Meets the Specifications
- 2. Used Oil Burner - Indicate Type(s) of Combustion Device(s)
  - a. Utility Boiler
  - b. Industrial Boiler
  - c. Industrial Furnace
- 3. Used Oil Transporter - Indicate Type(s) of Activity(ies)
  - a. Transporter
  - b. Transfer Facility
- 4. Used Oil Processor/Re-refiner - Indicate Type(s) of Activity(ies)
  - a. Process
  - b. Re-refine

**IX. Description of Hazardous Wastes (Use additional sheets if necessary)**

**A. Characteristics of Nonlisted Hazardous Wastes. (Mark 'X' in the boxes corresponding to the characteristics of nonlisted hazardous wastes your installation handles; See 40 CFR Parts 261.20 - 261.24)**

- 1. Ignitable (D001)
- 2. Corrosive (D002)
- 3. Reactive (D003)
- 4. Toxicity Characteristic (List specific EPA hazardous waste number(s) for the Toxicity characteristic contaminant(s))

**B. Listed Hazardous Wastes. (See 40 CFR 261.31 - 33; See instructions if you need to list more than 12 waste codes.)**

1	2	3	4	5	6
D004 Arsenic					
7	8	9	10	11	12

**C. Other Wastes. (State or other wastes requiring a handler to have an I.D. number; See instructions.)**

1	2	3	4	5	6

**X. Certification**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature <i>Thomas D. Hutchins</i>	Name and Official Title (Type or print) <i>Thomas D. Hutchins, Director</i> EH&S	Date Signed <i>7-18-97</i>
--	--	-------------------------------

**XI. Comments**

Note: Mail completed form to the appropriate EPA Regional or State Office. (See Section III of the booklet for addresses.)



GARY E. JOHNSON  
GOVERNOR

State of New Mexico  
**ENVIRONMENT DEPARTMENT**  
*Hazardous & Radioactive Materials Bureau*  
2044 Galisteo  
P.O. Box 26110  
Santa Fe, New Mexico 87502  
(505) 827-1557  
Fax (505) 827-1544



MARK E. WEIDLER  
SECRETARY

EDGAR T. THORNTON, III  
DEPUTY SECRETARY

September 5, 1997

Mr. Martin Soltero  
Roswell Compressor Station  
P.O. Box 1492  
El Paso, TX 79978

Dear Mr. Soltero:

Enclosed, please find for your files, a copy of the Notification of Regulated Waste Activity form you recently submitted to us.

The U.S. Environmental Protection Agency has issued an Identification number for your facility which is recorded on the top line of the form. This number should be used on all manifests and other documents concerning the transportation, treatment and disposal of your waste.

Please remember that this number has been assigned to the **specific location** and facility indicated on the form. Should any changes occur in any of this information, you must file a Subsequent Notification form with our agency.

If you have any questions about management of your hazardous waste, call the New Mexico Environment Department, Hazardous and Radioactive Materials Bureau at (505) 827-1558.

Sincerely,

A handwritten signature in cursive script, appearing to read "Anna Walker".

Anna Walker  
Management Analyst  
Administration and Special Projects  
NMED/HRMB

cc: Norma Silva, Program Manager  
Administration and Special Projects  
NMED/HRMB



July 21, 1997

EPA Region 6 Main Office  
Attention: Ms. Teena Hullum  
1445 Ross Avenue, Suite 1200  
Mail Code 6PDI  
Dallas, Texas 75202

Reference: **El Paso Natural Gas Company - EPA Notification of Regulated Waste Activity - Roswell Compressor Station**

Dear MS. Hullum:

Enclosed is the completed EPA Notification of Regulated Waste Activity form for El Paso Natural Gas Company's (EPNG) Roswell Compressor Station. This form is being submitted by EPNG for "pigging sludge" (Hazardous Waste code D004, Arsenic) removed from this facility.

As we discussed today during our telephone conversation, please call or fax me the facilities EPA Identification Number at 915/496-3174 or 915/496/2643 respectively.

Sincerely,

A handwritten signature in blue ink that reads "Martin A. Soltero".

Martin Soltero  
Environmental Engineer  
Environmental, Health and Safety Department

enclosures