




DEPARTMENT OF THE AIR FORCE

HEADQUARTERS 833D COMBAT SUPPORT GROUP (TAC)

HOLLOMAN AIR FORCE BASE NM 88330-500



REPLY TO  
ATTN OF: DEV

SUBJECT: Pollution Incident (7 March 1990)

15 MAR 1990

TO: 4449 MOBSS/CC

1. This is to provide final clean-up actions for the spill residue trapped under the hardstand near Bldg 906.
2. Remove the hardstand in the area and remove all visible traces of diesel contaminated soil. It is recommended this be done in sections, i.e., remove a portion of the hardstand and contaminated soils, then another portion, until all visible contamination is removed. When all visible contamination is completely removed, contact DEV for sampling and final approval.
3. The contaminated soils must be taken to the hydrocarbon recovery area at the sanitary landfill.
4. This work needs to be accomplished soon to prevent further contamination. If you cannot accomplish the above with your in-house resources, please let me know.

  
HOWARD E. MOFFITT  
Deputy Base Civil Engineer

CC: NMEID Hazardous Waste Section  
Attn: B Swanton/C Muckelroy/  
on