


FPM

URS

ENTERED



181 Kenwood Avenue
Oneida, New York 13421
315/336-7721
FAX 315/336-7722

29 November 2017

New Mexico Environment Department
Attn: Mr. John Kieling, Chief
Hazardous Waste Bureau
2905 Rodeo Park Drive East, Building 1
Santa Fe, NM 87505-6063

**RE: Errata Page for Table 4-6,
Final Interim Measures Progress Report #1, November 2016 to July 2017, T-38 Test Cell Fuel Spill
Site SS059/SS524 (SWMU 229), Holloman Air Force Base, New Mexico, June 2017, Holloman AFB,
EPA ID# NM6572124422
HWB-HAFB-16-027**

Dear Mr. Kieling,

An error has been identified in Table 4-6 of the *Final Interim Measures Progress Report #1* – previously submitted to the New Mexico Environment Department on 31 October 2017 for the SS059 site (Solid Waste Management Unit [SWMU] 229) at Holloman AFB. The subject table inadvertently included data pertaining to a well not associated with site SS059 (i.e., “SS059- *sic* MW-21”) – for clarification, there is currently no “MW21” present at SS059.

Attached, please find an errata page to correct the report error by removing the reference to the well which is actually associated with site SS017 (Area of Concern [AOC] Q). A revision to the complete native files, including tables and figures are also provided on the enclosed compact disc (CD). Relevant data for SS017-MW21 will be provided in a future report to be prepared for that site.

If you have any questions or require additional information, please contact Jon Mallonee at 303-740-3967 or via e-mail at jon.mallonee@aecom.com.

Very truly yours,

Jon Mallonee, PG
Holloman Base Deputy Manager,
URS

Ivana Raicevic, Ph.D.
Holloman MMRP Installation Manager,
FPM

FPM

Environmental & Engineering Solutions

Environmental & Engineering Solutions

URS

181 Kenwood Avenue
Oneida, New York 13421
315/336-7721
FAX 315/336-7722

Attachment(s): *Corrected Table 4-6, Final Interim Measures Progress Report #1 – SS059 (SWMU 229)*. Hard copy and CD.

cc: Mr. Brian Salem, NMED HWB (w/Atch)
Mr. Cornelius Amindyas, NMED HWB (w/o Atch)
Mr. Chuck Hendrickson, USEPA (w/CD)
Mr. James (Scott) Dorton, HAFB (w/Atch)
Mr. Charles Schick, HAFB (w/Atch)
Ms. Robin Paul, AFCEC (w/CD)
Mr. Scott Clark, Kirtland AFB (w/CD)

Table 4-6 IM Progress Report 1 - SS059 (SWMU 229)
LNAPL Removal Volumes
April 2015 through July 2017
Holloman AFB, New Mexico

Well ID	April/May 2015 (mL)	November 2016 (mL)	January 2017 (mL)	February 2017 (mL)	March 2017 (mL)	April 2017 (mL)	May 2017 (mL)	June 2017 (mL)	July 2017 (mL)	Total LNAPL Removed from Well (mL)	Total LNAPL Removed after January 2017 (mL)
SS059-A16	7,430	1,500	NS	NS	NS	NS	NS	NS	NS	8,930	0
SS059-A18	NLR	6,500	500	---	---	trace	30	25	---	7,055	55
SS059-A19	3,000	NLR	NS	NS	NS	NS	NS	NS	NS	3,000	0
SS059-A20	4,100	NLR	NS	NS	NS	NS	NS	NS	NS	4,100	0
SS059-A21	2,125	NLR	NS	NS	NS	NS	NS	NS	NS	2,125	0
SS059-B-12	NLR	6,000	590	---	---	trace	---	---	NS	6,590	0
SS059-B-13	NLR	1,500	NS	NS	NS	NS	NS	NS	NS	1,500	0
SS059-B-16	NLR	3,250	NS	NS	---	NS	10	---	NS	3,260	10
SS059-EXT-2	NLR	3,000	475	50	---	---	---	25	---	3,550	75
SS059-EXT-3	8,250	2,250	710	---	---	---	100	75	25	11,410	200
SS059-EXT-4	5,500	2,000	PSF	---	---	---	500	125	120	8,245	745
SS059-EXT-7	8,350	NLR	945	5	---	---	NS	NS	NS	9,300	5
SS059-EXT-8	6,610	1,250	PSF	---	---	---	NS	NS	NS	7,860	0
SS059-EXT-9	NLR	NLR	NS	NS	NS	NS	NS	NS	25	25	25
SS059-MW-3	1,330	NLR	NS	NS	NS	NS	NS	NS	NS	1,330	0
SS059-MW-30	NLR	2,750	NS	NS	NS	NS	NS	NS	NS	2,750	0
Total LNAPL Removed During Event (mL):	46,695	30,000	3,220	55	0	0	640	250	170		1,115
										Total LNAPL Removed from Site (mL)	81,280

Notes:

--- = Skimmer in place, no LNAPL present during removal event

mL = milliliters

NLR = No LNAPL Removed, LNAPL was present

NS = No Skimmer present during removal event

PSF = Passive Skimmer Failure resulting in no recovery/data

LNAPL = Light Non-Aqueous Phase Liquid