




DEPARTMENT OF THE AIR FORCE
HEADQUARTERS 377TH AIR BASE WING (AFMC)
CERTIFIED MAIL: Z 106 120 494
RETURN RECEIPT REQUESTED

ENTERED

10 AUG 1995

377 ABW/EMR
2000 Wyoming Blvd SE
Kirtland AFB NM 87117-5659

Ms. Nancy Morlock, Environmental Engineer
RCRA Permits Branch
U.S. EPA Region 6
1445 Ross Ave, Ste 1200
Dallas TX 75202-2733



Dear Ms. Morlock


In our 16 May 1995 letter, we notified you of a possible SWMU located near a KAFB training area and east of Sandia National Laboratories (SNL) ER Site 21.

Sandia National Laboratories conducted sampling for radioactivity; nothing above background was detected. Their results are at Atch 1.

The KAFB Compliance Branch took soil samples near the broken construction material and the three empty drums scattered along the arroyo. Their results are summarized and at Atch 2. Based on the sampling results, we feel this area does not qualify as a SWMU and should *not* be added to our permit. If you concur, we shall proceed to remove the scrap material and empty barrels, and advise you when this action is complete.

Please call me at (505) 846-2773/0053 if you have any questions.

Sincerely


CHRISTOPHER B. DeWITT, R.P.G.
Chief, Restoration Branch
Environmental Management Division

Attachments:

1. Sampling Results, SNL
2. Sampling Results, KAFB

cc:

NMED-HRMB (Mr. Pullen)
SNL Divs 7584/7585 (Mssrs. Sandhus and Trout)

KAFB1666

