

KAFB 06

State of New Mexico
ENVIRONMENT DEPARTMENT



BILL RICHARDSON
GOVERNOR

Hazardous Waste Bureau
2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303
Telephone (505) 428-2500
Fax (505) 428-2567

www.nmenv.state.nm.us



RON CURRY
SECRETARY

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

May 2, 2006

Mr. Carl J. Lanz
Chief, Restoration Section
377th CES / CEVR
2050 Wyoming Blvd. SE, Suite 118
Kirtland Air Force Base, NM 87117-5270

RE: NOTICE OF APPROVAL WITH MODIFICATIONS: INSTALLATION RESTORATION PROGRAM VOLUNTARY CORRECTIVE MEASURES WORK PLAN FOR SOLID WASTE MANAGEMENT UNIT WP-26, SEWAGE LAGOONS AND GOLF COURSE MAIN POND KIRTLAND AIR FORCE BASE, EPA ID# NMD9570024423 HWB-KAFB-06-005

Dear Mr. Lanz:

The New Mexico Environment Department (NMED) has reviewed the above-referenced document pursuant to New Mexico Hazardous Waste Management Regulations 20.4.1 NMAC. Based on staff review, NMED approves the Voluntary Corrective Measures Work Plan for SWMU WP-26 with the following modifications:

Kirtland Air Force Base (KAFB) shall collect soil samples from the depth interval 6 to 12 inches from the 6 proposed perimeter boring locations (*i.e.*, 2671, 2672, 2673, 2674, 2675, and 2676), and from the 12 proposed berm boring locations (*i.e.*, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, and 2668) for analysis of SVOCs, RCRA eight metals (*e.g.*, arsenic, barium, cadmium, chromium, lead mercury, selenium, and silver), herbicide, and pesticide concentrations.

KAFB2985



Mr. Carl J. Lanz
May 2, 2006
Page 2 of 2

If you have any questions regarding this matter or if you would like to discuss this response, please contact David L. Mayerson of my staff at (505) 222-9528.

Sincerely,



James P. Bearzi
Chief
Hazardous Waste Bureau

JPB:dlm

cc: W. Moats, NMED, HWB
W. McDonald, HWB
D. Mayerson, NMED, HWB
L. King, EPA-Region 6 (6PD-N)
File: Reading and ~~W. B. 2006~~