



Swanson, Baird, NMENV

From: Holmes Mark D Civ 377 MSG/CEVR [Mark.Holmes@kirtland.af.mil]
Sent: Tuesday, October 30, 2007 4:51 PM
To: Swanson, Baird, NMENV
Subject: ST-106E

Baird

Upon re-review of the Monitor well installation workplan for ST-106E, I noticed that we did not modify the wellhead completion section regarding additional protection due to the location within the bermed area of the jet fuel AST. Would you please recommend the type of additional protection you would approve for the wellhead completion to provide an adequate seal in case the AST leaked and fuel pooled within the bermed area. We are scheduled to begin installation of this well during the latter part of next week. Of course, as stated in the workplan, we may install a soil boring instead of a monitor well if we do not discover any contamination in the location we are currently drilling, KAFB-1066.

30 Oct 07: Baird, apparently this email was held back by our server (originally sent last week), so I'm sending it on to you. Although we have discussed the potential remedy (packer), please respond for the record.

Thanks,

//Signed//
Mark Holmes
Project Manager
Environmental Management
Restoration Section
505 846-9005

This inbound email has been scanned by the MessageLabs Email Security System.

KAFB3621



2/8/2010