



SUSANA MARTINEZ
Governor

JOHN A. SANCHEZ
Lieutenant Governor

NEW MEXICO 
ENVIRONMENT DEPARTMENT

Hazardous Waste Bureau

2905 Rodeo Park Drive East, Building 1
Santa Fe, New Mexico 87505-6303
Phone (505) 476-6000 Fax (505) 476-6030
www.nmenv.state.nm.us



RYAN FLYNN
Cabinet Secretary-Designate

BUTCH TONGATE
Deputy Secretary

TOM BLAINE, P.E.
Director
Environmental Health Division

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

April 24, 2014

Colonel Tom Miller
Base Commander
377 ABW/CC
2000 Wyoming Blvd. SE
Kirtland AFB, NM 87117-5606

John Pike
Director, Environmental Management Services
377 MSG
2050 Wyoming Blvd. SE, Suite 116
Kirtland AFB, NM 87117-5270

**RE: FINAL ACCELERATED CORRECTIVE MEASURES WORK PLAN, ZIA PARK
(CS-571), MARCH 2012
KIRTLAND AIR FORCE BASE, EPA ID# NM9570024423
HWB-KAFB-12-014**

Dear Col. Miller and Mr. Pike:

The New Mexico Environment Department (NMED) has reviewed the document *Final: Accelerated Corrective Measures Work Plan, Zia Park (CS-571), March 2012*, received on July 26, 2012. In this document, Shaw Environmental and Infrastructure, Inc., contractor for the U. S. Air Force (Permittee), proposes excavating contaminated soils discovered as a result of soil sampling conducted under the previously submitted SWMU Assessment Report (HWB-KAFB-12-011). Contamination in soils will be determined by comparison to the compound-specific cleanup levels found in the Permittee's Permit Part 6, Section 6.2.3.

This work plan allows for up to 40 cubic yards of contaminated soil to be excavated. Additional soils exceeding cleanup levels will be left in place thus, the subject accelerated corrective measure may fail to remove all contaminated soil.

NMED anticipates that less than 40 cubic yards of soil will need to be excavated and hereby approves the subject work plan.



Col. Miller and Mr. Pike
April 24, 2014
Page 2

If you have any questions regarding this letter, please contact Bill McDonald of my staff at (505) 222-9582.

Sincerely,

A handwritten signature in black ink, appearing to read "John E. Kieling". The signature is fluid and cursive, with a large initial "J" and a long, sweeping tail.

John E. Kieling
Chief
Hazardous Waste Bureau

cc: D. Cobrain, NMED HWB
W. Moats, NMED HWB
W. McDonald, NMED HWB
L. King, EPA-Region 6 (6PD-N)