



From: Agnew, Diane, NMENV

Sent: Tuesday, April 4, 2017 12:13 PM

To: CLARK, SCOTT C GS-13 USAF AFCEC/CZO <scott.clark@us.af.mil>

Cc: BODOUR, ADRIA A CIV USAF HAF AFCEC/CZRX <adria.bodour.1@us.af.mil>; LYNNES, KATHRYN D HQE USAF AFGSC 377 MSG/SAF/IEE <kathryn.lynnes@us.af.mil>; Julie McNeill

(jmcneill@portageinc.com) <jmcneill@portageinc.com>; Simpler, Trent SPA

(Trent.Simpler@usace.army.mil) <Trent.Simpler@usace.army.mil>; 'Salazar, Carlos F SPA'

<Carlos.F.Salazar@usace.army.mil>; Linda Dreeland <Linda.Dreeland@usace.army.mil>; Phaneuf, Mark J

SPA (Mark.J.Phaneuf@usace.army.mil) <Mark.J.Phaneuf@usace.army.mil>; O'GRADY, HOLLY M GS-12

USAF AFCEC AFCEC/CZOW <holly.ograde@us.af.mil>; PINO, ANTIONETTE R CTR USAF AFCEC

AFCEC/CZOW <antionette.pino.ctr@us.af.mil>; SEGURA, CHRISTOPHER G GS-13 USAF AFCEC/CZO

<christopher.segura.2@us.af.mil>; Kieling, John, NMENV <john.kieling@state.nm.us>; Hunter, Michelle,

NMENV <Michelle.Hunter@state.nm.us>; Ball, Justin, NMENV <Justin.Ball@state.nm.us>

Subject: RE: 1203 Written Notification to NMED GWQB

Hello:

NMED acknowledges receipt of this notification. Please submit a brief Corrective Action Report to complete the requirements specified in Section 20.6.2.1203 NMAC.

Diane

From: CLARK, SCOTT C GS-13 USAF AFCEC/CZO [mailto:scott.clark@us.af.mil]

Sent: Monday, March 20, 2017 4:01 PM

To: Hunter, Michelle, NMENV <Michelle.Hunter@state.nm.us>; Agnew, Diane, NMENV <Diane.Agnew@state.nm.us>; Kieling, John, NMENV <john.kieling@state.nm.us>

Cc: BODOUR, ADRIA A CIV USAF HAF AFCEC/CZRX <adria.bodour.1@us.af.mil>; LYNNES, KATHRYN D HQE USAF AFGSC 377 MSG/SAF/IEE <kathryn.lynnes@us.af.mil>; Julie McNeill

(jmcneill@portageinc.com) <jmcneill@portageinc.com>; Simpler, Trent SPA

(Trent.Simpler@usace.army.mil) <Trent.Simpler@usace.army.mil>; 'Salazar, Carlos F SPA'

<Carlos.F.Salazar@usace.army.mil>; Linda Dreeland <Linda.Dreeland@usace.army.mil>; Phaneuf, Mark J

SPA (Mark.J.Phaneuf@usace.army.mil) <Mark.J.Phaneuf@usace.army.mil>; O'GRADY, HOLLY M GS-12

USAF AFCEC AFCEC/CZOW <holly.ograde@us.af.mil>; PINO, ANTIONETTE R CTR USAF AFCEC

AFCEC/CZOW <antionette.pino.ctr@us.af.mil>; SEGURA, CHRISTOPHER G GS-13 USAF AFCEC/CZO

<christopher.segura.2@us.af.mil>

Subject: 1203 Written Notification to NMED GWQB

Hi All,

As a follow-up to the initial verbal notification of a release today that was given to Diane Agnew, GWQB, please find the written notification of the release below. The drilling fluids had been analyzed prior to this release and no hazardous constituents were present, and lab data and photos are attached for reference.

Written Notification of Release pursuant to 20.6.2.1203.A NMAC: Drilling fluids leaking from bottom of KAFB-106239 lined roll off (Roll off number KAFB-106239-LC)



(a) Person In Charge:

Scott Clark
Kirtland IST, AFCEC/CZO
2050 Wyoming Boulevard Southeast
Kirtland Air Force Base, New Mexico 87117-5270
505-846-9017
DSN 246-9017
Mobile 505-385-3679
scott.clark@us.af.mil

(b) Location of Discharge: Kirtland AFB, IDW storage yard on SW corner of Ridgecrest Drive SE and Perimeter RD (southwest of BFF GWTS)

(c) Date/Time Release: 18MAR17(?); drilling fluids began leaking through the liner sometime over weekend as no leak was seen on Friday 17MAR17 inspection. Leak was discovered during Monday waste inspections (20MAR17)

(d) Source and Cause of Discharge: Leakage through lined roll off in storage pending disposal off-site (Failed Liner)

(e) Description of Discharge: Drilling fluids from extraction well KAFB-106239; fluids were already analyzed for waste disposal (total metals, 8260 VOCs, 8270 SVOCs, and RCI) and contain no hazardous constituents. Sole detection of chloroform at 2.7 µg/L (PQL is 2.0 ug/L) is suspected laboratory contamination.

(f) Estimated Volume: 50 gallons; approximately 3-4 ft in width by 20 ft in length (see photographs)

(g) Actions Taken to Mitigate Potential Damage

Actions taken 20MAR17: Immediately upon discovery, soil was bermed to stop spread of fluid, and absorbent placed immediately beneath the leak location to prevent additional migration. ACT contacted (roll off leased from firm) to mobilize a replacement roll off asap. Drilling mud will be transferred to new (lined) roll off today via vacuum truck and all soil in contact with drilling mud will be removed and placed in new roll off.

Planned actions: No additional actions are planned.

Thanks, and if you have any questions just let us know.
Scott

//SIGNED//

Scott Clark
Restoration Program Manager
Kirtland IST, AFCEC/CZO
505-846-9017
DSN 246-9017
Mobile 505-385-3679
scott.clark@us.af.mil