

Permit

TONEY ANAYA
GOVERNOR

DENISE D. FOR
DIRECTOR



STATE OF NEW MEXICO

ENVIRONMENTAL IMPROVEMENT DIVISION

P.O. Box 968, Santa Fe, New Mexico 87504-0968
(505) 984-0020

June 5, 1986

Mr. Harold Valencia
Los Alamos Area Manager
U.S. Department of Energy
Los Alamos, New Mexico 87544

Dear Mr. Valencia:

I wish to arrange a technical interchange meeting between members of my staff and yours to discuss a portion of the RCRA permit which you have requested. The specific subject is any treatment activities in association with the NPDES-permitted outfalls which may fall under RCRA treatment definitions. I understand, from a conversation between Mr. Gallegos of your staff and Mr. Crossman of mine, that July 1 through 3 would be acceptable.

My staff members are:

Boyd Hamilton	no badge
C. Kelley Crossman	Badge 99555
Harry W. Kopp	no badge

EPA Region VI may also provide a representative for this meeting. This would be Ms. Jamie Wright if she is available.

It will be necessary for the attendees to visit each outfall point and observe any treatment, storage or accumulation facility associated with the waste stream. We will require appropriate escorts and knowledgeable staff members from the lab who can explain the waste operation at each point.

If you have any questions, please call Mr. Crossman at 827-2923 or me at 827-2924.

Sincerely,

Peter H. Pache
Program Manager
Hazardous Waste Section

PHP/CKC/mp

cc: Sam Becker, EPA (6H-C)
Jamie Wright, EPA (6H-CP)
Ernie Rebeck, GW/HW Bureau
Kathy Sisneros, Surface Water Bureau



14882