

TA16

SWMU 16-021(c)

Goering, Darlene, NMENV

From: Goering, Darlene, NMENV
Sent: Thursday, February 15, 2007 11:23 AM
To: 'Don Hickmott'
Subject: RE: Borehole map

Don

My original response (letter dated August 17th, 2006) to your borehole location proposal requested the southwest borehole be relocated approximately 40 feet to the northwest because this location would be closer to the pond, outfall, and previously-detected contamination. After reviewing the proposed locations again, I am inclined to agree with the location for the southwestern borehole. It appears that this location would serve to bound contamination (if not detected) on the south side of the outfall. If you have any questions, feel free to call.

Darlene Goering
Environmental Specialist
New Mexico Environment Department
2905 Rodeo Park Drive East, Bldg. 1
Santa Fe, NM 87505
505-476-6042
505-476-6030 Fax

-----Original Message-----
From: Don Hickmott [mailto:dhickmott@lanl.gov]
Sent: Tuesday, February 13, 2007 9:45 AM
To: Goering, Darlene, NMENV
Subject: Borehole map

Hi Darlene, Attached (per our conversation yesterday) is a copy of our letter with a red line showing the approximate 40 ft move of the southernmost borehole. As you can see this puts the borehole on the North side of the drainage - almost west of the contaminated borehole. Just wanted to make sure that was OK - nothing on the south side of the drainage. Don

