

# Los Alamos National Laboratory

ENVIRONMENTAL RESTORATION

*University of California*  
Environmental Restoration, MS M992  
Los Alamos, New Mexico 87545  
505-665-4557  
FAX 505-665-4747

*U. S. Department of Energy*  
Los Alamos Area Office, MS A316  
Los Alamos, New Mexico 87544  
505-665-7203  
FAX 505-665-4504

Ms. Barbara Driscoll  
NM/Federal Facilities Section  
Environmental Protection Agency  
Region 6  
1445 Ross Avenue, Suite 1200  
Dallas, TX 75202-2733

Date: **FEB 22 1995**  
Refer to: EM/ER:95-J043

O.U. 1079

Dear Ms. Driscoll:

**SUBJECT: SCHEDULES FOR SOLID WASTE MANAGEMENT UNIT (SWMU) 0-032 AND TECHNICAL AREA (TA)-32**

In December, you requested information on past activities at SWMU 0-032 and on expected schedules for SWMU 0-032 and TA-32. The information you requested is transmitted in this letter. The schedules for proposed activities are based on the 1995 Baseline, and may be subject to revision.

### **SWMU 0-032**

The information for past activities is taken from the field logs of SWMU 0-032, and the expected schedule is taken from the 1995 Baseline.

<u>ACTIVITY</u>	<u>DATE</u>
UST-4 Removal Complete	June 9, 1994
Junction Boxes 5N and 5S Removal Complete	June 7, 1994
Building 1 Boring Complete	April 14, 1994
Last Waste Characterization Sample Results Received	June 15, 1994
Last Resource Conservation and Recovery Act Facility Investigation (RFI) Characterization Sample Results Received	July 28, 1994



FEB 22 1995

B. Driscoll  
EM/ER:95-J043  
Page 2

Submit Draft RFI Report for SWMU 0-032 to the  
Environmental Protection Agency (EPA)

March 2, 1995

Note: The original RFI Work Plan called for reporting the work done for SWMUs 0-032 and 0-031(b), the two constituents of SWMU Group 0-4, in one RFI Report. Analytical results from 0-032 justify a recommendation for No Further Action. Substantially more field work was required at 0-031(b), and the analytical results indicate that Expedited Cleanup work is appropriate. Thus, RFI Reports for the two SWMUs are being prepared separately.

### TA-32

This schedule is taken from the 1995 Baseline.

<u>ACTIVITY</u>	<u>DATE</u>
Phase I Field Work for SWMUs 32-001, 32-002(a,b) Complete	January 27, 1995
Submit Draft of Phase I RFI Report (with Phase II Sampling Plan) for SWMUs 32-001, 32-002(a,b) to EPA	May 12, 1995
Start Phase II Field Work for SWMU 32-002(b) Outfall	September 5, 1995
Phase II Field Work for SWMU 32-002(b) Outfall Complete	May 14, 1996
Submit Draft of Phase II RFI Report for SWMU 32-002(b) Outfall to EPA	October 1, 1996
Start EC Field Work for SWMU 32-002(b) Outfall	December 13, 1996
EC Field Work for SWMU 32-002(b) Outfall Complete	September 17, 1997
Submit Draft of EC Report for SWMU 32-002(b) Outfall to EPA	December 3, 1997
Start EC Field Work for Septic Line in Mesa Top Portion of SWMUs 32-002(a,b)	December 27, 1996
EC Field Work for Septic Line in Mesa Top Portion of SWMUs 32-002(a,b) Complete	September 29, 1997

FEB 22 1997

B. Driscoll  
EM/ER:95-J043  
Page 3

*File SW  
on 1079*

Submit Draft of EC Report for Septic Line in  
Mesa Top Portion of SWMUs 32-002(a,b) to EPA

December 15, 1997


If you have any questions, please call Garry Allen at (505) 667-3394 or Bonnie Koch at (505) 665-7202.

Sincerely,



Jorg Jansen, Project Manager  
Environmental Restoration

Sincerely,





Theodore J. Taylor, Program Manager  
Los Alamos Area Office

JJ/bp

Cy:

- J. Jansen, EM/ER, MS M992
- T. Taylor, LAAO, MS A316
- T. Glatzmaier, EES-DO/ER, MS M992
- D. McInroy, EM/ER, MS M992
- G. Allen, CST-18, MS E525
- B. Hoditscheck, NMED
- B. Swanton, NMED-AIP, MS J993
- B. Koch, LAAO, MS A316
- J. Levings, ERD, MS A906
- E. Merrill, EM-452, HQ
- W. Spurgeon, EM-452, HQ
- EM/ER File, MS M992
- RPF, MS M707



TL