

OFFICE MEMORANDUM

TO : Homer Milford, Eng-4
Through : Dean Meyer, Group Leader, H-2
FROM : John Enders, H-1
SUBJECT: Request for work orders
SYMBOL :

DATE: 3/15/63

Would you please write a work order to perform the following?

1. Furnish labor to drive metal stakes into ground at locations in Area C designated by H-1. These are the identification stakes for disposal wells in this area. The CMR Bld. Section, H-1, will have to be contacted for entry into this Area.
2. Furnish labor and equipment to cover exposed trash in Pit #9, Area G. This cover will be needed within the next two weeks.
3. Provide labor and equipment to drill one four-foot diameter disposal well in Area C. Well should be at least 40 feet in depth. Location of well to be designated by Eng-3. CMR Bld. Section, H-1, will have to be contacted for entry into this Area.
4. Request Eng-2 to design a well cover for above well. The design may be similar to the covers for the two-foot wells in this Area.
5. Request Shops Dept. to fabricate above cover and Supply and Property to deliver finished cover to Area C.

The above requested disposal well is to be used for contaminated animal tissue disposal and for other material as required. Such a well will prevent access by predators, rodents and hawks, etc. which cannot be prevented at the present open disposal pits in Area G.

John Enders

cc: File

*Addendum to #11 -- backfill used wells
with dirt to ground
level.
Called into Milford, Eng-4, on 4/4/63*



TA-50




Fig. G-40. Crosssection of trenches with casks in place